



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFS2040A

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 23259
Reg No/Reg Date SFS2040A / 14/01/2015
Date In/Mileage 15/05/2018/ 38016
Chassis No WDD2120362B105087
Engine No 27492030300013
Make/Model MB/E 250 2.0 CGI SEDAN (W212
Colour/Trim 027 792 Palladium S/ 042 211 Leather Ant

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	15/05/2018/ 17:13	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :D18MTPV01001617 // 18-04-2018 DRIVE IN:30-04-2018 // TP CAR NO:SHC122X (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:15-05-2018 // LKK TAUFIKH BY/AUTHORIZED ON :				
A BPILAB REPAIR REAR END PANEL				960.00
A BPIRES RESPRAY REAR END PANEL				600.00
X REAR BOTTOM UNDER CARRIAGE COVER	1.00	38.15	00.00	38.15
X RIVET	4.00	4.42	00.00	17.68

ESTIMATE

SUPPLEMENTARY

Taufik 15/5/18 @ 1715
add + 3 days
23/5/18

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on 1615.83
Nett 1,615.83
113.11

Authorized signatory and company stamp

Total Payable 1,728.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg