

27/03/2002

ASS. REC. BY:

REF:

CS/FCL18008034 / R1s8bez

Special Instruction:

Surveyor

Ragall

ASSIGNMENT (Office)

From (Person):

WS

Sthara

of

FCL

Date/Time:

30042018 635pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 3215Y

Insured:

SHC 491E

at Workshop m/s

Ding Auto

Tel:

8303 9588

of

31 Corporation Rd

Policy No:

Claim No:

D18003353MTSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28042018

CA / REV / REP. / REV 24 HRS DS.

H.O.D. Endorsement:

Date/Time:

02052018 9AM

Person Contacted:

Alex

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 3215Y - CC4 / ALH D300311 / RYvh

DUA: 11022009

SHC 491E - RS / FCL17003076 / TJh3m2

DUA: 130217

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SAB 3215 Y**

at Workshop m/s **DINH AUTO**

of **31, Corporation M**

Insured: **FCI / DS**

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) **AKA**

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SAB 3215 Y** Yr Regn: **2016 / Jan**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / **Taxi** / Prime Mover /

Truck / Trailer or

Make: **Hyundai I40** c.c. **1685**

Colour: **Yellow** A/C: Insured / Std / NI / NA

Sp. Reading: **374400** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **KM4LB41UM6U080816**

Gen. Cond: Good / **Fair** / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Ni** / S/Rim / STD A/Rim or

Tyre Size: F: **205/60R16**

R: **7**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **TRIANGLE**

Front

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **28/04/18** D.O.I. **02/05/18**

Survey held at **DINH AUTO**

Des. of Damages: **FR** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

HS \$ 4,100/-
06/06/18 (\$ 21,324.28 - \$ 4,100/-) - Reduction = 80%

RECEIVED 06 JUN 2018

Date/Time, File Pass to?

06/06/18

1) **Typ 31**

Date/Time, File Return to?

2) _____

☐: Preli. Report

☒: Final Report

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: ☐: Site Insp (\$)

☐: Interview (\$)

☐: Tech. Invs (\$)

☐: Weekend (\$)

Survey Fee:

Transportation

☐ S + RS ☐ SI

☐ Photos

☐ Others

☐

TOTAL

11x15

170+165

50

50

63

6

148

Report Format :

Lump Sum / I.B.I. (\$) **4,100/- HS**

MOTOR SURVEY ASSIGNMENT

Date	30-04-2018	Our Ref No. D18003353MFSH
Accident Date	28-04-2018	Claim Type. Third Party
Insured Vehicle	SHC0491E	Third Party Vehicle. SHB3215Y
Survey Location	31 CORPORATION ROAD 649825	
Contact Person.	ALEX KHONG	
Contact No.	62654170/ 83039588	Fax No. 64534227
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DING AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 3 May 2018 2:18 PM
To: 'Catherine Chong (LKK Auto)'; 'Claim Workflow System';
ASSIGNMENTS@LKKAUTO.COM
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; 'SUR'
Subject: RE: SURVEY ASSESSMENT - D18003353MFSH/1
Attachments: SHB 3215Y - Preli Advise.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SHB 3215Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 2 May 2018 9:30 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003353MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 30 April, 2018 6:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003353MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Shirley Hiew (LKK Auto)

From: Admin@Ding Automotive <admin@dingautomotive.com.sg>
Sent: Friday, 1 June 2018 10:40 AM
To: 'Rasul (LKKAuto)'; taxiscs@stengg.com; 'Kelly Ding'; 'Michelle'
Cc: 'SUR'; 'Asher Sng (LKKAuto)'; 'Admin A'
Subject: RE: SHB3215Y - Request Item Photo.

Dear Rasul,

Thank you for your finalize amount.

Yes, we accept your offer.

Dear Michelle,

Please issue LOD as soon as possible.

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Friday, June 1, 2018 9:37 AM
To: Admin@Ding Automotive; taxiscs@stengg.com; 'Kelly Ding'; 'Michelle'
Cc: SUR; Asher Sng (LKKAuto); Admin A
Subject: RE: SHB3215Y - Request Item Photo.

FINALISED AMOUNT IS \$ 4,100.00 / 6 DAYS LUMP SUM
KINDLY CONFIRM

Best Regards,
Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Admin@Ding Automotive [mailto:admin@dingautomotive.com.sg]
Sent: Wednesday, 30 May, 2018 9:39 PM
To: taxiscs@stengg.com; Rasul (LKKAuto); 'Kelly Ding'; 'Michelle'; Rasul (LKKAuto)
Cc: 'Admin@Ding Automotive'; SUR; Asher Sng (LKKAuto); Admin A
Subject: RE: SHB3215Y - Request Item Photo.

Dear Rasul, SUR and LKK Motor Claims Officers,

Please help to finalize and close the attached and below vehicle with us as soon as possible.

After Paint .

Finalize Amount
Total Repair - 06 Days

Labour - \$1500 /-
Special Netts - \$435 /-
Parts - \$4037.20 /-
Parts after 20% discount = \$3229.76 /-
Total L+S+P = \$5164.76 /- - 20% Lump Sum
Final Amount = \$4131.80 /-

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

From: taxiscs@stengg.com [mailto:taxiscs@stengg.com]
Sent: Tuesday, May 8, 2018 3:19 PM
To: rasul@lkkauto.com
Cc: "ACCOUNTS@DINGAUTO.SG"@stms.st.com.sg; "ADMIN@DINGAUTOMOTIVE.COM.SG"@stms.st.com.sg;
sur@lkkauto.com; AsherSng@lkkauto.com; admin-a@lkkauto.com
Subject: SHB3215Y - Request Item Photo.

Dear Rasul ,

SHB3215Y Request item .

Please help to close this case ASAP

Thanks

Best Regards
Ding Automotive Pte Ltd
31 Corporation Road Singapore 649825
Alex Khong
Hp : 83039588 / 62657130

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]



Virus-free. www.avast.com

LKK: Consolidated D/S Statistics (Average) For the month of May 2018

May 2018									
(Six Months) Average from November to April'18									
Assignment from	No. of Cases Settled	AVE. COST OF REPAIR			AVE. COR+LOU/LOR+DISB		AVE. COST OF REPAIR		
		Claimed	Adjusted		Claimed for all	Paid for all	Claimed	Adjusted	Claimed for all
FLEET OPERATORS	190	\$ 10,540.20	\$ 3,038.94		\$ 11,238.30	\$ 3,551.28	\$ 14,472.95	\$ 4,281.80	\$ 15,269.34
GARAGE WKSP	109	\$ 12,901.79	\$ 4,723.42		\$ 13,739.02	\$ 5,263.94	\$ 14,115.98	\$ 5,041.56	\$ 14,979.65
CLAIMS DEPT.	133	\$ 10,374.83	\$ 4,455.03		\$ 11,036.01	\$ 4,996.62	\$ 11,169.61	\$ 4,191.15	\$ 11,885.12
Total Cases	432								
Reduction (%)		64.82%			62.49%		67.02%		
Average Settlement		\$ 11,085.15	\$ 3,899.93		\$ 11,806.99	\$ 4,428.39	\$ 13,338.96	\$ 4,399.05	\$ 14,122.24
Claims Rejected 30		\$ 287,858.73							
		206 \$ 2,740,801.09							
		64.88%							
		\$ 4,959.53							

ANALYSIS OF DATA-FOR PERIOD MAY 2018

- 1) Number of DS cases settled was **432** , with **542** new cases assigned to LKK.
- 2) Average Reduction from Workshop Estimate was **64.82%**[As compared to **67.02%** for the six months between November to April 2018].
- 3) Average Cost of Repair was **\$3,899.93** [As compared to **\$4,399.05** for the six months between November to April 2018].
- 4) Average Cost of Claims was **\$4,428.39** [As compared to **\$4,959.53** for the six months between November to April 2018]

Note: List of Insurance Companies Participate in Direct Settlement

- 1) AIG ASIA PACIFIC INSURANCE PTE LTD
- 2) AXA INSURANCE SINGAPORE PTE LTD
- 3) CHINA TAIPING INSURANCE (S) PTE LTD
- 4) DIRECT ASIA INSURANCE (SINGAPORE) PL
- 5) EQ INSURANCE COMPANY LTD
- 6) ECICS LTD
- 7) FWD SINGAPORE PTE LTD
- 8) INDIA INTERNATIONAL INSURANCE PL
- 9) LONPAC INSURANCE BERHAD
- 10) QBE INSURANCE (SINGAPORE) PTE LTD



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003353MFSH

Date: 03 May 2018

Our Ref: CS/FCI18008034/R1s3b

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 3215Y.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/05/2018 at the premises of M/s Ding Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>21,324.28</u> .
Revised Estimate Amount	: S\$ <u>4,346.60</u> .
"Check" Items Amount	: S\$ <u>5,949.19</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Mohd. Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/04/2018 14:38
Date Of Accident	28/04/2018 13:05
Exact Location Of Accident	ALONG BUKIT TIMAH ROAD TOWARDS WOODLAND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB3215Y
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40-1.7 D CRDI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	ANG KIM GUAN
NRIC No	S1630746G
Date Of Birth	28/10/1964
Occupation	OUTDOOR
Date Of Driving Pass	10/09/1987
Driving Experience	30 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97247065
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 426 CHOA CHU KANG AVENUE 4 #06-176 SINGAPORE 2368
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH STATEMENT .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC491E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLE2504G
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 28 APR 2018 At about 1305 hours, I was travelling on my taxi (SHB3215Y) along Bukit Timah towards woodland, I was keep driving on my lane, Suddenly in front of my vehicle (SLE2504G) emergency brake, I was stopped in time and after a few second the third party vehicle (SHC491E) hit on to my taxi rear, Cause my taxi push towards and bang the front vehicle (SLE2504G).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DING AUTOMOTIVE PTE LTD

BLK 10, NO.1-20 SIN MING INDUSTRIAL EST, SEC C SINGAPORE 575645
TEL : 6452 1228 FAX : 6452 0818

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

30/04/2018 16:07

JOB-NO: 50110610

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3215Y

TRANS: AUTO

CHASSIS: KMHLB41UMGU080816

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4DFU566458

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	0.00	1,500.00	Y		600
2 R&R FRONT SUPPORT PANEL & RADIATOR	1.00	120.00	0.00	120.00	Y		80?/
3 R&R CONDENSER & CHARGES TOP UP GAS	1.00	120.00	0.00	120.00	Y		60?/
4 ADJUST HEADLAMP AIM & CHECKING WIRING	1.00	80.00	0.00	80.00	Y		30
5 R&R TURBO INTERCOOLER	1.00	80.00	0.00	80.00	Y		X n n
6 R&R BOOTLID COMPENENTS	1.00	80.00	0.00	80.00	Y		X n n
7 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	80.00	0.00	80.00	Y		60
8 RUST PROOFING	1.00	80.00	0.00	80.00	Y		20
9 SUNDRIES	1.00	80.00	0.00	80.00	Y		10
10 R&R FRONT BONNET COMPONENTS	1.00	80.00	0.00	80.00	Y		X n n
11 CHECK & REPAIR WIRING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	160.00	0.00	160.00	Y		X n n
12 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	Y		180
13 RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	Y		X n n
14 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		180
15 RESPRAY REAR BUMPER DIFFUSER	1.00	180.00	0.00	180.00	Y		100
16 RESPRAY BOOTLID	1.00	250.00	0.00	250.00	Y		X n n
17 RESPRAY BOOTLID GARNISH	1.00	180.00	0.00	180.00	Y		X n n
18 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		180
TOTAL:		4,070.00	0.00	4,070.00			

MATERIALS

1 FRONT BUMPER	1.00	544.00	0.00	544.00	L	Y	DE -
2 FRONT BUMPER TOP SEAL	1.00	26.20	0.00	26.20	L	Y	X n n
3 FRONT BUMPER RETAINER LH	1.00	24.60	0.00	24.60	L	Y	X n n
4 FRONT BUMPER RETAINER RH	1.00	24.60	0.00	24.60	L	Y	12
5 FRONT BUMPER TOWING CAP	1.00	22.40	0.00	22.40	L	Y	X n n
6 FRONT BUMPER RADIATOR GRILLE	1.00	1,110.10	0.00	1,110.10	L	Y	CR
7 FRONT BUMPER GRILLE LOGO	1.00	35.00	0.00	35.00	L	Y	12
8 FRONT BUMPER GRILLE CHROME	1.00	150.10	0.00	150.10	L	Y	X n n
9 FRONT BUMPER REINFORCEMENT	1.00	402.10	0.00	402.10	L	Y	?
10 FRONT BUMPER REINFORCEMENT SPONGE	1.00	99.66	0.00	99.66	L	Y	?
11 FRONT BUMPER REINFORCEMENT STIFFENER	1.00	160.00	0.00	160.00	L	Y	?
12 HEADLAMP LH	1.00	1,808.10	0.00	1,808.10	L	Y	?
13 HEADLAMP RH	1.00	1,808.10	0.00	1,808.10	L	Y	?

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
14 HORN LH	1.00	83.73	0.00	83.73	L	Y	X su
15 HORN RH	1.00	83.73	0.00	83.73	L	Y	X su
16 RADIATOR SUPPORT PANEL	1.00	917.58	0.00	917.58	L	Y	X su
17 RADIATOR ASSY	1.00	698.42	0.00	698.42	L	Y	X su
18 RADIATOR COOLANT	1.00	40.00	0.00	40.00	L	Y	X su
19 AIR-COND CONDENSER ASSY	1.00	927.25	0.00	927.25	L	Y	X su
20 TURBO INTERCOOLER	1.00	1,050.20	0.00	1,050.20	L	Y	X su
21 BONNET	1.00	2,265.85	0.00	2,265.85	L	Y	X su
22 BONNET LOCK	1.00	36.90	0.00	36.90	L	Y	X su
23 BONNET LOCK CATCH	1.00	18.90	0.00	18.90	L	Y	X su
24 REAR BUMPER	1.00	637.85	0.00	637.85	L	Y	X su
25 REAR BUMPER REINFORCEMENT	1.00	438.40	0.00	438.40	L	Y	X su
26 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	85.63	0.00	85.63	L	Y	X su
27 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	85.63	0.00	85.63	L	Y	X su
28 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.62	0.00	89.62	L	Y	X su
29 REAR BUMPER RETAINER LH	1.00	38.63	0.00	38.63	L	Y	X su
30 REAR BUMPER RETAINER RH	1.00	38.63	0.00	38.63	L	Y	X su
31 REAR BUMPER REFLECTOR LH	1.00	42.50	0.00	42.50	L	Y	X su
32 REAR BUMPER REFLECTOR RH	1.00	42.50	0.00	42.50	L	Y	X su
33 REAR BUMPER DIFFUSER	1.00	157.55	0.00	157.55	L	Y	X su
34 BOOTLID	1.00	1,849.50	0.00	1,849.50	L	Y	X su
35 BOOTLID RUBBER BEADING	1.00	89.65	0.00	89.65	L	Y	X su
36 BOOTLID EMBLEM-LOGO	1.00	23.67	0.00	23.67	L	Y	X su
37 BOOTLID EMBLEM-I 40	1.00	33.55	0.00	33.55	L	Y	X su
38 BOOTLID EMBLEM-CRDI	1.00	36.50	0.00	36.50	L	Y	X su
39 REAR END PANEL	1.00	526.95	0.00	526.95	L	Y	X su
40 FRONT BUMPER RETAINER SCREW & GROMMET SET	1.00	15.00	0.00	15.00	S	Y	X su
41 FRONT BUMPER NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	X su
42 FRONT BUMPER GRILL CLIP SET	1.00	25.00	0.00	25.00	S	Y	X su
43 FRONT BUMPER CLIP SET	1.00	25.00	0.00	25.00	S	Y	X su
44 FRONT BUMPER REINFORCEMENT SCREW SET	1.00	15.00	0.00	15.00	S	Y	X su
45 REAR BUMPER CLIP SET	1.00	25.00	0.00	25.00	S	Y	X su
46 REAR BUMPER RUBBER PROTECTOR PAD	1.00	180.00	0.00	180.00	S	Y	X su
47 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	X su
48 REAR BUMPER UPPER SCREW&GROMMET SET	1.00	15.00	0.00	15.00	S	Y	X su
49 BOOTLID STICKER-COMFORTDELGRO BOOKING 65521111	1.00	80.00	0.00	80.00	S	Y	X su
50 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X su
TOTAL:		17,254.28	0.00	17,254.28			
TOTAL PARTS & LABOUR:		21,324.28	0.00	21,324.28			

EXCESS/LOADING:SS 0.00

No. Of Day:

6 days

RE-SURVEY: BEFORE(AFTER PAINTING)

PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 02 / 05 / 18 @ 1345

SURVEYED BY:

RASUL (KKK)

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
DAuto001

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
Ding Auto User 1							
ESTIMATOR							
STA AUTOCENTRE							
TEL:		FAX:					

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



DING AUTOMOTIVE PTE LTD

BLK 10, #01-20 SIN MING INDUSTRIAL EST, SEC C SINGAPORE 575645
TEL: 6452 1208 FAX: 6452 0834

TO :

APPROVAL REPORT 1ST Quotation

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet) CONTACT: 65533880
ADDRESS: 383 SIN MING DRIVE 64739522
SINGAPORE 575717 0

FAX NO:

08/05/2018 14:39

JOB-NO: 50110610

PAGE: 1 of 1

VEHICLE DETAILS

LICENSE NO: SHB3215Y TRANS: AUTO CHASSIS: KMHLB41UMGU080816
MAKE / MODEL: HYUNDAI / i40 ENGINE: D4FDFU566458
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	REV PRICE	APPROVAL
<u>LABOUR</u>				
1 RESPRAY BOOTLID GARNISH	1.00	180.00	0.00	No
2 R&R TURBO INTERCOOLER	1.00	80.00	0.00	No
3 RESPRAY FRONT BONNET	1.00	250.00	0.00	No
4 R&R BOOTLID COMPONENTS	1.00	80.00	0.00	No
5 R&R FRONT BONNET COMPONENTS	1.00	80.00	0.00	No
6 RESPRAY BOOTLID	1.00	250.00	0.00	No
7 CHECK & REPAIR WIRING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	160.00	0.00	No
8 ADJUST HEADLAMP AIM & CHECKING WIRING	1.00	80.00	30.00	Yes
9 SUNDRIES	1.00	80.00	10.00	Yes
10 RESPRAY REAR BUMPER DIFFUSER	1.00	180.00	100.00	Yes
11 RESPRAY FRONT BUMPER	1.00	250.00	180.00	Yes
12 RUST PROOFING	1.00	80.00	20.00	Yes
13 RESPRAY REAR BUMPER	1.00	250.00	180.00	Yes
14 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	600.00	Yes
15 RESPRAY REAR END PANEL	1.00	250.00	180.00	Yes
16 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	80.00	60.00	Yes
17 R&R CONDENSER & CHARGES TOP UP GAS	1.00	120.00	60.00	Yes
18 R&R FRONT SUPPORT PANEL & RADIATOR	1.00	120.00	80.00	Yes
TOTAL:		4,070.00	1,500.00	

MATERIALS

1 BOOTLID EMBLEM-CRDI	1.00	29.20	0.00	No
2 BONNET LOCK CATCH	1.00	15.12	0.00	No
3 BONNET	1.00	1,812.68	0.00	No
4 FRONT BUMPER TOWING CAP	1.00	17.92	0.00	No
5 BONNET LOCK	1.00	29.52	0.00	No
6 BOOTLID EMBLEM-LOGO	1.00	18.94	0.00	No
7 REAR BUMPER RETAINER RH	1.00	30.90	0.00	No
8 REAR END PANEL	1.00	421.56	0.00	No
9 HORN RH	1.00	66.98	0.00	No
10 FRONT BUMPER GRILLE CHROME	1.00	120.08	0.00	No
11 BOOTLID EMBLEM-I 40	1.00	26.84	0.00	No
12 TURBO INTERCOOLER	1.00	840.16	0.00	No
13 FRONT BUMPER RETAINER LH	1.00	19.68	0.00	No

TO :

APPROVAL REPORT 1ST Quotation**OWNER'S PARTICULARS**

NAME: CityCab PTE LTD (Fleet) CONTACT: 65533880
 ADDRESS: 383 SIN MING DRIVE 64739522
 SINGAPORE 575717 0

FAX NO:

08/05/2018 14:39

JOB-NO: 50110610

PAGE: 1 of 1

VEHICLE DETAILS

LICENSE NO: SHB3215Y TRANS: AUTO CHASSIS: KMHLB41UMGU080816
 MAKE / MODEL: HYUNDAI / i40 ENGINE: D4FDFU566458
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	REV PRICE	APPROVAL
14 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	68.50	0.00	No
15 BOOTLID STICKER-COMFORTDELGRO BOOKING 65521111	1.00	80.00	0.00	No
16 AIR-COND CONDENSER ASSY	1.00	741.80	0.00	No
17 FRONT BUMPER REINFORCEMENT STIFFENER	1.00	128.00	0.00	No
18 FRONT BUMPER REINFORCEMENT SPONGE	1.00	79.73	0.00	No
19 HEADLAMP LH	1.00	1,446.48	0.00	No
20 HORN LH	1.00	66.98	0.00	No
21 BOOTLID RUBBER BEADING	1.00	71.72	0.00	No
22 BOOTLID	1.00	1,479.60	0.00	No
23 REAR BUMPER RETAINER LH	1.00	30.90	0.00	No
24 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	68.50	0.00	No
25 FRONT BUMPER TOP SEAL	1.00	20.96	0.00	No
26 REAR BUMPER REFLECTOR LH	1.00	34.00	0.00	No
27 REAR END PANEL SEALANT	1.00	50.00	0.00	No
28 FRONT BUMPER REINFORCEMENT	1.00	321.68	0.00	No
29 RADIATOR ASSY	1.00	558.74	0.00	No
30 HEADLAMP RH	1.00	1,446.48	0.00	No
31 REAR BUMPER RUBBER PROTECTOR PAD	1.00	180.00	80.00	Yes
32 RADIATOR COOLANT	1.00	32.00	32.00	Yes
33 FRONT BUMPER GRILL CLIP SET	1.00	25.00	25.00	Yes
34 FRONT BUMPER RETAINER SCREW & GROMMET SET	1.00	15.00	15.00	Yes
35 REAR BUMPER	1.00	510.28	510.28	Yes
36 FRONT BUMPER NUMBER PLATE	1.00	40.00	35.00	Yes
37 REAR BUMPER REINFORCEMENT	1.00	350.72	350.72	Yes
38 FRONT BUMPER RETAINER RH	1.00	19.68	19.68	Yes
39 REAR BUMPER DIFFUSER	1.00	126.04	126.04	Yes
40 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	200.00	Yes
41 REAR BUMPER REFLECTOR RH	1.00	34.00	34.00	Yes
42 FRONT BUMPER GRILLE LOGO	1.00	28.00	28.00	Yes
43 FRONT BUMPER CLIP SET	1.00	25.00	25.00	Yes
44 REAR BUMPER REINFORCEMENT SPONGE	1.00	71.70	71.70	Yes
45 FRONT BUMPER RADIATOR GRILLE	1.00	888.08	888.08	Yes
46 RADIATOR SUPPORT PANEL	1.00	734.06	734.06	Yes
47 REAR BUMPER CLIP SET	1.00	25.00	25.00	Yes
48 REAR BUMPER UPPER SCREW&GROMMET SET	1.00	15.00	15.00	Yes
49 FRONT BUMPER	1.00	435.20	435.20	Yes

TO :

APPROVAL REPORT 1ST Quotation

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet) CONTACT: 65533880
ADDRESS: 383 SIN MING DRIVE 64739522
SINGAPORE 575717 0

FAX NO:

08/05/2018 14:39

JOB-NO: 50110610

PAGE: 1 of 1

VEHICLE DETAILS

LICENSE NO: SHB3215Y TRANS: AUTO CHASSIS: KMHLB41UMGU080816
MAKE / MODEL: HYUNDAI / i40 ENGINE: D4FDFU566458
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	REV PRICE	APPROVAL
50 FRONT BUMPER	1.00	15.00	15.00	Yes
REINFORCEMENT SCREW SET				
TOTAL:		13,943.41	3,664.76	

TOTAL PARTS & LABOUR : 18,013.41 5,164.76




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008034/R1sbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 491E	Veh. Inspected	SHB 3215Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003353MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	30/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU080816	Colour	YELLOW	
Odometer	374400	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/04/2018	Inspection Date	02/05/2018	
Survey held at	31 CORPORATION RD			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3215Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	544.00	544.00
1	FRONT BUMPER TOP SEAL	SERVICEABLE	26.20	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	24.60	-
1	FRONT BUMPER RETAINER RH	NECESSARY	24.60	24.60
1	FRONT BUMPER TOWING CAP	SERVICEABLE	22.40	-
1	FRONT BUMPER RADIATOR GRILLE	CRACKED	1,110.10	1,110.10
1	FRONT BUMPER GRILLE LOGO	NECESSARY	35.00	35.00
1	FRONT BUMPER GRILLE CHROME	SERVICEABLE	150.10	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	402.10	-
1	FRONT BUMPER REINFORCEMENT SPONGE	SERVICEABLE	99.66	-
1	FRONT BUMPER REINFORCEMENT STIFFENER	SERVICEABLE	160.00	-
1	HEADLAMP LH	SERVICEABLE	1,808.10	-
1	HEADLAMP RH	SERVICEABLE	1,808.10	-
1	HORN LH	SERVICEABLE	83.73	-
1	HORN RH	SERVICEABLE	83.73	-
1	RADIATOR SUPPORT PANEL	BENT	917.58	917.58
1	RADIATOR ASSY	SERVICEABLE	698.42	-
1	RADIATOR COOLANT	SERVICEABLE	40.00	-
1	AIR-COND CONDENSER ASSY	SERVICEABLE	927.25	-
1	TURBO INTERCOOLER	SERVICEABLE	1,050.20	-
1	BONNET	SERVICEABLE	2,265.85	-
1	BONNET LOCK	SERVICEABLE	36.90	-
1	BONNET LOCK CATCH	SERVICEABLE	18.90	-
1	REAR BUMPER	DEFORMED	637.85	637.85
1	REAR BUMPER REINFORCEMENT	CRACKED	438.40	438.40
1	REAR BUMPER REINFORCEMENT BRACKET LH	SERVICEABLE	85.63	-
1	REAR BUMPER REINFORCEMENT BRACKET RH	SERVICEABLE	85.63	-
1	REAR BUMPER REINFORCEMENT SPONGE	CRACKED	89.62	89.62
1	REAR BUMPER RETAINER LH	SERVICEABLE	38.63	-
1	REAR BUMPER RETAINER RH	SERVICEABLE	38.63	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	42.50	-

Report Ref No. CS/FCI18008034/R1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REFLECTOR RH	CUT	42.50	42.50
1	REAR BUMPER DIFUSSER	DEFORMED	157.55	157.55
1	BOOTLID	SERVICEABLE	1,849.50	-
1	BOOTLID RUBBER BEADING	SERVICEABLE	89.65	-
1	BOOTLID EMBLEM - LOGO	SERVICEABLE	23.67	-
1	BOOTLID EMBLEM - I40	SERVICEABLE	33.55	-
1	BOOTLID EMBLEM - CRDI	SERVICEABLE	36.50	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	526.95	-
	LESS 20% DISCOUNT		-	-799.44
			16,554.28	3,197.76
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	10.00
1	SET FRONT BUMPER RETAINER SCREW & GROMMET (SN)	NECESSARY	15.00	15.00
1	FRONT BUMPER NUMBER PLATE (SN)	CRACKED	40.00	35.00
1	SET FRONT BUMPER GRILL CLIP (SN)	NECESSARY	25.00	25.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	SET FRONT BUMPER REINFORCEMENT SCREW (SN)	NECESSARY	15.00	15.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	REAR BUMPER RUBBER PROTECTOR PAD (SN)	NECESSARY	180.00	80.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DISTORTED	230.00	200.00
1	SET REAR BUMPER UPPER SCREW & GROMMET (SN)	NECESSARY	15.00	15.00
1	BOOTLID STICKER - COMFORTDELGRO BOOKING 65521111 (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			780.00	445.00
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	600.00
	R&R FRONT SUPPORT PANEL & RADIATOR.		120.00	80.00
	R&R CONDENSER & CHARGES TOP UP GAS.		120.00	60.00
	ADJUST HEADLAMP AIM & CHECKING WIRING.		80.00	30.00
	R&R TURBO INTERCOOLER.	NOT NECESSARY	80.00	-

Report Ref No. CS/FCI18008034/R1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	R&R BOOTLID COMPONENTS.	NOT NECESSARY	80.00	-
	R&R SPARE TYRE BOARD / CARPET / TRIM.		80.00	60.00
	RUST PROOFING.		80.00	20.00
	R&R FRONT BONNET COMPONENTS.	NOT NECESSARY	80.00	-
	CHECK & REPAIR WIRING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	NOT NECESSARY	160.00	-
	RESPRAY FRONT BUMPER.		250.00	180.00
	RESPRAY FRONT BONNET.	NOT NECESSARY	250.00	-
	RESPRAY REAR BUMPER.		250.00	180.00
	RESPRAY REAR BUMPER DIFFUSER.		180.00	100.00
	RESPRAY BOOTLID.	NOT NECESSARY	250.00	-
	RESPRAY BOOTLID GARNISH.	NOT NECESSARY	180.00	-
	RESPRAY REAR END PANEL.		250.00	180.00
			3,990.00	1,490.00
GRAND TOTAL			21,324.28	5,132.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/FCI18008034/R1sbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.