

## Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date :

### RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	AIG ASIA PACIFIC INS PTE LTD
Vehicle Reg No	:	<b>SJH7778H</b>
Date of Accident	:	20.04.2018
Tyre of Claim	:	THIRD PARTY CLAIM
Model	:	BMW 318I
Chassis No	:	WBAPF72040FG90061

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 RR BUMPER (PDC)	\$ 1,109.10	
2 REAR BUMPER SET MOUNTING PARTS	\$ 33.15	
3 RR BUMPER TOW HOOK COVER	\$ 38.00	
4 RR BUMPER CTR GUIDE	\$ 31.60	
5 REPAIR WIRING KIT FOR BUMPER REAR	\$ 289.65	
6 RR BUMPER CARRIER	\$ 424.25	

**Total Parts = \$ 1,925.75**

1	SUNDRIES	\$	150.00
2	REPLACE / REPAIR REAR BUMPER, REAR BUMPER BEAM, END PANEL	\$	1,800.00
3	RESPRAY REAR BUMPER, REAR END PANEL	\$	1,500.00
4	WIRING CONNECTION & CHECK	\$	150.00
5	REMOVE & REPLACE REVERSE SENSOR	\$	150.00
6	REMOVE & REFIX REAR LIGHTING	\$	150.00
7	TUFF KOTE @ \$60 PER PANEL	\$	120.00
8	REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM & GARNISH	\$	300.00
9	TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK	\$	600.00

Total (Labour)	<b>\$ 4,920.00</b>
----------------	--------------------

Sub Total :	\$ 6,845.75
-------------	-------------

GST 7%	\$ 479.20
--------	-----------

<b>Grand Total :</b>	<b>\$ 7,324.95</b>
----------------------	--------------------

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

**WONG GUO XIANG (64777409 / 83833190)**