



Your Ref: MCT17121116/01/SP

Date: 23rd May 2018

Our Ref: CS1/III18008042/Lqbs2

M/s India International Insurance Pte Ltd

64 Cecil Street

#05-02 IOB Building

Singapore 049711

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.:
SLL 3236L INSURED VEHICLE NO: SH 8122L ACCIDENT ON 23/12/2017**

We thank you for your instruction on 02/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLL 3236L from M/s Eurokars Habitat Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLL 3236L and SH 8122L.
- c) Colour damaged vehicle photographs of SLL 3236L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLL 3236L
Make & Mode	: Mini Cooper S Clubman
Year of Registration	: 2017
Chassis Number	: WMWLN720X02F25303
Engine Capacity	: 1998 cc

2. Our finding is that the repair cost of \$2,214.43 (before GST) quoted by M/s Trans Eurokars Pte Ltd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.

Vehicle Inspection By:



K.K.LAU

*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser*