



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 02.05.2018

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01/02

AXA Tower

Singapore 068811

Rashid
4p 900/0068
3 days
4/5
02/05/18 @ 1200
Ready after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATE COST TO VEHICLE SHD2825H TOYOTA PRIUS HYBRID 1.5EX (2011)

To supply

1) 1pc	Rear bumper	\$	580.00	<i>DC -</i>
2) 1set	Rear bumper clip	\$	50.00	<i>new -</i>
3) 1pc	Left tail lamp	cra \$	720.00	<i>X inconsistent</i>
4) 1pc	Third brake lamp spoiler	cra \$	1,450.00	<i>X inconsistent</i>
Sub total parts		\$	2,800.00	
Less: 25% discount		\$	700.00	
		\$	2,100.00	<i>old damage</i>

To supply S.Nett Parts

1) 1pc	"Prime taxi" sticker	\$	55.00	<i>new -</i>
2) 1pc	Dial-A-Cab "6778 0808" sticker	\$	45.00	<i>new -</i>
3) 1pc	Anti slip mat	\$	50.00	<i>new -</i>
Sub total S.Nett Parts		\$	150.00	

L/charges

1) To tuff kote	\$	50.00	<i>20</i>
2) To remove rear bumper, left tail lamp, third brake lamp spoiler, knock / welding tail gate lower right & end panel. Replace left tail lamp, rear bumper & third brake lamp spoiler. Align & adjust rear bumper.	\$	850.00	<i>300</i>
3) To putty, respray painting rear bumper, end panel & tail gate. To polish	\$	850.00	<i>400</i>

Sub total L/charges	\$	1,750.00
Estimated Grand Total	\$	4,000.00