

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : PC 4376J

Vehicle Model : SCANIA

Accident Date : 27.04.2018

Original Reg Date : 03.01.2002 (31.12.2021)

Date : 04.05.2018

Chassis : YS4K4X20001840024

TP Ins. AXA

ESTIMATE

1	1 pc	Side Fiber Fender (Top) LH	X			SN
2	1 pc	Side Fiber Fender (Lower) LH	✓			SN
3	1 pc	Side Fiber Fender Glass Moulding LH	X			SN
4	6 pcs	Side Fiber Fender Glass Inner Seal LH	X			SN
5	6 pcs	Side Fiber Fender Glass Sealant LH	X			SN
6	1 pc	Rear Wheel Arch Fiber Cover LH	✓			SN
7	2 pcs	Rear Wheel Arch Fiber Cover Hinge LH	X			SN
8	1 pc	Rear Wheel Arch Fiber Cover Key Lock LH	✓			SN
9	1 pc	Rear Wheel Arch Fiber Cover Lamp LH	✓			SN
10	1 pc	Rear Bottom Side Gate LH	X			SN
11	2 pcs	Rear Bottom Side Gate Hinge LH	X			SN
12	1 pc	Rear Bottom Side Gate Key Lock LH	X			SN
13	2 set	Rear Bottom Side Gate Air Vent LH	X			SN
14	1 pc	Taillamp LH (Bottom)	X			SN
15	1 pc	Taillamps Inner Sealer LH (Bottom)	X			SN
16	1 set	Taillamps Clip	X			SN
17	1 pc	Rear Bumper	X			SN
18	2 pcs	Rear Bumper Side Bracket	X			SN
19	1 pc	Side Skirt LH	X			SN
20	1 pc	Rear Absorber LH	X			SN
21	1 pc	Rear Absorber Wheel Bearing with Hud LH	X			SN
22	1 pc	Side Sticker (Excursion Bus)	X			SN
23	1 pc	Rear Tyre LH (Outer)	unt	50%		SN
24	1 pc	Rear Rim LH (Outer)	X			SN

Labour charge

Panel Beating	1800	3,000.00
Spray painting - 2 tones	1500	2,500.00
Anti rust	X	250.00
Check Wiring	30	50.00
Remove and install side fender glass	X	800.00
Remove and install rear carrier	X	600.00
To check four wheel alignment	X	90.00
		\$ 7,290.00