

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 30/04/2018
TP Vehicle No. : SKB- 262-U
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : HO WAI MUN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076478044-02
Vehicle No. : SKX-7971-U
Make & Model : HONDA FIT 1.3 G F-PACKAGE A

Accident Date: 29/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	REAR BUMPER R	\$710.30	X
1	REAR BUMPER RETAINER RH 11	\$25.60	X
1	REAR BUMPER RETAINER LH 11	\$25.60	X
10	REAR BUMPER CLIPS 11	\$50.00	X
1	REAR FENDER LH R	\$635.60	X
1	REAR FENDER INNER SHIELD LH 11	\$35.60	X
10	REAR FENDER INNER SHIELD CLIPS LH 11	\$50.00	X
1	REAR DOOR LH 20 / Bent	\$799.40	/
1	LH REAR DOOR HINGE BOTTOM 11	\$50.60	X
1	LH REAR DOOR WEATHERSTRIP 11	\$85.00	X
1	LH REAR DOOR HINGE UPPER 11	\$48.50	X
1	LH REAR DOOR CHECKER 11	\$48.50	X
1	LH REAR DOOR PILLAR NS	\$709.60	X
1	LH REAR AXLE BEAM 11	\$959.70	X
1	LH REAR AXLE BEAM BEARING 11	\$281.90	X
1	LH REAR SHOCK ABSORBER MOULDING 11	\$95.60	X
1	LH REAR SHOCK ABSORBER 11	\$356.90	X
	Sub Total	\$4,968.40	799.4
	Discount 20% on Parts	(\$993.68)	639.52
		\$3,974.72	
Special Nett			
1	LH REAR FENDER SEALANT 11	\$65.00	X
	Sub Total	\$65.00	
Labour & Misc			
	TO STRAIGHTEN AND PANEL BEAT ACCIDNET AREAS	\$1,500.00	550
	TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	800 700
	TO TRANSFER AND REFIX DOOR FIXTURE	\$250.00	60
	TO CONDECT 4 WHEEL ALIGNMENT	\$250.00	60

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 30/04/2018
TP Vehicle No. : SKB- 262-U
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claim Department

Owner : HO WAI MUN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076478044-02
Vehicle No. : SKX-7971-U
Make & Model : HONDA FIT 1.3 G F-PACKAGE A

Accident Date: 29/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO REMOVE AND INSTALL TYRE AND BALANCING	11 \$150.00	X
	TO APPLY UNDERCOATING FOR RUST ROOFING	\$250.00	50
	TO CARRY OUT UNDERCARRIAGE REPAIR	11 \$350.00	X
	Sub Total	\$4,250.00	
	Sub Total	\$8,289.72	
	GST 7%	\$580.28	
	Total	\$8,870.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

SUPPLEMENTARY

Date : 07/06/2018
TP Vehicle No. : SKB- 262-U
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : HO WAI MUN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076478044-02
Vehicle No. : SKX-7971-U
Make & Model : HONDA FIT 1.3 G F-PACKAGE A

Accident Date: 29/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>Special Nett</u>			
1	LH REAR SPORT RIM	\$800.00	X
	Sub Total	\$800.00	
	Sub Total	\$800.00	
	GST 7%	\$56.00	
	Total	\$856.00	