

P&S, CASE OWNER:

CC 6 / AIG1800

8060, Aua352

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

20/4/18

Date / Time:

20/4/18

Registered in Merimen:

3/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 3900H

Name of Insured:

LOO HONGYI JAMES

Insured Tel No.:

HP:

96359353

Excess Sec II :SS

D.O.A.:

26/4/18

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

2100498097-01

Mazda 2

P16 7 TMS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLK 4436 Z

S8u 6920B

SLK 3900H

SLK 3931C



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Easy

TP

Date / Time

7/5
THSLK 3931C - WA (mer) 45012044113: 008 26/6/14
SLK 3900H, x

4 vehicles chain collision and OI 2nd vehicle.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

> THIN by Email!

After call ltr to OI:

23/5

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

9/10/18

Confirm with:

Sharan

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100

Repair Cost:

S\$

4815.00

Loss of Rental (LOR):

S\$

800.00

(

8

days) x 100

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

5617.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5617.00

Name 1:

KANG CAR REPAIRERS PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

CORRECT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKB3931CYr Regn: 2006 NAVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Colt Plus c.c. 1499Colour: Red A/C: Insured / Std / NI / NASp. Reading: 210579 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYLT293W62001008Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R15R: 185/55R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 30/04/18Survey held at Keny.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.MV: 22K.PV: 182K.Nett: 48K.

US - \$45004 Cred: \$7773.38/63%.)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$)

37391



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18008060/Aua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 03-05-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 3900H	Veh. Inspected	SKB 3931C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/04/2018	Inspection Date	30/04/2018	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800122
Date: 30 Apr 2018
Veh Reg No: SKB3931C
Make/Model: MITSUBISHI
COLTPLUSPRT
Chasis No: JMYLTZ23W6Z001008
Reg. Date: 08/11/2006
Your Ref No: SLK3900H

Claim Type: Third Party
Accident Date: 26/04/2018
TP Veh Reg No: SLK3900H

Thin Thin

Estimate Repair Cost to Vehicle No :SKB3931C

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Disturbed</i>	825.00	✓
2	1 PC BOOT LID GARNISH <i>new</i>	216.00	✗
3	1 PC BOOT LID LOGO	38.00	✓
4	1 PC BOOTLID "COLT" EMBLEM <i>3 new</i>	36.00	✓
5	1 PC BOOTLID "PLUS" EMBLEM	34.00	✓
6	1 PC BOOT LID STICKER <i>new</i>	295.00	✓
7	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	130.20	✗
8	1 PC BOOT LID LAMP LH <i>cracked</i>	195.00	✓
9	1 PC BOOT LID LAMP RH <i>at</i>	195.00	✓
10	1 PC BOOT LID LOCK <i>Paint</i>	412.00	✓
11	1 PC BOOT LID LOCK CHECKER <i>new</i>	48.00	✗
12	1 PC BOOT LID INNER HOLDING HANDLE <i>new</i>	38.00	✗
13	1 PC BOOT LID TRIM <i>2 Disturbed</i>	190.00	✓
14	1 PC BOOT LID AUTO LOCK SENSOR <i>2 new</i>	1,450.00	✗
15	2 PCS BOOT LID INNER SIDE RUBBER <i>new</i>	196.00	✗
16	2 PCS BOOTLID STOPPER RUBBER <i>new</i>	36.00	✗
17	1 PC REAR WINDSCREEN RUBBER <i>new</i>	120.00	✓
18	1 PC BOOT LID RUBBER <i>at</i>	180.00	✓
19	1 PC REAR PANEL <i>2 cracked</i>	420.00	✓
20	1 PC REAR PANEL TRIM <i>2 cracked</i>	155.00	✓
21	1 PC REAR FENDER TRIM RH <i>3 new</i>	275.00	✗
22	1 PC REAR FENDER TRIM LH	275.00	✗
23	1 PC SPARE TYRE TOP COVER <i>3 cracked</i>	406.00	✓
24	1 PC REAR COMPARTMENT COVER	595.00	✓
25	1 PC TAIL LAMP LH <i>3 cracked</i>	310.00	✓
26	1 PC TAIL LAMP - RH	310.00	✓
27	1 PC REAR BUMPER <i>2 cracked</i>	682.00	✓
28	1 PC REAR BUMPER BEAM <i>3 cracked</i>	159.00	✓
29	2 PCS REAR BUMPER BRACKET <i>new</i>	122.00	✗

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangear@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800122
Date: 30 Apr 2018
Veh Reg No: SKB3931C
Make/Model: MITSUBISHI COLTPLUSPRT
Chasis No: JMYLTZ23W6Z001008
Reg. Date: 08/11/2006
Your Ref No: SLK3900H

Claim Type: Third Party
Accident Date: 26/04/2018
TP Veh Reg No: SLK3900H

Estimate Repair Cost to Vehicle No :SKB3931C

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	2 PCS REAR BUMPER SIDE RETAINER <i>men</i>	78.00 ✓	
31	1 PC REAR BUMPER REFLECTOR - LH <i>men</i>	82.00 X	
32	1 PC REAR BUMPER REFLECTOR - RH <i>men</i>	82.00 X	
33	1 PC EXHAUST PIPE <i>men</i>	895.00 X	
34	2 PCS EXHAUST PIPE MOUNTING <i>men</i>	48.00 X	
		9,528.20	
	Less 10%	952.82	8,575.38
	Special Net		
35	1 PC REAR NUMBER PLATE <i>Best</i>	50.00 ✓	
36	1 SET BOOT LID TRIM CLIPS <i>men</i>	40.00 30	
37	1 PC REAR WINDSCREEN SEAL <i>men</i>	60.00 30	
38	1 PC REAR WINDSCREEN SEALANT <i>men</i>	60.00 30	
39	1 SET REAR PANEL TRIM CLIPS <i>men</i>	40.00 10	
40	1 SET REAR FENDER TRIM CLIPS RH <i>men</i>	40.00 X	
41	1 SET REAR FENDER TRIM CLIPS LH <i>men</i>	40.00 X	
42	1 SET REVERSE SENSORS <i>men</i>	250.00 20	
43	1 SET REAR BUMPER CLIPS <i>men</i>	48.00 30	
		628.00	628.00
	Labour		
44	1 TO CHECK WIRING	50.00 30	
45	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 100	
46	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
47	1 TO REMOVE AND REFIT REAR EXHAUST PIPE	150.00 X	
48	1 TO SPRAY UNDERSEAL	150.00 60	
49	1 (REAR) TO SPRAY PAINTING	1,200.00 80	
50	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 80	
51	1 TO REMOVE AND REFIT INNER TRIM	120.00 60	
		3,070.00	3,070.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/04/2018
TP Veh Reg No: SLK3900H

Estimate No: EST1800122
Date: 30 Apr 2018
Veh Reg No: SKB3931C
Make/Model: MITSUBISHI
COLTPLUSPRT
Chasis No: JMYLTZ23W6Z001008
Reg. Date: 08/11/2006
Your Ref No: SLK3900H

Estimate Repair Cost to Vehicle No :SKB3931C

Quantity	Description	List Price	Amount
		SS	SS
	Total		S\$ 12,273.38
	Add GST @ 7%		859.14
	Total Amount Payable		S\$ 13,132.52

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND ONE HUNDRED THIRTY TWO AND CENTS FIFTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim
L/S 30/04/18.
OK Days.

Total: 7351.50
L/S: 4.5K
ASIC

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Apr 2018 Edit Reg		30 Apr 2018 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LOO ZHONGYI JAVIER, ID: S8432651H, Tel: +6596359353		
Main Claimant:	ENG SENG LIANG, ID: S0213739I		
Vehicle Reg. No.:	SKB3931C	Date of Loss:	26/04/2018 19:00 - :59 [137 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0731436377SG	Policy/Cover Note No.:	2100498097 (Comprehensive) Coverage: 16/01/2018 - 15/01/2019
Vehicle Reg. No. (Insured):	SLK3900H	Policy No. (Claimant):	5062319774-04
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/05/2018]		
Driver/Custodian (Insured):	LOO ZHONGYI JAVIER (), NRIC: S8432651H, Tel: +6596359353		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB3931C (0731436377SG)**
[SLK3900H]

TP

ENG SENG LIANG

Apr 26 2018 7:00PM

[LOO ZHONGYI JAVIER]

Kang Car Repairers Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
----------------------------------	-------------------------------	------------------------------------	------------------------------	------------------------------	---

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	

Assessment Reports			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/05/18 14:06	Accident Statement From:OD - Reg. No: SLK3900H, Claimant: LOO ZHONGYI JAVIER	 Load HTM	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 19:01	General View	 Load JPG	☒
2	24/09/18 19:01	General View	 Load JPG	☒
3	24/09/18 19:01	General View	 Load JPG	☒
4	24/09/18 19:01	General View	 Load JPG	☒
5	24/09/18 19:01	General View	 Load JPG	☒
6	24/09/18 19:01	General View	 Load JPG	☒
7	24/09/18 19:01	General View	 Load JPG	☒
8	24/09/18 19:01	General View	 Load JPG	☒
9	24/09/18 19:01	General View	 Load JPG	☒
10	24/09/18 19:01	General View	 Load JPG	☒
11	24/09/18 19:01	General View	 Load JPG	☒
12	24/09/18 19:01	General View	 Load JPG	☒
13	24/09/18 19:01	General View	 Load JPG	☒
14	24/09/18 19:01	General View	 Load JPG	☒
15	24/09/18 19:01	General View	 Load JPG	☒
16	24/09/18 19:01	General View	 Load JPG	☒
17	24/09/18 19:01	General View	 Load JPG	☒
18	24/09/18 19:01	General View	 Load JPG	☒
19	24/09/18 19:01	General View	 Load JPG	☒
20	24/09/18 19:01	General View	 Load JPG	☒
21	24/09/18 19:01	General View	 Load JPG	☒
22	24/09/18 19:01	General View	 Load JPG	☒
23	24/09/18 19:01	General View	 Load JPG	☒
24	24/09/18 19:01	General View	 Load JPG	☒
25	24/09/18 19:01	General View	 Load JPG	☒
26	24/09/18 19:01	General View	 Load JPG	☒
27	24/09/18 19:01	General View	 Load JPG	☒
28	24/09/18 19:01	General View	 Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	24/09/18 19:01	General View	 Load JPG	✓
30	24/09/18 19:01	General View	 Load JPG	✓
31	24/09/18 19:01	General View	 Load JPG	✓
32	24/09/18 19:01	General View	 Load JPG	✓
33	24/09/18 19:01	General View	 Load JPG	✓
34	24/09/18 19:01	General View	 Load JPG	✓
35	24/09/18 19:01	General View	 Load JPG	✓
36	24/09/18 19:01	General View	 Load JPG	✓
37	24/09/18 19:01	General View	 Load JPG	✓
38	24/09/18 19:01	General View	 Load JPG	✓
39	24/09/18 19:01	General View	 Load JPG	✓
40	24/09/18 19:01	General View	 Load JPG	✓
41	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
42	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
43	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
44	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
45	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
46	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
47	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
48	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
49	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
50	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
51	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
52	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
53	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
54	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
55	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
56	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
57	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
58	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
59	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
60	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
61	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
62	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
63	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
64	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
65	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
66	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
67	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
68	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
69	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
70	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
71	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
72	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
73	24/09/18 19:01	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/05/18 12:51	TP GIA REPORT	 Load PDF	

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼	✓
2	31/10/18 14:19	AUTHORISATION TO ACT		Thumbnail Print
3	31/10/18 14:19	GIA SEARCH		Load PDF
4	31/10/18 14:19	LETTER TO OI		Load PDF
5	31/10/18 14:19	RELEASE VOUCHER		Load PDF
6	31/10/18 14:19	RENTAL RECEIPT		Load PDF
7	31/10/18 14:19	WORKSHOP INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset

Save

Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK3900H (Insd veh)	Model:	MITSUBISHI COLT PLUS SPRT
	SKB3931C (TP veh)		1.5 (A)
Date of Accident:	26/04/2018		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				13,132.52
Final Repair Cost	:	\$				4,815.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				800.00 8 days
LTA / GIA Search Fee	:	\$				2.00
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				5,617.00

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ 100 _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 5,617.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

31 Oct
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008060/AUA3S2
Date: 31/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498097
Claimant Vehicle No : SKB3931C **Insured Vehicle No :** SLK3900H
 Date of Loss: 26/04/2018 Nature of Claim: TP Claim No: 0731436377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB3931C**
 Make & Model: MITSUBISHI COLT PLUS SPRT, 1.5 (A) Engine No: 4A910030361
 Reg. Date: 08/11/2006 (Man. Year: 2006) Chassis No: JMYLTZ23W6Z001008
 Colour: Red Odometer: 210579 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,203.38	5,451.50	3,751.88	40.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,900.00	1,170.00	38.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,273.38	7,351.50	4,921.88	40.10
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	12,273.38	4,500.00	7,773.38	63.34
+ GST 7.00/7.00% (S\$)	859.14	315.00	544.14	63.34
Nett Amount (S\$)	13,132.52	4,815.00	8,317.52	63.34
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,617.00		

INSPECTION

Date of Assignment: 30/04/2018
 Date Inspected: 30/04/2018 Inspected At: Kang Car Repairers Pte Ltd (HQ)
 Estimated Period of Repair: 7.0 days No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	825.00 FL	*825.00 FL
2	1		*BOOT LID GARNISH	Not Necessary	216.00 FL	*- FL
3	1		*BOOT LID LOGO	Necessary	38.00 FL	*38.00 FL
4	1		*BOOTLID COLT EMBLEM	Necessary	36.00 FL	*36.00 FL
5	1		*BOOTLID PLUS EMBLEM	Necessary	34.00 FL	*34.00 FL
6	1		*BOOT LID STICKER	Necessary	295.00 FL	*295.00 FL
7	2		*REAR NUMBER PLATE LAMP	Not Necessary	130.20 FL	*- FL
8	1		*BOOT LID LAMP LH	Cracked	195.00 FL	*195.00 FL
9	1		*BOOT LID LAMP RH	Cut	195.00 FL	*195.00 FL
10	1		*BOOT LID LOCK	Damaged	412.00 FL	*412.00 FL
11	1		*BOOT LID LOCK CHECKER	Not Necessary	48.00 FL	*- FL
12	1		*BOOT LID INNER HOLDING HANDLE	Not Necessary	38.00 FL	*- FL
13	1		*BOOT LID TRIM	Deformed	190.00 FL	*190.00 FL
14	1		*BOOT LID AUTO LOCK SENSOR	Not Necessary	1,450.00 FL	*- FL
15	2		*BOOT LID INNER SIDE RUBBER	Not Necessary	196.00 FL	*- FL
16	2		*BOOTLID STOPPER RUBBER	Not Necessary	36.00 FL	*- FL
17	1		*REAR WINDSCREEN RUBBER	Necessary	120.00 FL	*120.00 FL
18	1		*BOOT LID RUBBER	Cut	180.00 FL	*180.00 FL
19	1		*REAR PANEL	Dented	420.00 FL	*420.00 FL
20	1		*REAR PANEL TRIM	Deformed	155.00 FL	*155.00 FL
21	1		*REAR FENDER TRIM RH	Not Necessary	275.00 FL	*- FL
22	1		*REAR FENDER TRIM LH	Not Necessary	275.00 FL	*- FL
23	1		*SPARE TYRE TOP COVER	Deformed	406.00 FL	*406.00 FL
24	1		*REAR COMPARTMENT COVER	Deformed	595.00 FL	*595.00 FL
25	1		*TAIL LAMP LH	Cracked	310.00 FL	*310.00 FL
26	1		*TAIL LAMP - RH	Cracked	310.00 FL	*310.00 FL
27	1		*REAR BUMPER	Deformed	682.00 FL	*682.00 FL
28	1		*REAR BUMPER BEAM	Bent	159.00 FL	*159.00 FL
29	2		*REAR BUMPER BRACKET	Not Necessary	122.00 FL	*- FL
30	2		*REAR BUMPER SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
31	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	82.00 FL	*- FL
32	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	82.00 FL	*- FL
33	1		*EXHAUST PIPE	Not Necessary	895.00 FL	*- FL
34	2		*EXHAUST PIPE MOUNTING	Not Necessary	48.00 FL	*- FL
35	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
36	1		*SET BOOT LID TRIM CLIPS	Necessary	40.00 FS	*30.00 FS
37	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*30.00 FS
38	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
39	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
40	1		*SET REAR FENDER TRIM CLIPS RH	Not Necessary	40.00 FS	*- FS
41	1		*SET REAR FENDER TRIM CLIPS LH	Not Necessary	40.00 FS	*- FS
42	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
43	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	10,156.20	6,015.00
- List Item Discount on L Items 10.00/10.00% (S\$)	952.82	563.50
Total Parts (S\$)	9,203.38	5,451.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	50.00	30.00
2	TO REMOVE AND REFIT REAR WINDSCREEN.	New	120.00	100.00
3	TO REMOVE AND REFIT REVERSE SENSOR.	New	80.00	50.00
4	TO REMOVE AND REFIX REAR EXHAUST PIPE.	New	150.00	0.00
5	TO SPRAY UNDERSEAL.	New	150.00	60.00
6	(REAR) TO SPRAY PAINTING.	New	1,200.00	800.00
7	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS.	New	1,200.00	800.00
8	TO REMOVE AND REFIT INNER TRIM.	New	120.00	60.00
Gross Labour Cost (\$\$)			3,070.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >