

REF: NS/INC/8008069/Svb2

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **PC 2403C**  
 Policy No: **5093187006** **080817**  
 Claims No: **MT/0992640-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Val. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 BIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Linn Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SHB 1108L** Yr Regn: **25/19/2013**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Toyota Proace** C.C. **1798**  
 Colour: **Maroon** A/C: **Insured / Std / NI / NA**  
 Sp. Reading: **779732** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: **JTDKN3CU105(91337)**  
 Gen. Cond: **Good / Fair / Poor / Burnt**  
 Steering: **In order / Jammed / Leaked / Burnt or**  
 Brake: **In order / Jammed / Leaked / Burnt or**  
 Modi: **NI / S/Rim / STD A/Rim or**  
 Tyre Size: F: **175/65R15**  
 R: **4**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /  
**TOYO / YOKO or** *Fellon*

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>30/4/18</u>	D.O.I. <u>2/5/18</u>

Survey held at **SMRT**  
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**  
**d/s Rear**  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<b>SHB 1108L - X</b>
	<b>PC 2403C - X</b>

**16/5/18 Sebastian confirmed LS \$ 1150 (Red 7804.20, 879)**  
**PC 2403C**

RECEIVED 18 MAY 2018

Date/Time. File Pass to?  : Preli. Report  
 : Final Report

Date/Time. File Return to?  
**18/5 - typist**

Report Format: **TP**  
 Lump Sum / L.B.F. (\$) **1150p**

Days Of Repair: **5**  
 Resurvey No. of Trip: **—**

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:	160
Transportation:	35
S + RS: \$	
Photos	
Others	
<b>TOTAL</b>	<b>195</b>



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18008069/Svb			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 03-05-2018			
189556		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	PC 2403C	Veh. Inspected	SHB 1108L
Policy No.	5093187006	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	30/04/2018	Inspection Date	02/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0994868-001	SMRT TAXIS PTE LTD	SHB 522E	SIQ 2939X	17/04/2018
2	MT/0991087-002	SMRT TAXIS PTE LTD	SHB 1772T	SLG 5592X	19/04/2018
3	MT/0983942-002	SMRT TAXIS PTE LTD	SHB 687M	YN 5496A	26/2/2018
4	MT/0992660-002	SMRT TAXIS PTE LTD	SHC 4568S	SIL 9197A	1/5/2018
5	MT/0992640-002	SMRT TAXIS PTE LTD	SHB 1108L	PC 2403C	30/4/2018
6	MT/0993012-002	SMRT TAXIS PTE LTD	SHB 8Z	SKA 5770S	2/5/2018
7	MT/0992770-002	SMRT TAXIS PTE LTD	SHC 4741H	SHC 6357X	3/5/2018

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

My Desktop  
Notice of Loss

Policy Query

Policy No.  Date of Accident   
 Vehicle No. (For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5093187006	HUA SIN TRAVEL & COACH PTE LTD	201619187D	GFT	Comprehensive	PC2403C	PC2403C	05/08/2017	

Continue

**Veron Chen (LKKAuto)**

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>  
**Sent:** Thursday, 17 May 2018 11:07 AM  
**To:** Sebastian Yeang (LKK Auto)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** RE: SHB1108L

Hi

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]  
**Sent:** Wednesday, 16 May 2018 10:19 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** RE: SHB1108L

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,  
Sebastian | Automotive Assessor  
LKK Auto Consultants  
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Friday, 11 May 2018 3:14 PM  
**To:** Sebastian Yeang (LKK Auto)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** SHB1108L

Hi Sebastian,

Attached herewith the repair estimate of SHB 1108L having Case No: TAX/04/18/2146.

There is no change to the approved amount of \$1,150 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Friday, 11 May 2018 3:14 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2018 17:02
Date Of Accident	30/04/2018 16:00
Exact Location Of Accident	SENTOSA GATEWAY (NEAR VIVOCITY)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1108L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	KHENG THIE KIN
NRIC No	S2572346E
Date Of Birth	01/11/1954
Occupation	OUTDOOR
Date Of Driving Pass	20/11/1989
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	54
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG SENTOSA GATEWAY (NEAR VIVOCITY) WITH ONE PASSENGER (MALE CHINESE) ON BOARD. SUDDENLY I FELT AN IMPACT AT THE RIGHT PORTION OF MY TAXI. A BUS PC2403C WHICH WAS TRAVELLING ON MY RIGHT HAD CUT TOWARDS MY LANE AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC2403C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

### Vehicle Details

Vehicle No.:	SHB1108L
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5894530
Chassis No.:	JTDKN36U105691337
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	25 Oct 2013
First Registration Date:	25 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Oct 2021
PARF Rebate Amount:	\$6,276.00

### Intended COE Rebate Details

COE Expiry Date:	24 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$26,623.00
<b>Total Rebate Amount:</b>	<b>\$32,899.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 May 2018

OK

## SMRT Accident Vehicle Repair Estimates

*NTUC*

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHB1108L  
 Ref. No : TAX/04/18/2146  
 Reg. Date : 25/10/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : KHENG TJIE KIN  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 30/04/2018 04:00:00 PM  
 Accident Reported Date / Time : 30/04/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095838  
 Special Instruction to ARC,if any :  
 PC2403C  
 Prepared Date : 02/05/2018 10:22:17 AM



*Sebastian  
 2/5/18  
 - Long Sun Repair.  
 - Question Mark Item  
 Photo.  
 - Photo After Paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U10-5691337

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 3,439.38	3,439.38
Other Charges	: 945.00	0.00
<b>TOTAL</b>	<b>: 6,723.38</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 6,700.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	<i>4 days</i>
Arc / Surveyor Sign Off Date	: 02/05/2018 01:22:24 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/05/2018 01:22:24 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	<del>0.00</del> 500
<b>Total Labour</b>	<b>845.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	378.00	<del>0.00</del> 200
TO RESPRAY REAR FENDER RH	378.00	<del>0.00</del> 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	<del>0.00</del> 100
TO RESPRAY RIM	180.00	<del>0.00</del> 50
TO REPSRAY REAR BUMPER	378.00	<del>0.00</del> 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,494.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	<del>0.00</del> 30
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✗
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 ✓
TO TRANSFER DOOR MECHANISM	120.00	0.00 ✗
TO REPLACE SUNDRY PARTS	100.00	0.00 ✓
TO WASH AND VACUUM	60.00	0.00 ✗
<b>Total Other Costs</b>	<b>945.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace R	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace R	No
65631-47041			SILL MEMBER PLATE RR/RH	1	57.50	25.00	43.12	Replace	Replace R	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace R	No
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace X	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace ✓ N/C	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ N/C	No
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace ✓	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace R	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ N/C	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ✓	No
<b>TOTAL MATERIALS</b>								<b>4,299.25</b>	<b>4,299.23</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>3,439.38</b>	<b>3,439.38</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

*Chia*

*FIDAX*

*7-5-18 / 16:07*

*7-5-18 / 14:07*


*7-5-18 / 14:07*

**SMRT Accident Vehicle Repair Estimates**

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHB1108L  
 Ref. No : TAX/04/18/2146  
 Reg. Date : 25/10/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : KHENG TJIE KIN  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 30/04/2018 04:00:00 PM  
 Accident Reported Date / Time : 30/04/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : *Sebastian*  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095838  
 Special Instruction to ARC, if any :  
 PC2403C *NTUC 43*  
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121  
 LUMPSUM REPAIR  
 Prepared Date : 02/05/2018 10:22:17 AM

*7/5*



Recording Camera

Radio Antenna


1<sup>st</sup> witness *N*

Date *2-5-18*

2<sup>nd</sup> witness

Date

Vehicle to Wega Date In: *2/5*      Towing:  
 Time In: *0645*      Driver: *Huo*  
 Wega Job No: *05/0275*  
 Vehicle sent to SMRT Date In: *7/05/18*      Towing:  
 Time In: *13:52*      Driver: *3*  
 Received by (SMRT):



*7/5/18 15:52 PASS Qe*

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U10-5691337 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	500.00
Total Spray Painting Charges	: 1,494.00	750.00
Total Material Charges	: 208.94	149.40
Other Charges	: 945.00	-249.40
<b>TOTAL</b>	<b>: 3,492.94</b> 8954.20	<b>1,150.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	5.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 02/05/2018 01:22:24 PM	02/05/2018 02:00:32 PM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/05/2018 01:22:24 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1805-0132 Invoice No :  
Quotation Date : 8/5 Invoice Date :  
Invoice Amount : Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00 ✓	500.00 /
<b>Total Labour</b>	<b>845.00</b>	<b>500.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	378.00 ✓	200.00 /
TO RESPRAY REAR FENDER RH	378.00 ✓	200.00 /
TO RESPRAY ROCKER PANEL MOULDING	180.00 ✓	100.00 /
TO RESPRAY RIM	180.00 ✓	50.00 /
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,494.00</b>	<b>750.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 NA
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>945.00</b>	<b>30.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67003-47080		6505486	DOOR RR/RH	1	954.50	100.00	0.00	Replace	Repair	No <i>R</i>
75851-47900			MOULDING BODY, RH	1	673.60	100.00	0.00	Replace	Repair	No <i>R</i>
65631-47041			SILL MEMBER PLATE RR/RH	1	57.50	100.00	0.00	Replace	Repair	No <i>R</i>
61604-47090			FENDER RR/RH	1	766.80	100.00	0.00	Replace	Repair	No <i>R</i>
62710-47130			QUARTER GLASS RR/RH	0	846.50	25.00	0.00	Replace	Not given	No <i>X</i>
	COMMO N		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>X</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No <i>/</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>/</i>
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.98	Replace	Check	No <i>X</i>
42611-47140		6505658	WHEEL, DISC	1	1,490.20	100.00	0.00	Replace	Repair	No <i>R</i>
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
			PIXEL STICKER	2	60.00 <i>120</i>	0.00	120.00	Replace	Replace	No <i>/</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
<b>TOTAL MATERIALS</b>							<b>5670.20</b>	<b>326.48</b>	<b>149.40</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>208.94</b>	<b>149.40</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

149.40 /  
 + 500.00 /  
 + 780.00 /

1429.40 /

- 207

1143.52 /

4/5 \$1150/- /

Submission  
 10/5/18



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18008069/Svbn2			
73 BRAS BASAH ROAD		Date: 23-05-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE		Code: INC4	
189556			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	PC 2403C	Veh. Inspected	SHB 1108L
Policy No.	5093187006	Coverage (\$)	0.00
Claim No.	MT/0992640-002	Excess (\$)	0.00
Assign From		Assign Date	02/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U105691337	Colour	MAROON
Odometer	779732	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	30/04/2018	Inspection Date	02/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1108L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	SOLAR FILM	NOT NECESSARY	125.00	-
1	DOOR RR/RH	TO REPAIR	954.50	-
1	MOULDING BODY,RH	TO REPAIR	673.60	-
1	SILL MEMBER PLATE RR/RH	TO REPAIR	57.50	-
1	FENDER RR/RH	TO REPAIR	766.80	-
1	WHEEL,DISC	TO REPAIR	1,490.20	-
1	BUMPER REAR	TO REPAIR	458.60	-
			5,795.20	149.40
<b>LABOUR</b>				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			1,405.00	500.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			1,594.00	780.00
TO REPLACE SUNDRY PARTS.			100.00	-
TO WASH AND VACUUM.			60.00	-
			3,159.00	1,280.00
<b>GRAND TOTAL</b>			<b>8,954.20</b>	<b>1,429.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,150.00</b>

Report Ref No. NS/INC18008069/Svbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.