

INS. CASE OWNER:

GONARD

CC<sup>4</sup>/LPC1800

8086, TI 80386

LKK:  
IDAC

## ASSIGNMENT

Survivor:

TAUMIKH

DOI:

15	05	18
----	----	----

Date / Time :

3/5/18

Registered in Merimex:

Pre-assign / CCU / FTE

SBM 5207



Insured Vehicle No.

Name of Insured

Insured Tel No.

**Excess Sec II :SS**

Is driver the owner?

( YES ~~AND~~ )

Nature of Accident :

If **NO**, Driver Name / Age :

TEREMY TUN GHEE LIN

Driver Tel No. :

(V/L: ~~YES~~ / NO)

Claim No. \_\_\_\_\_

Policy No.

Make / Model

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers Liability		
4. Employment Practices Liability		
5. Fidelity and Bonding		
6. Commercial Automobile		
7. Aircraft and Helicopter		
8. Watercraft		
9. Umbrella		
10. Other		



INSRS:  
WSP:  
Tel :  
Liability  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/Time		STAGE	DATE / PIC
01/05/18	56W 574 54-X	Non-Reporting ltr (1st):	
01/05/18	56W 574 54-X	Non-Reporting ltr (2nd):	
01/05/18	56W 574 54-X	Non-Reporting ltr (Final):	
01/05/18	56W 574 54-X	Notification ltr (if non-pickup):	
01/05/18	56W 574 54-X	Call OI:	
01/05/18	56W 574 54-X	After call ltr to OI:	
01/05/18	56W 574 54-X	Documentation Check List:	
01/05/18	56W 574 54-X	Notification ltr (if non-pickup)	
01/05/18	56W 574 54-X	After call ltr to OI:	
01/05/18	56W 574 54-X	Authorisation To Act:	
01/05/18	56W 574 54-X	Release Voucher:	
01/05/18	56W 574 54-X	Final Repair Bill:	
01/05/18	56W 574 54-X	Car Rental Invoice:	
01/05/18	56W 574 54-X	Towing Invoice:	
01/05/18	56W 574 54-X	LTA / GLA:	
01/05/18	56W 574 54-X	Medical Bill:	
01/05/18	56W 574 54-X	PIR:	
01/05/18	56W 574 54-X	Mandate/Reject Instruction:	
01/05/18	56W 574 54-X	LOD	
01/05/18	56W 574 54-X	Payment Breakdown Form:	

<b>PRELIMINARY ADVICE</b>		Date/Time: 21/06/18	Sent By: BS	Post-Repair Photos: <input type="checkbox"/> <input type="checkbox"/>	Others: <input type="checkbox"/> <input type="checkbox"/>
<b>FINALIZATION</b>		Date/Time:	Confirm with:	Confirm by:	
Repair Cost: P/P	S\$ 3,619.46	( 3 days)	Reduction: 21 %	Email <input type="checkbox"/>	Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>		Date/Time: 09/10/18	Confirm with: MR YIK	Email <input checked="" type="checkbox"/>	Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27		If NO or B 28, Ass. Lia :	
Repair Cost: (w/good)	S\$ 3,872.82			COLD REAR-ENDED TO	
Loss of Rental (LOR) (w/good)	S\$ 428.00	( 4 days)	X \$100	DU PLACED BY TP	
Loss of Use (LOU):	S\$ —	( \$ x days)		KAREED	
Loss of Income (LOI):	S\$ —	( \$ x days)		COPY SENT 20/6/18	
LOR only <input checked="" type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	S\$ 2.00				
Medical:	S\$ —			1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ —	(e.g. Tow/ Independent )		2) Report Format:	
Legal Cost	S\$ —			3) Survey fee: \$450.00	
<b>Total:</b>	S\$ 4,302.82	<b>Global Sum S\$:</b> —			
<b>FINAL PAYMENT</b>		Date/Time:	Confirm with:	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Payee 1:	S\$ 4,302.82	Name 1:	CYOL & CARRIAGE INDUSTRIES PTE LTD		
Payee 2: (Strike if N.A.)	S\$ —	Name 2:	—		
Payee 3: (Strike if N.A.)	S\$ —	Name 3:	—		

Signature

Tanghi

REF: 4

LPC 8086 P. W63

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / ITA / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

-

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

yk

Veh No:

SLW51454

Yr Regn: 2018

Feb

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz C180

C/V

1595

Colour

Black

A/C

Insured / Std / NI / NA

Sp Reading

4771

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2050422K 360133

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R17

R:

22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/5/18

Survey held at

CFC London Corp

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Plp \$3,69.46  
CRAD: \$959.95 (21%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RE \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: \$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18008086/hb3

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 03-05-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBM 520Z	Veh. Inspected	SLW 5145U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/05/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	02/05/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18008086/T1hb3

Date: 21.05.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLW5145U**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.05.2018 at the premises of M/s Cycle & Carriage Industries Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,579.41
Revised Estimate Amount	: S\$	3,736.05
"Check" Items Amount	: S\$	453.36
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. TAUFIKH  
Licensed Appraiser

**Catherine Chong (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 3 May, 2018 9:39 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: Accident involving motor vehicle nos. SLW 5145 U & SBM 520 Z // Propose for Direct Settlement  
**Attachments:** img-502183755-0001.pdf

Our Ref: to be advised

Dear Catherine,

Kindly proceed to conduct the survey and revert to them on Direct Settlement.

At this juncture, our insured has yet to lodge a report.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

03052018 @ 10:13am  
Yik veh not in  
check liability

-----Original Message-----

**From:** Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]  
**Sent:** Wednesday, 2 May, 2018 6:40 PM  
**To:** GERALD POH WEE BIN  
**Subject:** Accident involving motor vehicle nos. SLW 5145 U & SBM 520 Z // Propose for Direct Settlement

**To:** Lonpac Ins  
**Attn:** Motor Claims Dept

**RE:** Accident involving motor vehicle nos. SLW 5145 U & SBM 520 Z along Clementi road before entering slip road,  
**Accident date:** 02/05/2018

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SLW 5145 U), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SBM 520 Z) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at chanhoe.yik@cyclecarriage.com.sg

Thanks & Regards,

Yik Chan Hoe  
Mercedes-Benz Body Care & Repair Center  
Cycle & Carriage Industries Pte Ltd  
Pandan Loop Service Center  
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLW5145U

LKK

Tan Siao Yuen (chen Xiaoyan)

53 Hume Avenue  
#04-05  
Singapore 598751

## Vehicle &amp; Document Information

WIP No 23297  
Reg No/Reg Date SLW5145U / 19/02/2018  
Date In/Mileage / 0  
Chassis No WDD2050402R360133  
Engine No 27491031236818  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 021 197 Obsidian Bl/ 041 118 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator				
WCV34166	CRDVCH	02/05/2018/ 18:36	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : 1800014762 // 02/05/2018								
DRIVE IN/EXCESS : 02/05/2018 // TP VEH NO SBM520Z LONPAC								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								960 1200.00
BODY PANELS WITH REFINISH.								600 750.00
A BPIRES								
RESPRAY REAR BUMPER							0.10	✓ 380.00
A BPILAB								
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO								✓ 120.00
STANDARD SETTINGS.								
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT								
M REAR BUMPER					1.559.96	1.00	1676.05 00.00	1676.05 ✓
M REAR BUMPER LOWER CHROME MOULDING					1.00	1.00	245.09 00.00	245.09 X
M REAR BUMPER LOWER					1.00	1.00	208.27 00.00	208.27 X

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Tan Jiah 97445349  
"wp"  
15/5/18 @ 1700  
3 days  
sur @ 1800000

Confirmed &amp; accepted by

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

7% GST on **Nett 4,579.41**  
**4579.41**  
**Total Payable 4,899.97**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

Finalization

## ESTIMATE FOR SLW5145U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

### Vehicle & Document Information

WIP No 23297  
Reg No/Reg Date SLW5145U / 19/02/2018  
Date In/Mileage 15/05/2018 / 4771  
Chassis No WDD2050402R360133  
Engine No 27491031236818  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 021 197 Obsidian Bl/ 041 118 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	19/06/2018/ 14:31	YK	395 / Yik Chan Hoe

### Description of Goods / Services

	Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICE NO/ACC DATE : 1800014762 // 02/05/2018 DRIVE IN/EXCESS : 02/05/2018 // TP VEH NO SBM520Z LONPAC DATE IN/DATE SURVEY: 15/05/2018 @ 1700 // TAUFIKH LKK BY/AUTHORIZED ON : DIRECT SETTLEMENT // VIC LKK				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				960.00
A BPIRES RESPRAY REAR BUMPER				600.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00
X REAR TRIM BUMPER	1.00	1559.46	00.00	1559.46

Attn: Taufikh  
03 Working Days

ESTIMATE

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: ehanchoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 3,619.46  
7% GST on 3619.46 253.36  
Total Payable 3,872.82

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Monday, 9 July, 2018 2:43 PM  
**To:** Yik Chan Hoe  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** RE: Your Ref: SLW 5145U\_ACCIDENT INVOLVING VEHICLES SBM 520Z AND SLW 5145U ON 02/05/2018  
**Attachments:** DV.pdf

Without Prejudice

Dear Mr Yik,

We refer further to our below email and we confirmed in receipt of your LOD and supporting documents.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we confirm acceptance of your offer of \$4,302.82 (all in) to settle your client's claim.

Kindly let the owner sign the attached DV then forward the original signed DV together with the Authorization to Act letter duly signed by the owner to us (LKK) for payment processing.

The above amount is to be made payable to CYCLE & CARRIAGE INDUSTRIES PTE LTD.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*

Best Regards,

Vic Alpeh | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicapah@lkkauto.com](mailto:vicapah@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAUTO)  
**Sent:** Wednesday, 9 May, 2018 11:33 AM  
**To:** Yik Chan Hoe  
**Cc:** Admin A; Vic (LKKAUTO); Bevan Lim (LKK Auto)  
**Subject:** Your Ref: SLW 5145U\_ACCIDENT INVOLVING VEHICLES SBM 520Z AND SLW 5145U ON 02/05/2018

Your Ref: SLW 5145U  
Our Ref: CC1/LPC18008086/hb3

"WITHOUT PREJUDICE"

Dear Sir/Madam,

**ACCIDENT INVOLVING VEHICLES SBM 520Z AND SLW 5145U ON 02/05/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BQI Accredited settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

**Vic Alpeh | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6741-4108 | email: [vic@lkk.com](mailto:vic@lkk.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 4, #02-25 | S(408933)

**LKK**  *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18008086/T1hb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 20-08-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBM 520Z	Veh. Inspected	SLW 5145U
Policy No.	Z17VP05015903	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020583	Excess (\$)	0.00
Assign From	GERALD	Assign Date	03/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD2050402R360133	Colour	BLACK
Odometer	4771	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	02/05/2018	Inspection Date	15/05/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 5145U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (SN)	DEFORMED	1,676.05	1,559.46
1	REAR BUMPER LOWER CHROME MOULDING (SN)	NOT NECESSARY	245.09	-
1	REAR BUMPER LOWER (SN)	NOT NECESSARY	208.27	-
			2,129.41	1,559.46
	<b><u>LABOUR</u></b>			
	PANEL BEATING TO REPAIR AFFECTED AREAS ,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		1,200.00	960.00
	RESPRAY REAR BUMPER.		750.00	600.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS ,RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE .		120.00	120.00
			2,450.00	2,060.00
	<b>GRAND TOTAL</b>		<b>4,579.41</b>	<b>3,619.46</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,619.46</b>

Report Ref No. CC4/LPC18008086/T1hb3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.