



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW5145U

LKK

Tan Siao Yuen (chen Xiaoyan)

53 Hume Avenue
#04-05
Singapore 598751

Vehicle & Document Information

WIP No 23297
Reg No/Reg Date SLW5145U / 19/02/2018
Date In/Mileage / 0
Chassis No WDD2050402R360133
Engine No 27491031236818
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian Bl/ 041 118 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator			
WCV34166	CRDVCH	02/05/2018/ 18:36	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 1800014762 // 02/05/2018
DRIVE IN/EXCESS : 02/05/2018 // TP VEH NO SBM520Z LONPAC
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO
STANDARD SETTINGS.

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT

M REAR BUMPER

1.00 1676.05 00.00

M REAR BUMPER LOWER CHROME MOULDING

1.00 245.09 00.00

M REAR BUMPER LOWER

1.00 208.27 00.00

960 1200.00

600 750.00

0.10 ✓ 380.00

✓ 120.00

1676.05 ✓

245.09

208.27

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Tanjum 97445349
wp
15/5/18 @ 1700
3 days
sur e/insurance

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Nett 4,579.41
7% GST on 4579.41 320.56
Total Payable 4,899.97

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg