

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8733 K

1 pc	Rear exhaust pipe	\$	1,009.00
1 pc	Rear exhaust pipe hanger	\$	34.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00	\$	92.00
			\$ 2,994.00
Less 10%			\$ 299.40
			\$ 2,694.60

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
	Sundry	\$	50.00 20
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$	120.00 20
	To dismantle and replace rear exhaust pipe	\$	80.00 50
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc <i>Floor board</i>	\$	700.00 750.00
	To putty and spray painting on rear bumper, end panel, <i>Floor board.</i>	\$	500.00 540
	To apply rustproofing on the repaired and replaced panels.	\$	150.00 50
			\$ 4,852.60

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by:

Signature:

Date:

Calvin (Ck)
3/5/18 10/10h.
4/5
After Repair Ltd.