

INSURANCE OWNER:

68800 FBM
Chan KuanCC 4 WSM
/AXA1800

8098, Dpbbsz

LKK:

IDAC:

Surveyor:

Bryan

DOI:

ASSIGNMENT

3/5/18

Date / Time:

3/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

6BE 76766

Name of Insured:

YUAN YING LAURETTE

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

2/14/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

YANG JINGSHAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

88600 FBM / 12931

Policy No.:

6A 23728/1

Make / Model:

Toyota

Place of Accident:

YISHUN AVE 8

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SNC 631T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Soon
Hock
Chunni

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2/14/18
MT

SNC 631T - 4

6BE 76766 - 4

* snowstorm

WE ARE OF THE VIEW THAT REPAIRS ESTIMATION
IS ON THE HIGH SIDE.PLEASE CHECK OF DAMAGES CONSISTENCY AND BE STRINGENT ON COR.
TO BRING DOWN COR..TP REPORTED DUE TO THE IMPACT, TP LOST CONTROL AND
HIT ONTO GOVERNMENT PROPERTY, PLS CHECK FOR DAMAGES CONSISTENCY
DAMAGES TO THE FRONT.PLEASE VERIFY WHAT DID TP COLLIDED ONTO THAT
CAUSED THE FRONTAL DAMAGES. -5/2/18 4:49 PM CHAN Kian Chuan

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

2/14/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: \$11770.00

Loss of Rental (LOR):

S\$

1312.08

(

11

days)

Loss of Use (LOU):

S\$

-

(\$

x

-

days)

Loss of Income (LOI):

S\$

520.00

(\$

x

11

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

13639.53

Global Sum S\$:

3630.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

13630.00

Name 1:

Chunni Motor Work Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 350.00

COPY SENT
w/w/h

REF: p

ASSIGNMENT

COE April 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Veh No: BHC 631 T Yr Regn: 2014 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 C.C. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 473710 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDFU579391

C/No: KMHLEB41WUMEU052424

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: ---

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake


Front	Rear
R/Bal. <u>S</u> mm	R/Bal. <u>S</u> mm
L/Bal. <u>S</u> mm	L/Bal. <u>S</u> mm
D.O.A. <u>25/04/2018</u>	D.O.I. <u>03/05/2018</u>

Survey held at Chunni AMK

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or.

Front y Rear

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	AXA GBE 2626 G check consistency of frontal damage. Video show TP may have hit kerb at the frontal portion.
	45 \$ 1100 (Reel \$ 19190.34 / 64%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R


Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008098/Dpb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 03-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 2626G	Veh. Inspected	SHC 631T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/04/2018	Inspection Date		
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

to Survey by (LKK)

FAX : 6542 6039 AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille S/C			\$ 294.35 X
	Radiator Grille H Emblem S/C			\$ 113.65 X
	Front Bumper Cover distortion			\$ 562.30 ✓
	Front Bumper Sponge & HAI			\$ 142.20 Z X
	Front Bumper Reinforcement & HAI			\$ 526.10 Z X
	Front Bumper Centre Grille distortion HAI			\$ 178.60 W X
	Front Bumper Centre Grille Top Garnish clutter HAI	HAI	\$ 80.00	\$ 160.00 W X
	Front Bumper Bracket Top (LH/RH) S/C		\$ 22.40	\$ 44.80 X
	Front Bumper Bracket (LH/RH) S/C		\$ 24.60	\$ 49.20 X
	Front Bumper Retainer Mounting S/C		\$ 9.20	\$ 18.40 X
	Headlamp Support Top Cover S/C			\$ 398.00 X
	Headlamp Support Panel Assy & NAI			\$ 1,067.50 Z X
	Headlamp (LH/RH) & NAI		\$ 1,388.00	\$ 2,776.00 Z X
	Radiator HAI			\$ 850.20 X
	Radiator Fan Blade,Cowling,Motor Assy HAI			\$ 792.95 X
	Radiator Bracket (RH/LH) S/C		\$ 6.50	\$ 13.00 X
	Radiator Guard S/C		\$ 35.00	\$ 70.00 X
	Horn Unit (LH/RH) HAI		\$ 86.75	\$ 173.50 X
	Horn Wire HAI			\$ 156.50 X
	Aircon Condenser HAI			\$ 1,137.35 X
	Inter Cooler HAI			\$ 921.90 X
	Inter Cooler Mounting (2 PCS) HAI			\$ 25.90 X
	SUB TOTAL		562.30	\$ 10,472.40
	LESS 20%		449.84	\$ 2,094.48
	DISCOUNTED TOTAL			\$ 8,377.92
	Front Number Plate GST HAI			\$ 25.00 Nett W X
	Front No Plate Trim Cover S/C			\$ 30.00 Nett X
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 200/-
	Spray Painting Charge			\$ 250.00 50/-
	Wiring Charge			\$ 50.00 200/-
	Towing Charge			\$ 60.00 30/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 HAI
	TOTAL LABOUR		430/-	\$ 1,510.00 ? HAI

SHC 631T

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker Hbc			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo Hbc			\$ 100.00	Nett ✓
	Rear No. Plate Svc			\$ 25.00	Nett X
	Rear Bumper Reverse Sensor Dam			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo Hbc			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) Hbc		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant Hbc			\$ 46.00	Nett ✓
			561.70	\$ 586.70	
	Labour Charge				
	Panel Beating			\$ 2,200.00	1200/-
	Spray Painting Charge			\$ 1,400.00	1000/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	40/-
	Remove/Refix Exhaust Pipe			\$ 360.00	60/-
			2530/-		
	TOTAL LABOUR			\$ 4,650.00	
	ESTIMATE TOTAL			\$ 30,190.34	
	03/05/2018 @ 1445W			16390.18	
	Not Insured			4513100/-	
	1/2 same 10 days.				
					
	LKK Auto				
					
	LKK Auto Consultants hence notify the Repairer of the following:				
	• To resurvey before/after spray painting				
	• To display damaged part(s) during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairer				
	Signature: This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
	Date: be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

pending
insurance
company
approval.



Service Request Details

Claim

S8M00FBM

Reference

None 

Loss Date

April 25, 2018

Request Date

May 2, 2018

Due Date

May 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

02052018 @ 5:04pm

Issue veh in

Chennai Soon Hack

Bryan

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC631T

Make

TPVD HYUNDAI

Service Address

...

Primary Contact/Insured

YUAN XING LAUNDRETTE

1 YISHUN STREET 23, #06-26, YS ONE, 768441, Singapore
98981718

WINNER@WINNER.COM.SG

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

5/2/18 4:49 PM

FROM

CHAN Kian Chuan

SUBJECT

Re:HIGH ESITMATION

BODY

TP REPORTED DUE TO THE IMPACT, TP LOST CONTROL AND...



TYPE



SENT

5/2/18 4:36 PM

FROM

CHAN Kian Chuan

BODY

WE ARE OF THE VIEW THAT REPAIRS ESTIMATION IS ON ...





<SEEK MANDATE> - S8M00FBM [ACCIDENT INVOLVING GBE 2626G(OI) & SHC 631T(TP) ON 25/04/2018]

Type

🔔 Question

Message

Liability: 100%. Insured driver rear-ended third party taxi. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. From third party video, third party taxi front portion may have hit the kerb. We seek your mandate up to \$16,184.49(all-in). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 19 Sept 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19.09.2018

Survey Details:

Date of loss	25.04.2018
Date of appointment	03.05.2018
Date of survey	03.05.2018
Location of survey	Chunni Motor Work Pte Ltd

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 631T
Make and Model	Hyundai I40 (1685cc)
Date of registration	30.04.2014
Excess	NIL
Market Value	
Parf/COE Rebate	
Nett Loss	

Repair details:

Initial Estimate	\$ 30,190.34
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 13,430.18
Check items (estimate)	NIL
Labour	\$ 2,960.00
Supplementary	NIL
Total	\$ 16,390.18
Lump Sum(if applicable)	\$ 13,100.00

Number of days for repair	<u>10</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 19.09.2018

Remarks:

Based on TP video, Tp taxi may have hit the kerb at the frontal portion.

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	14,017.00	
Loss of use		NIL	
Loss of rental	\$	1,560.00	(12days x \$130.00)
Loss of income	\$	600.00	(12days x \$50.00)
LTA/GIA search fees	\$	7.49	
Others		NIL	
Proposed Total	\$	16,184.49	



Re:<SEEK MANDATE> - S8M00FBM [ACCIDENT INVOLVING GBE 2626G(OI) & SHC 631T(TP) ON 25/04/2018]

Type

🔍 Question

Message

WE DO NOT AGREE WITH YOU THAT TPV MAY HAVE HIT THE KERB. AS PER THE VIDEO FOOTAGE, THIS IS A HEAD TO REAR COLLISION AND AFTER THE IMPACT, TPV DID NOT COME INTO CONTACT WITH THE KERB. BASED ON SURVEY PHOTOS, THERE IS NO PHOTOS SHOWING DAMAGES/ PARTS OF ANY FRONTAL DAMAGES. PLS REVIEW ON YOUR IA AND RE-SEEK MANDATE WITHOUT ANY FRONTAL DAMAGES.

Reply



RE: Re:<SEEK MANDATE> - S8M00FBM [ACCIDENT INVOLVING GBE 2626G(OI) & SHC 631T(TP) ON 25/04/2018]

Type

🔍 Question

Message

Liability: 100%. Insured driver rear-ended third party taxi. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$15,435.49(all-in). IA with mandate(revised) had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Thank you. Hsiao Tong - 21 Sept 2018

Reply