

To Survey by (LKK)


FAX : 6542 6039 AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille S/C			\$ 294.35
	Radiator Grille H Emblem S/C			\$ 113.65
	Front Bumper Cover <i>distorted</i>			\$ 562.30
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Centre Grille <i>distorted</i>			\$ 178.60
	Front Bumper Centre Grille Top Garnish <i>crack</i>		\$ 80.00	\$ 160.00
	Front Bumper Bracket Top (LH/RH) S/C		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) S/C		\$ 24.60	\$ 49.20
	Front Bumper Retainer Mounting S/C		\$ 9.20	\$ 18.40
	Headlamp Support Top Cover S/C			\$ 398.00
	Headlamp Support Panel Assy ?			\$ 1,067.50
	Headlamp (LH/RH) ?		\$ 1,388.00	\$ 2,776.00
	Radiator H/L			\$ 850.20
	Radiator Fan Blade, Cowling, Motor Assy H/L			\$ 792.95
	Radiator Bracket (RH/LH) S/C		\$ 6.50	\$ 13.00
	Radiator Guard S/C		\$ 35.00	\$ 70.00
	Horn Unit (LH/RH) H/L		\$ 86.75	\$ 173.50
	Horn Wire H/L			\$ 156.50
	Aircon Condenser H/L			\$ 1,137.35
	Inter Cooler H/L			\$ 921.90
	Inter Cooler Mounting (2 PCS) H/L			\$ 25.90
	SUB TOTAL			\$ 10,472.40
	LESS 20%			\$ 2,094.48
	DISCOUNTED TOTAL			\$ 8,377.92
	Front Number Plate <i>Cut</i>			\$ 25.00
	Front No Plate Trim Cover S/C			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Towing Charge			\$ 60.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,510.00

SHC 631T

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Bnc			\$ 1,681.40 ✓
	Boot Lid Rubber deformed			\$ 115.80 ✓
	Boot Lid Hinge (LH/RH) dagn		\$ 178.10	\$ 356.20 X
	Boot Lid Lock Upper bst			\$ 137.90 ✓
	Boot Lid Lock Lower bst			\$ 31.70 ✓
	Boot Lid 'H' Emblem hlc			\$ 27.20 ✓
	Boot Lid CRDI Plate hlc			\$ 41.00 ✓
	Boot Lid Lamp (LH/RH) cyalc		\$ 556.80	\$ 1,113.60 ✓
	Licence Lamp (LH/RH) sru		\$ 33.95	\$ 67.90 X
	Boot Lid Trimboard torn			\$ 172.70 ✓
	Boot Lid Trimboard Clips (10pcs) hbc			\$ 11.00 ✓
	Bootlid Moulding bst			\$ 85.00 ✓
	Bootlid i40 Emblem hbc			\$ 41.00 ✓
	Bootlid Lower Garnish ctalc			\$ 398.00 ✓
	Rear Bumper cyalc			\$ 603.60 ✓
	Rear Bumper Reinforcement broken			\$ 504.35 ✓
	Rear Bumper Reinforcement Bracket (LH/RH) R NH		\$ 180.00	\$ 360.00 RX
	Rear Bumper Clip 10 pcs hbc			\$ 22.00 ✓
	Rear Bumper Bracket sru		\$ 49.00	\$ 98.00 X
	Rear Bumper Sponge torn			\$ 143.40 ✓
	Rear Bumper Under Cover Deented			\$ 225.00 ✓
	Rear Bumper Reflector Lamp (LH/RH) R NH		\$ 32.00	\$ 64.00 RX
	Tail Lamp (LH/RH) clanc		\$ 565.60	\$ 1,131.20 ✓
	Tail Lamp Quarter Panel (LH/RH) O/S Deented N/S NN		\$ 97.90	\$ 195.80 ✓
	Rear Panel Bnc			\$ 592.30 ✓
	Rear Panel Garnish deformed			\$ 57.70 ✓
	Rear Panel Lower Panel R Deented			\$ 495.50 RL
	Spare Tyre Holder sru			\$ 28.80 X
	Spare Tyre Panel Bnc			\$ 900.50 ✓
	Spare Tyre Panel Cushion sru			\$ 209.05 X
	Rear Towing Hook sru			\$ 94.60 X
	Member Assy- Rear Floor Centre sru			\$ 170.75 ?
	Panel Assy-Rear Floor Side (RH) dagn			\$ 92.40 X
	Exhaust Pipe Insulator R NH		\$ 58.55	\$ 117.10 RX
	Exhaust Silencer O/S ST N/S R bst		\$ 954.00	\$ 1,908.00 W
	Exhaust Pipe Hanger sru		\$ 58.55	\$ 117.10 X
	Exhaust Pipe Centre NH			\$ 1,150.30 X
	Rear Fender With Housing (RH) Bnc			\$ 4,736.80 ✓
	Rear Fender Inner Lining (RH) sru			\$ 164.40 X
	Rear Fender Air-Duct NH			\$ 51.60 X
	Rear Fender Trim Board (RH) bst			\$ 188.75 ✓
	Rear Windscreen Moulding hbc			\$ 60.00 ✓
	SUB TOTAL			\$ 18,763.40
	LESS 20%			\$ 3,752.68
	DISCOUNTED TOTAL			\$ 15,010.72

SHC 631T

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker Hw			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo Hw			\$ 100.00	Nett ✓
	Rear No.Plata SVL			\$ 25.00	Nett ✗
	Rear Bumper Reverse Sensor Dm			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo Hw			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) Hw		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant Hw			\$ 46.00	Nett ✓
				\$ 586.70	
	Labour Charge				
	Panel Beating			\$ 2,200.00	1200/r
	Spray Painting Charge			\$ 1,400.00	1000/r
	Wiring Charge			\$ 50.00	30/r
	Tuff Kote			\$ 100.00	40/r
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/r
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/r
	Remove/Refix Reverse Sensor			\$ 120.00	40/r
	Remove/Refix Fuel Tank			\$ 150.00	40/r
	Remove/Refix Exhaust Pipe			\$ 360.00	60/r
	TOTAL LABOUR			\$ 4,650.00	
	ESTIMATE TOTAL			\$ 30,190.34	
	03/05/2018 @ 1445w Not Antur 1/ same 10 dgs.  2KK Auto 				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					