

INS. CASE OWNER:

Lynette

CC 4 ASM
AXA1800 8101, Kp6352

LKK:

IDAC:

Surveyor:

Lynette

DOI:

ASSIGNMENT

3/5/18

Date / Time:

3/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

STV 6309L

Name of Insured:

BEEHIVE RAI

Insured Tel No.:

HP: 9277060

Excess Sec II :SS

D.O.A:

27/4/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

MADHURASHI F RAI

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

S8MOOFUV / 42909

Policy No.:

6A115767

Make / Model:

Tulipora

Place of Accident:

MENTI ARE 6 BY SUPRO
TMS 7th BOON LAYOI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability:

Final ? Yes / No

SHC 50530



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
cab

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/5/18
LNT

SHC 50530 - L4/14/17/18/19/20/21/22/23/24/25/26/27/28/29/30/31/32/33/34/35/36/37/38/39/40/41/42/43/44/45/46/47/48/49/50/51/52/53/54/55/56/57/58/59/60/61/62/63/64/65/66/67/68/69/70/71/72/73/74/75/76/77/78/79/80/81/82/83/84/85/86/87/88/89/90/91/92/93/94/95/96/97/98/99/100/101/102/103/104/105/106/107/108/109/110/111/112/113/114/115/116/117/118/119/120/121/122/123/124/125/126/127/128/129/130/131/132/133/134/135/136/137/138/139/140/141/142/143/144/145/146/147/148/149/150/151/152/153/154/155/156/157/158/159/160/161/162/163/164/165/166/167/168/169/170/171/172/173/174/175/176/177/178/179/180/181/182/183/184/185/186/187/188/189/190/191/192/193/194/195/196/197/198/199/200/201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220/221/222/223/224/225/226/227/228/229/230/231/232/233/234/235/236/237/238/239/240/241/242/243/244/245/246/247/248/249/250/251/252/253/254/255/256/257/258/259/260/261/262/263/264/265/266/267/268/269/270/271/272/273/274/275/276/277/278/279/280/281/282/283/284/285/286/287/288/289/290/291/292/293/294/295/296/297/298/299/300/301/302/303/304/305/306/307/308/309/310/311/312/313/314/315/316/317/318/319/320/321/322/323/324/325/326/327/328/329/330/331/332/333/334/335/336/337/338/339/340/341/342/343/344/345/346/347/348/349/350/351/352/353/354/355/356/357/358/359/360/361/362/363/364/365/366/367/368/369/370/371/372/373/374/375/376/377/378/379/380/381/382/383/384/385/386/387/388/389/390/391/392/393/394/395/396/397/398/399/400/401/402/403/404/405/406/407/408/409/410/411/412/413/414/415/416/417/418/419/420/421/422/423/424/425/426/427/428/429/430/431/432/433/434/435/436/437/438/439/440/441/442/443/444/445/446/447/448/449/450/451/452/453/454/455/456/457/458/459/460/461/462/463/464/465/466/467/468/469/470/471/472/473/474/475/476/477/478/479/480/481/482/483/484/485/486/487/488/489/490/491/492/493/494/495/496/497/498/499/500/501/502/503/504/505/506/507/508/509/510/511/512/513/514/515/516/517/518/519/520/521/522/523/524/525/526/527/528/529/530/531/532/533/534/535/536/537/538/539/540/541/542/543/544/545/546/547/548/549/550/551/552/553/554/555/556/557/558/559/560/561/562/563/564/565/566/567/568/569/570/571/572/573/574/575/576/577/578/579/580/581/582/583/584/585/586/587/588/589/590/591/592/593/594/595/596/597/598/599/600/601/602/603/604/605/606/607/608/609/610/611/612/613/614/615/616/617/618/619/620/621/622/623/624/625/626/627/628/629/630/631/632/633/634/635/636/637/638/639/640/641/642/643/644/645/646/647/648/649/650/651/652/653/654/655/656/657/658/659/660/661/662/663/664/665/666/667/668/669/670/671/672/673/674/675/676/677/678/679/680/681/682/683/684/685/686/687/688/689/690/691/692/693/694/695/696/697/698/699/700/701/702/703/704/705/706/707/708/709/710/711/712/713/714/715/716/717/718/719/720/721/722/723/724/725/726/727/728/729/730/731/732/733/734/735/736/737/738/739/740/741/742/743/744/745/746/747/748/749/750/751/752/753/754/755/756/757/758/759/760/761/762/763/764/765/766/767/768/769/770/771/772/773/774/775/776/777/778/779/780/781/782/783/784/785/786/787/788/789/790/791/792/793/794/795/796/797/798/799/800/801/802/803/804/805/806/807/808/809/810/811/812/813/814/815/816/817/818/819/820/821/822/823/824/825/826/827/828/829/830/831/832/833/834/835/836/837/838/839/840/841/842/843/844/845/846/847/848/849/850/851/852/853/854/855/856/857/858/859/860/861/862/863/864/865/866/867/868/869/870/871/872/873/874/875/876/877/878/879/880/881/882/883/884/885/886/887/888/889/890/891/892/893/894/895/896/897/898/899/900/901/902/903/904/905/906/907/908/909/910/911/912/913/914/915/916/917/918/919/920/921/922/923/924/925/926/927/928/929/930/931/932/933/934/935/936/937/938/939/940/941/942/943/944/945/946/947/948/949/950/951/952/953/954/955/956/957/958/959/960/961/962/963/964/965/966/967/968/969/970/971/972/973/974/975/976/977/978/979/980/981/982/983/984/985/986/987/988/989/990/991/992/993/994/995/996/997/998/999/1000/1001/1002/1003/1004/1005/1006/1007/1008/1009/1010/1011/1012/1013/1014/1015/1016/1017/1018/1019/1020/1021/1022/1023/1024/1025/1026/1027/1028/1029/1030/1031/1032/1033/1034/1035/1036/1037/1038/1039/1040/1041/1042/1043/1044/1045/1046/1047/1048/1049/1050/1051/1052/1053/1054/1055/1056/1057/1058/1059/1060/1061/1062/1063/1064/1065/1066/1067/1068/1069/1070/1071/1072/1073/1074/1075/1076/1077/1078/1079/1080/1081/1082/1083/1084/1085/1086/1087/1088/1089/1090/1091/1092/1093/1094/1095/1096/1097/1098/1099/1100/1101/1102/1103/1104/1105/1106/1107/1108/1109/1110/1111/1112/1113/1114/1115/1116/1117/1118/1119/1120/1121/1122/1123/1124/1125/1126/1127/1128/1129/1130/1131/1132/1133/1134/1135/1136/1137/1138/1139/1140/1141/1142/1143/1144/1145/1146/1147/1148/1149/1150/1151/1152/1153/1154/1155/1156/1157/1158/1159/1160/1161/1162/1163/1164/1165/1166/1167/1168/1169/1170/1171/1172/1173/1174/1175/1176/1177/1178/1179/1180/1181/1182/1183/1184/1185/1186/1187/1188/1189/1190/1191/1192/1193/1194/1195/1196/1197/1198/1199/1200/1201/1202/1203/1204/1205/1206/1207/1208/1209/1210/1211/1212/1213/1214/1215/1216/1217/1218/1219/1220/1221/1222/1223/1224/1225/1226/1227/1228/1229/1230/1231/1232/1233/1234/1235/1236/1237/1238/1239/1240/1241/1242/1243/1244/1245/1246/1247/1248/1249/1250/1251/1252/1253/1254/1255/1256/1257/1258/1259/1260/1261/1262/1263/1264/1265/1266/1267/1268/1269/1270/1271/1272/1273/1274/1275/1276/1277/1278/1279/1280/1281/1282/1283/1284/1285/1286/1287/1288/1289/1290/1291/1292/1293/1294/1295/1296/1297/1298/1299/1300/1301/1302/1303/1304/1305/1306/1307/1308/1309/1310/1311/1312/1313/1314/1315/1316/1317/1318/1319/1320/1321/1322/1323/1324/1325/1326/1327/1328/1329/1330/1331/1332/1333/1334/1335/1336/1337/1338/1339/1340/1341/1342/1343/1344/1345/1346/1347/1348/1349/1350/1351/1352/1353/1354/1355/1356/1357/1358/1359/1360/1361/1362/1363/1364/1365/1366/1367/1368/1369/1370/1371/1372/1373/1374/1375/1376/1377/1378/1379/1380/1381/1382/1383/1384/1385/1386/1387/1388/1389/1390/1391/1392/1393/1394/1395/1396/1397/1398/1399/1400/1401/1402/1403/1404/1405/1406/1407/1408/1409/1410/1411/1412/1413/1414/1415/1416/1417/1418/1419/1420/1421/1422/1423/1424/1425/1426/1427/1428/1429/1430/1431/1432/1433/1434/1435/1436/1437/1438/1439/1440/1441/1442/1443/1444/1445/1446/1447/1448/1449/1450/1451/1452/1453/1454/1455/1456/1457/1458/1459/1460/1461/1462/1463/1464/1465/1466/1467/1468/1469/1470/1471/1472/1473/1474/1475/1476/1477/1478/1479/1480/1481/1482/1483/1484/1485/1486/1487/1488/1489/1490/1491/1492/1493/1494/1495/1496/1497/1498/1499/1500/1501/1502/1503/1504/1505/1506/1507/1508/1509/1510/1511/1512/1513/1514/1515/1516/1517/1518/1519/1520/1521/1522/1523/1524/1525/1526/1527/1528/1529/1530/1531/1532/1533/1534/1535/1536/1537/1538/1539/1540/1541/1542/1543/1544/1545/1546/1547/1548/1549/1550/1551/1552/1553/1554/1555/1556/1557/1558/1559/1560/1561/1562/1563/1564/1565/1566/1567/1568/1569/1570/1571/1572/1573/1574/1575/1576/1577/1578/1579/1580/1581/1582/1583/1584/1585/1586/1587/1588/1589/1590/1591/1592/1593/1594/1595/1596/1597/1598/1599/1600/1601/1602/1603/1604/1605/1606/1607/1608/1609/1610/1611/1612/1613/1614/1615/1616/1617/1618/1619/1620/1621/1622/1623/1624/1625/1626/1627/1628/1629/1630/1631/1632/1633/1634/1635/1636/1637/1638/1639/1640/1641/1642/1643/1644/1645/1646/1647/1648/1649/1650/1651/1652/1653/1654/1655/1656/1657/1658/1659/1660/1661/1662/1663/1664/1665/1666/1667/1668/1669/1670/1671/1672/1673/1674/1675/1676/1677/1678/1679/1680/1681/1682/1683/1684/1685/1686/1687/1688/1689/1690/1691/1692/1693/1694/1695/1696/1697/1698/1699/1700/1701/1702/1703/1704/1705/1706/1707/1708/1709/1710/1711/1712/1713/1714/1715/1716/1717/1718/1719/1720/1721/1722/1723/1724/1725/1726/1727/1728/1729/1730/1731/1732/1733/1734/1735/1736/1737/1738/1739/1740/1741/1742/1743/1744/1745/1746/1747/1748/1749/1750/1751/1752/1753/1754/1755/1756/1757/1758/1759/1760/1761/1762/1763/1764/1765/1766/1767/1768/1769/1770/1771/1772/1773/1774/1775/1776/1777/1778/1779/1780/1781/1782/1783/1784/1785/1786/1787/1788/1789/1790/1791/1792/1793/1794/1795/1796/1797/1798/1799/1800/1801/1802/1803/1804/1805/1806/1807/1808/1809/1810/1811/1812/1813/1814/1815/1816/1817/1818/1819/1820/1821/1822/1823/1824/1825/1826/1827/1828/1829/1830/1831/1832/1833/1834/1835/1836/1837/1838/1839/1840/1841/1842/1843/1844/1845/1846/1847/1848/1849/1850/1851/1852/1853/1854/1855/1856/1857/1858/1859/1860/1861/1862/1863/1864/1865/1866/1867/1868/1869/1870/1871/1872/1873/1874/1875/1876/1877/1878/1879/1880/1881/1882/1883/1884/1885/1886/1887/1888/1889/1890/1891/1892/1893/1894/1895/1896/1897/1898/1899/1900/1901/1902/1903/1904/1905/1906/1907/1908/1909/1910/1911/1912/1913/1914/1915/1916/1917/1918/1919/1920/1921/1922/1923/1924/1925/1926/1927/1928/1929/1930/1931/1932/1933/1934/1935/1936/1937/1938/1939/1940/1941/1942/1943/1944/1945/1946/1947/1948/1949/1950/1951/1952/1953/1954/1955/1956/1957/1958/1959/1960/1961/1962/1963/1964/1965/1966/1967/1968/1969/1970/1971/1972/1973/1974/1975/1976/1977/1978/1979/1980/1981/1982/1983/1984/1985/1986/1987/1988/1989/1990/1991/1992/1993/1994/1995/1996/1997/1998/1999/2000/2001/2002/2003/2004/2005/2006/2007/2008/2009/2010/2011/2012/2013/2014/2015/2016/2017/2018/2019/2020/2021/2022/2023/2024/2025/2026/2027/2028/2029/2030/2031/2032/2033/2034/2035/2036/2037/2038/2039/2040/2041/2042/2043/2044/2045/2046/2047/2048/2049/2050/2051/2052/2053/2054/2055/2056/2057/2058/2059/2060/2061/2062/2063/2064/2065/2066/2067/2068/2069/2070/2071/2072/2073/2074/2075/2076/2077/2078/2079/2080/2081/2082/2083/2084/2085/2086/2087/2088/2089/2090/2091/2092/2093/2094/2095/2096/2097/2098/2099/2100/2101/2102/2103/2104/2105/2106/2107/2108/2109/2110/2111/2112/2113/2114/2115/2116/2117/2118/2119/2120/2121/2122/2123/2124/2125/2126/2127/2128/2129/2130/2131/2132/2133/2134/2135/2136/2137/2138/2139/2140/2141/2142/2143/2144/2145/2146/2147/2148/2149/2150/2151/2152/2153/2154/2155/2156/2157/2158/2159/2160/2161/2162/2163/2164/2165/2166/2167/2168/2169/2170/2171/2172/2173/2174/2175/2176/2177/2178/2179/2180/2181/2182/2183/2184/2185/2186/2187/2188/2189/2190/2191/2192/2193/2194/2195/2196/2197/2198/2199/2200/2201/2202/2203/2204/2205/2206/2207/2

REF:

ASMLAXA)

Surveyor

ASSIGNMENT

From:

Date: 03/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHC 5053D

at Workshop m/s

Trans Cab

of

No. 2 AMK 9463

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5053D Yr Regn: 12 / 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude C.C. 1995

Colour:

White / Red

A/C: Insured / Std / NI / NA

Sp. Reading:

517643

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABC15AUC 276011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti: 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

6 mm

L/Bal.

8 mm

L/Bal.

6 mm

D.O.A.

27/4/18

D.O.I.

3/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/5

File pass to Catherine
11/2/18 @ 3800

(Red of 44616.47 / 92%).

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008101/Kpb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 03-05-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SVJ 6309L		Veh. Inspected	SHC 5053D
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	03/05/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/04/2018		Inspection Date	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5053D**AAD1804-276***Not Authorized
C/Sy B*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5053D

VF1ABL15AUC276071

RENAULT

LATITUDE

27.4.2018

AxA

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPR BRACKET SIDE RH REAR
- 5 1 BUMPR RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPR BRACKET SIDE LH REAR
- 8 1 BUMPR RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Audns</i>	1,108.46	✓
\$	<i>nd/ds</i>	768.84	✓
\$	<i>cm</i>	113.47	✓
\$	<i>sn</i>	135.97	X
\$	<i>sn</i>	44.99	X
\$	<i>sn</i>	43.61	X
\$	<i>cm</i>	135.97	X
\$	<i>ds</i>	44.99	✓
\$	<i>cm</i>	43.61	✓
\$	<i>ds</i>	777.52	✓
\$	<i>ds</i>	225.95	✓
\$	<i>ds</i>	225.95	✓
\$	<i>ds</i>	2,872.68	
\$	<i>sn</i>	470.06	
\$	<i>sn</i>	323.05	
\$	<i>sn</i>	493.35	
\$	<i>sn</i>	493.35	
\$	<i>sn</i>	225.36	
\$	<i>sn</i>	225.36	
\$	<i>sn</i>	276.08	
\$	<i>sn</i>	276.08	
\$	<i>sn</i>	367.84	
\$	<i>sn</i>	367.84	
\$	<i>sn</i>	586.45	
\$	<i>sn</i>	168.13	
\$	<i>sn</i>	202.67	
\$	<i>sn</i>	74.40	
\$	<i>sn</i>	50.52	
\$	<i>sn</i>	221.81	

X

Trans-cab Auto Services Pte Ltd**AAD1804-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5053D

30	1 DOOR PANEL REAR LH	\$	R 2,844.66	}	X	
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn 671.45			
32	1 FENDER PANEL REAR LH	\$	R 3,299.13			
33	1 WHEELARCH REAR LH	\$	Sn 543.47			
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn 671.45			
35	1 FENDER PANEL REAR RH	\$	R 3,299.13			
36	1 WHEELARCH REAR RH	\$	Sn 543.47			
37	1 TAILLAMP RH	\$	Sn 552.55			
38	1 TAILLAMP PANEL RH	\$	R 986.70			
39	1 TAILLAMP LH	\$	Sn 552.55			
40	1 TAILLAMP PANEL LH	\$	R 986.70			
41	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77			
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn 404.56			
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88			
44	1 SPARE WHEEL PANEL TRIM	\$	Sn 612.21			
45	1 EXHAUST REAR	\$	R 7,489.05			
46	1 EXHAUST CAP REAR	\$	R 230.49			
47	1 FUEL FLAP L70Y	\$	Sn 343.57			
TOTAL		\$	39,057.17			
10%		\$	3,905.72			
		\$	35,151.45			

Special Nett

1	1SET PARKING AID	\$	Phon	700.00	✓
2	1SET REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	✓
5	1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	✓
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	✓
7	1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	✓
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	✓
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	} X
11	1SET BOOT FINISHER CLIP	\$	nn	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	nn	30.00	
13	1 BOOT STICKER "6555-3333"	\$	nn	30.00	
14	1 BOOT INNER TRIM CLIP	\$	nn	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	

Trans-cab Auto Services Pte Ltd**AAD1804-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5053D

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00	}	X
17 1 FENDER INNER TRIM CLIP LH	\$	28.00		
18 1 FENDER INNER TRIM CLIP LH	\$	28.00		
19 1 TAILLAMP CLIP RH	\$	5.00		
20 1 TAILLAMP CLIP LH	\$	5.00		
21 2 REAR WINDSCREEN SELANT	\$	80.00		
22 1 WINDSCREEN MOULDING	\$	100.00		
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00		
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	}	
25 1 SPARE TYRE	\$	330.00		

TOTAL \$ 2,225.02**TOTAL PARTS \$ 37,376.47****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	3001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X



Service Request Details

Claim

S8M00FVV

Reference

None 

Loss Date

April 27, 2018

Request Date

May 3, 2018

Due Date

May 10, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Kenneth

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC5053D

Make

TPVD RENAULT

Service Address

...

Primary Contact/Insured

BEENAA RAI

BLK 671 #16-367, CHOA CHU KANG CRESCENT, 680671, Singapore
90071520

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

NON-REPORTING

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Hsiao Tong (LKKAUTO)

From: Candy Kong <candy.kong@transcab.com.sg>
Sent: Wednesday, 2 May 2018 4:20 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'deshuan.tan'
Subject: ARRANGE FOR SURVEY SHC5053D
Attachments: img-502161921-0001.pdf

Categories: Shailendra

Dear all,

Please arrange for survey as below :

SJV6309L - 27.04.2018 AT 1515 Hrs - SHC5053D

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 19 November 2018 10:21 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; claims@transcab.com.sg
Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHC 5053D(DOA: 27/04/2018) - AAD1804-276

Your ref: **AAD1804-276 (SHC 5053D)**
Our ref: CC4/ASM18008101/Kpb3

Without Prejudice

Hi Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AXA.

Kindly advise if there is any after repair/ after paint photos for SHC 5053D(DOA: 27/04/2018). If so, kindly let us have a copy of the photos.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 **<MANDATE IA> - S8M00FVV [ACCIDENT INVOLVING
SVJ 6309L(OI) & SHC 5053D(TP) ON 27/04/2018]**

Type

 Question

Message

Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$4,745.39(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 19 Nov 2018

[Reply](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19.11.2018

Survey Details:

Date of loss	27.04.2018
Date of appointment	03.05.2018
Date of survey	03.05.2018
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 5053D
Make and Model	Renault Latitude (1995cc)
Date of registration	02.12.2013
Excess	NIL
Market Value/ Book Value	(est)
Parf/COE Rebate	(est)
Nett Value/ ERV	\$ - (est)

Repair details:

Initial Estimate	\$ 48,416.47
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,965.28
Check items (estimate)	NIL
Labour	\$ 800.00
Supplementary	NIL
Total	\$ 4,765.28
Lump Sum(if applicable)	\$ 3,800.00

Number of days for repair	<u>2.5</u>
---------------------------	------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

2.5 recommended repair days + 2PRS = 4.5days

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 4,066.00	
Loss of use	NIL	
Loss of rental	\$ 446.94	(4.5days x \$99.32)
Loss of income	\$ 225.00	(4.5days x \$50.00)
LTA/GIA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 4,745.39	



Re:<MANDATE IA> - S8M00FVV [ACCIDENT INVOLVING SJV 6309L(OI) & SHC 5053D(TP) ON 27/04/2018]

Type

🔍 Question

Message

MANDATE APPROVED

Reply

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Thursday, 13 December 2018 10:11 AM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'; 'Zhe Wei'; claims@transcab.com.sg
Subject: RE: Your ref: AAD1804 -276 (SHC 5053D) *Our Ref: CC4/ASM18008101/Kpb3 [ACCIDENT INVOLVING SJV 6309L(AXA) AND SHC 5053D ON 27/04/2018]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 24 November 2018 9:15 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg) <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg
Subject: Your ref: AAD1804 -276 (SHC 5053D) *Our Ref: CC4/ASM18008101/Kpb3 [ACCIDENT INVOLVING SJV 6309L(AXA) AND SHC 5053D ON 27/04/2018]

Your ref: **AAD1804 -276 (SHC 5053D)**
Our Ref: CC4/ASM18008101/Kpb3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SJV 6309L(AXA) AND SHC 5053D ON 27/04/2018

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 4,066.00
2. Loss of Rental (4.5days x \$99.32)	\$ 446.94
3. Loss of Income (4.5days x \$50.00)	\$ 225.00
4. LTA/GIA Search Fee	\$ 7.45
TOTAL	<u>\$ 4,745.39</u>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJV 6309L (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHC 5053D (TP veh)		
Date of Accident:	27/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	52,212.20
Final Repair Cost	:	\$	4,066.00
Loss of Token Sum	:	\$	225.00
Rental (if any)	:	\$	446.94
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	4,745.39

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111				

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	:	\$ 4,745.39

NUR SHAQILAH BTE ABDOL
WAHAB

07/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008101/Kpb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 07-01-2019



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 6309L	Veh. Inspected	SHC 5053D
Policy No.	GA115767	Coverage (\$)	0.00
Claim No.	S8M00FVV	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	03/05/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC276071	Colour	WHITE / RED
Odometer	517643	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	8 mm
L/H Front Tyre	215/60R16	GITI	8 mm
R/H Rear Tyre	215/60R16	FALKEN	6 mm
L/H Rear Tyre	215/60R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/04/2018	Inspection Date	03/05/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2.500 Working Days
-------------------------------------	--------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5053D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED / DENTED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	DENTED / DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	CRACKED	135.97	135.97
1	BUMPER RETAINER LH REAR (CONSISTENT)	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR LH (CONSISTENT)	CRACKED	43.61	43.61
1	BUMPER BEAM REAR (CONSISTENT)	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	BENT	225.95	225.95
1	BOOT REAR (CONSISTENT)	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER (CONSISTENT)	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT BADGE (CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	586.45	-
1	BOOT SWITCH (CONSISTENT)	SERVICEABLE	168.13	-
1	BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CC4/ASM18008101/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE LAMP (CONSISTENT)	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG (CONSISTENT)	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	SERVICEABLE	612.21	-
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR (CONSISTENT)	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y (CONSISTENT)	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-3,905.72	-344.48
			35,151.43	3,100.28
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN) (CONSISTENT)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00

Report Ref No. CC4/ASM18008101/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
1	ST BOOT FINISHER CLIP (SN) (CONSISTENT)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	SERVICEABLE	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
			2,225.02	865.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	440.00

Report Ref No. CC4/ASM18008101/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, DOOR PANEL REAR LH, FENDER PANEL REAR LH, FENDER PANEL INNER TRIM REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		4,200.00	300.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			-	-
			-	-
			-	-
			11,420.00	800.00
GRAND TOTAL			48,796.45	4,765.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CC4/ASM18008101/Kpb3s2



Report Ref No. CC4/ASM18008101/Kpb3s2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.