

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0514/2018/CCS
Date : 02-May-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tee Geok Cheng
Address : Blk 308B Ang Mo Kio Avenue 1
#07-401
Singapore 562308
Telephone : HP +65 91769690
Type of Claim : Own Damage Claims
Policy No. : 1700074706
Vehicle No : **SLU 9009 P**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Nov-17
Engine No : CVN 044893
Chassis No : WAUZZZF47JA021996
Mileage :
Date In : 30-Apr-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Apr-18
Place of Accident : Along AYE towards Tuas bef exit 11 Clementi Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 9009 P.

S/n	Nature of Jobs		Estimated Charges	Remarks
1	To tow and recover vehicle from scene of accident.	S/N	Waived	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓
3	To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,100.00	✓
4	To remove center console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and central protection.	S/N \$	3,600.00	✓
5	To renew front windscreen.	S/N \$	480.00	✓
6	To remove front fittings, dismantle front bumper, bonnet and both front fenders. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$	5,400.00 3000.	
7	To remove and reinstall both front door panel trims, dismantle wing mirror assy and renew damaged trims.	S/N \$	600.00	✓
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 11,540.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 9009 P.

S/n	Nature of Jobs	Estimated Charges	Remarks
8	To respray front bumper, both front fenders, bonnet, bonnet hinges, both A-pillar and both front doors.	\$ 6,000.00	3850. ^{7 pieces.}
9	To remove and transfer rear parking aid system with rear lid kick sensor assy.	S/N \$ 360.00	✓
10	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00	550
11	To respray rear bumper.	\$ 800.00	550
12	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 19,984.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 9009 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,849.00	✓
2	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 171.00	✗
3	RADIATOR GRILLE <i>Cancelled</i>	\$ 972.00	✓
4	FRONT BUMPER GRILLE - LH/RH <i>new</i>	2 \$ 236.00	✗
5	FRONT BUMPER FOAM <i>Cancelled</i>	\$ 107.00	✓
6	FRONT REINFORCEMENT BEAM <i>Bent</i>	\$ 702.00	✓
7	FRONT BUMPER SUPPORT - LH/RH <i>2nd</i>	2 \$ 48.00	✓
8	FRONT LOCK CARRIER BRACKET <i>Smashed</i>	\$ 118.00	✓
9	FRONT REINFORCEMENT BEAM BRACKET - LH/RH ?	2 \$ 390.00	?
10	FRONT REINFORCEMENT BEAM BOLT SET ?	\$ 84.00	?
11	FRONT BUMPER GUIDE - LH/RH <i>new</i>	2 \$ 64.00	✗
12	FRONT BUMPER TOP COVER <i>Distorted</i>	\$ 109.00	✓
13	BONNET RELEASE LEVEL <i>Bent</i>	\$ 12.00	✓
14	BONNET BOWDEN CABLE ?	\$ 50.00	?
15	SIGN ' CAUTION ' STICKER <i>new</i>	\$ 12.00	✓
16	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 7.00	✓
17	FRONT FENDER - LH/RH <i>Repair</i>	2 \$ 1,330.00	✗
18	FRONT FENDER ATTACHMENT PARTS	\$ 90.00	✗
19	FRONT FENDER CLOSING ELEMENT - LH/RH <i>2 new</i>	2 \$ 88.00	✗
20	FRONT FENDER BRACKET - FRONT LH/RH	2 \$ 62.00	✗
SUB-TOTAL SPARE PARTS CHARGES		\$ 6,501.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 9009 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER BRACKET - CENTER LH/RH	2 \$	86.00 ✓
22	FRONT FENDER RIVET SET	\$	24.00 ✓
23	FRONT FENDER BRACE - LH/RH	2 \$	206.00 ✓
24	FRONT FENDER TOP COVER - FRONT LH/RH	2 \$	40.00 ✓
25	FRONT FENDER TRIM - OUTER LH/RH	2 \$	54.00 ✓
26	FRONT FENDER STONE CHIP GUARD - LH/RH	2 \$	88.00 ✗
27	FRONT WHEEL SPOILER - LH/RH	2 \$	126.00 ✗
28	FRONT WHEEL HOUSING LINER - LH/RH	2 \$	430.00 ✗
29	WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$	156.00 ✗
30	BONNET <i>Distorted</i>	\$	2,163.00 ✓
31	BONNET ATTACHMENT PARTS <i>me</i>	\$	105.00 ✓
32	BONNET HINGE - LH/RH ?	2 \$	532.00 ?
33	BONNET IMPART PROTECTION - LH/RH <i>me</i>	2 \$	48.00 ✓
34	BONNET IMPART PROTECTION - CENTER	\$	24.00 ✓
35	BONNET LOCK STRIKER - LH/RH <i>Bent</i>	2 \$	88.00 ✓
36	BONNET LOCK <i>Jammed</i>	2 \$	376.00 ✓
37	BONNET LOCK BOWDEN CABLE - INNER ?	\$	50.00 ?
38	LED HEADLIGHT - LH/RH <i>cracked</i>	2 \$	13,946.00 ✓
39	POWER MODULE FOR MAIN LIGHT ?	2 \$	1,389.00 ?
40	CONTROL UNIT FOR LIGHT CONTROL ?	2 \$	1,314.00 ?
SUB-TOTAL SPARE PARTS CHARGES		\$ 21,245.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 9009 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	HEADLIGHT COMPENSATING PIECE ?	4 \$ 140.00 ?	
42	HEADLIGHT WASHER CYLINDER - LH/RH ?	2 \$ 368.00 ?	
43	HEADLIGHT CYLINDER BRACKET ?	2 \$ 11.00 ?	
44	HEADLIGHT WASHER PIPE ?	\$ 79.00 ?	
45	FRONT LOCK CARRIER <i>Distorted</i>	\$ 891.00 ✓	
46	FRONT LOCK CARRIER AIR GUIDE - LH/RH LOWER ?	2 \$ 46.00 ?	
47	FRONT LOCK CARRIER AIR GUIDE - LH/RH UPPER ?	2 \$ 20.00 ?	
48	FRONT LOCK CARRIER AIR GUIDE - CENTER ?	\$ 14.00 ?	
49	A/C CONDENSER <i>Distorted</i>	\$ 540.00 ✓	
50	A/C CONDENSER PRESSURE SENSOR ?	\$ 170.00 ?	
51	CONDENSER VALVE ?	\$ 46.00 ?	
52	PRESSURE SENSOR CONNECTOR ?	\$ 20.00 ?	
53	RADIATOR ?	\$ 585.00 ?	
54	RADIATOR RUBBER BUSH ?	\$ 38.00 ?	
55	COOLANT ?	\$ 133.00 ?	
56	RADIATOR FAN RING ?	\$ 230.00 ?	
57	RADIATOR FAN WITH CONTROL UNIT ?	\$ 2,055.00 ?	
58	INTAKE AIR DUCT ?	\$ 18.00 ?	
59	AIR FILTER AIR GUIDE ?	\$ 31.00 ?	
60	AIR FILTER ?	\$ 338.00 ?	
SUB-TOTAL SPARE PARTS CHARGES		: \$ 5,773.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 9009 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	FRONT DOOR CHROME TRIM - LH/RH <i>at</i>	2 \$ 530.00 ✓	
62	FRONT DOOR WINDOW GUIDE - LH/RH <i>new</i>	2 \$ 784.00 ✗	
63	REAR BUMPER <i>del</i>	\$ 1,907.00 ✓	
64	REAR BUMPER FIXING PARTS <i>new</i>	\$ 63.00 ✗	
65	REAR BUMPER SPOILER <i>at</i>	\$ 216.00 ✓	
66	REAR KICK SENSOR SECURING STRIP ?	\$ 191.00 ?	
67	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$ 70.00 ✗	
68	REAR PARKING AID SENSOR ?	2 \$ 421.00 ?	
69	FRONT NO. PLATE <i>new</i>	S/N \$ 25.00 ✓	
70	FRONT WINDSCREEN <i>cracked</i>	\$ 1,004.00 ✓	
71	GEL FOIL FOR RAIN SENSOR <i>new</i>	\$ 127.00 ✓	
72	GLASS PRIMER <i>new</i>	\$ 19.00 ✓	
73	FRONT WINDSCREEN TRIM - LOWER ?	\$ 85.00 ?	
74	DASHBOARD <i>torn</i>	\$ 4,604.00 ✓	
75	PASSENGER AIR BAG UNIT <i>3 Activated</i>	\$ 3,981.00 ✓	
76	STEERING WHEEL AIR BAG UNIT	\$ 3,111.00 ✓	
77	HEAD AIR BAG UNIT - LH/RH <i>Activated</i>	2 \$ 3,384.00 ✓	
78	AIR BAG CRASH SENSOR <i>3 Activated</i>	3 \$ 818.00 ✓	
79	FRONT SEAT BELT - LH/RH	2 \$ 1,912.00 ✓	
80	FRONT SEAT BELT HEIGHT ADJUSTER - LH/RH ?	2 \$ 306.00 ?	
SUB-TOTAL SPARE PARTS CHARGES		\$ 23,558.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 9009 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	AIR BAG CONTROL UNIT <i>Activated</i>	\$ 1,870.00	✓
82	ROOF LINING <i>crumpled</i>	\$ 1,682.00	✓
83	A-PILLAR TRIM - UPPER LH/RH <i>not in</i>	2 \$ 360.00	X
84	BATTERY CENTRAL PROTECTION <i>Not</i>	\$ 470.00	✓
85	FRONT WINDSCREEN SEALANT <i>Not</i>	S/N \$ 200.00	✓
86	SUNDRIES	\$ 800.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 62,459.00
TOTAL LABOUR CHARGES			\$ 19,984.00
GRAND TOTAL			\$ 82,443.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King.*
Surveyed Date : *03/05/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 18 Days*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

*Front 15 days } 18 Days.
Rear 3 days }*

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant