

ASS. REC. BY: Adrian Ling

REF:

CC3 / ALH18008105 / A93b 9/1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 180K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 08/12/18 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGY2345C Yr Regn: 2018, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 cc 1984.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 5676. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF50HJA0S0087

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 03/05/18

Survey held at: Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

0DA16.

SGY 2345C - CC3/ALH18008105/Kee

PLA: 240418

04/05/18 @ 15:48 pm. revised to Tresh via merimen.

7/5/18 Inform Kee Siang Authorised repair via email @ 14:51 pm By Joyce Lee

04/05/18 @ 16:22 mandate approved by Victor Koh.

(\$16,714.52 Red - 50%)

RECEIVED 20 AUG 2018

Date/Time, File Pass to?

20/03/18

1) Jypst

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ 16,423.48 P/P)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2102B
Vehicle Details	
Vehicle No.:	SGY2345C
Vehicle to be Exported:	No
Intended De-registration Date:	04 May 2018
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CVK050891
Chassis No.:	WAUZZZF50JA050037
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$37,949.00
Original Registration Date:	10 Jan 2018
First Registration Date:	10 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$45,129.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jan 2028
PARF Rebate Amount:	\$33,846.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$43,840.00
Total Rebate Amount:	\$77,686.00

The information contained herein is correct as at 04 May 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 20 July 2018 2:04 PM
To: 'Boo seng yak'
Cc: 'Adrian Ling'; 'Janice Lee (LKKAuto)'; sur@lkkauto.com; jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SGY2345 C - OD AIG - SURVEYED 3 MAY 18

Dear Mr Boo,

Confirm final fig \$16,423.48 @ 8 days of repairs before excess \$800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Wednesday, 4 July 2018 5:38 PM

To: Adrian Ling <adrianling@lkkauto.com>; Janice Lee (LKKAuto) <janicelee@lkkauto.com>; sur@lkkauto.com; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SGY2345 C - OD AIG - SURVEYED 3 MAY 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$16,423.48 @ 8 days of repairs exclude 1 Sunday and 1 Public Holiday.

Guo Qiang re-inspected vehicle on 23 May 18.

I attached some photographs for your attention too.

Your early closure is well appreciated.

Best regards - jb

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, May 07, 2018 2:51 PM
To: Claims; Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: SGY 2345 C Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGY 2345C (excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Friday, May 04, 2018 8:52 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; claims@premiumauto.com.sg

Subject: RE: SGY 2345 C Own Damage Claims

Dear Shirley,

Attached is the Amended GIA report for your kind reference. Kindly advise on approval and excess amount.

Thank you.

Best Regards,

Kee Siang

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 8 May 2018 9:12 AM
To: 'Tr, Tinesh'
Cc: sur@lkkauto.com
Subject: RE: OD / 9735177838SG / SGY2345C -DOA 24/04/2018

Dear Tinesh,

GIA report has been amend and uploaded inside merimen.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tr, Tinesh [mailto:Tinesh.Tr@aig.com]
Sent: Friday, 4 May 2018 2:36 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: sur@lkkauto.com
Subject: RE: OD / 9735177838SG / SGY2345C -DOA 24/04/2018

Hi Shirley,

Received with thanks.

Kindly request the workshop to amend the GIA report since video footage is submitted/provided in merimen.

Circumstances of Accident

AT ABOUT 1.18PM, I WAS DRIVING ON WHAMPOA FLYOVER WHEN I COLLIDED WITH TRAN TAXI SHB7715U. HE KNOCKED INTO THE BUMPER OF THE VAN GX6060C IN FRONT OF HIM. THERE WAS A PASSENGER IN THE BACK SEAT OF THE TAXI. SHE DID NOT HIT THE BACK THE FRONT SEAT THOUGH, SHE IS NOT WEAR SEAT BELT. NO ONE IN THE VAN WAS INJL. THE TAXI DRIVER HAD NO EXTERNAL INJURIES AND DROVE OFF AFTER EXCHANGE OF PARTICULARS. THE TAXI PASSENGER DECLINED AMBULANCE.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Janice Lee (LKKAuto)

From: Tr, Tinesh <Tinesh.Tr@aig.com>
Sent: Friday, May 04, 2018 2:36 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: OD / 9735177838SG / SGY2345C -DOA 24/04/2018

Hi Shirley,

Received with thanks.

Kindly request the workshop to amend the GIA report since **video footage is submitted/provided** in merimen.

Circumstances of Accident

AT ABOUT 1.18PM, I WAS DRIVING ON WHAMPOA FLYOVER WHEN I COLLIDED WITH TRANSC TAXI SHB7715U. HE KNOCKED INTO THE BUMPER OF THE VAN GX6060C IN FRONT OF HIM. THERE WAS A PASSENGER IN THE BACK SEAT OF THE TAXI. SHE DID NOT HIT THE BACK OF THE FRONT SEAT THOUGH, SHE IS NOT WEAR SEAT BELT. NO ONE IN THE VAN WAS INJURE THE TAXI DRIVER HAD NO EXTERNAL INJURIES AND DROVE OFF AFTER EXCHANGE OF PARTICULARS. THE TAXI PASSENGER DECLINED AMBULANCE

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Thanks,

Regards,

Tinesh Rajantran
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, May 04, 2018 1:27 PM
To: Tr, Tinesh
Cc: sur@lkkauto.com
Subject: RE: OD / 9735177838SG / SGY2345C -DOA 24/04/2018

Dear Rajantran,

We refer to the below email above matter.

Documents and video accident has been uploaded insided merimen.

Thank you.

Best Regards,

Shirley Hlew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tr, Tinesh [<mailto:Tinesh.Tr@aig.com>]

Sent: Friday, 4 May 2018 9:42 AM

To: sur@lkkauto.com

Subject: OD / 9735177838SG / SGY2345C -DOA 24/04/2018

Hi ALL,

Kindly send insured driving license in order for us to confirm coverage this case.

Thanks,

Regards,

Tinesh Rajantran

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

View Received Message

This mail is associated with :

***SGY2345C (9735177838SG)**

OD

Apr 24 2018 1:00PM

[JULIANA POH]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 20/07/2018 12:19 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16423,48) - SGY2345C - Claim Handler: Tr, Tinesh

Approved:16423.48:

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 18 Jul 2018

Preliminary Advice

Vehicle No	: SGY2345C	Accident Date	: 24/04/2018
Make	: AUDI A5	Policy No.	: 1700095007
Assignment Date	: 03/05/2018	Excess	: S\$800.00
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 8 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,138.00
Revised Amount	:S\$	16,423.48 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	16,423.48
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	77,686.00
Salvage Value	:S\$	
Margin for Repair	:S\$	102,314.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT \$ 1,626.88.

Print Received Message

This mail is associated with :

***SGY2345C (9735177838SG)**

OD

Apr 24 2018 1:00PM

[JULIANA POH]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/05/2018 16:22 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9877.00) - SGY2345C - Claim Handler: Tr, Tinesh

Approved:9877.00:Re-inspection to be done for damage check and supplementary items / labour.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr. Tinesh

Date: 04 May 2018

Preliminary Advice

Vehicle No	: SGY2345C	Accident Date	: 24/04/2018
Make	: AUDI A5	Policy No.	: 1700095007
Assignment Date	: 03/05/2018	Excess	: S\$0.00
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,386.00
Revised Amount	:S\$	9,877.00
Check Items (Estimated)	:S\$	15,412.00
Total	:S\$	25,289.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	77,686.00
Salvage Value	:S\$	
Margin for Repair	:S\$	102,314.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2018 19:50
Date Of Accident	24/04/2018 13:20
Exact Location Of Accident	WHAMPOA FYLOVER (CTE JOINING TO PIE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY2345C
Insured/Policyholder	
Name Of Registered Owner	JULIANA POH
NRIC No	S7622102B
Email Address	POH.JULIANA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84990543
Alternative Phone No	OFFICE-68443702

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 2.0 TFS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700095007
Cover Note Number	

Driver

Name of Driver	JULIANA POH
NRIC No	S7622102B
Date Of Birth	22/07/1976
Occupation	INDOOR
Date Of Driving Pass	12/07/1997
Driving Experience	20 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84990543
Fax Number	
Contact Number	OFFICE-68443702
EMail Address	POH.JULIANA@GMAIL.COM

Address	BLK 7 LORONG 42 GEYLANG #05-03
Postcode	398028
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT ABOUT 1.18PM, I WAS DRIVING ON WHAMPOA FLYOVER WHEN I COLLIDED WITH TRANSCAB TAXI SHB7715U. HE KNOCKED INTO THE BUMPER OF THE VAN GX6060C IN FRONT OF HIM. THERE WAS A PASSENGER IN THE BACK SEAT OF THE TAXI. SHE DID NOT HIT THE BACK OF THE FRONT SEAT THOUGH, SHE IS NOT WEAR SEAT BELT. NO ONE IN THE VAN WAS INJURED. THE TAXI DRIVER HAD NO EXTERNAL INJURIES AND DROVE OFF AFTER EXCHANGE OF PARTICULARS. THE TAXI PASSENGER DECLINED AMBULANCE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB7715U
Vehicle Make/Model/Colour	TRANSCAB
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	YEO KIM LAI
NRIC/Passport Number	S1122970J
Contact Number	98651977
Address	BLK 105 POTONG PASIR AVE 1 #02-436
Postcode	1335
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GX6060C
Vehicle Make/Model/Colour	TOYOTA LITE ACE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHEE KOK CHOY
NRIC/Passport Number	G7713793P
Contact Number	91853002
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

24/4/18

4:14pm




Driver's Signature
(If driver is not the policyholder)
Date & Time:

24/4/18

4:14pm



Reporting Centre Personnel's Signature

Name: 
NRIC/FIN No. 56552564M

Sketch Plan #2

SKETCH PLAN



Accident Photo





Name of Policyholder : JULIANA POH
Period of Insurance : 10 Jan 2018 To 09 Jan 2019
Engine No. : CVK050891
Chassis No. : WAUZZZF50JA050037

Vehicle No. : SGY2345C
Policy No. : 1700095007
Endorsement No. :
Issued Date : 30 Jan 2018

Make/Model	AUDI A5 Sportback 2.0TFSI S Tronic (Design)		
Engine Capacity/Tonnage	1,984.00 CC	Sum Insured	Market Value
Driver Restriction	NA	Off Peak Car	No
		Insuring with COE/PARF	Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

JULIANA POH - \$1600 (Own Damage)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 8338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125268

PREMIUM LEASING -YCL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7622102B



Name

JULIANA POH

傅蓮娜

Race

CHINESE

Date of birth

22-07-1976

Sex

F

S7622102B

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number: S7622102B

Name

JULIANA POH
(JULIANA FU)

Birth Date 22 Jul 1976

Issue Date 30 Jun 2003



000611729E

3918496



NRIC No. S7622102B



Date of issue

10-08-2006

APT BLK 7 LORONG 42 GEYLANG #05-03
SINGAPORE 398028

NRIC No: S7622102B

Date: 24/05/2010

No: 8506550

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

12 Jul 1997



Licence No: S7622102B

NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0497/2018/JT
Date	:	26-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Juliana Poh
Address	:	Blk 7 Lorong 42 Geylang #05-03 Singapore 398028
Telephone	:	HP +65 8499 0543
Type of Claim	:	Own Damage Claim
Policy No.	:	1700095007
Vehicle No	:	SGY 2345 C
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	Jan-18
Engine No	:	CVK 050891
Chassis No	:	WAUZZZF50HJA050037
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	24-Apr-18
Place of Accident	:	Whampoa Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGY 2345 C.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantlle and renew front bumper assy, both headlights, and bonnet. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,400.00 1000	
3	To remove and reinstall RHS front door panel trims, dismantle RHS wing mirror assy.	S/N \$ 300.00 ✗	
4	To respray front bumper, bonnet and RHS front door. ✗	\$ 2,300.00 1200	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>5,672.00</u>	

LINK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification/s is allowed
- Supplementary item(s), must be resurveyed and is subject to final approve from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. ^{SGY} SCY 2345 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	\$ 1,970.00 ✓	1,576.00
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 349.00 ✓	
3	SECURING STRIP <i>new</i>	\$ 60.00 ✓	
4	AIR GRILLE - CENRE <i>crushed</i>	\$ 171.00 ✓	136.20
5	RADIATOR GRILLE <i>crushed</i>	\$ 2,022.00 ✓	1,617.60
6	RADIATOR GRILLE SUPPORT - LHS/RHS <i>new new</i>	\$ 100.00 ✓	
7	RADIATOR GRILLE BACK COVER <i>new new</i>	\$ 165.00 ✓	
8	FOAM PIECE <i>Rehd</i>	\$ 107.00 ✓	85.20
9	REINFORCEMENT BEAM <i>Bent</i>	\$ 702.00 ✓	561.60
10	FRONT BUMPER SUPPORT - LHS/RHS <i>Damaged</i>	\$ 48.00 ✓	38.24
11	LOCK CARRIER BRACKET <i>crushed</i>	\$ 118.00 ✓	94.00
12	FRONT BUMPER TOP COVER <i>Rehd</i>	\$ 109.00 ✓	87.20
13	RELEASE LEVER <i>new new</i>	\$ 12.00 ✓	
14	CAUTION SIGN <i>new</i>	\$ 12.00 ✓	9.28
15	AC STICKER <i>new</i>	\$ 7.00 ✓	4.58
16	AIR GRILLE - LHS/RHS <i>new</i>	\$ 828.00 ✓	
17	LED HEADLIGHT - LHS/RHS <i>new crushed</i>	\$ 14,038.00 ✓	5615.20
18	BONNET <i>Dented</i>	\$ 2,499.00 ✓	1,999.20
19	BONNET SEAL - LHS/RSH/CENTRE <i>new</i>	\$ 72.00 ✓	56.64
20	FRONT NUMBER PLATE <i>Bent</i>	S/N \$ 25.00 ✓	
21	SUNDRIES <i>new</i>	\$ 300.00 ✓	17.76
TOTAL SPARE PARTS		:	\$ 23,714.00
TOTAL LABOUR CHARGES		:	\$ 5,672.00
GRAND TOTAL		:	\$ 29,386.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 03/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Apr

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 8841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0497/2018/KS 23-May-18 KEE SIANG 1 SGY 2345 C Audi A5 SB 2.0 TFSI
--	---	--

Quantity	Description	Unit Price	Amount
Parts			
1	HEXAGON HEAD BOLT <i>new</i>	\$ 47.00	\$ 37.44 ✓
2	FRONT FENDER LHS <i>Rep</i>	\$ 920.00	\$ ✓
3	FRONT FENDER BRACKET <i>3 new</i>	\$ 31.00	\$ ✓
4	FRONT FENDER CLOSING ELEMENT	\$ 65.00	\$ ✓
5	FRONT FENDER STONE CHIP GUARD <i>new</i>	\$ 44.00	\$ 34.56 ✓
6	FRONT FENDER CHROME TRIM <i>new</i>	\$ 138.00	\$ 110.40 ✓
7	HEADLAMP LIFT CYLINDER- LH <i>changed</i>	\$ 174.00	\$ 139.20 ✓
8	FRONT BUMPER AIR GUIDE - LH (QTY:2) <i>2 yd</i>	\$ 40.00	\$ 31.12 ✓
9	CHARGE AIR COOLER <i>Painted</i>	\$ 514.00	\$ 411.20 ✓
10	CHARGE AIR COOLER SEAL <i>new</i>	\$ 79.00	\$ 62.96 ✓
TOTAL PARTS		\$ 2,052.00	\$ 826.88
LABORS			
1	To renew lhs front fender <i>(Repair)</i>	\$ 900.00	\$ 250.00 ✓
2	To respray lhs front fender	\$ 800.00	\$ 550.00 ✓
			\$ 800.00
Total parts/labour		\$ 3,752.00	\$ 1,626.88

Premium Automobiles Pte Ltd

LKS Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0497/2018/JT
Date : 26-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Hi Adrian

You recommended 5 days

We took 8 days exclude 1 Sunday
and 1 Public Holiday - Added jobs
jb 4 Jul 18

Owner's Name : Ms Juliana Poh
Address : Blk 7 Lorong 42 Geylang
#05-03
Singapore 398028
Telephone : HP +65 8499 0543
Type of Claim : Own Damage Claim
Policy No. : 1700095007
Vehicle No : **SGY 2345 C**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Jan-18
Engine No : CVK 050891
Chassis No : WAUZZZF50HJA050037
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Apr-18
Place of Accident : Whampoa Flyover

23242
2750320

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGY 2345 C.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper assy, both headlights, and bonnet. Re-organize front crash management components. Reinstall all parts removed.	\$	2,400.00	\$ 1,000.00
3	To remove and reinstall RHS front door panel trims, dismantle RHS wing mirror assy.	S/N \$	300.00	nil
4	To respray front bumper, bonnet and RHS front door.	\$	2,300.00	\$ 1,200.00
4a	Added labour charges - see attached	\$	1,700.00	\$ 800.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,372.00</u>	<u>\$ 3,672.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SCY 2345 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,970.00	\$ 1,576.00
2	FRONT BUMPER FIXING PARTS	\$ 349.00	
3	SECURING STRIP	\$ 60.00	
4	AIR GRILLE - CENRE	\$ 171.00	\$ 136.80
5	RADIATOR GRILLE	\$ 2,022.00	\$ 1,617.60
6	RADIATOR GRILLE SUPPORT - LHS/RHS	\$ 100.00	
7	RADIATOR GRILLE BACK COVER	\$ 165.00	
8	FOAM PIECE	\$ 107.00	\$ 85.20
9	REINFORCEMENT BEAM	\$ 702.00	\$ 561.60
10	FRONT BUMPER SUPPORT - LHS/RHS	\$ 48.00	\$ 38.24
11	LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
12	FRONT BUMPER TOP COVER	\$ 109.00	\$ 87.20
13	RELEASE LEVER	\$ 12.00	
14	CAUTION SIGN	\$ 12.00	\$ 9.28
15	AC STICKER	\$ 7.00	\$ 4.88
16	AIR GRILLE - LHS/RHS	\$ 828.00	
17	LED HEADLIGHT - LHS/RHS	\$ 14,038.00	\$ 5,615.20
18	BONNET	\$ 2,499.00	\$ 1,999.20
19	BONNET SEAL - LHS/RSH/CENTRE	\$ 72.00	\$ 56.64
20	FRONT NUMBER PLATE	S/N \$ 25.00	\$ 25.00
21	<i>Added parts - see attached</i>	\$ 2,052.00	\$ 826.88
22	SUNDRIES	\$ 300.00	\$ 17.76
TOTAL SPARE PARTS		\$ 25,766.00	\$ 12,751.48
TOTAL LABOUR CHARGES		\$ 7,372.00	\$ 3,672.00
GRAND TOTAL		\$ 33,138.00	\$ 16,423.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGY 2345 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0497/2018/MAS

14 Aug 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SGY 2345 C, Audi A5 SB 2.0 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no **SGY 2345 C**, claimant, **Ms. Juliana Poh**, please find the related document per attached.

1. A copy of the Original invoice no. 85012813 – S\$16,717.12
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGY 2345 C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7622102B



Name

JULIANA POH

傅蓮娜

Race

CHINESE

Date of birth

22-07-1976

Sex

F

S7622102B

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7622102B

JULIANA POH
(JULIANA FU)

Birth Date 22 Jul 1976

Issue Date 30 Jun 2003



301640E

NRIC No: S7622102B



Date of issue
10-08-2006

APT BLK 7 LORONG 42 GEYLANG #05-03
SINGAPORE 398028

NRIC No: S7622102B

Date: 24/05/2010


No: 6506550

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

12 Jul 1997



Licence No: S7622102B

NP 428A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : JULIANA POH
 Period of Insurance : 10 Jan 2018 To 09 Jan 2019
 Engine No. : CVK050891
 Chassis No. : WAUZZZF50JA050037

Vehicle No. : SGY2345C
 Policy No. : 1700095007
 Endorsement No. :
 Issued Date : 30 Jan 2018

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
 Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

JULIANA POH - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125266

PREMIUM LEASING -YCL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


 AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

55CKSA



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6366 2223
Main Telefax: 6471 3733
Page 1 10:17

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6366 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408723
Telephone: 6388 1111
Fax: 6388 1111
GST Reg. No. 199902271W

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2223
6828 1233

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012813 Date : 06/08/2018 Order : SGV2345C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGV2345C (V 36314) Regn Date: 18/01/2018 Mileage: 6487 WIP No.: 63465
Model: RS SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF50JA050037 Engine: CVK 050891 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER ASSY, LHS HEADLIGHTS AND BONNET, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1200.00	1.00	1,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733
Page 2 10:17

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408699
Telephone: 6388 1233
Telefax: 6441 4125

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2323
6828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012813 Date : 06/08/2018 Order : SGY2345C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGY2345C (V 36314) Regn Date: 10/01/2018 Mileage: 6487 WIP No.: 63465

Model: R5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF50JA050037 Engine: CVK 050891 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REPAIR LHS FRONT FENDER	250.00	1.00	250.00
S	BODYWORK	M: TO RESPRAY LHS FRONT FENDER	550.00	1.00	550.00
X	ABW6823029	HOOD	1.00	2499.00	1,999.20
X	ABW6853823B 9B9	(AIR) (SK) STONEGUARD	1.00	43.20	34.56
X	ABW6853601A PUZ	(AIR) (SK) TRIM	1.00	138.00	118.40
X	ABW6955101A	(AIR) (SK) CYLINDER	1.00	174.00	139.20
X	ABW6121283AF	(AIR) (SK) AIR DUCT	1.00	25.70	20.56
X	ABW6121673B	(AIR) (SK) AIR DUCT	1.00	13.20	10.56
X	ABW0145117	(AIR) (SK) WASHER	1.00	78.70	62.96
X	ABW6853651R RN4	GRILLE	1.00	2022.00	1,617.60
X	ABW0145805	COOLER	1.00	514.00	411.20
X	ABW6941773E	(VOR) (GER) HEADLIGHT	1.00	7019.00	5,615.20
X	ABW6807081B	COVER	1.00	109.00	87.20
X	ABW6807550J	FOAM INSER	1.00	106.50	85.20
X	ABW0807113	BRACKET	1.00	702.00	561.60
X	ABW6807065D GRU	COVER	1.00	1978.00	1,576.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6366 2223
Main Telefax: 6471 3733
Page 3 10:17

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6366 2223
Telefax: 6475 1023

Ubi Service Centre
59 Ubi Road 1
Singapore 408609
Telephone: 6380 1121
Telefax: 6380 1121

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauts.com.sg
6366 2323
6628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012813 Date : 06/08/2018 Order : SGY2345C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGY2345C (V 36314) Regn Date: 10/01/2018 Mileage: 6487 WIP No.: 63465

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF50JA050037 Engine: CVK 050891 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
X	ABW0007334	SUPPORT Less 020%	1.00	23.90	19.12
X	ABW0007333	SUPPORT Less 020%	1.00	23.90	19.12
X	ABW6823125	PROTECTION Less 020%	1.00	23.60	18.88
X	ABW6823126	PROTECTION Less 020%	1.00	23.60	18.88
X	ABW6807683 989	GRILLE Less 020%	1.00	171.00	136.80
X	ABW0010515A	STICKER Less 020%	1.00	6.10	4.88
X	ABK0010520A	PLATE Less 020%	1.00	11.60	9.28
X	ABW6807771	BRACKET Less 020%	1.00	117.50	94.00
X	AN 0161057	POP-RIVET Less 020%	6.00	2.90	13.92
X	AN 91093901	RIVET Less 020%	4.00	0.70	2.24
X	AN 02300311	NUT Less 020%	4.00	0.50	1.60
X	AN 10036203	BOLT Less 020%	4.00	11.70	37.44
X	ABW6823124	PROTECTION Less 020%	1.00	23.60	18.88

Parts 12,726.48
Labour 0.00
Sublet 3,697.00
Menus 0.00
Lubricant 0.00

Sub-Total 15,623.48

7% GST 1,093.64

Grand Total 16,717.12



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGY 2345 C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0497/2018/KS
25TH May 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SB 2.0 TFSI
Vehicle Chassis No. : WAUZZZF50HJA050037
Vehicle Regn No. : **SGY 2345 C**
Vehicle Mileage : 6489 KM
Vehicle Owner : Ms. Juliana Poh
Certificate No : 1700095007
Policy Excess : S\$856.00 (inclusive GST)
Accident Date : 24th April 2018
Place : Whampoa Flyover
Repair Cost : \$ 16,717.12
WIP No. : 63465
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 30/5/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Apr 2018		03 May 2018 15:40 Edit Adj Rpt	\$16,423.48 Edit Estimates	\$16,423.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: JULIANA POH , ID: S7622102B, Tel: +6584990543, Email: POH.JULIANA@GMAIL.COM									
Vehicle Reg. No.: SGY2345C		Date of Loss: 24/04/2018 13:00 - :59 [3 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 9735177838SG		Policy/Cover Note No.: 1700095007 (Comprehensive)							
		Excess: S\$800.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/05/2018]									
Driver/Custodian: JULIANA POH (41 / Female), NRIC: S7622102B, Tel: +6584990543									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (20/07/2018): Alert - Adj Mandate Approved (\$16423.48) - SGY2345C - Claim Handler: Tr, Tinesh AIG_SG (04/05/2018): Alert - Adj Mandate Approved (\$9877.00) - SGY2345C - Claim Handler: Tr, Tinesh AIG_SG (04/05/2018): SGY2345C / OD / 24/04/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents









*SGY2345C (9735177838SG)
OD
Apr 24 2018 1:00PM
[JULIANA POH]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	04/05/18 13:23	Video - Accident													Load MP4					
															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	04/05/18 15:48	Adjuster Immediate Advice													Load HTM					
2	18/07/18 10:48	Adjuster Immediate Advice													Load HTM					
3	18/07/18 10:57	Adjuster Immediate Advice													Load HTM					
															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
2	04/05/18 13:21	Chassis Number													Load JPG	<input checked="" type="checkbox"/>				
3	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
4	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
5	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
6	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
7	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
8	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
9	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
10	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
11	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
12	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
13	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
14	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
15	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
16	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
17	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
18	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
19	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
20	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
21	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
22	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
23	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
24	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
25	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
26	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
27	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
28	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
29	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				
30	04/05/18 13:21	General View													Load JPG	<input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
32	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
33	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
34	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
35	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
36	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
37	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
38	04/05/18 13:21	General View	Load JPG	<input checked="" type="checkbox"/>
39	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	16/07/18 19:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/05/18 13:19	DRIVING & IC DOC	Load PDF	
2	04/05/18 13:19	ESTIMATE - MARKED	Load PDF	
3	08/05/18 09:10	SGY 2345 C -GIA (AMEND)	Load PDF	
4	18/07/18 10:42	ESTIMATE MARKED	Load PDF	
5	18/07/18 10:42	SUPPLEMENTARY	Load PDF	
6	24/08/18 10:41	WORKSHOP INVOICE	Load PDF	
7	24/08/18 10:41	DISCHARGE VOUCHER	Load PDF	

Linked Accident Report Documents

			View View in Browser		
Video			1 per page:		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/05/18 20:41	Video - Accident		Load MP4	
Assessment Reports			1 per page:		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	24/04/18 20:25	Accident Statement		Load HTM	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
2	04/05/18 20:48	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	04/05/18 20:48	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	24/04/18 20:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	24/04/18 20:12	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	24/04/18 20:12	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18008105/ASBQ2

Date: 24/08/2018

REFERENCE

Insured/Claimant: JULIANA POH Policy No: 1700095007
Date of Loss: 24/04/2018 Nature of Claim: OD Claim No: 9735177838SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY2345C**
Make & Model: AUDI A5, 2.0 SPORTBACK (A) Engine No: CVK050891
Reg. Date: 10/01/2018 (Man. Year: 2017) Chassis No: WAUZZZF50JA050037
Colour: Black Odometer: 5676 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$180,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,556.88	12,751.48	12,805.40	50.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,372.00	3,672.00	3,700.00	50.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,928.88	16,423.48	16,505.40	50.12
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	32,128.88	15,623.48	16,505.40	51.37
+ GST 7.00/7.00% (S\$)	2,249.02	1,093.64	1,155.38	51.37
Nett Amount (S\$)	34,377.90	16,717.12	17,660.78	51.37

INSPECTION

Date of Assignment: 03/05/2018
Date Inspected: 03/05/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,970.00 FS	*1,576.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	349.00 FS	*- FS
3	1		*SECURING STRIP	Not Necessary	60.00 FS	*- FS
4	1		*AIR GRILLE -CENRE	Cracked	171.00 FS	*136.80 FS
5	1		*RADIATOR GRILLE	Cracked	2,022.00 FS	*1,617.60 FS
6	2		*RADIATOR GRILLE SUPPORT -LHS/RHS	Not Necessary	100.00 FS	*- FS
7	1		*RADIATOR GRILLE BACK COVER	Not Necessary	165.00 FS	*- FS
8	1		*FOAM PIECE	Deformed	107.00 FS	*85.20 FS
9	1		*REINFORCEMENT BEAM	Bent	702.00 FS	*561.60 FS
10	2		*FRONT BUMPER SUPPORT-LHS/RHS	Damaged	48.00 FS	*38.24 FS
11	1		*LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
12	1		*FRONT BUMPER TOP COVER	Deformed	109.00 FS	*87.20 FS
13	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
14	1		*CAUTION SIGN	Necessary	12.00 FS	*9.28 FS
15	1		*AC STICKER	Necessary	7.00 FS	*4.88 FS
16	2		*AIR GRILLE -LHS/RHS	Not Necessary	828.00 FS	*- FS
17	1		*LED HEADLIGHT-LHS/RHS	N/S Cracked	14,038.00 FS	*5,615.20 FS
18	1		*BONNET	Dented	2,499.00 FS	*1,999.20 FS
19	2		*BONNET SEAL -LHS/RHS/CENTRE	Necessary	72.00 FS	*56.64 FS
20	1		*FRONT BUMPER PLATE	Bent	25.00 FS	*25.00 FS
21	1		*SUNDRIES	Necessary	300.00 FS	*17.76 FS
22	1		*HEXAGON HEAD BOLT	Necessary	37.44 FS	*37.44 FS
23	1		*FRONT FENDER LHS	Repair	920.00 FS	*- FS
24	1		*FRONT FENDER BRACKET	Not Necessary	31.00 FS	*- FS
25	1		*FRONT FENDER CLOSING ELEMENT	Not Necessary	65.00 FS	*- FS
26	1		*FRONT FENDER STONE CHIP GUARD	Necessary	34.56 FS	*34.56 FS
27	1		*FRONT FENDER CHROME TRIM	Necessary	110.40 FS	*110.40 FS
28	1		*HEADLAMP LIFT CYLINDER -LH	Damaged	139.20 FS	*139.20 FS
29	2		*FRONT BUMPER AIR GUIDE-LH	Damaged	31.12 FS	*31.12 FS
30	1		*GUARD AIR COOLER	Dented	411.20 FS	*411.20 FS
31	1		*GUARD AIR COOLER SEAL	Necessary	62.96 FS	*62.96 FS
Total Parts (\$\$)					25,556.88	12,751.48

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW LHS FRONT FENDER	New	900.00	250.00
2	TO RESPRAY LHS FRONT FENDER	New	800.00	550.00
3	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ASSY ,BOTH HEADLIGHTS AND BONNET .RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIMS,DISMANTLE RHS WING MIRROR ASSY	New	300.00	0.00
6	TO RESPRAY FRONT BUMPER ,BONNET AND RHS FRONT DOOR	New	2,300.00	1,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,372.00	3,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >