

ASS. REC. BY:

REF:

CS/CTI18008109 / Ustbbs

Special Instruction:

Surveyor

meimer

## ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI.

Date/Time:

03/05/2018 224pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 2393J

Insured:

at Workshop m/s

Car City Auto

Tel:

6781 0300

of

Blk 9006 Tampines St 93 #01-198

Policy No:

DMP(SN30)24851800

Claim No:

SM18D0214501

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

25042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

08052018 347pm

Person Contacted:

Mr. Ho

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLX 2393J - X

08/05/18

we follow instruction by Eddie from CTI via tele - conversation  
 @ 10:34 a.m., submit ~~but~~ IN inside meimer first due to Autoday  
 Can't do adjustment.

08/05/18

@ 11:18am revised to Irene Tay Hui Ping via meimer.

08/05/18

@ 12:24 p.m mandate approved by Alfred Toh via meimer.

REF: C11

minimum

## ASSIGNMENT

From: Date: 03052018

Estimated Cost:

① OB / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLX 2393J

at Workshop m/s

Car City Auto

of

Blk 9006 Tampines St 93 #01-198

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

\$ 500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

40k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

13.1

%

3 Val.: Yes or No

CA / REP. / 24 HRS

Date:

Person Contacted:

Dep 11

Vehicle: IN / OUT

Veh No: SLX2393J Yr Regn: 2 10

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA,

Make:

Toyota Lexus 15250 cc 2500

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

152158

T/Radio: Insured / Std / NI / NA

Eng/No:

JTHBK262505116982

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 245/45R17

BS / DUN / EXNOVA FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/4/18

D.O.I.

3/5/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08/05/18 @ 15:29pm Workshop asky p/p because NO second p/p  
 15/05/18 @ 11:57pm Reused to Mr. Ho authorized repair via email.  
 15/05/18 @ 11:57pm tele - Conversation with Eddie about p/p instruction given by Eddie, if finalization figure more than \$2,477.55, please seek mandate again.

(\$ 473.56 Red - 16%)

RECEIVED 01 AUG 2018

Date/Time: File Pass to?

01/08/18



: Preli. Report

1)

Typist



: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

220

Transportation:

) S + R = \$

) Photos

) Collect

TOTAL

Report Format:

Lump Sum / I.B.I: \$ 2,425.19 p/p

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Workshop (\$

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified                    | Est Submitted                       | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 28 Apr 2018<br>Sendback Est | 28 Apr 2018<br>16:07<br>S\$2,898.75 | 03 May 2018<br>14:29<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

|                   |   |                        |   |
|-------------------|---|------------------------|---|
| Insured:          | ZHANG MINGKUI, ID: S8168021C, Tel: +6581610916, Email: KULE_ZHANG@HOTMAIL.COM                                       |                        |   |
| Vehicle Reg. No.: | SLX2393J  | Date of Loss:          | 25/04/2018 18:00 - :59<br>[98 Months and 20 Days From LTA<br>Reg Date (Man Yr)] |
| Claim Type:       | OD / SNM18D02145C01   | Policy/Cover Note No.: | DMPCSN3024851800<br>(Comprehensive)   |
|                   |   | Excess:                | S\$500.00   |
| Repairer:         | Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300            |                        |   |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] |                        |   |
| Adjuster:         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/05/2018]                                   |                        |   |
| Driver/Custodian: | ZHANG MINGKUI (36 / Male), NRIC: S8168021C, Tel: +6581610916  |                        |   |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT  |                        |   |

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



## ALL ASSOCIATED TASKS

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

View All

Search Tasks

Create New Task

Complete

## Shirley Hiew (LKK Auto)

---

**From:** CAR CITY AUTO CENTRE PTE LTD <ccacpl@singnet.com.sg>  
**Sent:** Monday, 30 July 2018 2:10 PM  
**To:** ShirleyHiew@lkkauto.com  
**Subject:** Re: RE: SLX 2393J-DOA: 25/04/2018 (CTI OD)

Dear Miss Shirley,

Ok \$2425.19

Ho

-----Original Message-----

From : ShirleyHiew@lkkauto.com  
Date : 30/07/2018 - 13:18 GMT+8  
To : ccacpl@singnet.com.sg  
Subject : RE: RE: SLX 2393J-DOA: 25/04/2018 (CTI OD)

Dear Mr.Ho,

Enclosed herewith autodax report as your requested.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** CAR CITY AUTO CENTRE PTE LTD [mailto:ccacpl@singnet.com.sg]  
**Sent:** Monday, 30 July 2018 11:42 AM  
**To:** ShirleyHiew@lkkauto.com  
**Subject:** Re: RE: SLX 2393J-DOA: 25/04/2018 (CTI OD)

Dear Miss Shirley,

Please forward us a copy of the Audatex report.

Regards,

Ho Too Boon

CAR CITY AUTO CENTRE PTE LTD  
TEL: 67810300 FAX: 67820300  
EMAIL: [ccacpl@singnet.com.sg](mailto:ccacpl@singnet.com.sg)

-----Original Message-----

From : [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)  
Date : 27/07/2018 - 11:49 GMT+8  
To : [ccacpl@singnet.com.sg](mailto:ccacpl@singnet.com.sg)  
Cc : [sur@lkkauto.com](mailto:sur@lkkauto.com)  
Subject : RE: SLX 2393J-DOA: 25/04/2018 (CTI OD)

Dear Mr.Ho,

Please confirm final fig \$2,425.19 @ 4 days of repairs before excess \$500/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Tuesday, 8 May 2018 3:29 PM

**To:** [ccacpl@singnet.com.sg](mailto:ccacpl@singnet.com.sg)

**Cc:** 'SUR' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** SLX 2393J-DOA: 25/04/2018 (CTI OD)

Dear Mr.Ho,

As instructed by our client, please proceed to repair the insured vehicle **SLX 2393J (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 8 May 2018 3:29 PM  
**To:** 'ccacpl@singnet.com.sg'  
**Cc:** 'SUR'  
**Subject:** SLX 2393J-DOA: 25/04/2018 (CTI OD)

Dear Mr.Ho,

As instructed by our client, please proceed to repair the insured vehicle **SLX 2393J (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**SLX2393J (SNM18D02145C01)**

OD

Apr 25 2018 6:00PM

[ZHANG MINGKUI]

Car City Auto Centre Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 08/05/2018 12:24 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (\$2477.55) - SLX2393J - Claim Handler: Irene Tay Hui Ping

Approved:2477.55:PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$2,477.55 BEFORE EXCESS OF \$500.00.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 08 May 2018

**Preliminary Advice**

|                    |   |                         |                    |
|--------------------|---|-------------------------|--------------------|
| Vehicle No         | : SLX2393J  | Accident Date           | : 25/04/2018       |
| Make               | : TOYOTA LEXUS  | Policy No.              | : DMPCSN3024851800 |
| Assignment Date    | : 03/05/2018  | Excess                  | : S\$500.00        |
| Date of Inspection | : 03/05/2018  | Est. Duration of Repair | : 4 days           |
| Inspection At      | : Car City Auto Centre Pte Ltd (HQ)<br>Blk 9006 #01-198, Tampines Street 93<br>Singapore 528840 |                         |                    |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 2,898.75 |
| Revised Amount              | :S\$ | 2,017.55 |
| Check Items (Estimated)     | :S\$ | 460.00   |
| Total                       | :S\$ | 2,477.55 |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 40,000.00 |
| COE / PARF Rebate  | :S\$ | 25,010.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 14,990.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT   |   |
|--|---|
| Date Of Report   | 26/04/2018 15:35                              |
| Date Of Accident   | 25/04/2018 18:20                              |
| Exact Location Of Accident   | ALONG PASIR RIS DRIVE 12                      |
| Country/State of Loss  | SINGAPORE                                     |
| DETAILS OF OWN VEHICLE   |   |
| Vehicle Registration Number  | SLX2393J                                      |
| Insured/Policyholder   |   |
| Name Of Registered Owner   | ZHANG MINGKUI                                 |
| NRIC No  | S8168021C                                     |
| Email Address  | KULE_ZHANG@HOTMAIL.COM                        |
| Mobile Phone No  | (LOCAL) +65-81610916                          |
| Alternative Phone No   | OFFICE-81610916                               |
| Vehicle Particulars  |   |
| Manufacturer   | TOYOTA  |
| Model  | LEXUS-2.5 IS250 (A)                           |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                                   |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES   |
| If No, Please state action to be taken                                       |   |
| Vehicle Category   | PRIVATE CAR                                   |
| Insurance Company  |   |
| Name of Insurance Company  | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage   | COMPREHENSIVE                                 |
| Fleet Policy   | NO  |
| Policy Number  | DMPCSN3024851800                              |
| Cover Note Number  |   |
| Driver   |   |
| Name of Driver   | ZHANG MINGKUI                                 |
| NRIC No  | S8168021C                                     |
| Date Of Birth  | 13/11/1981                                    |
| Occupation   | INDOOR  |
| Date Of Driving Pass   | 15/11/2012                                    |
| Driving Experience   | 5 YEARS AND 5 MONTHS                          |
| Gender   | MALE  |
| Mobile Number  | (LOCAL) +65-81610916                          |
| Fax Number   |   |
| Contact Number   | OFFICE-81610916                               |
| EEmail Address   | KULE_ZHANG@HOTMAIL.COM                        |

|   |                       |
|---|-----------------------|
| Address   | 1, FLORA DRIVE #04-03 |
| Postcode  | 507009                |
| Was driver an employee of the Insured's Company     | NO                    |
| If No, Relationship of the Driver with the Insured  | OWNER                 |
| Vehicle Registration Number of Driver's Own Vehicle | -                     |
|   | -                     |
|   | -                     |
| Insurance Company of Driver's Own Vehicle           | -                     |
|   | -                     |
|   | -                     |

#### General Information of the Accident

|                    |                            |
|--------------------|----------------------------|
| Type Of Accident   | COLLISION - MAJOR/MINOR RD |
| Weather Conditions | CLEAR                      |
| Road Surface       | DRY                        |

#### Other Information

|   |   |
|---|---|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   |   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  |   |
| Was any other material or property damaged?   | YES                                       |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 4   |
| Passenger 1   | NAME: : DING LILI<br>GENDER: : FEMALE     |
| Passenger 2   | NAME: : CHENG JIAHONG<br>GENDER: : FEMALE |
| Passenger 3   | NAME: : LI CHEN HUI<br>GENDER: : FEMALE   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

AS PER SKETCH PLAN ATTACHED.

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |             |
|-----------------------------|-------------|
| Vehicle Registration Number | SDV8989G    |
| Vehicle Make/Model/Colour   |             |
| Details Of Properties       |             |
| Vehicle Category            | PRIVATE CAR |
| Name of Driver              |             |
| NRIC/Passport Number        |             |
| Contact Number              | 96792337    |

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


26.04.2018  
3.20 pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: Sany  
NRIC/FIN No.: 51842

# SKETCH PLAN



A: SLX23937  
B: SDV8989G

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

24. APR, 18:20, SLX23937 出路口没有注意  
到左后方 SDV8989G 车, 致 SDV8989G 的右车  
身撞到 SLX23937 左前车头。附近正在修路。

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

\* *[Signature]*

Policyholder's Signature

Date & Time: 26.04.2018  
3.20pm

GIAMC SketchPlan Form\_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Saly

NRIC/FIN No.: 51842

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                         |
|-------------------------------------|-------------------------|
| <b>Vehicle Owner Particulars</b>    |                         |
| Owner ID Type:                      | Singapore NRIC          |
| Owner ID:                           | 8021C                   |
| <b>Vehicle Details</b>              |                         |
| Vehicle No.:                        | SLX2393J                |
| Vehicle to be Exported:             | No                      |
| Intended De-registration Date:      | 03 May 2018             |
| Vehicle Make:                       | TOYOTA                  |
| Vehicle Model:                      | LEXUS IS250 AUTO STD FL |
| Primary Colour:                     | White                   |
| Manufacturing Year:                 | 2010                    |
| Engine No.:                         | 4GR0627784              |
| Chassis No.:                        | JTHBK262505116982       |
| Maximum Power Output:               | 153.0 kW (205 bhp)      |
| Open Market Value:                  | \$38,495.00             |
| Original Registration Date:         | 05 Feb 2010             |
| First Registration Date:            | 05 Feb 2010             |
| Transfer Count:                     | 1                       |
| Actual ARF Paid:                    | \$38,495.00             |
| <b>Intended PARF Rebate Details</b> |                         |
| PARF Eligibility:                   | Yes                     |
| PARF Eligibility Expiry Date:       | 04 Feb 2020             |
| PARF Rebate Amount:                 | \$21,172.00             |
| <b>Intended COE Rebate Details</b>  |                         |
| COE Expiry Date:                    | 04 Feb 2020             |
| COE Category:                       | E - Open Category       |
| COE Period(Years):                  | 10                      |
| QP Paid:                            | \$21,899.00             |
| COE Rebate Amount:                  | \$3,838.00              |
| <b>Total Rebate Amount:</b>         | <b>\$25,010.00</b>      |

The information contained herein is correct as at 03 May 2018

OK

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 8021C

**Vehicle Details**

Vehicle No.: SLX2393J  
Vehicle to be Exported: Yes  
Intended De-registration Date: 30 Apr 2018  
Vehicle Make: TOYOTA  
Vehicle Model: LEXUS IS250 AUTO STD FL  
Primary Colour: White  
Manufacturing Year: 2010  
Engine No.: 4GR0627784  
Chassis No.: JTHBK262505116982  
Maximum Power Output: 153.0 kW (205 bhp)  
Open Market Value: \$38,495.00  
Original Registration Date: 05 Feb 2010  
First Registration Date: 05 Feb 2010  
Transfer Count: 1  
Actual ARF Paid: \$38,495.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 04 Feb 2020  
PARF Rebate Amount: \$21,172.00

**Intended COE Rebate Details**

COE Expiry Date: 04 Feb 2020  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$21,899.00  
COE Rebate Amount: \$3,857.00  
Total Rebate Amount: \$25,029.00

The information contained herein is correct as at 26 Apr 2018

OK


**Inchcape**  
 inchcapepreowned.com.sg

**VIEW CERTIFIED CARS**

**TOYOTA Preferred**  
Certified Pre-Owned



### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2009 Honda Insight Hybrid At \$17800 Only! Call Us!







Very Low Mileage Done!  
 Immaculate Condition! Definitely  
 Cheapest In The Market!  
 AutoPrestige Gallery StarAd


[Browse by Category](#)
[Sort by](#)

6 vehicles

Lexus IS250

[Advanced](#)

|   | Make                       | Model | Price           | Depreciation        | Reg Date           | Eng Cap         | Mile      |
|---|----------------------------|-------|-----------------|---------------------|--------------------|-----------------|-----------|
| <b>Search Selection</b>   | <b>Lexus IS250</b>         |       | Any             | Any                 | <b>2010</b>        | Any             |           |
|    | <b>Lexus IS250</b>         |       | <b>\$45,800</b> | <b>\$14,730 /yr</b> | <b>22-Feb-2010</b> | <b>2,500 cc</b> | <b>13</b> |
| Full Maintained By Lexus, Car In Excellent Shape. Test Drive To Be Impressed. Low Mileage With Service Records Availal<br>Arrangement Available. Act Now. |                            |       |                 |                     |                    |                 |           |
| Posted: 02-May-2018 Tags: 2010 Lexus IS250, Lexus IS250, Lexus, IS250, Used Lexus   |                            |       |                 |                     |                    |                 |           |
|    | <b>Lexus IS250</b>         |       | <b>\$47,800</b> | <b>\$14,350 /yr</b> | <b>30-Apr-2010</b> | <b>2,500 cc</b> | <b>98</b> |
| 2 Owners Only. Car In Excellent Shape. Test Drive To Be Impressed. Low Mileage With Service Records Available. Flexibl<br>House Loan Available. Act Now.  |                            |       |                 |                     |                    |                 |           |
| Posted: 28-Apr-2018 Tags: 2010 Lexus IS250, Lexus IS250, Lexus, IS250, Used Lexus   |                            |       |                 |                     |                    |                 |           |
|    | <b>Lexus IS250C Luxury</b> |       | <b>\$72,999</b> | <b>\$16,740 /yr</b> | <b>29-Oct-2010</b> | <b>2,500 cc</b> | <b>40</b> |
| Luxury Version With Built In GPS, Reverse Camera, Park Assist, LED Daytime Running Light, Rear Aircon And Higher PAR                                      |                            |       |                 |                     |                    |                 |           |
| Posted: 23-Apr-2018 Tags: 2010 Lexus IS250C, Lexus IS250C, Lexus, IS250C, Used Lexus  |                            |       |                 |                     |                    |                 |           |
|    | <b>Lexus IS250</b>         |       | <b>\$47,000</b> | <b>\$14,660 /yr</b> | <b>26-Mar-2010</b> | <b>2,500 cc</b> | <b>11</b> |
| Graded <b>B</b> by <b>STAR</b>  |                            |       |                 |                     |                    |                 |           |
| New Road Tax! Original Beautiful Paintwork And Interior! Maintained By A Fussy Owner! Accident Free! Loan And Trade<br>View Before Sold!                  |                            |       |                 |                     |                    |                 |           |
| Posted: 14-Apr-2018 Tags: 2010 Lexus IS250, Lexus IS250, Lexus, IS250, Used Lexus   |                            |       |                 |                     |                    |                 |           |

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

is **IS250C**

**\$63,800**

**\$17,940 /yr**

**02-Jun-2010**

**2,500 cc**



Send

**CAR CITY AUTO CENTRE  
PTE LTD  
BLK 9006 TAMPINES  
STREE 93  
#01-198  
SINGAPORE 528840**

**Claim Reference: CCA00371  
Assessment Number: CCA00371  
Version: CAR CITY/1  
Date Calculated: 28/04/2018 03:33**

**Full Report - V1  
Registration: SLX2393J  
Printed: 28/04/2018 10:33**

### Summary Information

|                       |                                |                            |            |
|-----------------------|--------------------------------|----------------------------|------------|
| <b>Claim</b>          |                                |                            |            |
| Location:             | Singapore (SG)                 | Currency:                  | SGD        |
| Printed by:           | HO TOO BOON                    | Date of Incident:          | 25/04/2018 |
| Authorisation Status: | Interim                        | Able to Authorise Repairs: | TBA        |
| Work Provider:        | China Taiping Insurance (S) Pt | Repairs Authorised:        | TBA        |
| Claim Reference:      | CCA00371                       | Estimated Repair Time:     |            |
| Policy Number:        | DMPCSN3024851800               | Quote Due Date:            |            |
| Other Reference:      |                                | Actual Repair Days:        |            |
| Third Party:          |                                | Parts Ordered Date:        |            |
| Insured Amount:       |                                | Hire Car Start:            |            |
| Under Warranty:       |                                | Hire Car End:              |            |
| Warranty Expired:     |                                | Vehicle Collected:         |            |

Not Allowed  
2/4/18  
Loss \$500  
3/5/18  
Try 4/5.  
4dy.

### Vehicle Details

| Vehicle             | Model Specs       |                      |
|---------------------|-------------------|----------------------|
| Manufacturer:       | LEXUS             | FROM 03.2010         |
| Model:              | IS 250 C          | I-KEY                |
| Sub Model:          | 250C              | MULTIMEDIA SYSTEM    |
| Model Sheet Number: | 2483 18           | HEADLAMP WASHERS     |
| Registration:       | SLX2393J          | SEATS WITH MEMORY    |
| Registration Month: | February          | AUX-AUDIO CONNECTION |
| Registration Year:  | 2010              | REARVIEW CAMERA      |
| VIN Number:         | JTHBK262505116982 | AUTO GEARBOX 6 SPEED |
| Manufacture Year:   | 2010              | PRE-CRASH SYSTEM     |
| Odometer:           | 151959            | WHEELS 8J X 17 ALLOY |
| Colour:             | White             | PAINTING OFF VEHICLE |
| Engine Number:      | 4GR0627784        |                      |
| Fuel Level:         | %                 |                      |

TRIM PREMIUM  
FOLDING MIRROR MEMO  
XENON HEADLAMPS  
RAIN SENSOR  
2COMP GLASS ADHESIVE  
FRT/RR PARK DIST CON  
2.5 LTR 153 KW  
ST/WHEEL SWITCH CONT  
225/45-245/45 WR 17  
TYRE PRESSURE CHECK  
TWO COAT PEARL/MICA

### Vehicle Condition

| Vehicle Status            |              |                               |             |
|---------------------------|--------------|-------------------------------|-------------|
| Pre-Accident Condition:   | Excellent    | Severity of Impact:           | Heavy Panel |
| Steering:                 | Satisfactory | Vehicle Status on Inspection: | Roadworthy  |
| Brakes Pedal Travel:      | Satisfactory | Date of Inspection:           | 26/04/2018  |
| Place of Inspection:      |              |                               |             |
| Pre-Accident Damage:      |              |                               |             |
| Tyres Condition:          | Excellent    |                               |             |
| Tyres - Tread Depth (MM): |              |                               |             |

|     | Axes | Left Tyre Depth | Right Tyre Depth |     |
|-----|------|-----------------|------------------|-----|
| LHF | 0    | 9.0             | 9.0              | RHF |

# CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00371

Assessment Number: CCA00371

Version: CAR CITY/1


Date Calculated: 28/04/2018 03:33

Full Report - V1


Registration: SLX2393J

Printed: 28/04/2018 10:33

LHR 1 9.0 9.0  
Damage Areas:



RHR  
Direction of Impact:



## Addresses

## Cost Summary

|                           |            |
|---------------------------|------------|
| Total Labour              | \$751.80   |
| Total Paint/Material      | \$168.95   |
| Total Parts               | \$1,936.00 |
| Total of Additional Costs | \$42.00    |
| Repair Cost Exc GST:      | \$2,898.75 |
| Overall Discount (0.0%):  | - \$0.00   |
| Excess:                   | -\$500.00  |
| After Deduction -         |            |
| Grand Total Exc GST:      | \$2,398.75 |
| 7 % GST:                  | \$167.91   |
| Grand Total Inc GST:      | \$2,566.66 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR  
Price/Dent = \$42.00/HR

### Repair /

### Guide Number Repair Details

|           |                                    | WU    | Cost Price (\$) |
|-----------|------------------------------------|-------|-----------------|
| NO NUMBER | ADJUST HEADLAMPS                   | 3.0   | 12.60 /         |
| B010)     | R + R FRONT BUMPER                 | 5.0   | 21.00 /         |
| B010)     | R + R FRONT BUMPER REINFORCEMENT   | 2.0   | 8.40 /          |
| B020)     | RENEW FRONT BUMPER (REMOVED)       | 6.0   | 25.20 /         |
| B030      | R + R FRONT GRILLE                 | 4.0   | 16.80 /         |
| NO NUMBER | RENEW L/F BUMPER BRACKET           | 1.0   | 4.20 /          |
| NO NUMBER | RENEW R/F BUMPER BRACKET           | 1.0   | 4.20 /          |
| B040)     | R + R LEFT HEADLAMP                | 1.0   | 4.20 /          |
| B040)     | RENEW L/HEADLAMP (REMOVED)         | 3.0   | 12.60 /         |
| 531041)   | R + R LEFT FRONT WHEEL ARCH COVER  | 3.0   | 12.60 /         |
| 531041A)  | R + R RIGHT FRONT WHEEL ARCH COVER | 3.0   | 12.60 /         |
| 420018)   | R + R L/F FRONT WHEEL              | 1.0   | 4.20 x          |
| 420018)   | R + R R/F FRONT WHEEL              | 1.0   | 4.20 x          |
| NO NUMBER | R + R LOWER RADIATOR SHROUD        | 1.0   | 4.20 x          |
| 0741      | REPAIR L/F WING                    | 8.0*  | 33.60 /         |
| 0839      | REPAIR L/W-HOUSE SUPPORT           | 7.0*  | 29.40 /         |
| 1009      | REPAIR INNER FRT PANEL CPL         | 13.0* | 54.60 x         |
| 7201      | REPAIR L/F WHEEL                   | 35.0* | 147.00 x        |
| 0420      | CHECK GRILLE MOULDING              |       |                 |

### LABOUR COST

|                                      |        |      |
|--------------------------------------|--------|------|
| Total Work Units                     | 98.0   |      |
| Corrosion Protection External Labour | 0.0HRS | 0.00 |

# CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00371

Assessment Number: CCA00371

Version: CAR CITY/1

Date Calculated: 28/04/2018 03:33

Full Report - V1

Registration: SLX2393J

Printed: 28/04/2018 10:33

|                                      |         |                 |
|--------------------------------------|---------|-----------------|
| Corrosion Protection Internal Labour | 0.0HRS  | 0.00            |
| Sub Total                            | 9.8HRS  | \$411.60 197.40 |
| Paint Labour                         | 8.1HRS  | \$340.20        |
| Total Labour                         | 17.9HRS | \$751.80 537.60 |

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number Description WU Cost Price (\$)

|      |                                     |      |  |
|------|-------------------------------------|------|--|
|      | - PAINTING OFF VEHICLE              |      |  |
|      | - TWO COAT PEARL/MICA               |      |  |
| 283  | FRONT BUMPER NEW PART PAINT K1R     | 11.0 |  |
| 299  | L/F BUMPER COVER NEW PART PAINT K1R | 3.0  |  |
| 741  | L/F WING REPAIR PAINTING >50%       | 17.0 |  |
| 7201 | L/F WHEEL REPAIR PAINTING >50%      | 12.0 |  |
| 471  | BONNET SURFACE PAINT                | 11.0 |  |
| 742  | R/F WING SURFACE PAINT              | 6.0  |  |
| 1009 | INNER FRT PANEL CPL SURFACE PAINT   | 7.0  |  |

## LABOUR COST - PAINT

### TIME(PAINT)

|                                    |        |
|------------------------------------|--------|
| Preparation Main Work Metal        | 9.0    |
| Preparation Comp. Work Plastic     | 5.0    |
| Preparation Work Multi Layer Paint | 0.0    |
| Total Work Units (10WU/HR)         | 81.0   |
| Total Paintwork Labour             | 8.1HRS |

\$340.20  
Cost Price

## MATERIAL COST - PAINT

|                                    |                 |
|------------------------------------|-----------------|
| New Part Painting - Plastic K1R    | \$51.66         |
| Surface-/Blend Paint               | \$66.48 50.05   |
| Repair Painting                    | \$23.71 17.78   |
| Material-Const Main Work Metal     | \$18.10         |
| Material-Const Comp. Work Plastic  | \$9.00          |
| Total Excluding Pearlescent Uplift | \$168.95 146.59 |
| Pearlescent Uplift @ 0.0%          | \$0.00          |
| Total Paint Material Cost          | \$168.95        |

## PARTS

| Guide No.    | Qty | Description          | Part Number       | Supplier     | Bet. | Price (\$) |
|--------------|-----|----------------------|-------------------|--------------|------|------------|
| 253          | 1   | L/F BUMPER GRILLE    | 52438 53030       |              | 0%   | 32.00*     |
| 283          | 1   | FRONT BUMPER         | 52119 53960       |              | 0%   | 280.00*    |
| 317          | 1   | L/F OUT BUMPER BRKT  | 52536 53011       |              | 0%   | 42.00*     |
| 318          | 1   | R/F OUT BUMPER BRKT  | 52535 53011       |              | 0%   | 42.00*     |
| 321          | 1   | L/INN BUMPER BRACKET | 52116 53060       |              | 0%   | 60.00*     |
| 322          | 1   | R/INN BUMPER BRACKET | 52115 53060       |              | 0%   | 60.00*     |
| 340          | 1   | FRT BUMPER REINF     | 52131 53040       |              | 0%   | 185.00*    |
| 344          | 1   | FRT IMPACT ABSORBER  | 52611 53110       |              | 0%   | 60.00*     |
| 412          | 1   | LWR RADIATOR GRILLE  | 53112 53130       |              | 0%   | 105.00*    |
| 423          | 1   | RADIATOR GRILL SEAL  | 53119 53010       |              | 0%   | 32.00*     |
| 561          | 1   | LEFT HEADLAMP ASSY   | 81070 53450       |              | 0%   | 430.00*    |
| 637          | 1   | L/F FOG LAMP         | 81220 0W031       |              | 0%   | 160.00*    |
| 841          | 1   | L/F WHEELHOUSE COVER | 53806 53050       | inner shield | 0%   | 165.00*    |
| 1016         | 1   | LOWER AIR GUIDE      | 53289 53070       |              | 0%   | 115.00*    |
| 1169         | 1   | L/RADIATOR AIR GUIDE | 53154 53010       |              | 0%   | 68.00*     |
| f: OEM Parts |     |                      | Sub Total         |              |      | \$1,836.00 |
| g: Original  |     |                      | Mark Up From Cost | (0 %)        |      | \$0.00     |

# CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00371  
 Assessment Number: CCA00371  
 Version: CAR CITY/1  
 Date Calculated: 28/04/2018 03:33

Full Report - V1  
 Registration: SLX2393J  
 Printed: 28/04/2018 10:33

|               |                    |         |                   |
|---------------|--------------------|---------|-------------------|
| h: Secondhand | Sundry Parts       | (Fixed) | \$100.00          |
| p: Parallel   | <b>Total Parts</b> |         | <b>\$1,936.00</b> |
| x: Exchange   |                    |         |                   |

## NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

### Extras

| Description  | SPECIALIST | Betterment          | Price          |
|--------------|------------|---------------------|----------------|
| AUDATEX FEES |            | 0%                  | \$42.00        |
|              |            | <b>Total Extras</b> | <b>\$42.00</b> |

### Final Calculation

|   |           |                   |
|---|-----------|-------------------|
| <b>Total Parts</b>                                |           | <b>\$1,936.00</b> |
| <b>Labour</b>                                     |           |                   |
| Total Panel/Mechanical                            | \$411.60  |                   |
| Total Paintwork                                   | \$340.20  |                   |
| <b>Total Labour</b>                               |           | <b>\$751.80</b>   |
| <b>Additional Costs</b>                           |           |                   |
| Corr Prot Materials External                      | \$0.00    |                   |
| Corr Prot Materials Internal                      | \$0.00    |                   |
| Cost of Specialist                                | \$42.00   |                   |
| <b>Total of Additional Costs</b>                  |           | <b>\$42.00</b>    |
| <b>Total Paint/Material Costs</b>                 |           | <b>\$168.95</b>   |
| <b>Repair Costs Excludes GST</b>                  |           | <b>\$2,898.75</b> |
| <b>Deductions</b>                                 |           |                   |
| Deduction for Excess ( Fixed )                    | -\$500.00 |                   |
| <b>Total Deductions</b>                           |           | <b>-\$500.00</b>  |
| <b>Grand Total Excludes GST (After Deduction)</b> |           | <b>\$2,398.75</b> |
| GST @ 7 %   |           | <b>\$167.91</b>   |
| <b>Grand Total Includes GST (After Deduction)</b> |           | <b>\$2,566.66</b> |

3328.75

### Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 10 Jul 2018)**Parts:** 143 TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Car City Auto Centre Pte Ltd/SLX2393J/10/07/2018 17:50**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No.                      | Qty | Part No. | Particulars                           | %Disc | %Depr | Amount        |
|--------------------------|-----|----------|---------------------------------------|-------|-------|---------------|
| 1                        | 1   |          | *right headlamp assy <i>bulburene</i> | 0.00  | 0.00  | *430.00 F     |
| <b>Total Parts (S\$)</b> |     |          |                                       |       |       | <b>430.00</b> |

F=Franchise part.

**Car City Auto Centre Pte Ltd/SLX2393J/10/07/2018 17:50.** Not valid without Reference section.Generated using **Merimen e-Claims IEAS**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: CCA00371  
Assessment Number: CCA00371  
Version: LKKAUTOC/6  
Date Calculated: 24/07/2018 07:18

Full Report - V1  
Registration: SLX2393J  
Printed: 24/07/2018 14:31

## Summary Information

### Claim

|                       |                                |                            |            |
|-----------------------|--------------------------------|----------------------------|------------|
| Location:             | Singapore (SG)                 | Currency:                  | SGD        |
| Printed by:           | LKK AUTO                       | Date of Incident:          | 25/04/2018 |
| Authorisation Status: | Interim                        | Able to Authorise Repairs: | TBA        |
| Work Provider:        | China Taiping Insurance (S) Pt | Repairs Authorised:        | TBA        |
| Claim Reference:      | CCA00371                       | Estimated Repair Time:     |            |
| Policy Number:        | DMPCSN3024851800               | Quote Due Date:            |            |
| Other Reference:      |                                | Actual Repair Days:        |            |
| Third Party:          |                                | Parts Ordered Date:        |            |
| Insured Amount:       |                                | Hire Car Start:            |            |
| Under Warranty:       |                                | Hire Car End:              |            |
| Warranty Expired:     |                                | Vehicle Collected:         |            |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | LEXUS             |
| Model:              | IS 250 C          |
| Sub Model:          | 250C              |
| Model Sheet Number: | 2483 18           |
| Registration:       | SLX2393J          |
| Registration Month: | February          |
| Registration Year:  | 2010              |
| VIN Number:         | JTHBK262505116982 |
| Manufacture Year:   | 2010              |
| Odometer:           | 151959            |
| Colour:             | White             |
| Engine Number:      | 4GR0627784        |
| Fuel Level:         | %                 |

#### Model Specs



|                      |                      |
|----------------------|----------------------|
| FROM 03.2010         | TRIM PREMIUM         |
| I-KEY                | FOLDING MIRROR MEMO  |
| MULTIMEDIA SYSTEM    | XENON HEADLAMPS      |
| HEADLAMP WASHERS     | RAIN SENSOR          |
| SEATS WITH MEMORY    | 2COMP GLASS ADHESIVE |
| AUX-AUDIO CONNECTION | FRT/RR PARK DIST CON |
| REARVIEW CAMERA      | 2.5 LTR 153 KW       |
| AUTO GEARBOX 6 SPEED | ST/WHEEL SWITCH CONT |
| PRE-CRASH SYSTEM     | 225/45-245/45 WR 17  |
| TYRE PRESSURE CHECK  | PAINTING OFF VEHICLE |
| TWO COAT PEARL/MICA  |                      |

### Vehicle Condition

#### Vehicle Status

|                           |              |                               |             |
|---------------------------|--------------|-------------------------------|-------------|
| Pre-Accident Condition:   | Excellent    | Severity of Impact:           | Heavy Panel |
| Steering:                 | Satisfactory | Vehicle Status on Inspection: | Roadworthy  |
| Brakes Pedal Travel:      | Satisfactory | Date of Inspection:           | 26/04/2018  |
| Place of Inspection:      |              |                               |             |
| Pre-Accident Damage:      |              |                               |             |
| Tyres Condition:          | Excellent    |                               |             |
| Tyres - Tread Depth (MM): |              |                               |             |

|               |       | Left Tyre | Right Tyre |                      |
|---------------|-------|-----------|------------|----------------------|
|               | Axles | Depth     | Depth      |                      |
| LHF           | 0     | 9.0       | 9.0        | RHF                  |
| LHR           | 1     | 9.0       | 9.0        | RHR                  |
| Damage Areas: |       |           |            | Direction of Impact: |



## Addresses

## Cost Summary

|                           |            |
|---------------------------|------------|
| Total Labour              | \$537.60   |
| Total Paint/Material      | \$146.59   |
| Total Parts               | \$1,699.00 |
| Total of Additional Costs | \$42.00    |
| Repair Cost Exc GST:      | \$2,425.19 |
| Overall Discount (0.0%):  | - \$0.00   |
| Excess:                   | -\$500.00  |
| After Deduction -         |            |
| Grand Total Exc GST:      | \$1,925.19 |
| 7 % GST:                  | \$134.76   |
| Grand Total Inc GST:      | \$2,059.95 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR  
Price/Dent = \$42.00/HR

### Repair /

### Guide Number Repair Details

|           |                                   | WU   | Cost Price (\$) |
|-----------|-----------------------------------|------|-----------------|
| NO NUMBER | ADJUST HEADLAMPS                  | 3.0  | 12.60           |
| B010)     | R + R FRONT BUMPER                | 5.0  | 21.00           |
| B020)     | RENEW FRONT BUMPER (REMOVED)      | 6.0  | 25.20           |
| B030      | R + R FRONT GRILLE                | 4.0  | 16.80           |
| NO NUMBER | RENEW L/F BUMPER BRACKET          | 1.0  | 4.20            |
| B040)     | R + R LEFT HEADLAMP               | 1.0  | 4.20            |
| B040)     | RENEW L/HEADLAMP (REMOVED)        | 3.0  | 12.60           |
| 1000      | REMOVE&REFIT R+R R/FT WHEEL CR    | 3.0* | 12.60           |
| 1000      | REMOVE&REFIT R+R LEFT FT WHEEL CR | 3.0* | 12.60           |
| 1000      | REMOVE&REFIT R+R F/BUMPER REINFOR | 2.0* | 8.40            |
| 1000      | RENEW R/F BUMPER BRACKET          | 1.0* | 4.20            |
| 0741      | REPAIR L/F WING                   | 8.0* | 33.60           |
| 0839      | REPAIR L/W-HOUSE SUPPORT          | 7.0* | 29.40           |
| 0420      | CHECK GRILLE MOULDING             |      |                 |

### LABOUR COST

|                                      |         |          |
|--------------------------------------|---------|----------|
| Total Work Units                     | 47.0    |          |
| Corrosion Protection External Labour | 0.0HRS  | 0.00     |
| Corrosion Protection Internal Labour | 0.0HRS  | 0.00     |
| Sub Total                            | 4.7HRS  | \$197.40 |
| Paint Labour                         | 8.1HRS  | \$340.20 |
| Total Labour                         | 12.8HRS | \$537.60 |

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

### Guide Number Description

|                        | WU | Cost Price (\$) |
|------------------------|----|-----------------|
| - PAINTING OFF VEHICLE |    |                 |

|                              |   |               |                   |
|------------------------------|---|---------------|-------------------|
|                              | - TWO COAT PEARL/MICA                     |               |                   |
| 283                          | FRONT BUMPER NEW PART PAINT K1R           | 11.0          |                   |
| 299                          | L/F BUMPER COVER NEW PART PAINT K1R       | 3.0           |                   |
| 741                          | L/F WING REPAIR PAINTING >50%             | 17.0          |                   |
| 471                          | BONNET SURFACE PAINT                      | 11.0          |                   |
| 742                          | R/F WING SURFACE PAINT                    | 6.0           |                   |
| 1009                         | CPL SURFACE PAINT INNER FRT PANEL         | 7.0*          |                   |
| 7201                         | L/F WHEEL REPAIR PAINTING>50%             | 12.0*         |                   |
| <b>LABOUR COST - PAINT</b>   |   |               |                   |
|                              | <b>TIME(PAINT)</b>                        | <b>67.0</b>   |                   |
|                              | Preparation Main Work Metal               | 9.0           |                   |
|                              | Preparation Comp. Work Plastic            | 5.0           |                   |
|                              | Preparation Work Multi Layer Paint        | 0.0           |                   |
|                              | <b>Total Work Units (10WU/HR)</b>         | <b>81.0</b>   |                   |
|                              | <b>Total Paintwork Labour</b>             | <b>8.1HRS</b> | <b>\$340.20</b>   |
| <b>MATERIAL COST - PAINT</b> |   |               | <b>Cost Price</b> |
|                              | New Part Painting - Plastic K1R           |               | \$51.66           |
|                              | Surface-/Blend Paint                      |               | \$50.05           |
|                              | Repair Painting                           |               | \$17.78           |
|                              | Material-Const Main Work Metal            |               | \$18.10           |
|                              | Material-Const Comp. Work Plastic         |               | \$9.00            |
|                              | <b>Total Excluding Pearlescent Uplift</b> |               | <b>\$146.59</b>   |
|                              | Pearlescent Uplift @ 0.0%                 |               | \$0.00            |
|                              | <b>Total Paint Material Cost</b>          |               | <b>\$146.59</b>   |

**PARTS**

|               |     |                      |             | Price Valid: 01/06/2015 |                   |
|---------------|-----|----------------------|-------------|-------------------------|-------------------|
| Guide No.     | Qty | Description          | Part Number | Supplier                | Bet. Price (\$)   |
| 283           | 1   | FRONT BUMPER         | 52119 53960 |                         | 0% 280.00*        |
| 637           | 1   | L/F FOG LAMP         | 81220 0W031 |                         | 0% 160.00*        |
| 317           | 1   | L/F OUT BUMPER BRKT  | 52536 53011 |                         | 0% 42.00*         |
| 841           | 1   | L/F WHEELHOUSE COVER | Renew       |                         | 0% 165.00*        |
| 321           | 1   | L/INN BUMPER BRACKET | Renew       |                         | 0% 60.00*         |
| 561           | 1   | LEFT HEADLAMP ASSY   | 81070 53450 |                         | 0% 430.00*        |
| 423           | 1   | RADIATOR GRILL SEAL  | 53119 53010 |                         | 0% 32.00*         |
| 562           | 1   | RIGHT HEADLAMP ASSY  | Renew       |                         | 0% 430.00*        |
| f: OEM Parts  |     | Sub Total            |             |                         | \$1,599.00        |
| g: Original   |     | Mark Up From Cost    |             | (0 %)                   | \$0.00            |
| h: Secondhand |     | Sundry Parts         |             | (Fixed)                 | \$100.00          |
| p: Parallel   |     | <b>Total Parts</b>   |             |                         | <b>\$1,699.00</b> |
| x: Exchange   |     |                      |             |                         |                   |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

| Description         | Betterment | Price          |
|---------------------|------------|----------------|
| AUDATEX FEES        | 0%         | \$42.00        |
| SPECIALIST          |            |                |
| <b>Total Extras</b> |            | <b>\$42.00</b> |

**Final Calculation**

|                         |                   |
|-------------------------|-------------------|
| <b>Total Parts</b>      | <b>\$1,699.00</b> |
| <b>Labour</b>           |                   |
| Total Panel/Mechanical  | \$197.40          |
| Total Paintwork         | \$340.20          |
| <b>Total Labour</b>     | <b>\$537.60</b>   |
| <b>Additional Costs</b> |                   |



Claim Reference: CCA00371

Full Report - V1

Assessment Number: CCA00371

Registration: SLX2393J

Version: LKKAUTOC/6

Printed: 24/07/2018 14:31

Date Calculated: 24/07/2018 07:18

---

|   |           |                   |
|---|-----------|-------------------|
| Corr Prot Materials External                      | \$0.00    |                   |
| Corr Prot Materials Internal                      | \$0.00    |                   |
| Cost of Specialist                                | \$42.00   |                   |
| <b>Total of Additional Costs</b>                  |           | <b>\$42.00</b>    |
| <b>Total Paint/Material Costs</b>                 |           | <b>\$146.59</b>   |
| <b>Repair Costs Excludes GST</b>                  |           | <b>\$2,425.19</b> |
| <b>Deductions</b>                                 |           |                   |
| Deduction for Excess ( Fixed )                    | -\$500.00 |                   |
| <b>Total Deductions</b>                           |           | <b>-\$500.00</b>  |
| <b>Grand Total Excludes GST (After Deduction)</b> |           | <b>\$1,925.19</b> |
| GST @ 7 %   |           | <b>\$134.76</b>   |
| <b>Grand Total Includes GST (After Deduction)</b> |           | <b>\$2,059.95</b> |

---

**Assessment Notes**

---



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CAR CITY AUTO CENTRE PTE LTD

BLK 9006 TAMPINES ST 93

#01-198

SINGAPORE 528840

TEL: 67810300 FAX: 67820300

ATTN: NG 96445447, ADULLA, NICK

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9615

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea),  
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-07427

DATE : 15/05/2018

CUSTOMER ID : CAR018

VEH REG. NO. : SLX2393J

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

| SO STOCKID        | DESCRIPTION               | StkLoc | QTY | U/PRICE | AMOUNT |
|-------------------|---------------------------|--------|-----|---------|--------|
| 1. T52119-53949   | FRT BUMPER 283            | WH     | 1   | 280.00  | 280.00 |
| IS250/NEW         |                           | W      |     |         |        |
| 2. T52536-22070   | FRT BUMPER BRACKET/LH 317 | WH     | 1   | 42.00   | 42.00  |
| MARK X            |                           | W      |     |         |        |
| 3. T52115-53020   | FRT BUMPER SUPPORT/RH 322 | WH     | 1   | 60.00   | 60.00  |
| IS250/GSE20       |                           | W      |     |         |        |
| 4. T53119-53020/1 | RAD GRILLE TOP BUSH 423   | WH     | 1   | 32.00   | 32.00  |
| IS250             |                           | W      |     |         |        |
| 5. T81170-53250   | HEAD LAMP LH 561          | WH     | 1   | 430.00  | 430.00 |
| IS250-GSE20       |                           | W      |     |         |        |
| 6. T81130-53250   | HEAD LAMP RH 562          | WH     | 1   | 430.00  | 430.00 |
| IS250-GSE20       |                           | W      |     |         |        |
| 7. T81221-53280/1 | FOG LAMP LH 637           | WH     | 1   | 160.00  | 160.00 |
| IS250-GSE20       |                           | W      |     |         |        |
| 8. T53806-53020   | FRT FENDER LINER LH 841   | WH     | 1   | 165.00  | 165.00 |
| IS250-GSE20       |                           | W      |     |         |        |

SUB-TOTAL : 1,599.00  
ADD GST 7.00 % 111.93

E. & O.E

TOTAL AMOUNT S\$ : 1,710.93

[P] 15/05/2018 10:57:05AM

[E] 15/05/2018 10:54:11AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



\*AR201805-07427\*

Goods Received in Good Order

*[Signature]*

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case    | Notified                                    | Est Submitted                              | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'd | Status  |
|---------|---|--|--|--|--|------------|---|
| Main    | 28 Apr 2018<br><a href="#">Sendback Est</a> | 28 Apr 2018<br>16:07<br><b>S\$2,898.75</b> | 03 May 2018<br>14:29<br><a href="#">Edit Adj Rpt</a> | <b>S\$2,425.19</b><br><a href="#">Edit Estimates</a> | <b>S\$2,425.19</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |
| Supp #1 | 10 Jul 2018<br>17:49                        | 10 Jul 2018<br>17:50<br><b>S\$430.00</b>   | 10 Jul 2018<br>17:50                                 |  |  | (Combined) | <b>Combined with Main</b><br><a href="#">Uncombine Suppl.</a>   |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

|                   |   |                        |  |
|-------------------|---|------------------------|--|
| Insured:          | ZHANG MINGKUI, ID: S8168021C, Tel: +6581610916, Email: KULE_ZHANG@HOTMAIL.COM                                       |                        |  |
| Vehicle Reg. No.: | SLX2393J  | Date of Loss:          | 25/04/2018 18:00 - :59<br>[98 Months and 20 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | OD / SNM18D02145C01   | Policy/Cover Note No.: | DMPCSN3024851800 (Comprehensive)   |
|                   |   | Excess:                | S\$500.00  |
| Repairer:         | Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300            |                        |  |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] |                        |  |
| Adjuster:         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/05/2018]      |                        |  |
| Driver/Custodian: | ZHANG MINGKUI (36 / Male), NRIC: S8168021C, Tel: +6581610916  |                        |  |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT  |                        |  |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA\_TAIPING (08/05/2018): Alert - Adj Mandate Approved (S\$2477.55) - SLX2393J - Claim Handler: Irene Tay H...

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

SLX2393J (SNM18D02145C01)

OD

Apr 25 2018 6:00PM

[ZHANG MINGKUI]

Car City Auto Centre Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
**View** [View in Browser](#) ▼

### Assessment Reports

 1 per page ▼ ☒

| No | Finalized On   | Car City Auto Centre Pte Ltd (HQ)   |   | Thumbnail | Print |
|----|----------------|-------------------------------------|---|-----------|-------|
| 1  | 28/04/18 16:07 | <b>Repairer Estimates</b>           | 1 | Load HTM  |       |
| 2  | 10/07/18 17:50 | <b>Repairer Estimates Suppl. #1</b> | 1 | Load HTM  |       |
| No | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)   |   | Thumbnail | Print |
| 1  | 08/05/18 11:18 | <b>Adjuster Immediate Advice</b>    | 1 | Load HTM  |       |

### Photos/Images

 3 per page ▼ ☒

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |   | Thumbnail | Print                               |
|----|-----------------|-----------------------------------|---|-----------|-------------------------------------|
| 1  | 04/05/18 07:45  | <b>Chassis Number</b>             | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 2  | 04/05/18 07:46  | <b>Odometer Reading</b>           | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 3  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 4  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 5  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 6  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 7  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 8  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 9  | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 10 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 11 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 12 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 13 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 14 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 15 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 16 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 17 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 18 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 19 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 20 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 21 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 22 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 23 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 24 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 25 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 26 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 27 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 28 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 29 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 30 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |
| 31 | 04/05/18 07:47  | <b>General View</b>               | 1 | Load JPG  | <input checked="" type="checkbox"/> |

| Assessment Reports |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No                 | Finalized On    | Car City Auto Centre Pte Ltd (HQ) | Thumbnail  | Print                               |
| 32                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 33                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 04/05/18 07:47  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 57                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 58                 | 11/07/18 08:24  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation      |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 30/07/18 16:47  | AUTODAX                           | Load PDF   |                                     |
| 2                  | 30/07/18 16:47  | ESTIMATE MARKED                   | Load PDF   |                                     |
| 3                  | 20/08/18 15:45  | SUPPLEMENTARY                     | Load PDF   |                                     |
| 4                  | 20/08/18 15:45  | PARTS INVOICE                     | Load PDF   |                                     |

## Linked Accident Report Documents

| Assessment Reports |                |                                   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|------------|-------------------------------------|
| No                 | Finalized On   | Car City Auto Centre Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 26/04/18 17:46 | Accident Statement                | Load HTM   |                                     |
| Photos/Images      |                |                                   | 3 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Car City Auto Centre Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 26/04/18 16:00 | SCENE PHOTO                       | Load JPG   | <input checked="" type="checkbox"/> |
| 2                  | 26/04/18 16:00 | SCENE PHOTO                       | Load JPG   | <input checked="" type="checkbox"/> |
| 3                  | 26/04/18 16:00 | SCENE PHOTO                       | Load JPG   | <input checked="" type="checkbox"/> |
| 4                  | 26/04/18 16:00 | SCENE PHOTO                       | Load JPG   | <input checked="" type="checkbox"/> |
| 5                  | 26/04/18 16:00 | SCENE PHOTO                       | Load JPG   | <input checked="" type="checkbox"/> |
| 6                  | 26/04/18 16:00 | INSURED VEH                       | Load JPG   | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                   | 1 per page ▼   | ✓     |
|--------------------|----------------|-----------------------------------|--|-------|
| No                 | Finalized On   | Car City Auto Centre Pte Ltd (HQ) | Thumbnail  | Print |
| 7                  | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 8                  | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 9                  | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 10                 | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 11                 | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 12                 | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 13                 | 26/04/18 16:00 | CHASSIS BO                        |  Load JPG | ✓     |
| 14                 | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| 15                 | 26/04/18 16:00 | INSURED VEH                       |  Load JPG | ✓     |
| Documentation      |                |                                   | 1 per page ▼   | ✓     |
| No                 | Finalized On   | Car City Auto Centre Pte Ltd (HQ) | Thumbnail  | Print |
| 1                  | 26/04/18 15:54 | Sketch Plan                       |  Load TIF |       |
| 2                  | 26/04/18 15:54 | Sketch Plan #2                    |  Load TIF |       |
| 3                  | 26/04/18 15:56 | INSUED IC & DL                    |  Load TIF |       |
| 4                  | 26/04/18 15:56 | INSURED CI                        |  Load TIF |       |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CT118008109/USBS2

Date: 20/08/2018

## REFERENCE

Insured/Claimant: ZHANG MINGKUI Policy No: DMPCSN3024851800  
Date of Loss: 25/04/2018 Nature of Claim: OD Claim No: SNM18D02145C01

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLX2393J  
Make & Model: TOYOTA LEXUS, 2.5 IS250 (A) Engine No: 4GR0627784  
Reg. Date: 05/02/2010 (Man. Year: 2010) Chassis No: JTHBK262505116982  
Colour: White Odometer: 152156 km  
Engine Capacity: 2500 cc  
Market Value/New Car Price: S\$40,000.00  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/45R17 Rear Tyre Size: 245/45R17  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's      | Adjuster's      | Difference    | Diff %       |
|-------------------------------------|-----------------|-----------------|---------------|--------------|
| Parts                               | 2,266.00        | 1,599.00        | 667.00        | 29.44        |
| Miscellaneous Items                 | 142.00          | 142.00          | 0.00          | 0.00         |
| Labour                              | 920.75          | 684.19          | 236.56        | 25.69        |
| Paintwork Labour                    | 0.00            | 0.00            | 0.00          |              |
| Towing                              | 0.00            | 0.00            | 0.00          |              |
| <b>Calculated Gross Total (S\$)</b> | <b>3,328.75</b> | <b>2,425.19</b> | <b>903.56</b> | <b>27.14</b> |
| <b>- Excess (S\$)</b>               | <b>500.00</b>   | <b>500.00</b>   | <b>0.00</b>   | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>2,828.75</b> | <b>1,925.19</b> | <b>903.56</b> | <b>31.94</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>198.01</b>   | <b>134.76</b>   | <b>63.25</b>  | <b>31.94</b> |
| <b>Nett Amount (S\$)</b>            | <b>3,026.76</b> | <b>2,059.95</b> | <b>966.81</b> | <b>31.94</b> |

## INSPECTION

Date of Assignment: 03/05/2018 Present Location: Car City Auto Centre Pte Ltd (HQ)  
Car City Auto Centre Pte Ltd (HQ)  
Date Inspected: 03/05/2018 Inspected At: Blk 9006 #01-198, Tampines Street 93  
Singapore 528840  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 20 Aug 2018)

**Parts:** 143      TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLX2393J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

| No.                      | Qty | Part No. | Particulars                           | Condition      | Repairer's      | Amount          |
|--------------------------|-----|----------|---------------------------------------|----------------|-----------------|-----------------|
| 1                        | 1   | NA       | *FRONT BUMPER                         | Distorted      | 280.00 F        | *280.00 F       |
| 2                        | 1   | NA       | *FRT BUMPER REINF                     | Repair         | 185.00 F        | *- F            |
| 3                        | 1   | NA       | *FRT IMPACT ABSORBER                  | Not Necessary  | 60.00 F         | *- F            |
| 4                        | 1   | NA       | *L/F BUMPER GRILLE                    | Not Necessary  | 32.00 F         | *- F            |
| 5                        | 1   | NA       | *L/F FOG LAMP                         | Cracked        | 160.00 F        | *160.00 F       |
| 6                        | 1   | NA       | *L/F OUT BUMPER BRKT                  | Bent           | 42.00 F         | *42.00 F        |
| 7                        | 1   | NA       | *L/F WHEELHOUSE COVER<br>INNER SHIELD | Torn           | 165.00 F        | *165.00 F       |
| 8                        | 1   | NA       | *L/INN BUMPER BRACKET                 | Cracked        | 60.00 F         | *60.00 F        |
| 9                        | 1   | NA       | *L/RADIATOR AIR GUIDE                 | Not Necessary  | 68.00 F         | *- F            |
| 10                       | 1   | NA       | *LEFT HEADLAMP ASSY                   | Cracked        | 430.00 F        | *430.00 F       |
| 11                       | 1   | NA       | *LOWER AIR GUIDE                      | Not Necessary  | 115.00 F        | *- F            |
| 12                       | 1   | NA       | *LWR RADIATOR GRILLE                  | Not Necessary  | 105.00 F        | *- F            |
| 13                       | 1   | NA       | *R/F OUT BUMPER BRKT                  | Not Necessary  | 42.00 F         | *- F            |
| 14                       | 1   | NA       | *R/INN BUMPER BRACKET                 | Not Necessary  | 60.00 F         | *- F            |
| 15                       | 1   | NA       | *RADIATOR GRILL SEAL                  | Necessary      | 32.00 F         | *32.00 F        |
| <b>Supplementary #1</b>  |     |          |                                       |                |                 |                 |
| 16                       | 1   |          | *right headlamp assy                  | Holder Cracked | 430.00 F        | *430.00 F       |
| <b>Total Parts (S\$)</b> |     |          |                                       |                | <b>2,266.00</b> | <b>1,599.00</b> |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No                         | Qty | Particulars  | Repairer's | Amount |
|----------------------------|-----|--------------|------------|--------|
| <b>Miscellaneous Items</b> |     |              |            |        |
| 1                          | 1   | AUDATEX FEES | 42.00      | 42.00  |
| 2                          | 1   | SUNDRY PARTS | 100.00     | 100.00 |
| Sub Total (S\$)            |     |              | 142.00     | 142.00 |

Recommended Labour

| No                      | Particulars                   | Lab.Type | Repairer's | Amount |
|-------------------------|-------------------------------|----------|------------|--------|
| <b>Labour Items</b>     |                               |          |            |        |
| 1                       | Total Paint Labour            | New      | 340.20     | 340.20 |
| 2                       | Total Paint Materials         | New      | 168.95     | 146.59 |
| 3                       | Total Panel/Mechanical Labour | New      | 411.60     | 197.40 |
| Gross Labour Cost (S\$) |                               |          | 920.75     | 684.19 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >