

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: PA8945B

MODEL : MERCEDES BENZ VITO

POLICY NO : GA228725/1

CHASSIS NO : WDF63970523422973

YEAR OF MANUFACTURE : 2009

DATE / TIME OF ACCIDENT: 30/04/2018 Time: 1604Hrs at IBIS BENCOOLEN HOTEL SINGAPORE.

THIRD PARTY VEHICLE NO: SH9234R

Date: 03/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N		Quantity	Unit Price S\$	Condition	Amount S\$
1	Bonnet X Repair	1			
2	Bonnet Hinge LH X	1			
3	Bonnet Hinge RH X	1			
4	Bonnet Insulator X	1			
5	Bonnet Insulator Clips X	1			
6	Bonnet Lock Assy ?	1			
7	Bonnet Weatherstrip Long ?	1			
8	Bonnet Weatherstrip Short ?	1			
9	Bonnet Emblem - MCL	1			
10	Front Bumper - 875 M's	1			
11	Front Bumper Side Retainer LH - 1/2 MCL	1			
12	Front Bumper Side Retainer RH	1			
13	Front Bumper Centre Bracket - CRA	1			
14	Front Bumper Upper Grille - BK	1			
15	Front Bumper Upper Grille Emblem - MCL	1			
16	Front Bumper Lower Lip ?	1			
17	Front Bumper Tow Cover ?	1			
18	Front Bumper Number Plate Garnish - M's	1			
19	Front Fender LH X	1			
20	Front Fender Shield LH - TV	1			
21	Front Fender RH X	1			
22	Front Fender Shield RH - TV	1			
23	Head Lamp LH ?	1			
24	Head Lamp Bracket LH ?	1			
25	Head Lamp Lining Chrome LH - CRA	1			
26	Head Lamp RH ?	1			
27	Head Lamp Bracket RH ?	1			
28	Head Lamp Lining Chrome RH ?	1			
29	Front Bumper Lock Catch X	1			
30	Front Support Panel ?	1			
31	Front Support Panel Top Garnish ?	1			
32	Front Bumper Reinforcement - BT	1			
33	Horn High Pitch X	1			
34	Horn Low Pitch X	1			

35	Oil Cooler Piping	?	1	
36	Aircon Condenser	?	1	
37	Aircon Condenser Fan Motor	X	1	
38	Aircon Condenser Blade Motor	X	1	
39	Aircon Condenser Cowling	?	1	
40	Radiator	?	1	
41	Radiator Fan Motor	X	1	
42	Radiator Blade Motor	X	1	
43	Radiator Cowling	?	1	
				Sub-Total: -
				Less: 10% discount -
				Total Parts after 10% discount: -

Special Nett Items

1	Anti-rust coating	3	80.00	X	240.00
2	Front number plate with casing	1	100.00	30	100.00
3	Radiator coolant	1	80.00	?	80.00
4	Front Bumper Clips	10			
5	Front Fender Shield Clips	20			
6	Front Support Panel Top Garnish Clips	10			
					420.00

Total Parts: 420.00

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	400	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	400	1,500.00
3	Provide skill labour to disconnect and check electrical wiring	30	60.00
4	Provide skill labour to remove and replace air-con condenser, pipes and radiator Vacuum air-con system and refill gas	?	150.00
5	Provide skill labour to mount vehicle onto chassis alignment bench	X	300.00
Total Labour:			3,510.00

Total Parts & Labour: 3,930.00
GST 7% 275.10
Grand Total: 4,205.10

Estimate Repair Duration 10 days

ACCIDENT VEHICLE OF : PA8945B

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

4 Days.
 Lump sum repair.
 After repair photos.
 Guo Qiang - 8288 0282
 03/5/18

Survey attended by: