

ASS. REC. BY:

REF:

CS/FCU8008121 / T14bnz

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person): QWS Serene Lee of FCI Date/Time: 03052018 9:29am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 3920Z Insured: SHA 4589Sat Workshop m/s Goldbell Tel: 8816 7798of Blk K Pandan Loop Estate #01-12Policy No: D1800 3343MFSH Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 26042018
(Client's Record)CA / REV / REP. / REV 24 HRS DS 04052018 @ H.O.D. Endorsement:Date/Time: 03052018 10:17am Person Contacted: Andy Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 3920Z - X
	SHA 4589S - NS/DNC) 6003247 / H14bnz DUA: 060216
	Finalized at lump sum \$1250 (Red. 2939.51 : 70%)

Inspector

Tan Jiah

REF: FCI

ASSIGNMENT

From: Date: 04052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 3920Z
at Workshop m/s: Goldbell
of: Blk K Pandan Loop #01-12

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Andy
12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKW3920Z Yr Regn: 2015 / 00

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai CC 1197

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 52332 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFEA31141484120

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/60R17
R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 4/5/18 @ 1230

Survey held at Goldbell Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 MAY 2018

Date/Time: File Pass to?

1) 215 Typist
Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ 1250)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

3 + RS \$

Photos

Others

TOTAL

135
50
50
24

259

MOTOR SURVEY ASSIGNMENT

Date	30-04-2018	Our Ref No. D18003343MFSH
Accident Date	26-04-2018	Claim Type. Third Party
Insured Vehicle	SHA4589S	Third Party Vehicle. SKW3920Z
Survey Location	10 TUAS AVENUE 18	
Contact Person.	ANDY OOI LEE KEONG	
Contact No.	64589596/ 64589596	Fax No. 64587172
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GOLDBELL ENGINEERING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Certificate of Insurance Pg. 1



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048823
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

4774 0842

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11M13903

Policy No. : D17MTPV01014216

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the PRIVATE CAR Policy wordings, ref. MTP.27

Insured : CHANG QI REN DARREN
Address : 21, TERRASSE LANE
#04-10
SINGAPORE 544774

Business/Profession : OTHERS

INSURED DETAILS

Date of Birth & Age : 12 OCT 1982 & 35 years old
Driving Experience in Singapore : 14 years
Identification Type : NRIC(Singaporean)
Identification No. : S82343531
Marital Status : MARRIED
Gender : Male
Period of Insurance : 28 OCTOBER 2017 00:00 TO 27 OCTOBER 2018 23:59
Persons or Classes of Persons entitled to drive : Refer to Certificate of Insurance
Limitations as to use : Refer to Certificate of Insurance

VEHICLE DETAILS

Vehicle Registration No. : SKW3620Z
Chassis No. : SJNFEAJ11U1484120
Engine No. : HRA2188780A
Vehicle Make & Model : NISSAN NISSAN
QASHQAI 1.2 DIG-T (A)
Cc : 1198
Type of Body : SUV
Year of Registration : 2015
Seating Capacity (including driver) : 5
Estimated value of Vehicle : Market value at time of loss
Hire Purchase Owner : NIL

PREMIUM DETAILS

Premium	1,479.00
Less No Claim Discount (50%)	(739.50)
Less Offence free Discount (5%)	(38.98)
Less EDG Discount (10%)	(70.25)
Total	S\$ 632.27
GST	S\$ 44.26
Premium (incl. GST)	S\$ 676.53

Coverage : Comprehensive - ExcelDrive GOLD
Excess : S 400 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess : N.A.
Additional Excess : Named Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500
Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000
Un-named All Other Drivers - \$500

The terms shall be defined as follows:
'Young Drivers' shall be defined as drivers (including the insured) who are below 25 years old.
'Inexperienced Drivers' shall be defined as drivers (including the insured) who have less than 2 years of driving experience in Singapore.
'Elderly Drivers' shall be defined as drivers (including the insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to insured's spouse provided he/she is 25 years old & above but less than 70 years old &/or has 2 or more years driving experience.

Endorsements Applicable : Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess
Endorsement E - Excess Clause
Endorsement H - Total Loss
Endorsement M - Inclusion Of Special Perils
Endorsement P6 - Riot And Strike Endorsement
Endorsement V - No Claim Discount Protection

Insured Copy

Certificate of insurance Pg. 2



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048523
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903195

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11M13903

Policy No. : D17MTPV01014218

Endorsement Y2 - ExcelDrive Gold Plan
Endorsement Z - Loss of Use Benefit

Additional Cover : NIL

Named Drivers : 1. Name : CHANG QI REN DARREN
Date of Birth & Age : 12 OCT 1982 & 35 years old
Driving Experience in Singapore : 14 years

Date of Issue : 29 SEPTEMBER 2017
Intermediary Name : MONEYSMART FINANCIAL PTE. LTD.
Producer Code & Name : MSF13910 & MONEYSMART FINANCE
PTE. LTD. (CO-BRAND)
User Code : CORPWEB/CORPWEB
Old Policy No. : NIL

Signed on this 29th day of September 2017
for and on behalf of SOMPO INSURANCE SINGAPORE PTE. LTD.

Authorised Signatory
Ci Code : 22A

24-HOUR EMERGENCY HOTLINE
Tel: (65) 6226 3323

Specialist from 24 Hours Mobile Accident Response Service (MARS) will:
- Take photographs of the vehicle involved.
- Assist the driver to complete the accident statement and arrange for e-filing to General Insurance Association of Singapore (GIA) within 24 hours.
- Arrange towing service if necessary to the nearest ExcelDrive Workshop.
* When overseas, inform the operator that you would like to place a collect call, or call on reverse charge basis.
Insured Copy

Nric & driving licence Pg. 1



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

10 Apr 2003

Licence No: S82343531

NP 428A





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date : 30/04/2018
To : MS FIRST CAPITAL INSURANCE LIMITED
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : ANDYOOILK
Office / Mobile : +65 6458 9596
Email / Fax No. : AndyOoiLK@goldbell.com.sg

Reg No : SKW3920Z
Model :
Chassis No : SJNFEAJ11U1484120
Engine No : HRA2188780A
D.O.P. :
Ref. No. : GBE/SVC/SALES
D.O.A. : 24/04/2018
Policy No. : D17MTPV01014216
Claim Type : TP CLAIM
Workshop : PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER	1	645.30	-10	580.77	645.30
2		REAR BUMPER REINFORCEMENT	1	619.20	-10	557.28	557.28
3		REAR BUMPER SPONGE	1	126.40	-10	113.76	113.76
4		REAR BUMPER BRACKET LH	1	126.00	-10	113.40	113.40
5		REAR BUMPER BRACKET RH	1	126.00	-10	113.40	113.40
6		REAR END PANEL = photo A	1	482.60	-10	434.34	434.34
7		TAILGATE QASHQAI EMBLEM	1	87.00	-10	78.30	78.30
8		TAILGATE LOGO	1	59.70	-10	53.73	53.73

PARTS TOTAL : 2,109.51

SPECIAL NETT ITEMS

1 REAR BUMPER REVERSE SENSOR

1 380.00

PARTS TOTAL: 380.00

LABOUR CHARGES

1 TO PUTTY , CLEAN , SPRAY PAINT & POLISH ,ETC

800 800.00

2 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS

900 900.00

LABOUR TOTAL : 1,700.00

SUB-TOTAL : 4,189.51

GST @ 7% for \$ 4,189.51 293.27

GRAND TOTAL (S\$) : 4,482.78

Taufik 97495749
- wp
4/5/18
Rising after repair
4 days
gna@bluants.com
taufik@bluants.com





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 198903963G

Page 2 / 2

ESTIMATE

Date	: 30/04/2018	Reg No	: SKW3920Z
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	:
Attn.	:	Chassis No	: SJNFEAJ11U1484120
Office / Mobile	:	Engine No	: HRA2188780A
Email Address	:	D.O.P.	:
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 24/04/2018
Attn.	: ANDYOOILK	Policy No.	: D17MTPV01014216
Office / Mobile	: +65 6458 9596	Claim Type	: TP CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No: 1980030630

Page 1 / 2

ESTIMATE

Date	: 30/04/2018	Reg No	: SKW3920Z
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	:
Attn.	:	Chassis No	: SJNFEA111U1484120
Office / Mobile	:	Engine No	: HRA2188780A
Email Address	:	D.O.P.	:
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 24/04/2018
Attn.	: ANDYOOILK	Policy No.	: D17MTPV01014216
Office / Mobile	: +65 6458 9596	Claim Type	: TP CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER	1	717.00	-10	645.30	645.30
2		REAR BUMPER REINFORCEMENT	1	619.20	-10	557.28	557.28
3		REAR BUMPER SPONGE	1	126.40	-10	113.76	113.76
4		REAR BUMPER BRACKET LH	1	126.00	-10	113.40	113.40
5		REAR BUMPER BRACKET RH	1	126.00	-10	113.40	113.40
6		REAR END PANEL = plus to 15	1	482.60	-10	434.34	434.34
7		TAILGATE QASHQAI EMBLEM	1	87.00	-10	78.30	78.30
8		TAILGATE LOGO	1	59.70	-10	53.73	53.73

PARTS TOTAL : 2,109.51

SPECIAL NETT ITEMS

1 REAR BUMPER REVERSE SENSOR

P-645.30-10%
= 580.77
200 at.
380.00

PARTS TOTAL: 380.00

LABOUR CHARGES

1 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC
2 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS

S/N - 200.00
L - 800.00
800 800.00
400 900.00

LABOUR TOTAL : 1,700.00

SUB-TOTAL : 4,189.51

GST @ 7% for \$ 4,189.51 293.27

GRAND TOTAL (\$\$) : 4,482.78

Tanjin 97745749
- wp
4/5/18

Passing after repair
4 days
sun @ 11am to 12am
tanjin @ 11am to 12am

TOTAL - 1580.77 - 20%

45 1250.00





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18008121/T1tbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4589S	Veh. Inspected	SKW 3920Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003343MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	03/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1484120	Colour	BLUE	
Odometer	52332	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	FALKEN	6 mm	
L/H Front Tyre	215/60 R17	FALKEN	6 mm	
R/H Rear Tyre	215/60 R17	FALKEN	6 mm	
L/H Rear Tyre	215/60 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2018	Inspection Date	04/05/2018	
Survey held at	BLK K PANDAN LOOP #01-12			
Repairer	GOLDBELL ENGINEERING PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3920Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	717.00	645.30
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	619.20	-
1	REAR BUMPER SPONGE	NOT NECESSARY	126.40	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	126.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	126.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	482.60	-
1	TAILGATE QASHQAI EMBLEM	NOT NECESSARY	87.00	-
1	TAILGATE LOGO	NOT NECESSARY	59.70	-
	LESS 10% DISCOUNT		-234.39	-64.53
			2,109.51	580.77
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	CUT	380.00	200.00
			380.00	200.00
	LABOUR			
	TO PUTTY,CLEAN,SPRAY PAINT & POLISH,ETC.		800.00	400.00
	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS,INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	400.00
			1,700.00	800.00
	GRAND TOTAL		4,189.51	1,580.77
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CS/FCI18008121/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.