

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8332D

DATE 2/5/2018 10:08

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid X			\$ 1,681.40	
	Boot Lid Lock Upper X			\$ 137.90	
	Boot Lid Lock Lower X			\$ 31.70	
	Boot Lid 'H' Emblem X			\$ 27.20	
	Boot Lid CRDI Plate X			\$ 41.00	
	Rear Bumper X 1/2			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Clips X			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover X			\$ 225.00	
	Rear Panel X			\$ 592.30	
	Rear Panel Garnish X			\$ 57.70	
	Rear Panel Lower Panel X			\$ 495.50	
	SUB TOTAL			\$ 5,021.05	
	LESS 20%			\$ 1,004.21	
	DISCOUNTED TOTAL			\$ 4,016.84	
	Boot Lid Comfort Logo & Tel No. Sticker X			\$ 30.00	Nett
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
				\$ 215.70	
	Labour Charge				
	Panel Beating			\$ 850.00	100
	Spray Painting Charge			\$ 600.00	200
	Wiring Charge			\$ 50.00	X
	Tuff Kote			\$ 50.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	X
	TOTAL LABOUR			\$ 1,670.00	
	ESTIMATE TOTAL			\$ 5,902.54	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No further work on(s) is allowed
- Surveyor's report must be resurveyed and approved by the insurance company

Kalin LKK

2/5/18 1120h

2 Rgs.

P/P After Repair photo