

INS. CASE OWNER:

CC 6 /AIG1800

8129, A 46352

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

2/5/18

Date / Time:

2/5/18

Registered in Merimen:

2/5/18

Pre-assign / CCU / FTE

SLH 5404B



Insured Vehicle No.:

LEE HOON WEE RAYMOND.

Claim No.:

15602042944

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

97374235

Make / Model:

MAZDA

Excess Sec II :\$S

D.O.A.:

26/4/18

Place of Accident:

FIVE LANE FROM TPE  
EXIT TO TAMPINES AVE 7

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SFH 4805K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Leang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

2/5/18

14/5/2018 pphk:  
12:5pm

SFH 4805K - X SLH 5404B - X

please beware gear issue was mention in TP report

spoke to OJ, OJ confirmed accident details. Informed OJ about  
TP claim and HED insurer. OJ agreed to settle and waive the  
HED issue. sent letter to OJ.

PINKUDED.

TP LOW IN BY MAX

MAX OFFER TO TP.

TP ACCEPTED OFFER.

ALL BOSS IN ORDER.

TO CLOSE.

RECEIVED 04 JUL 2018

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	4/17/18/18
After call ltr to OI:	18/05/18
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	<input type="checkbox"/>
After call ltr to OI:	<input type="checkbox"/>
Authorisation To Act:	<input type="checkbox"/>
Release Voucher:	<input type="checkbox"/>
Final Repair Bill:	<input type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>
Towing Invoice:	<input type="checkbox"/>
LTA / GIA:	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>
PIR:	<input type="checkbox"/>
Mandate/Reject Instruction:	<input type="checkbox"/>
LOD:	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>
Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS 4,000.00 / 6 days	Reduction: 49 %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.:	27 /
Repair Cost:	SS 4,000.00	
Loss of Rental (LOR):	SS 650.00 ( 5 days) x \$ 130.00	
Loss of Use (LOU):	SS - (\$ x days)	
Loss of Income (LOI):	SS - (\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
GIA/LTA Search	SS 29.00	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent )	
Legal Cost	SS -	
Total:	SS 5,479.00	Global Sum SS: -
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 5,479.00	Name 1: LEANG AUTOMOTIVE
Payee 2: (Strike if N.A.)	SS -	Name 2: -
Payee 3: (Strike if N.A.)	SS -	Name 3: -

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its  
repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SFG 480SK Yr Regn: 2007 octType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream C.C. 1799.Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 218922 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RA61048198Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17.R: 215/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A.

Survey held at Leamy

Rear

R/Bal. 06 mmL/Bal. 06 mmD.O.I. 02/05/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ALG.</u>
	<u>HS &amp; 4,800.00</u>
	<u>CRWD: &amp; 4,661.40 (49%)</u>
	<u>MV: 37K</u>
	<u>TV: 22.2K</u>
	<u>Nett: 14.8K</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18008129/Ahb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 03-05-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLH 5404B	Veh. Inspected	SFG 4805K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	28/04/2018	Inspection Date	02/05/2018	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP Alc

SFG 480 SIC

Vic

Hards Stream

RNG 1048198-

Rear Number Plate	30(SN) X
Rear Number Plate Holder	30(SN) X
Rear Bumper Distorted	688.90 /
Rear Bumper Clips. New	30 /
Rear Bumper Side Holder x02 New	24 2x2 = 48.40 /
Rear Bumper Tow Cover. Behind	28.50 /
Rear Bumper Bracket x02 Bent	18 x 2 = 36 /
Reverse Sensor Damaged	<del>280(SN)</del> 100(SN)
Rear End Panel Dented	550.20 /
Rear End Panel Inner Member Repair	325.50 X.
Rear End Panel Top Garnish. Behind	116.70 /
Rear End Panel Sealant. New	60(SN) /
Taillamp x02 Cooled.	352.4 x 2 = 704.80 /
Tailgate Dented.	903.20 /
Tailgate Lock Damaged	109.60 /
Tailgate Weatherstripe. Ut	121.60 /
Tailgate Inner Trim Board Cooled	284 /
Tailgate Inner Trim Board Clips. New	30. /

STG48051C

Tailgate Glass Moulding	NE	7070	/
Tailgate Glass Sealant	NE	60(SN)	/
Stream Wording		3160	-
PSZ Wording	NE	35.80	-
Rear Fender Inner Trim Board	x02	224.7 x 2 = 449.40	-
Rear Fender Inner Trim Board Cups	NE	60	/ 30
Spare Tyre Carrier	NE	121.60	x
Rear Exhaust Pipe	3rd	515.70	-
Rear Exhaust Mounting	NE	30.40	x
Floor Panel Top Cover	x02	119.2 x 2 = 238.40	x

4600.8  
3680.64  
S.N: 320

total: 6060.64	Panel Beating	1200	800.
1/s: 48K.	Spray Painting	1300	800
06 Days	Wiring	50	30.
	To undersend	120	40.
	To remove reverse sensor	100	50.
	To remove upholstery	150	60.
	To transfer tailgate fittings	150	80.
	To remove tailgate glass	180	120.
	To remove exhaust pipe	150	80.
		<u>9,461.40</u>	

LKK Auto Consultants is the

the Repairer of the following:

- To resurvey before and after spray painting
- To do a pre-survey and a final survey
- Parts price
- Third party costs
- No illegal modifications
- Supplementary damage

IS subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Date

Signature

Your Ref: SFG 4805K  
Our Ref: CC6/AIG18008129/Ahb3

To: M/s **LEANG AUTOMOTIVE**

By Fax Only (69093046)

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES SLH 5404B AND SFG 4805K ON 28/04/2018

We refer to the above matter and we confirmed in receipt of your Letter of Demand.

On a without prejudice basis and purely for an amicable settlement and without admission of liability to our Insured's part, we proposed a global sum settlement of **\$5,320.00** (all in) to settle your clients claim.

If agreeable, kindly chop and sign the attached DV then forward back a copy to us for our Principal to process the payment.

The above amount is to be made payable to **LEANG AUTOMOTIVE**.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*



Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

“We/I, **LEANG AUTOMOTIVE** (“the workshop”) hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$5,300.00** (Global Sum – all in) for vehicle no. **SFG 4805K** that was damaged pursuant to the accident which occurred on **28/04/2018** (date) along **TPE TOWARDS TAMPINES AVENUE 7** (location) involving vehicle no/s **SLH 5404B**. This is pursuant to the inspection conducted on **02/05/2018** (date) at “the workshop”.

We/I confirm that we/I are/am authorized by the owner **SMITH ONG** (“the third party claimant”) of vehicle no. **SFG 4805K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by “the third party claimant”.

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that “the third party claimant” after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SFG 4805K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of “the third party claimant” pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_ (day) of \_\_\_\_\_ (month) **2018** (year)

\_\_\_\_\_  
Signed by appointed surveyor

\_\_\_\_\_  
Signed by “the workshop” (with chop)



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

“We/I, **LEANG AUTOMOTIVE** (“the workshop”) hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,800.00**(Repair Cost), **S\$650.00** (Loss of Rental/Use), **S\$29.00** (Disbursement), for vehicle no. **SFG 4805K** that was damaged pursuant to the accident which occurred on **28/04/2018** (date) along **TPE TOWARDS TAMPINES AVENUE 7** (location) involving vehicle no/s **SLH 5404B**. This is pursuant to the inspection conducted on **02/05/2018** (date) at “the workshop”.

We/I confirm that we/I are/am authorized by the owner **SMITH ONG** (“the third party claimant”) of vehicle no. **SFG 4805K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by “the third party claimant”.

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that “the third party claimant” after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SFG 4805K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of “the third party claimant” pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_ (day) of \_\_\_\_\_ (month) **2018** (year)

\_\_\_\_\_  
Signed by appointed surveyor

\_\_\_\_\_  
Signed by “the workshop” (with chop)



# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018 <a href="#">Edit Reg</a>		02 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEE CHOON WEE RAYMOND, ID: S7341780E, Tel: +6597334235		
Main Claimant:	SMITH ONG, Co. Reg. No.: 53353070M		
Vehicle Reg. No.:	SFG4805K	Date of Loss:	28/04/2018 11:00 - :59 [126 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1560204299SG	Policy/Cover Note No.:	2100492770 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH5404B	Policy No. (Claimant):	5094320550
		Excess:	
Repairer:	Leang Automotive (HQ) BLK 1 KAKI BUKIT AVE 6 #02-12 AUTOBAY@ KAKI BUKIT, 417883 Kaki Bukit - Tel: 9028 6516		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/05/2018]		
Driver/Custodian (Insured):	LEE CHOON WEE RAYMOND (), NRIC: S7341780E, Tel: +6597334235		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date   Priority   Type   Task Group   Subject   Handler   Assigned By   Completed On   Created On   Done?

No results.



## Claim Documents

**\*SFG4805K (1560204299SG)**  
**[SLH5404B]**  
**TP**  
**SMITH ONG**  
**Apr 28 2018 11:00AM**  
**[LEE CHOON WEE RAYMOND]**  
**Leang Automotive**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a> ▼	
<b>Letters/Correspondences</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	<b>Third Party Express Settlement – Payment Breakdown</b>	1 Edit	
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/05/18 10:41	<b>Accident Statement</b> From: SC - Reg. No: SLH5404B, Claimant: LEE CHOON WEE RAYMOND	1 Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
2	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
3	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
4	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
5	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
6	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
7	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
8	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
9	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
10	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
11	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
12	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
13	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
14	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
15	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
16	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
17	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
18	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
19	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
20	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
21	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
22	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
23	18/06/18 11:24	<b>General View</b>	1 Load JPG	<input checked="" type="checkbox"/>
24	18/06/18 11:24	<b>Reinspection Photo</b>	1 Load JPG	<input checked="" type="checkbox"/>
25	18/06/18 11:24	<b>Reinspection Photo</b>	1 Load JPG	<input checked="" type="checkbox"/>
26	18/06/18 11:24	<b>Reinspection Photo</b>	1 Load JPG	<input checked="" type="checkbox"/>
27	18/06/18 11:24	<b>Reinspection Photo</b>	1 Load JPG	<input checked="" type="checkbox"/>
28	18/06/18 11:24	<b>Reinspection Photo</b>	1 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
29	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
30	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
31	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
32	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
33	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
34	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
35	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
36	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
37	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
38	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
39	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
40	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
41	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
42	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
43	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
44	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
45	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
46	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
47	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
48	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
49	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
50	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
51	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
52	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
53	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
54	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
55	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
56	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
57	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
58	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓
59	18/06/18 11:24	Reinspection Photo	1	Load JPG	✓

Documentation			1 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/05/18 17:51	TP GIA REPORT	1	Load PDF	
2	14/05/18 13:40	LETTER TO OI	1	Load PDF	
3	19/06/18 12:14	TP ESTIMATE - MARKED	1	Load PDF	
4	09/07/18 10:21	AUTHORISATION TO ACT	1	Load PDF	
5	09/07/18 10:21	GIA SEARCH	1	Load PDF	
6	09/07/18 10:21	RELEASE VOUCHER	1	Load PDF	
7	09/07/18 10:21	RENTAL RECEIPT	1	Load PDF	
8	09/07/18 10:21	WORKSHOP INVOICE	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/05/18 15:21	OI GIA REPORT	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH5404B (Insd veh)	Model:	HONDA STREAM 1.8 (A)
	SFG4805K (TP veh)		
Date of Accident:	28/04/2018		

Global Sum Settlement	:	[ ]	Yes	[ X ]	No	
Repair Estimate	:	\$				9,461.40
Final Repair Cost	:	\$				4,800.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				5 days
LTA / GIA Search Fee	:	\$				29.00
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				5,479.00
<b>Is Third Party Workshop GIA Registered?</b> [ ] <b>YES</b> [ X ] <b>NO</b> (Kindly indicate below)						
<b>A) For Non GIA Registered Workshop:</b>			Agreed Liability ____100____(%)			
<b>B) For GIA Registered Workshop:</b>			BOLA Applicable: Yes/ No    BOLA Scenario No: ____			
BOLA Liability: ____ (%)			Assessed Liability (*): ____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Leang Automotive	:	\$ 5,479.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

09 Jul  
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008129/AHB3S2

Date: 09/07/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492770  
 Claimant Vehicle No: SFG4805K Insured Vehicle No: SLH5404B  
 Date of Loss: 28/04/2018 Nature of Claim: TP Claim No: 1560204299SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFG4805K  
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1753880  
 Reg. Date: 08/10/2007 (Man. Year: 2007) Chassis No: RN61048198  
 Colour: Brown Odometer: 218922 km  
 Engine Capacity: 1799 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,131.40	4,000.64	2,130.76	34.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,060.00	1,270.00	38.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,461.40</b>	<b>6,060.64</b>	<b>3,400.76</b>	<b>35.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,461.40</b>	<b>4,800.00</b>	<b>4,661.40</b>	<b>49.27</b>
<b>+ Car Rental (5.0 x S\$130.00/day) (S\$)</b>		650.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>5,479.00</b>		

## INSPECTION

Date of Assignment: 02/05/2018  
 Date Inspected: 02/05/2018 Inspected At: Leang Automotive (HQ)  
 BLK 1 KAKI BUKIT AVE 6 #02-12 AUTOBAY@ KAKI BUKIT  
 Singapore 417883  
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	688.90 F	*688.90 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	48.40 F	*48.40 FL
4	1		*REAR BUMPER TOW COVER	Deformed	28.90 F	*28.90 FL
5	2		*REAR BUMPER BRACKET	Bent	36.00 F	*36.00 FL
6	1		*REAR END PANEL	Dented	590.20 F	*590.20 FL
7	1		*REAR END PANEL INNER MEMBER	Repair	325.50 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	116.70 F	*116.70 FL
9	2		*TAILLAMP	Cracked	704.80 F	*704.80 FL
10	1		*TAILGATE	Dented	903.20 F	*903.20 FL
11	1		*TAILGATE LOCK	Damaged	109.60 F	*109.60 FL
12	1		*TAILGATE WEATHERSTRIPE	Cut	121.60 F	*121.60 FL
13	1		*TAILGATE INNER TRIM BOARD	Cracked	284.00 F	*284.00 FL
14	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
15	1		*TAILGATE GLASS MOULDING	Necessary	70.70 F	*70.70 FL
16	1		*STREAM WORDING	Necessary	31.60 F	*31.60 FL
17	1		*RSZ WORDING	Necessary	35.80 F	*35.80 FL
18	1		*REAR FENDER INNER TRIM BOARD	O/s Deformed	449.40 F	*224.70 FL
19	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 F	*30.00 FL
20	1		*SPARE TYRE CARRIER	Not Necessary	121.60 F	*- FL
21	1		*REAR EXHAUST PIPE	Bent	515.70 F	*515.70 FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	30.40 F	*- FL
23	2		*FLOOR PANEL TOP COVER	Not Necessary	338.40 F	*- FL
24	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
25	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
26	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,131.40</b>	<b>4,920.80</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	920.16
<b>Total Parts (\$\$)</b>	<b>6,131.40</b>	<b>4,000.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING.	New	1,200.00	800.00
2	SPRAY PAINTING.	New	1,200.00	800.00
3	WIRING.	New	50.00	30.00
4	TO UNDERSEAL.	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR.	New	100.00	50.00
6	TO REMOVE UPHOLSTERY.	New	150.00	60.00
7	TO TRANSFER TAILGATE FITTINGS.	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS.	New	180.00	120.00
9	TO REMOVE EXHAUST PIPE.	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,330.00</b>	<b>2,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >