

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authored
Rehmy Bepaim
2 days

Date : 09/05/2018

QUOTATION -THIRD PARTY CLAIM

ALG.

~~NTUC INCOME INSURANCE CO-OPERATIVE LTD~~

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : SJJ 7002 C
Model : TOYOTA VELLFIRE
Insured Ins: NTUC INCOME

Accident on : 09/05/2018

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SLG 8568 Y		
1	FRONT BUMPER <i>Buc 1/2</i>	\$ 2,120.00	✓
1	FRONT BUMPER RH SIDE RETAINER	\$ <i>52</i> 212.00	X
1	FRONT BUMPER SENSOR	\$ <i>52</i> 380.00	✓
1	FRONT BUMPER BEAM	\$ <i>2</i> 685.00	X
1	HEADLAMP RH	\$ 3,125.00	✓
		\$ 6,522.00	
	Less 25%	\$ 1,630.50	
		\$ 4,891.50	
	<u>S/NETT PARTS</u>		
1SET	REVERSE SENSORS <i>250</i>	\$ 300.00	X
	TOTAL S/NETT	\$ 300.00	
	TOTAL PARTS :	\$ 5,191.50	
QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 5,191.50	
	Labour charges to replace, repair accident affected area	\$ 600.00	<i>250</i>
	Check wiring system, replace sensor, focus headlamp	\$ 120.00	<i>701</i>
	To do anti rust, undercoat for rear accident affected area	\$ <i>22</i> 120.00	X
	To do spray painting on affected area	\$ 700.00	<i>300</i>
	Total Labour :	\$ 1,540.00	
	Total Parts & Labour :	\$ 6,731.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: