

**CHUNNI MOTOR WORK PTE LTD**

To Sumet by (SEE)

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7836J

DATE : 2.05.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 AIG

| Qty | Parts Description/ Labour                                         | Type | Unit Price  | Amount      |
|-----|-------------------------------------------------------------------|------|-------------|-------------|
|     | Bonnet <i>Dented</i>                                              |      |             | \$ 1,526.00 |
|     | Bonnet Hinge (LH/RH) <i>bt</i>                                    |      | \$ 91.30    | \$ 182.60   |
|     | Radiator Grille <i>chrome</i>                                     |      |             | \$ 1,480.00 |
|     | Radiator Grille H Emblem <i>huc</i>                               |      |             | \$ 290.80   |
|     | Radiator Grille Chrome Moulding <i>chrome</i>                     |      |             | \$ 395.50   |
|     | Front Bumper Cover <i>Dented</i>                                  |      |             | \$ 1,052.20 |
|     | Front Bumper Sponge <i>torn</i>                                   |      |             | \$ 142.20   |
|     | Front Bumper Reinforcement <i>bt</i>                              |      |             | \$ 526.10   |
|     | Front Bumper Grille (RH) <i>deformed</i>                          |      |             | \$ 285.50   |
|     | Front Bumper Grille Airduct (RH) <i>s/c</i>                       |      |             | \$ 155.00   |
|     | Front Bumper Lip <i>s/c</i>                                       |      |             | \$ 62.50    |
|     | Front Bumper Bracket Top (LH/RH) <i>o/s broken</i> <i>N/S s/c</i> |      | \$ 22.40    | \$ 44.80    |
|     | Front Bumper Bracket (LH/RH) <i>o/s broken</i> <i>N/S s/c</i>     |      | \$ 24.60    | \$ 49.20    |
|     | Front Bumper Retainer Mounting <i>o/s broken</i> <i>N/S s/c</i>   |      | \$ 9.20     | \$ 18.40    |
|     | Headlamp Support Top Cover <i>s/c</i>                             |      |             | \$ 398.00   |
|     | Headlamp Support Panel Assy <i>broken</i>                         |      |             | \$ 1,067.50 |
|     | Headlamp (LH/RH) <i>broken</i>                                    |      | \$ 1,388.00 | \$ 2,776.00 |
|     | Headlamp Halogen Bulb (RH) <i>s/c</i>                             |      |             | \$ 14.40    |
|     | Radiator <i>2 bt</i>                                              |      |             | \$ 850.20   |
|     | Radiator Fan Blade, Cowling, Motor Assy <i>NM</i>                 |      |             | \$ 792.95   |
|     | Radiator Bracket (RH) <i>s/c</i>                                  |      |             | \$ 6.50     |
|     | Radiator Guard <i>2 s/c</i>                                       |      |             | \$ 35.00    |
|     | Front Fender (RH) <i>Bnc</i>                                      |      |             | \$ 619.00   |
|     | Front Fender Apron Panel (RH) <i>Bnc</i>                          |      |             | \$ 1,575.50 |
|     | Front Fender Shield (RH) <i>dislodged</i>                         |      |             | \$ 169.80   |
|     | Aircon Condenser <i>2 bt</i>                                      |      |             | \$ 1,137.35 |
|     | Front Windscreen Glass <i>chrome</i>                              |      |             | \$ 1,059.25 |
|     | Front Windscreen Moulding <i>huc</i>                              |      |             | \$ 60.00    |
|     | Wiper Panel Top Garnish <i>s/c</i>                                |      |             | \$ 91.20    |
|     | Wiper Container <i>deformed</i>                                   |      |             | \$ 61.90    |
|     | Wiper Container Motor <i>Dem</i>                                  |      |             | \$ 65.90    |
|     | Front Wheel Rim (RH) <i>NM</i>                                    |      |             | \$ 351.90   |
|     | Front Wheel Hub Cap (RH) <i>NM</i>                                |      |             | \$ 150.70   |
|     | Front Wheel Bearing <i>2 Dem</i>                                  |      |             | \$ 258.50   |
|     | Front Shock Absorber (Assy) (RH) <i>distorted</i>                 |      |             | \$ 342.20   |
|     | Front Shock Absorber Mounting (RH) <i>huc</i>                     |      |             | \$ 75.10    |
|     | Front Drive Shaft (RH) <i>NM</i>                                  |      |             | \$ 1,069.55 |
|     | Rack & Pinion Assy <i>distorted</i>                               |      |             | \$ 2,184.00 |
|     | STG Tie End <i>distorted</i>                                      |      |             | \$ 69.50    |
|     | Stabilizer Bar <i>huc</i>                                         |      |             | \$ 252.30   |
|     | Stabilizer Bar Bush (RH) <i>huc</i>                               |      |             | \$ 16.10    |
|     | Stabilizer Bar Link <i>huc</i>                                    |      |             | \$ 81.70    |
|     | Stabilizer Bracket <i>huc</i>                                     |      |             | \$ 24.00    |
|     | Front Suspension Lower Arm (RH) <i>distorted</i>                  |      |             | \$ 715.10   |
|     | Front Chasis Member <i>o/s Bent</i>                               |      |             | \$ 1,575.85 |
|     | Knuckle Arm (RH) <i>distorted</i>                                 |      |             | \$ 582.95   |

| Amount |
|--------|
|--------|

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHA 7836J (Supplementary)

DATE : 8.05.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

| Qty                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Parts Description/ Labour                | Type | Unit Price | Amount        |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|------|------------|---------------|
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Fan Belt <i>torn</i>                     |      |            | \$ 155.00 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Fan Belt Tensioner <i>Dem</i>            |      |            | \$ 260.80 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Pulley-Idler <i>Dem</i>                  |      |            | \$ 189.50 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Water Pump Assy <i>NN</i>                |      |            | \$ 280.00 X   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Timing Chain Outlet Cover <i>Dem</i>     |      |            | \$ 958.40 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Timing Chain Casket Upper <i>N/C</i>     |      |            | \$ 128.50 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Timing Chain Casket Lower <i>N/C</i>     |      |            | \$ 100.80 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Alternator Assy <i>distorted</i>         |      |            | \$ 1,124.15 ✓ |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Radiator Spare Tank <i>crack</i>         |      |            | \$ 48.00 ✓    |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Aircon Suction & Liquid Hose <i>is +</i> |      |            | \$ 658.90 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Aircon Discharge Hose <i>is +</i>        |      |            | \$ 233.30 ✓   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | SUB TOTAL                                |      |            | \$ 4,137.35   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | LESS 20%                                 |      |            | \$ 827.47     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | DISCOUNTED TOTAL                         |      |            | \$ 3,309.88   |
| <p>15/05/2018 @ 1408 hrs.</p> <p><i>[Signature]</i></p> <p>LKK Auto</p> <p><i>[Signature]</i></p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                          |      |            |               |
| <div style="border: 1px solid black; padding: 5px;"> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div> |                                          |      |            |               |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.                                                                                                                                                                                                                                                                                                                                                                                                                               |                                          |      |            |               |