

ASS. REC. BY:

REF:

CS/AG118008139 /Atbnz

Special Instruction:

Surveyor

## ASSIGNMENT (Office)

From (Person):

Julie

of

AG1

Date/Time:

03052018 504pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 93813

Insured:

SHV 3112S

at Workshop m/s

Ace Auto Solution

Tel:

9189 2617

of

23 Kaki Bukit Ave 4 #04-01

Policy No:

Claim No:

C10001562/AH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

03052018 509pm

Person Contacted:

Shaimi

Vehicle IN /

OUT

Date/Time

Action/Instruction (✓) Estimate

SLT 93813 - X

SHV 3112S - X

lump sum \$3200 (Red: 4511.60 : 58%)

ASS. REC. BY: Adrian Ling

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLT98815Yr Regn: 2017, NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astrac.c. 999Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 1178

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: W0LBE6EA2H6168934Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.I. 08/05/18Survey held at Ace Auto SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Budget Direct.

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

☐

Preli. Report

☒

Final Report

1) 12/6 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

250

Report Format: TPLump Sum / I.B.I: (\$ \$3200/-)

**Catherine Chong (LKK Auto)**

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Thursday, 3 May, 2018 5:04 PM  
**To:** 'SUR'; assignments@lkkauto.com  
**Cc:** Albert Hong  
**Subject:** FW: Accident vehicle between our insured SLT9881S and your insured SGV3112S on 27/04/2018 | Claim ref: C10001562/AH  
**Attachments:** SLT9881S 3 PARTY CLAIM.PDF

Hi Team

Please accept TPPD survey and survey on a without prejudice basis.

Thank you,  
-Julie

**From:** Suhaimi Ong <aceautosolution@gmail.com>  
**Sent:** Thursday, 3 May, 2018 12:52 AM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Subject:** Accident vehicle between our insured SLT9881S and your insured SGV3112S on 27/04/2018

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you notice that our clients' vehicle is not in our workshop at this time and would require your appointed surveyor to arrange an appointment to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization not done promptly on the above said vehicle.

- 1)
- 2)
- 3)

**Take Notice :** This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Please note that this notification does not in any way prejudice our client(s) rights nor shall it be deemed as a waiver of any of their rights, as such our client(s) rights are expressly reserved.

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2018 16:41
Date Of Accident	27/04/2018 18:30
Exact Location Of Accident	SLIP ROAD FROM TPE TO PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT9881S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	OH SIEN JUN THOMAS
NRIC No	S8847324H
Email Address	THOMAS.OH.SJ@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91711965
Alternative Phone No	OFFICE-91711965

### Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA-999CC HB (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00621600
Cover Note Number	

### Driver

Name of Driver	OH SIEN JUN THOMAS
NRIC No	S8847324H
Date Of Birth	18/11/1988
Occupation	INDOOR
Date Of Driving Pass	14/06/2013
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91711965
Fax Number	
Contact Number	OFFICE-91711965
EEmail Address	THOMAS.OH.SJ@GMAIL.COM

Address	684D EDGEDALE PLAINS
Postcode	824684
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : TABITHA ONG
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE REPORT ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV3112S
Vehicle Make/Model/Colour	SUZUKI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	POH YANG SHAN
NRIC/Passport Number	
Contact Number	91814744
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

- 1 - Please report correctly the details of the accident to speed up the claims process.
- 2 - This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 - Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 - The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 - Any false reporting may be referred to the Police for investigation.
- 6 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 - By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 - **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/4/18 1410

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# SKETCH PLAN



(A) SLT9881S  
(B) SGV3112S

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped my car (SLT9881S) at the slip road towards PIE at Upper Changi Road East as there is a pedestrian waiting at pedestrian crossing. (SGV3112S) car cannot stop on time and knock onto the bumper of my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 30/4/18 1410

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man with glasses.

Licence Number: S8847324H

Name: OH SIEN JUN, THOMAS (HU XIANJUN)

Birth Date: 18 Nov 1988

Issue Date: 14 Jun 2013

Barcode: 002191311G

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8847324H

Portrait of a man with glasses.

Name: OH SIEN JUN, THOMAS (HU XIANJUN)

胡 贤 俊

Race: CHINESE

Date of birth: 18-11-1988

Country of birth: SINGAPORE

Sex: M

Small circular emblem at the bottom left.

Small crest at the top right.

Small circular emblem at the bottom right.

**CERTIFICATE OF INSURANCE**Motor Vehicles (Third-Party Risks Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)**OPEL WORKSHOPS**MZ300  
COMPREHENSIVE  
ORIGINALCERTIFICATE NO: **MPC17A00621600**Chassis No: **W0LBE6EA2HG168934**Agency Name: **ALPINE INSURANCE AGENCY PTE LTD**Engine No: **B1171437HRXX0533**Agency Code: **A0000062**1. Index Mark and Registration Number of Vehicle: **SLT9881S**2. Name of Policyholder: **OH SIEN JUN THOMAS (HU XIANJUN)**3. Period of Insurance (both dates inclusive): **20 November 2017 to 19 November 2018**

4. Persons or Classes of Persons entitled to drive

- a) The Policyholder and all Named Drivers declared under the policy
- b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

5. Limitations as to use

Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

6. EXCESS APPLICABLE

WINDSCREEN

SGD 100.00

SECTION I - INSURED/NAMED DRIVER

SGD 1,000.00

ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:

SECTION I - AGE &lt;=25, AGE &gt;70 OR DRIVING EXP &lt;2 YEARS OLD

SGD 3,000.00

7. Hire Purchase Company: **MAYBANK**

Signed for and on behalf of ECICS Limited



Chief Executive Officer

**Important Notice:**

- i) Policyholders are hereby warned that it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid insurance under the Act.
- ii) On the sale of a motor vehicle, Policyholders must surrender all insurance papers issued including the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).
- iii) The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle has been sold or transferred.
- iv) The Payment Before Cover Warranty or Premium Payment Warranty found in the Policy must be complied with otherwise there would be no liability under the Policy and Certificate of Insurance.

**Ace Auto Solution**  
 Registration number : 53228991M  
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**Repair Estimate**

Date : 8/5/2018

Reference: SLT9881S  
 Make: OPEL ASTRA  
 HB 1.0 AT

*TP Budget Direct  
 Denise*

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLT9881S  
 CHASSIS NO.: W0LBE6EA2HG168934  
 ENGINE NO.: B1171437HRXX0533

Name of insured : Oh Sien Jun Thomas  
 Date of accident.: 27/4/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

No.	Qty	Part Description	Price (SGD)
1	1	Rear Bumper Upper <i>Repld</i>	\$ 1,700.00
2	1	Rear Bumper Lower Moulding <i>cut</i>	\$ 450.00
3	1	Rear Bumper Towing Cover <i>new</i>	\$ 86.00
4	1	LHF Bumper Reflector <i>2 new can be d</i>	\$ 80.00
5	1	RHF Bumper Reflector <i>2 new can be d</i>	\$ 80.00
6	1	Rear Bumper Absorber	\$ 145.00
7	1	Rear Bumper Reinforment Bar <i>Best</i>	\$ 450.00
8	1	Rear Tailgate WeatherStrip <i>new</i>	\$ 180.00
9	1	Rear End Panel <i>2 new</i>	\$ 953.00
10	1	Rear End Panel Trim	\$ 135.00
11	1	Rear Bumper Centre Bracket, Guide <i>2</i>	\$ 65.00
12	1	LHR Bumper Bracket, Guide	\$ 75.00
13	1	RHR Bumper Bracket, Guide <i>new</i>	\$ 75.00
14	1	LHR Lower Bumper Bracket	\$ 40.00
15	1	RHR Lower Bumper Bracket	\$ 40.00
16	1	Rear Tailgate Sensor <i>2 new can be d</i>	\$ 180.00
17	2	Rear Number Plate Lamp <i>2 new can be d</i>	\$ 60.00
18	2	Rear Bumper Air Ventilator <i>2 new can be d</i>	\$ 120.00

*3245  
 2920.50*

Parts Total: \$ 4,914.00

Less 10%: \$ 491.40

Total: \$ 4,422.60

### Labour Description

No. Price (SGD)

#### Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 800.00	2w
2	Carry out spray painting on accident affected area (\$200 per panel)	\$ 800.00	2w
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
4	To remove and refix reverse sensor and conduct test	\$ 80.00	50
5	To remove and refix reverse camera and conduct test	\$ 80.00	x.
6	To conduct water leakage test after repairs of vehicle	\$ 80.00	x.

480

Labour Total: \$ 1,870.00

### Others

### Other Description

No. Qty Price (SGD)

#### Rear portion

1	1	Rear number plate <i>Quilc</i>	\$ 45.00	-
2	10	Rear bumper clip <i>see</i>	\$ 65.00	30
3	6	Rear end panel trim clip <i>see</i>	\$ 39.00	x.
4	1	Reverse sensor 1 set <i>Dangd</i>	\$ 600.00	150
5	1	Rear reverse camera <i>see Dangd</i>	\$ 550.00	* 400.
6	1	Rear end panel insulation seal <i>see</i>	\$ 120.00	+

Other Total: \$ 1,419.00

GRAND TOTAL: \$ 7,711.60

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Suhaimi

HP : 9189 2617 Email - [aceautosolution@gmail.com](mailto:aceautosolution@gmail.com)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items must be resurveyed and is subject to final approval by the Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian Lj  
L/s 08/05/18.  
03 Apr

total: 4025.50  
h/s: 3.2K

625

**Ace Auto Solution**  
 Registration number : 53228991M  
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933  
**INVOICE**

To : Auto & General Insurance (Singapore) Pte Limited

Invoice No: ACC-2015001  
 Invoice Date:

Vehicle No: SLT9881S  
 Chasis No: W0LBE6EA2HG168934  
 Engine No: B1171437HRXX0533

DESCRIPTION	AMOUNT SGD
-------------	---------------

<u>Parts</u>			<u>Price (SGD)</u>
<u>No.</u>	<u>Qty.</u>		
<u>1</u>	1	Rear Bumper Upper	\$ 1,700.00
<u>2</u>	1	Rear Bumper Lower Moulding	\$ 450.00
<u>3</u>	1	LHF Bumper Reflector	\$ 80.00
<u>4</u>	1	Rear Bumper Reinforment Bar	\$ 450.00
<u>5</u>	1	Rear Bumper Centre Bracket, Guide	\$ 65.00
<u>6</u>	1	LHR Bumper Bracket, Guide	\$ 75.00
<u>7</u>	1	RHR Bumper Bracket, Guide	\$ 75.00
<u>8</u>	1	LHR Lower Bumper Bracket	\$ 40.00
<u>9</u>	1	RHR Lower Bumper Bracket	\$ 40.00
<u>10</u>	1	Rear Tailgate Sensor	\$ 180.00
<u>11</u>	2	Rear Number Plate Lamp	\$ 30.00
<u>12</u>	2	Rear Bumper Air Ventilator	\$ 60.00

Total: \$ 3,245.00  
 Less 10%: \$ 324.50  
 Parts Total : \$ 2,920.50

**Labour**

<u>No.</u>		<u>Price (SGD)</u>
	<b><u>Rear portion</u></b>	
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 200.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 per panel)	\$ 200.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 50.00

Labour Total : \$ 480.00

**Other**

No.

Price (SGD)

**Rear portion**

1	1	Rear number plate	\$ 45.00
2	10	Rear bumper clip	\$ 30.00
3	1	Reverse sensor 1 set	\$ 150.00
4	1	Rear reverse camera	\$ 400.00

Other Total : \$ 625.00

Total : \$ 4,025.50

Less lump sum 20%: \$ 805.10

**Grand Total: \$ 3,200.00**

Yours Faithfully,

  
Suhaimi  
Service Executive  
Tel: 9189 2617 Fax: 6844 5185  
Email : aceautosolution@gmail.com

**E & O E**

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

**Please check and finalize with me this invoice**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18008139/Atbn2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 19-06-2018



Code : AGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 3112S	Veh. Inspected	SLT 9881S
Policy No.		Coverage (\$)	0.00
Claim No.	C10001562/AH	Excess (\$)	0.00
Assign From	JULIE	Assign Date	03/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	OPEL ASTRA	c.c	999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0LBE6EA2HG168934	Colour	GREY
Odometer	11178	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	6 mm
L/H Front Tyre	225/45 R17	MICHELIN	6 mm
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	27/04/2018	Inspection Date	08/05/2018
Survey held at	ACE AUTO SOLUTION 23 KAKI BUKIT AVE 4, #04-01 (SOUTH WING) SINGAPORE 415933		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 9881S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER UPPER	DEFORMED	1,700.00	1,700.00
1	REAR BUMPER LOWER MOULDING	CUT	450.00	450.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	86.00	-
1	LHF BUMPER REFLECTOR	CRACKED	80.00	80.00
1	RHF BUMPER REFLECTOR	NOT NECESSARY	80.00	-
1	REAR BUMPER ABSORBER	NOT NECESSARY	145.00	-
1	REAR BUMPER REINFORMENT BAR	BENT	450.00	450.00
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	180.00	-
1	REAR END PANEL	NOT NECESSARY	953.00	-
1	REAR END PANEL TRIM	NOT NECESSARY	135.00	-
1	REAR BUMPER CENTRE BRACKET, GUIDE	NECESSARY	65.00	65.00
1	LHR BUMPER BRACKET, GUIDE	NECESSARY	75.00	75.00
1	RHR BUMPER BRACKET, GUIDE	NECESSARY	75.00	75.00
1	LHR LOWER BUMPER BRACKET	NECESSARY	40.00	40.00
1	RHR LOWER BUMPER BRACKET	NECESSARY	40.00	40.00
1	REAR TAILGATE SENSOR	CRACKED	180.00	180.00
2	REAR NUMBER PLATE LAMP	N/S CRACKED	60.00	30.00
2	REAR BUMPER AIR VENTILATOR	N/S CRACKED	120.00	60.00
	LESS 10% DISCOUNT		-491.40	-324.50
			4,422.60	2,920.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN)	CRACKED	45.00	45.00
10	REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
6	REAR END PANEL TRIM CLIP (SN)	NOT NECESSARY	39.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	600.00	150.00
1	REAR REVERSE CAMERA (SN)	DAMAGED	550.00	400.00
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
			1,419.00	625.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.		800.00	200.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		800.00	200.00

Report Ref No. CS/AGI18008139/Atbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.	NOT NECESSARY	80.00	-
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
			1,870.00	480.00
	<b>GRAND TOTAL</b>		<b>7,711.60</b>	<b>4,025.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,200.00</b>

Report Ref No. CS/AGI18008139/Atbn2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.