

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

03 MAY 2018

## ESTIMATE

@GPM

Estimate No. : b1 46822	Page No. : 1 of 2
Date Estimated : 03/05/2018	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Tan Mui Huang Irene 35 Mount Sinai Rise #04-03 Singapore 276955	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP171L	LB17654	31/01/2018	X3 xDrive30i	0

DESCRIPTION	VALUE
To replace front bumper and attachments.	850 <del>1,700.00</del>
Painting front bumper and arch cover.	934 <del>1,112.00</del>
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 <del>177.00</del>
Sundries.	80.00
Total Labour 1:	<b>3,069.00</b>

DESCRIPTION	QTY	PRIC	VALUE
LH GUIDE BUMPER	1	54.30	? 54.30
FRT BUMPER LH INSERT	1	58.95	? 58.95
LH COVER FOR AIR INLET	1	102.70	? 102.70
FRT LH FOG LAMP SUPPORT	1	68.60	? 68.60
LH AIR CURTAIN	1	47.75	? 47.75
FRT BUMPER LH TRIM	1	54.15	? 54.15
Grill, side,	1	81.45	? 81.45
FRT BUMPER PANEL PRIMED (M/ICAM)	1	1,563.75	de 1,563.75
SET MOUNTING PDC/PMA SENSOR FRT (M)	1	135.05	? 135.05
FRONT LEFT BRAKE DUCT	1	51.50	? 51.50
FRT LH WHEEL ARCH TRIM PRIMED (M)	1	247.30	? 247.30
FRT LH WHEEL ARCH TRIM (M)	1	187.35	? 187.35
LH FOG LAMP LED	1	406.75	? 406.75
Total Parts :			<b>3,059.60</b>

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X**

## E S T I M A T E

Estimate No. : <b>b1 46822</b>	Page No. : <b>2 of 2</b>
Date Estimated : <b>03/05/2018</b>	
Prepared By : <b>Inthiran A/L Thurasamy</b>	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SJP171L</b>	<b>LB17654</b>	<b>31/01/2018</b>	<b>X3 xDrive30i</b>	<b>0</b>

**Lawyer Consultants hence notify the Proprietor of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts notes are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Structural modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Form provided by Repairer

Date: \_\_\_\_\_

Claims CD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date/Time **07/05/18 @ 1620** Excess S\$ \_\_\_\_\_

Surveyor's Name **RASUL** Sign \_\_\_\_\_

Surveyor's Tel **90010068** Authorised Yes / No \_\_\_\_\_

Appraised Date \_\_\_\_\_ Time \_\_\_\_\_

ISSUE AND TAKE PHOTO BY SURVEYOR Yes / No **Yes** / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend **3 days**

Labour 1	:	<b>3,069.00</b>
Parts	:	<b>3,059.60</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>429.00</b>
<b>Grand Total</b>	<b>:</b>	<b>6,557.60</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***