



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721

TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg

GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: SKQ2299Y **S8M00FRV**

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate No: **MCS1102401**

Date: 03 May 2018

Policy No: GA072906/1


Veh Reg No: **SKQ2299Y**


Make/Model: BMW 325I

Estimate Repair Cost to Vehicle No :SKQ2299Y

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	650.00 Bf	
2 FRONT BONNET LOGO		1 PC	50.00 na	
3 HEADLAMP - LH		1 PC	1,150.00 CRA	
4 HEADLAMP - RH		1 PC	1,150.00 CRA	
5 HEADLAMP LOWER BRACKET - LH		1 PC	55.00 X	
6 HEADLAMP LOWER BRACKET - RH		1 PC	55.00 X	
7 FRONT BONNET LOCK LOWER - LH		1 PC	32.00 X	
8 FRONT BONNET LOCK LOWER - RH		1 PC	32.00 X	
9 FRONT BUMPER		1 PC	680.00 DE	
10 HEADLAMP NOZZLE COVER - LH		1 PC	38.00 X	
11 HEADLAMP NOZZLE COVER - RH		1 PC	38.00 X	
12 RADIATOR GRILLE - LH		1 PC	75.00 CRA	
13 RADIATOR GRILLE - RH		1 PC	75.00 CRA	
14 RADIATOR GRILLE AIR GUIDE		1 PC	85.00 CRA	
15 RADIATOR SUPPORT PANEL		1 PC	400.00 DE	
16 EXPANSION TANK BYPASS HOSE		1 PC	50.00 at	
17 AIR INTAKE DUCT		1 PC	65.00 CRA	
18 AIR INTAKE DUCT CLIP		2 PC	3.00 na	
19 BRACE PANEL		1 PC	18.00 R	
20 FRONT BONNET LOCK CABLE		1 PC	18.00 at	
				4,719.00
Special Nett				
21 COOLANT		1 PC	35.00 na	
22 NO. PLATE		1 PC	35.00 CRA	
				70.00
LABOUR				
23 TO CHECK WIRING AND REFOCUS HEADLAMP		1 PC	40.00 ✓	
24 TO REMOVE AND REPLACE A/C CONDENSER, PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS		1 EA	120.00 100	
25 TO DISMANTLE THE FRONTAL DAMAGED PARTS. TO REMOVE & REFIT FRONT SUPPORT PANEL & TO REFIT LISTED PARTS BACK SAME		1 PC	800.00 600	
26 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & FRONT FENDER RH		1 PC	800.00 600	

1,760.00





AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department
Your Ref No: SKQ2299Y
Claim Type: Own Damage
Accident Date: 30/04/2018

Estimate No: MCS1102401
Date: 03 May 2018
Policy No: GA072906/1
Veh Reg No: SKQ2299Y
Make/Model: BMW 325I

Estimate Repair Cost to Vehicle No :SKQ2299Y

Amount Before Excess	S\$ 6,549.00
Add GST @ 7%	458.43
Total Amount payable	<u>S\$ 7,007.43</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND AND SEVEN AND CENTS FORTY THREE ONLY

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

Rasul
Hp 90010068

6 days

P/P

04/05/18 P1555

EXCESS: 500

Authorised

Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: