

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 15 May 2018

Preliminary Advice

Insured Vehicle No : SKV7502B
TP Vehicle No : SJP1973H
Make : FIAT 500
Date of Inspection : 14/05/2018
Inspection At : BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117
Singapore 575636
Accident Date : 27/04/2018
Assignment Date : 04/05/2018
Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,640.00
Revised Amount (Labour)	:S\$	745.00 (PENDING PARTS PRICES)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	745.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.