

22/03/2002

ASS. REC. BY:

REF: CS/C7118008181/Tirber

Special Instruction:

Surveyor
Munier

Thaikh

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

C71

Date/Time:

04052018 1039am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 7677H

Insured:

at Workshop m/s

Cycle & Carriage
188 Pandan Loop

Tel:

9186 5113

of

Policy No:

OMPASN 3045341702

Claim No:

SNM 780 02246001

Sum Insured:

Excess:

\$ 500

Make of Veh:

D.O.A.

30042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

04052018 11am

Person Contacted:

Kerlyn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKL 7677H - X

Report thru Munier

8/5/18

Inform Kerlyn thru phone & email authorise repair

Confirm \$10,795.77 @ 6 days (Red: \$6026.00, 361.1)

(08/11/13)

REF:

CTI

Surveyor: Taylor**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

☒ **OD** WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 40

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 884K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Kevlyn

Veh No: SICL 7677M Yr Regn: 2013, Dec.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz B200 c.c. 1595Colour: white A/C: Insured / Std / NI / NASp. Reading: 66835 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPD24624323 2-13659Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 4/5/180/515Survey held at C&C Pindar LoopDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFrt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) tupid

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 220

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

220Report Format: ODLump Sum / I.B.I: (\$ 10,795.77)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		04 May 2018 10:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAN LIH LIN		
Vehicle Reg. No.:	SKL7677H	Date of Loss:	30/04/2018 18:00 - :59
Claim Type:	OD / SNM18D02246C01	Policy/Cover Note No.:	DMPCSN3045341702 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte.
Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 07 May 2018

Preliminary Advice

Vehicle No	: SKL7677H	Accident Date	: 30/04/2018
Make	: MERCEDES-BENZ 200	Policy No.	: DMPCSN3045341702
Assignment Date	: 04/05/2018	Excess	: S\$500.00
Date of Inspection	: 04/05/2018	Est. Duration of Repair	: 6.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,434.50
Revised Amount	:S\$	9,884.67
Check Items (Estimated)	:S\$	3,990.23
Total	:S\$	13,874.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	55,997.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,003.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SKL7677H (SNM18D02246C01)**

OD

Apr 30 2018 6:00PM

[TAN LIH LIN]

Cycle & Carriage Industries Pte Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 08/05/2018
11:14 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13874.90) - SKL7677H - Claim Handler: Irene Tay Hui Ping

Approved:13874.90:Please proceed to authorize repairs UP TO \$13,874.90 BEFORE Excess of \$500.00. RE-INSPECTION of vehicle required.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, May 08, 2018 11:23 AM
To: Kerlyn Ong Kai Li
Cc: SUR
Subject: RE: SKL7677H

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKL 7677H (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kerlyn Ong Kai Li [mailto:kerlyn.ong@cyclecarriage.com.sg]
Sent: Monday, May 07, 2018 11:20 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Irene Tay <irene.tay@sg.cntaiping.com>
Subject: SKL7677H

Dear Officer,

Any update if the repair is authorised?

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0657J
Vehicle Details	
Vehicle No.:	SKL7677H
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B 200 AT ABS AIRBAGS HID 2WD 5DR(CHROME)
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	27091030281346
Chassis No.:	WDD2462432J213659
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$25,067.00
Original Registration Date:	20 Dec 2013
First Registration Date:	20 Dec 2013
Transfer Count:	1
Actual ARF Paid:	\$17,094.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2023
PARF Rebate Amount:	\$12,820.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$76,889.00
COE Rebate Amount:	\$43,177.00
Total Rebate Amount:	\$55,997.00

The information contained herein is correct as at 07 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 13:22
Date Of Accident	30/04/2018 18:20
Exact Location Of Accident	T-JUNCTION BETWEEN ROBIN RD & BT. TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL7677H
Insured/Policyholder	
Name Of Registered Owner	TAN LIH LIN
NRIC No	S8120657J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84992772
Alternative Phone No	OFFICE-84992772

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	B200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3045341702
Cover Note Number	

Driver

Name of Driver	TAN LIH LIN
NRIC No	S8120657J
Date Of Birth	18/07/1981
Occupation	INDOOR
Date Of Driving Pass	27/08/2001
Driving Experience	16 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84992772
Fax Number	
Contact Number	OFFICE-84992772
Email Address	NOEMAIL

Address	22 WILBY RD #03-17
Postcode	276306
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHLOE TAN GENDER: : FEMALE
Passenger 2	NAME: : KATIE TAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	-
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20180430/7021. MY CAR WAS STATIONARY ALONG ROBIN RD, AT THE JUNCTION WAITING TO TURN LEFT INTO BUKIT TIMAH RD. AN UBER CAR TURNING LEFT INTO ROBIN RD HIT A MOTORCYCLE (JQC4249). THE MOTORCYCLE LOST BALANCE AND CAME TOWARDS MY CAR. IT HIT THE FRONT RIGHT BUMPER OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REFER CSE KO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JQC4249
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	

Circumstances of Accident

REFER TO POLICE REPORT NO.T/20180430/7021

Attachment(s)

Are accident photos available for attachment?

No ☒ Yes ☐

Was there any video captured by Car Camera?

No ☐ Yes ☒

Was there any audio recorded?

No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

JQC 4249

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLJ 2544 P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Was there any witness?

No ☐ Yes ☐

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time 02/05/2018 1132

Driver's Signature

(If driver is not the policyholder)

Date & Time

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT NO.T/20180430/7021

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)



Policyholder's Signature
Date & Time 02/05/2018 1132

Driver's Signature
(If driver is not the policyholder)
Date & Time

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Reporting Centre Personnel's
Name: KERLYN
NRIC/FIN No.:



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.ctaiping.com
Co. Reg. No. 200706384E

MOTOR ACCIDENT ADVICE FORM
(Applicable to Windscreen Claim)

Agency		Claim No	
1) PARTICULARS OF INSURED			
Name	Tan Lih Lin	Policy No	DMPCBN3045341702
Address	22 Wilby Road #03-17 S276306	Contact Nos (H) - (HP) 84992772	
Occupation	Girl Servant	Registration No	SKL7677H
Year Model		C.C./Tonnage	
		Make	Mercedes B200
		Amount Insured	
2) ACCIDENT INFORMATION			
Date of Accident	30 April 2018	Time	6-28pm
Place	T-Junction between Robin Rd + Bukit Timah Rd.	Approximate Speed	0km/h
Name of Police Station Reported To	Electronic Police Centre.		
3) PARTICULARS OF DRIVER			
Name of Person driving your vehicle	Tan Lih Lin	Age	37
Licence No	S8120657J	Date of Expiry	2 July 2018
Relationship to owner	Same as insured		
If Assured was not driving, does driver own a motor vehicle? If so, please state:	Contact Nos		
Your Car No	Name of Insurance Co	Occupation of Driver	(H) -
-	-	-	(HP) Same as insured
4) DETAILS OF DAMAGE TO YOUR VEHICLE			
Front right bumper badly damaged			
5) DAMAGES TO THIRD PARTY PROPERTY			
a. Registration Number(s) and details of damage to the other vehicle(s) involved			
JQC 4249 (Motorcycle)			
No damages at all			
b. Any other property			
6) INJURY TO PERSONS			
Name	Address	Extend of Injury	
nil			
7) WITNESS			
Passenger's Name	Address	Other Witness Name	Address
nil			
8) Have you obtained an estimate for repair? If so, give name of repairers and amount of estimate.		No	
No liability attaches this Company UNLESS the vehicle is inspected after accident and the estimate for the cost repairs approved.			



中国太平
CHINA TAIPING


中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaping.com
Co. Reg No 200708384E

DETAIL OF ACCIDENT

PLEASE EXPLAIN CLEARLY THE CIRCUMSTANCES UNDER WHICH THE ACCIDENT TOOK PLACE.

SKETCH:



My vehicle (SKL7677^H) was stationary along Robin Road, at the T-junction, waiting to turn left into Bukit Timah Road. An Uber car turning left into Robin Road hit a motorcycle (JQC 4249). The motorcycle lost balance and came towards my car. It hit the front right ^{bumper} ~~bumper~~ of my car. (Evidence: Car dash cam video, photos)
(TP called in; police report lodged)

NOTE:- Every communication you receive in connection with this matter should be forwarded to the Company without delay.

DATA PRIVACY STATEMENT

In accordance with the Personal Data Protection Act 2012, I consent to the collection, use, disclosure of and/or process of my personal data (whether contained in the Claim Form or otherwise obtained) by China Taiping Insurance (Singapore) Pte Ltd, its affiliates and service providers (within or outside Singapore), for the purpose relating to the evaluation of the claim and to provide advice and information relating to the claim to me by Short Message Service (SMS), Multimedia Messaging Service (MMS) and fax messages (notwithstanding the registration of my telephone or mobile number in the Singapore's Do Not Call Registry)


Yes, I have read and agreed to the above Data Privacy Statement.


Signature of Claimant

Name:
NRIC/FIN/Passport No

30.4.18

Date


Insured Signature


Driver Signature

FOR OFFICE USE ONLY

NAMED DRIVERS:-

- _____
- _____
- _____
- _____

ENDORSEMENTS:-

- _____
- _____
- _____

PERIOD OF INSURANCE:-

FROM: _____ TO: _____

EXCESS:-

- Section I :-
- Section II :-
- Unnamed Driver :-
- TOTAL =
- NO CLAIM BONUS =

SINGAPORE ACCIDENT STATEMENT

ACCIDENT STATEMENT

Date Of Accident	30/04/2018
Time Of Accident	1828
Exact Location Of Accident	T-JUNCTION BETWEEN ROBIN RD & BT TIMAH RD
Country/State of Loss	Singapore/ Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL 7677 H
Insured/Policyholder	
Name Of Registered Owner	Tan Lih Lin
NRIC No	S8120657J
Email Address	
Mobile Phone No	84992772
Alternative Phone No	

Vehicle Particulars

Manufacturer	MEREDES-BENZ
Model	B200
Exact Purpose for which vehicle was being used at time of accident	Private use <input checked="" type="checkbox"/> Commercial use <input type="checkbox"/> Hire & reward <input type="checkbox"/> Others - Please specify
Are you claiming under your own insurance policy for repair to your vehicle?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Other
If No, Please state action to be taken	Third Party Claim <input type="checkbox"/> Reporting Only <input type="checkbox"/>
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA
Type Of Coverage	Comprehensive Others
Fleet Policy	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Policy Number	DMPCSN3045341702
Cover Note Number	

Driver

Name of Driver	Tan Lih Lin
NRIC No	S8120657J
Date Of Birth	18/07/1981
Occupation	Indoor <input checked="" type="checkbox"/> Outdoor <input type="checkbox"/>
Date Of Driving Pass	27/08/2001
Driving Experience	
Gender	Male <input type="checkbox"/> Female <input checked="" type="checkbox"/>
Mobile Number	84992772
Fax Number	
Contact Number	
Email Address	
Address	22 Wilby Road #03-17 Singapore 276306
Postcode	

Was driver an employee of the Insured's Company

Yes ☐ No ☒

If No, Relationship of the Driver with the Insured

Owner ☒ Paid Driver ☐ Relative ☐ Friend ☐ Parent ☐
Spouse ☐ Children ☐ Sibling ☐ Other: _____

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

Clear ☒ Raining ☐ Others

Road Surface

Dry ☒ Wet ☐ Others

Details of Injured Persons

Was anybody injured in the Accident?

No ☒ Yes ☐

Name

Address

Injuries Sustained

If vehicle Occupants, state in which vehicle?

Were seat belts worn?

No ☐ Yes ☐

Was injured conveyed to hospital by ambulance?

No ☐ Yes ☐

Other Information

Was any foreign vehicle involved in this accident?

No ☐ Yes ☒

Number of vehicles involved in the accident

3

Was any other material or property damaged?

No ☐ Yes ☒

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

No ☒ Yes ☐

Number of Passengers (Including Driver)

2

Passenger 1

CHLOE TAN

Male ☐ Female ☒

Passenger 2

KATIE TAN

Male ☐ Female ☒

Passenger 3

Male ☐ Female ☐

Passenger 4

Male ☐ Female ☐

Passenger 5

Male ☐ Female ☐

Details of Police Action

Was the accident reported to the police?

No ☐ Yes ☒

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No ☐ Yes ☐

NO If Yes, against whom?





REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8120657J**
Name:
**TAN LIH LIN
(CHEN LILIN)**

Birth Date: 18 Jul 1981
Issue Date: 10 Jul 2003

000644200H

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8120657J**



Name
**TAN LIH LIN
(CHEN LILIN)
陈力琳**

Race
CHINESE

Date of birth: **18-07-1981** Sex: **F**

Country of birth
SINGAPORE

S8120657J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	PASS DATE
Class 3		27 Aug 2001

NP 428A

Licence No: S8120657J

FOR C&C USE ONLY

4792891

NRIC No: **S8120657J**

Date of issue
14-11-2011

22 WILBY ROAD #03-17
SINGAPORE 276308
NRIC No: **S8120657J** Date: **05/07/2016**



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MXLER SN
AN0561A
Cov.Type: C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSN3045341702	Engine No :27091030281346 Chassis No:WDD2462432J213659
1. Index Mark and Registration Number of Vehicle	SKL7677H	
2. Name of Policy Holder	MRS TAN LIH LIN	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	3 JULY 2017	NAMED DRIVERS EX SECT. IS\$500.00 ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. I - AGE <= 25.....S\$3,000.00 EX SECT. I - AGE >= 26.....S\$500.00 * AGE AS AT DATE OF ACCIDENT
4. Date of Expiry of Insurance	2 JULY 2018	EX ON WINDSCREENS\$100.00
5. Persons or Classes of Persons entitled to drive *		

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED.
ONE TIME WAIVER OF EXCESS FOR THE FIRST S\$1,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : DBS BANK LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:



Authorised Officer

Authorised Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Tel: 6389 6111 Fax: 6225 3592 Website: www.sg.cntaiping.com



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL7677H

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 23311
Reg No/Reg Date SKL7677H / 20/12/2013
Date In/Mileage / 0
Chassis No WDD2462432J213659
Engine No 27091030281346
Make/Model MB/B 200 CGI SEDAN CHROME PK
Colour/Trim 026 650 Calcit Whit/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	02/05/2018/ 15:06	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : DMPCSN3045341702 // 30/04/2018								
TOWED IN/EXCESS : 02/05/2018 // \$500								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNTOW								✓ 140.00
ACCIDENT TOWING FROM ROBIN RD TO PLSC								
USING KING DOLLEY								1920 3600.00
WO: 146489								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								1200 1800.00
A BPIRES								
RESPRAY FRONT BUMPER & RH/ FRONT FENDER								
A BPILAB							0.10	✓ 380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								✓ 120.00
A BPILAB								✓ 540.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT								
A BPILAB								
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT								
M FRONT BUMPER					1.00	1436.34	00.00	del 1436.34
M LH/ FRONT BUMPER CHROME MOULDING					1.00	108.84	00.00	net 108.84
M RH/ FRONT BUMPER CHROME MOULDING					1.00	108.84	00.00	mis 108.84
M FRONT BUMPER LOWER GRILLE					1.00	104.20	00.00	mis 104.20
M RH/ FOG LAMP GRILLE					1.00	66.44	00.00	del 66.44
M RH/ FOG LAMP ORNAMENTAL MOULDING					1.00	126.99	00.00	del 126.99
M FRONT BUMPER COMPANY SIGN					1.00	63.80	00.00	net 63.80
M FRONT BUMPER COMPANY SIGN LOCK CLIP					1.00	2.51	00.00	net 2.51
M FRONT BUMPER LOWER COVER					1.00	276.68	00.00	Chr 276.68
M FRONT DISTANCE SENSOR					4.00	278.69	00.00	mis 1114.76
M FRONT DISTANCE SENSOR SPACER RING					4.00	6.93	00.00	net 27.72
M ELECTRICAL WIRING HARNESS					1.00	146.70	00.00	mis 146.70
M FRONT IMPACT ABSORBER					1.00	127.41	00.00	mis 127.41

Confirmed & accepted by

Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center

188 Pandan Loop

Singapore 128378

Tel: 6777 8388

Fax: 6779 5383

www.mercedes-benz.com.sg

Page 1 of 2



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL7677H

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No **23311**
Reg No/Reg Date **SKL7677H / 20/12/2013**
Date In/Mileage **/ 0**
Chassis No **WDD2462432J213659**
Engine No **27091030281346**
Make/Model **MB/B 200 CGI SEDAN CHROME PK**
Colour/Trim **026 650 Calcit Whit/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	02/05/2018/ 15:06	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CTR/ BASIC MOUNTING FOR BUMPER	1.00	136.28	00.00	136.28
M RH/ FRONT FENDER	1.00	646.47	00.00	646.47
M RH/ FRONT FENDER INTERMEDIATE LAYER	1.00	9.06	00.00	9.06
M RH/ FRONT WHEEL HOUSE COVERING	1.00	183.04	00.00	183.04
M RH/ HEADLAMP UNIT	1.00	2527.94	00.00	2527.94
M RH/ HEADLAMP CONTROL UNIT	1.00	908.93	00.00	908.93
M RH/ HEADLAMP RANGE ADJUSTMENT	1.00	1141.41	00.00	1141.41
M FRONT CROSS MEMBER	1.00	310.54	00.00	310.54

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 97445749
4/5/18 @ 1515
EX \$0
Revent, Not Authorise
sur @ lkk auto.com
6 days
23/5/18

Confirmed & accepted by

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

15434.90
12,554.90
7% GST on 12554.90 878.84
Total Payable 13,433.74

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL7677H

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 23311
Reg No/Reg Date SKL7677H / 20/12/2013
Date In/Mileage 08/05/2018/ 65108
Chassis No WDD2462432J213659
Engine No 27091030281346
Make/Model MB/B 200 CGI SEDAN CHROME PK
Colour/Trim 026 650 Calcit Whit/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	14/05/2018/ 17:01		301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/ FRONT DISK WHEEL	1.00	503.18	00.00	503.18
X LOCK CLIP	1.00	2.51	00.00	2.51
X RH/ FRONT FENDER BRACKET	1.00	11.76	00.00	11.76
X HORN	1.00	180.78	00.00	180.78
X TELESCOPIC NOZZLE	1.00	180.59	00.00	180.59
R RH/ DAYTIME RUNNING LIGHT	1.00	508.45	00.00	508.45

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 1,387.27**
1387.27 97.11

Authorized signatory and company stamp

Total Payable 1,484.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany


Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address				Owner Name & Vehicle Info			
CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 Contact No 62222366				Cust No/Name	/Ms Tan Lih Lin		
				Reg No/Reg Date	SKL7677H / 20/12/2013		
				Date In/Mileage	08/05/2018/ 65108		
				Chassis No	WDD2462432J213659		
				Engine No	27091030281346		
				Make/Model	MB/B 200 CGI SEDAN CHROME PK		
				Colour/Trim	026 650 Calcit Whit/ 041 101 ARTICO Blac		
							
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
WC000668	Credit	19/06/2018/ 14:38	KO	301 / Kerlyn Ong	23311	28143203	
Description of Goods / Services					Qty	Unit Price S\$	Amount S\$
M BPNSUN							F.O.C.
POLICY NO/ACC DATE : DMPCSN3045341702 // 30/04/2018							
TOWED IN/EXCESS : 02/05/2018 // \$500							
DATE IN/DATE SURVEY:4-5-18 // LKK TAUFIKH							
BY/AUTHORIZED ON :8-5-18 // Jannice Lee (Ms) LKK							
S BPNTOW							140.00
ACCIDENT TOWING FROM ROBIN RD TO PLSC							
USING KING DOLLEY							
WO: 146489							
A BPILAB							1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							
A BPIRES							1200.00
RESPRAY FRONT BUMPER & RH/ FRONT FENDER							
A BPILAB					0.10		380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT							
A BPILAB							120.00
TO REMOVE,REPLACE HEADLAMP WITH FOCUS . NETT							
A BPILAB							540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT							
S BPNSUB							(A) 60.00
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,(RUN FLAT)							
WHEEL BALANCE AND INSTALL NEW VALVE HEAD							
X BPNEXC							-500.00
INSURANCE EXCESS							
X	FRONT BUMPER			1.00	1436.34	1436.34	
X	LH/ FRONT BUMPER CHROME MOULDING			1.00	108.84	108.84	
X	RH/ FRONT BUMPER CHROME MOULDING			1.00	108.84	108.84	
X	RH/ FOG LAMP GRILLE			1.00	66.44	66.44	
X	ORNAMENTAL MOLDING			1.00	126.99	126.99	
X	FRONT BUMPER COMPANY SIGN			1.00	63.80	63.80	
X	FRONT BUMPER COMPANY SIGN LOCK CLIP			1.00	2.51	2.51	
X	FRONT BUMPER LOWER COVER			1.00	276.68	276.68	

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 Contact No 62222366	Cust No/Name /Ms Tan Lih Lin Reg No/Reg Date SKL7677H / 20/12/2013 Date In/Mileage 08/05/2018/ 65108 Chassis No WDD2462432J213659 Engine No 27091030281346 Make/Model MB/B 200 CGI SEDAN CHROME PK Colour/Trim 026 650 Calcit Whit/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WC000668	Credit	19/06/2018/ 14:38	K0	301 / Kerlyn Ong	23311	28143203
Description of Goods / Services				Qty	Unit Price S\$	Amount S\$
X RH/ FRONT FENDER				1.00	646.47	646.47
X RH/ FRONT FENDER INTERMEDIATE LAYER				1.00	9.06	9.06
X RH/ FRONT WHEEL HOUSE COVERING				1.00	183.04	183.04
X RH/ HEADLAMP UNIT				1.00	2527.94	2527.94
X RH/ FRONT DISK WHEEL				1.00	503.18	503.18
X LOCK CLIP				1.00	2.51	2.51
X RH/ FRONT FENDER BRACKET				1.00	11.76	11.76
X HORN				1.00	180.78	180.78
X TELESCOPIC NOZZLE				1.00	180.59	180.59

16795.77

Parts	6,435.77	Nett	10,295.77
Labour	4,160.00	7% GST on	10295.77
Standard Menu	0.00		
Specialist Job	200.00	Total Payable	11,016.47
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	-500.00	Total Due	11,016.47
Total(w/o GST)	10,295.77		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)



























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		04 May 2018 10:39 Edit Adj Rpt	S\$10,795.77 Edit Estimates	S\$10,795.77 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAN LIH LIN , ID: S8120657J								
Vehicle Reg. No.:	SKL7677H	Date of Loss:	30/04/2018 18:00 - :59 [52 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D02246C01	Policy/Cover Note No.:	DMPCSN3045341702 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/05/2018]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> CHINA_TAIPIING (08/05/2018): Alert - Adj Mandate Approved (S\$13874.90) - SKL7677H - Claim Handler: Irene Tay ... 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL7677H (SNM18D02246C01)
 OD
 Apr 30 2018 6:00PM
 [TAN LIH LIN]
 Cycle & Carriage Industries Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Video									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print	
1	13/08/18 10:41	Video - Accident								Load MP4		
									1 per page		<input checked="" type="checkbox"/>	
Assessment Reports										Thumbnail	Print	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	07/05/18 14:14	Adjuster Immediate Advice								Load HTM		
									3 per page		<input checked="" type="checkbox"/>	
Photos/Images										Thumbnail	Print	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
2	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
3	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
4	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
5	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
6	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
7	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
8	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
9	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
10	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
11	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
12	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
13	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
14	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
15	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
16	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
17	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
18	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
19	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
20	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
21	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
22	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
23	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
24	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
25	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
26	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
27	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
28	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
29	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
30	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
31	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	
32	07/05/18 14:33	General View								Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
33	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/18 14:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	13/08/18 11:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/05/18 10:43	ESTIMATE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 14:32	Certificate of Insurance	 Load PDF	
2	07/05/18 14:32	SKL 7677H ESTIMATE	 Load PDF	
3	07/05/18 14:32	Singapore Accident Statement	 Load PDF	
4	07/05/18 14:32	Claimant's NRIC AND DL	 Load PDF	
5	13/08/18 15:03	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118008182/T1RBE2

Date: 13/08/2018

REFERENCE

Insured/Claimant: TAN LIH LIN Policy No: DMPCSN3045341702
Date of Loss: 30/04/2018 Nature of Claim: OD Claim No: SNM18D02246C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL7677H**
Make & Model: MERCEDES-BENZ 200, 2.0 (A) Engine No: 27091030281346
Reg. Date: 20/12/2013 (Man. Year: 2013) Chassis No: WDD2462432J213659
Colour: White Odometer: 66835 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$84,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,962.17	6,435.77	4,526.40	41.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,920.00	4,360.00	1,560.00	26.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,882.17	10,795.77	6,086.40	36.05
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	16,382.17	10,295.77	6,086.40	37.15
+ GST 7.00/7.00% (S\$)	1,146.75	720.70	426.05	37.15
Nett Amount (S\$)	17,528.92	11,016.47	6,512.45	37.15

INSPECTION

Date of Assignment: 04/05/2018

Date Inspected: 04/05/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2018)
Parts:	143	MERCEDES-BENZ 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL7677H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,436.34 FS	*1,436.34 FS
2	1		*LH / FRONT BUMPER CHROME MOULDING	Necessary	108.84 FS	*108.84 FS
3	1		*RH / FRONT BUMPER CHROME MOULDING	Missing	108.84 FS	*108.84 FS
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	104.20 FS	*- FS
5	1		*RH / FOG LAMP GRILLE	Deformed	66.44 FS	*66.44 FS
6	1		*RH / FOG LAMP ORNAMENTAL MOULDING	Deformed	126.99 FS	*126.99 FS
7	1		*FRONT BUMPER COMPANY SIGN	Necessary	63.80 FS	*63.80 FS
8	1		*FRONT BUMPER COMPANY SIGN LOCK CLIP	Necessary	2.51 FS	*2.51 FS
9	1		*FRONT BUMPER LOWER COVER	Cracked	276.68 FS	*276.68 FS
10	4		*FRONT DISTANCE SENSOR	Not Necessary	1,114.76 FS	*- FS
11	4		*FRONT DISTANCE SENSOR SPACER RING	Not Necessary	27.72 FS	*- FS
12	1		*ELECTRICAL WIRING HARNESS	Not Necessary	146.70 FS	*- FS
13	1		*FRONT IMPACT ABSORBER	Not Necessary	127.41 FS	*- FS
14	1		*CTR / BASIC MOUNTING FOR BUMPER	Not Necessary	136.28 FS	*- FS
15	1		*RH / FRONT FENDER	Bent	646.47 FS	*646.47 FS
16	1		*RH / FRONT WHEEL HOUSE COVERING	Deformed	183.04 FS	*183.04 FS
17	1		*RH/ HEADLAMP UNIT	Cracked	2,527.94 FS	*2,527.94 FS
18	1		*RH / HEADLAMP CONTROL UNIT	Not Necessary	908.93 FS	*- FS
19	1		*RH / HEADLAMP RANGE ADJUSTMENT	Not Necessary	1,141.41 FS	*- FS
20	1		*FRONT CROSS MEMBER	Not Necessary	310.54 FS	*- FS
21	1		*RH / FRONT DISK WHEEL	Cut	503.18 FS	*503.18 FS
22	1		*LOCK CLIP	Necessary	2.51 FS	*2.51 FS
23	1		*RH / FRONT FENDER BRACKET	Bent	11.76 FS	*11.76 FS
24	1		*HORN	Cracked	180.78 FS	*180.78 FS
25	1		*TELESCOPIC NOZZLE	Cracked	180.59 FS	*180.59 FS
26	1		*RH / DAYTIME RUNNING LIGHT	Not Necessary	508.45 FS	*- FS
27	1		*RH / FRONT FENDER INTERMEDIATE LAYER	Necessary	9.06 FS	*9.06 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,962.17	6,435.77
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT TOWING FROM ROBIN RD TO PLSC	New	140.00	140.00
2	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	2,880.00	1,920.00
3	RESPRAY FRONT BUMPER & RH / FRONT FENDER	New	1,800.00	1,200.00
4	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
5	TO REMOVE, REPLACE HEADLAMP WITH FOCUS	New	120.00	120.00
6	TO INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
7	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD	New	60.00	60.00
Gross Labour Cost (\$\$)			5,920.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >