

ASS. REC. BY:

REF:

CS/GAU8008184/Tlrbez

Special Instruction:

Surveyor:

Tausik

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAL

Date/Time:

03052018 522pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 684K

Insured:

at Workshop m/s

Kedeng Seng Motor.

Tel:

6273 7469

of

Blk 1006 Bukit Merah Lane 2 #01-08

Policy No:

Claim No:

CLMOMV000000254

Sum Insured:

Excess:

JBA 8750

Make of Veh:

D.O.A.

27042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

03052018

1055am

Person Contacted:

Mr. Teo

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBH 684K - NBA (GAU8008062/Y

D.O.A: 270418

Revert thru email

8/5/18

Speak to Mr Teo for authorise repair; Transport 2 way is not given.

Confirm with Mr Teo & /s \$3750 @ 5 days

Red: \$1920.20, 34%.

Taylor

REF:

GAI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess \$ _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

\$5200. 6000 (handbook 7/5)

DAC Accident Rpt. _____

Consistent? Yes or No

GIA / PR Seen _____

Consistent? Yes or No

Est. Repairs _____

days

Res. Yes or No

Lum Sum _____

%

3 Val. Yes or No

☒ REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle IN / OUT

Date / Time

Action / Instruction

Veh No. _____

FBH684K

Yr Regn

2013 1Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Honda GLH125

cc 125

Colour

white

A/C

Insured / Std / NI / NA

Spr. Reading

30004

T Radio

Insured / Std / NI / NA

Eng No

C No

LALJA1149C313-6352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size

F: 2.75 - 18

R: 3.00 - 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Metzeller

Front:

Rear:

R/Bal

5 mm

R/Bal

5 mm

L/Bal

mm

L/Bal

mm

D.O.A.

D.O.I.

4/5/18 R/L 655

Survey held at:

Leong Seig Rim Lane 2 #01-08

Des. of Damages:

☒ Fr / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 12 JUN 2018

Date/Time File Pass to?



: Preli. Report



: Final Report

Date/Time File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

250

Transportation

) S - RS S

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: 00

Lump Sum / T.B.I.: (\$ 3750



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 7 May 2018

Our Ref: CS/GAI18008184/T1rb

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. FBH 684K .


We thank you for the instruction on 03/05/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 04/05/2018 at the premises of m/s: LEONG SENG MOTOR PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: S\$ <u>5,670.20</u> .
Revised Estimate Amount	: S\$ <u>4,443.70</u> .
"Check" Items (Estimated)	: S\$ <u>630.00</u> .
Total Repair cost (Estimated)	: S\$ <u>5,073.70</u> .
Pre-Accident Value	: S\$ <u>6,000.00</u> .
COE/PARF value	: S\$ <u>726.00</u> .
Nett Value	: S\$ <u>5,274.00</u> .

Description of Damage:

The vehicle sustained damages
at the front portion and n/s body.



Comment:

We have not authorize repair.

Repair day: 5 days

Yours faithfully

TAUFIKH

Automotive Assessor

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, May 07, 2018 5:27 PM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: Fw: Gia report for FBH684K
Attachments: FBH 684K GAI OD.pdf

Dear Rachel,

Enclosed preliminary revised for FBH 684K.
Repair day : 5 days

We have not authorize repair.

Kindly let us have your claim reference.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, May 04, 2018 11:00 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Fw: Gia report for FBH684K

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Thursday, 3 May, 2018 5:22 PM
To: LKK Assignments <assignments@lkkauto.com>
Cc: leongseng <leongsen@singnet.com.sg>
Subject: FW: Fw: Gia report for FBH684K

Hi Mr Teo
Noted on your request for OD claim.

Hi LKK
Please accept assignment for OD survey. Attached is GIA report and estimates.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Ngian, Kelvyna
Sent: Thursday, May 3, 2018 5:15 PM
To: leongseng <leongsen@singnet.com.sg>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: FW: [External] Fw: Gia report for FBH684K

Hi Rachel

Kindly assist

Thanks
Kelvyna

From: leongseng <leongsen@singnet.com.sg>
Sent: Thursday, May 03, 2018 5:07 PM
To: General Claims <GeneralClaims@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Fw: Gia report for FBH684K

Dear Sir/Mdm

Pls be informed that owner of motorbike FBH684K (Certis Cisco) had appointed us to do an O/D claim for them.

Pls find enclosed accident report and our repair estimate.

Kindly arrange for your appointed surveyor to conduct damage survey on the bike.

Pls be informed that our workshop is located at Blk 1006 Bukit Merah Lane 2 #01-08 S(159762) Tel 62737469.

Thanks

c s teo
Leon Seng Motor PL

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2018 09:14
Date Of Accident	27/04/2018 21:35
Exact Location Of Accident	ENG NEO AVENUE TURNING FROM PIE LAMPOST 10952
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH684K
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91407334
Alternative Phone No	OFFICE-91407334

Vehicle Particulars

Manufacturer	HONDA
Model	GLH125-125CC
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	MT20171662

Driver

Name of Driver	MOHAMED ALIFF BIN MOHAMED YUSOFF
NRIC No	S9143557H
Date Of Birth	04/12/1991
Occupation	OUTDOOR
Date Of Driving Pass	25/10/2010
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91407334
Fax Number	
Contact Number	OTHERS-91407334
EMail Address	NOEMAIL

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180428/2016

1 of 3

Police Station Of Origin
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No: T/20180428/2016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 28/04/2018 03:05		Vide Report No		Station Diary No 8	
Informant's Particulars					
Name of Informant MOHAMED ALIFF BIN MOHAMED YUSOFF			Address APT BLK 632B SENJA ROAD #03-121 SINGAPORE 672632		
ID Type / ID No NRIC NO / S9143557H			Contact No Home/Office		Mobile 91407334
Nationality SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 26	Date of Birth: 04/12/1991	Type of Informant: Driver		
Race Malay		Language		Institution / School Name	
Occupation: Certis Cisco		Driving Licence Information: Class:		Date of Expiry:	

General Information of the Accident

Type of Accident	Non-Injury	Drink Drive No	Date/Time of Accident 27/04/2018 21:35	Type of Location: Bend
Location Along Road 1 ENG NEO AVENUE eng neo ave turning from PIE, L/P 109252				
Weather Clear		Road Surface Wet	Road Speed Limit	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume Light	
Type of Collision: Skidded			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBH684K	Motorcycle				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



(/)

Bike model

Honda GLH 125

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Honda GLH 125 (/listing/usedbike/honda-honda-glh-125/3324/)



(/listing/usedbike/honda-honda-glh-125/3324/)

SGD\$5200

Reg : 10/02/2012

Type: Street Bikes

125cc

58124km

Used Honda CB125E available for sales. Bike available for viewing at 1 Kaki Bukit Ave 6 #02-54/55
Autobay S'pore 417883 Tel:68446378 Trade in welcome. Loan available. 0% interest credit card ...

Posted on : 01/05/2018

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-GLH-125/3324/)

Honda GLH 125 (/listing/usedbike/honda-honda-glh-125/745/)



(/listing/usedbike/honda-honda-glh-125/745/)

SGD\$5500

Reg : 10/02/2012

Type: Street Bikes

125cc

20000km

Bike available for viewing at : Unique Motorsports Pte Ltd- 1007/1009 Serangoon Road Singapore 328168.
Tel: 63415378. Trade in welcome. Loan available. 0% interest credit card installment plans ava...

Posted on : 01/05/2018

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-GLH-125/745/)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0882K
Vehicle Details	
Vehicle No.:	FBH684K
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	HONDA
Vehicle Model:	GLH125
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	JA11E2005184
Chassis No.:	LALJA11U9C3136352
Maximum Power Output:	-
Open Market Value:	\$1,382.00
Original Registration Date:	26 Feb 2013
First Registration Date:	26 Feb 2013
Transfer Count:	0
Actual ARF Paid:	\$208.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,512.00
COE Rebate Amount:	\$726.00
Total Rebate Amount:	\$726.00

The information contained herein is correct as at 07 May 2018

OK

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBH684K

Model : CB125

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Headlamp assy <i>cat</i>		\$ 245.00		
2	Headlamp stay <i>bt</i>		\$ 80.00		
3	Front signal lamp <i>ana</i>	2	\$ 100.00		
4	Handle bar <i>bt</i>		\$ 165.00		
5	Handle grip <i>unt</i>		\$ 20.00		
6	Handle balancer <i>dd</i>		\$ 35.00		
7	Mirror <i>cra</i>		\$ 65.00		
8	Clutch lever <i>unt</i>		\$ 25.00		
9	Meter assy <i>cua</i>		\$ 480.00		
10	Meter stay <i>bt</i>		\$ 145.00		
11	Front fender <i>aa</i>		\$ 150.00		
12	Front fork assy <i>bt</i>		\$ 860.00		
13	Front wheel axle <i>dd</i>		\$ 95.00		
14	Front wheel rim <i>bt ?</i>		\$ 330.00		
15	Front wheel bearing <i>rec ?</i>	2	\$ 50.00		
16	Fuel tank <i>dd</i>		\$ 580.00		
17	Gear pedal <i>dd</i>		\$ 68.00		
18	Front foot rest <i>cat</i>		\$ 55.00		
19	Rear signal lamp <i>dis</i>		\$ 50.00		
20	Rear shock absorber <i>nn x</i>		\$ 285.00		
21	Rear swing arm <i>nn ?</i>		\$ 320.00		
22	Sprocket & chain <i>dd</i>		\$ 75.00		
23	ERP IU <i>wt</i>			\$ 165.00	
24	ERP IU bracket <i>bt</i>			\$ 25.00	
25	Front wind shield <i>aa</i>			\$ 150.00	
26	Side box <i>ant</i>			\$ 280.00	
27	Repair alignment		180.	\$ 250.00	
28	Logo sticker <i>rec</i>		100	\$ 150.00	
29	Respray		250.	\$ 350.00	
30	Transport 2 way <i>nn x</i>		80.	\$ 100.00	
31	Labour		250.	\$ 350.00	
32	Tanjung 97495749				
33	LKK Auto Consultants hence notice to be advise				
34	the Repairer of the following: 4/5/18 P 1700 Lumpsum				
35	• To resurvey before/after spray painting				
36	• To display damaged part(s) during resurvey				
37	• Parts prices are subject to confirmation				
38	• Third party survey is on a "Without Prejudice" basis				
39	• No illegal modification(s) is allowed				
39	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				

Acknowledged by Repairer
Signature: Less 10%
Date:

\$ 4,278.00 \$ 1,820.00
\$ 427.80
\$ 3,850.20

5670.20

2/5/18

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBH684K

Model : CB125

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Headlamp assy	cat	\$ 245.00		
2	Headlamp stay	bt	\$ 80.00		
3	Front signal lamp	cna	\$ 100.00		
4	Handle bar	bt	\$ 165.00		
5	Handle grip	cut	\$ 20.00		
6	Handle balancer	dd	\$ 35.00		
7	Mirror	cna	\$ 65.00		
8	Clutch lever	cut	\$ 25.00		
9	Meter assy	cna	\$ 480.00		
10	Meter stay	bt	\$ 145.00		
11	Front fender	an	\$ 150.00		
12	Front fork assy	bt	\$ 860.00		
13	Front wheel axle	dd	\$ 95.00		
14	Front wheel rim	bt	\$ 330.00		
15	Front wheel bearing	an - 2	\$ 50.00		
16	Fuel tank	dd	\$ 580.00		
17	Gear pedal	dd	\$ 68.00		
18	Front foot rest	cut	\$ 55.00		
19	Rear signal lamp	dis	\$ 50.00		
20	Rear shock absorber	an x	\$ 285.00		
21	Rear swing arm	an x	\$ 320.00		
22	Sprocket & chain	dd	\$ 75.00		
23	ERP IU	cut		\$ 165.00	
24	ERP IU bracket	bt		\$ 25.00	
25	Front wind shield	cut		\$ 150.00	
26	Side box	cut		\$ 280.00	
27	Repair alignment		180	\$ 250.00	
28	Logo sticker		100	\$ 150.00	
29	Respray		250	\$ 350.00	
30	Transport 2 way		an 80	\$ 100.00	X
31	Labour		250	\$ 350.00	
32				1400	
33			3673		
34			4/5/18 P 1700 lumpsum	10% - 3305.70	
35			Resurvey before paint	1400	
36			5 days	4705.70	
37			sur @ 11kauto.com	463750	
38			sur @ 11kauto.com		
39					

\$ 4,278.00 \$ 1,820.00

Less 10%

\$ 427.80

\$ 3,850.20




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18008184/T1rbe2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 19-06-2018	
			Code : GAI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		FBH 684K
Policy No.		Coverage (\$)		0.00
Claim No.	CLMOMVM000000254	Excess (\$)		0.00
Assign From	RACHEL TAN	Assign Date		03/05/2018
2. Vehicle Particulars & Condition				
Make & Model	HONDA GLH125	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	LALJA11U9C3136352	Colour	WHITE	
Odometer	30004	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.75-18	METZELER	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	3.00-18	METZELER	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2018	Inspection Date	04/05/2018	
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.			
5a. Remarks				
A)THE MARKET VALUE IS S\$6,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 684K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP ASSY	CUT	245.00	245.00
1	HEADLAMP STAY	BENT	80.00	80.00
2	FRONT SIGNAL LAMP	CRACKED	100.00	100.00
1	HANDLE BAR	BENT	165.00	165.00
1	HANDLE GRIP	CUT	20.00	20.00
1	HANDLE BALANCER	DENTED	35.00	35.00
1	MIRROR	CRACKED	65.00	65.00
1	CLUTCH LEVER	CUT	25.00	25.00
1	METER ASSY	CRACKED	480.00	480.00
1	METER STAY	BENT	145.00	145.00
1	FRONT FENDER	CRACKED	150.00	150.00
1	FRONT FORK ASSY	BENT	860.00	860.00
1	FRONT WHEEL AXLE	DENTED	95.00	95.00
1	FRONT WHEEL RIM	BENT	330.00	330.00
2	FRONT WHEEL BEARING	NECESSARY	50.00	50.00
1	FUEL TANK	DENTED	580.00	580.00
1	GEAR PEDAL	DENTED	68.00	68.00
1	FRONT FOOT REST	CUT	55.00	55.00
1	REAR SIGNAL LAMP	DISTORTED	50.00	50.00
1	REAR SHOCK ABSORBER	NOT NECESSARY	285.00	-
1	REAR SWING ARM	NOT NECESSARY	320.00	-
1	SPROCKET & CHAIN	DENTED	75.00	75.00
	LESS 10% DISCOUNT		-427.80	-367.30
			3,850.20	3,305.70
<u>SPECIAL NETT ITEMS</u>				
1	ERP IU (SN)	CUT	165.00	165.00
1	ERP IU BRACKET (SN)	BENT	25.00	25.00
1	FRONT WIND SHIELD (SN)	CRACKED	150.00	150.00
1	SIDE BOX (SN)	CUT	280.00	280.00
1	LOGO STICKER (SN)	NECESSARY	150.00	100.00
			770.00	720.00
<u>LABOUR</u>				
	REPAIR ALIGNMENT.		250.00	180.00

Report Ref No. CS/GAI18008184/T1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY.	NOT NECESSARY	350.00	250.00
	TRANSPORT 2 WAY.		100.00	-
	LABOUR.		350.00	250.00
			1,050.00	680.00
GRAND TOTAL			5,670.20	4,705.70

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,750.00
LESS EXCESS			-750.00
NETT LIABILITY			3,000.00

Report Ref No. CS/GAI18008184/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.