

ASS. REC. BY:

REF:

CS/MSH18008186/Kvbz

Special Instruction:

Survivor:

Kcanath

ASSIGNMENT (Office)

From (Person):

Merimen Kothuane wung

of

ms47

Date/Time:

04/05/2018 10:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 8649J

Insured:

SLK 3783D

at Workshop m/s

Supreme Auto

Tel:

6452 0715

9736 8619

of

176 Sin Ming Drive #02-01

mr chew

Policy No:

1240 4386 16mx

Claim No:

557378

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

04/05/2018 10:39am

Person Contacted:

Dylan

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 8649J - X
	SLK 3783D - X
7/5/18	Send preli. revised by merimen
5/5/18	@ 3:52pm Suki will check
24/5/18	@ 4:33pm Suki will check

ASS. REC. BY:

REF: MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Supreme Lim Tan

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK 88897 Yr Regn: 2, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Airo c.c. 1498

Colour:

M. Silver A/C: Insured / Std / NI / NA

Sp. Reading

123354 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NRE161. 0010233

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Nexen

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/118

Rear

R/Bal.

8

Spoke

L/Bal.

8

Hankcode

D.O.I.

4/5/118

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/13

Plu parts Corolla, GUA not ready

27/11/18

@ 949am LS \$1050 confirmed with mr Chew (Red 3679-38, 7810)

RECEIVED 2 - NOV 2018

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

28/11 - typist

Days Of Repair: 2

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I: (\$

1050/-

150
10
160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong Chew Shong	Date: 07 May 2018
Preliminary Advice	

Insured Vehicle No	: SLK3783D	Accident Date	: 02/05/2018
TP Vehicle No	: SKZ8649J	Assignment Date	: 04/05/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 2.00
Date of Inspection	: 04/05/2018		
Inspection At	: SUPREME AUTO SERVICE PTE LTD (HQ) 176 SIN MING DRIVE #02-01, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,729.38
Revised Amount	:S\$	1,732.33
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,732.33
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018		04 May 2018 10:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN HWEE LENG (CHEN HUILING), ID: S7834715E, Tel: +6590484478, Email: NOEMAIL		
Main Claimant:	MCQUEEN RENTALS PTE LTD, Co. Reg. No.: 201600605G		
Vehicle Reg. No.:	SKZ8649J	Date of Loss:	02/05/2018 13:00 - :59 [26 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 557378	Policy/Cover Note No.:	A29043861QMX (Comprehensive) Coverage: 06/11/2017 - 08/11/2018
Vehicle Reg. No. (Insured):	SLK3783D	Policy No. (Claimant):	
		Excess:	
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0715		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/05/2018]		
Driver/Custodian (Insured):	TAN HWEE LENG (CHEN HUILING) (39 / Female), NRIC: S7834715E, Tel: +6590484478		
Adj Asg. Remarks:	TP Agree on SJE - LKK Auto Consultants		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0605G

Vehicle Details

Vehicle No.:	SKZ8649J
Vehicle to be Exported:	No
Intended De-registration Date:	10 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5G A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	2NR8510220
Chassis No.:	NRE1610010233
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,581.00
Original Registration Date:	05 Feb 2016
First Registration Date:	05 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$7,581.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2026
PARF Rebate Amount:	\$5,685.00

Intended COE Rebate Details

COE Expiry Date:	04 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$36,084.00
Total Rebate Amount:	\$41,769.00

The information contained herein is correct as at 10 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2018 17:07
Date Of Accident	02/05/2018 13:10
Exact Location Of Accident	BLK 14 SIN MING LANE MIDVIEW CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ8649J
Insured/Policyholder	
Name Of Registered Owner	MCQUEEN RENTALS PTE LTD
Co Reg No	201600605G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98526105

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5077614080-02
Cover Note Number	

Driver

Name of Driver	DALEEP KUMAR S/O TIKAMDAS NARWANI
NRIC No	S1367167B
Date Of Birth	24/03/1959
Occupation	OUTDOOR
Date Of Driving Pass	10/04/1985
Driving Experience	33 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98526105
Fax Number	
Contact Number	
Email Address	PHILIPKUMAR8@GMAIL.COM

Address	BLK 245 TAMPINES ST 21 #06-319 SINGAPORE
Postcode	521245
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK3783D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HWEE LENG
NRIC/Passport Number	S7834715E
Contact Number	90484478
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	DALEEP KUMAR S/O TIKAMDAS NARWANI
------	-----------------------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

NECK INJURIES

SKZ8649J

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the minor road near Blk 14 Sin Ming lane at Midview City. The car No. SLK3783P driven by Tan Hwee Leng hit me from behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature: _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUIRENS RENTAL PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 04/05/2018

Not Authored
Call @ 1050h
Monday After Policy
2 days

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : TOYOTA COROLLA AXIO/ SKZ 8649 J	
1 pc	rear bumper <i>477.20</i>	<i>mf.m</i> 836.70 ✓
1 pc	rear bumper retainer <i>131.00</i>	<i>D.S</i> 197.50 ✓
1 pc	rear bumper lamp R/H	<i>L</i> 115.30 X
1 pc	rear bumper bracket	<i>R</i> 89.40 X
1 pc	rear end panel	<i>R</i> 487.50 X
1 pc	rear end panel garnish	<i>Su</i> 309.70 X
1 pc	rear tail lamp assy R/H <i>548.90</i>	<i>su</i> 648.90 ✓
1 pc	rear fender dust cover	<i>Su</i> 127.50 X
	Sub-total	2,812.50
	Less 25%	703.13
	Sub-total	2,109.38
1 set	reverse sensor <i>s.nett</i>	<i>su</i> 250.00 X
	Sub-total	2,359.38
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1,000.00 <i>200</i>
	To check wiring system.	50.00 <i>200</i>
	To spray painting on affected areas.	1,100.00 <i>200</i>
	To apply rust proofing on affected areas.	<i>nn</i> 80.00 X
	To apply waterproof sealant on affected areas.	<i>nn</i> 80.00 X
	To install reverse sensors	60.00 <i>500</i>
	Total	4,729.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008186/KVBN2

Date: 28/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29043861QMX
Claimant Vehicle No :	SKZ8649J	Insured Vehicle No :	SLK3783D
Date of Loss:	02/05/2018	Nature of Claim:	TP
		Claim No:	557378

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8649J	Engine No:	2NR8510220
Make & Model:	TOYOTA COROLLA, 1.5 G AXIO HYBRID (A)	Chassis No:	NRE1610010233
Reg. Date:	05/02/2016 (Man. Year: 2015)	Odometer:	123354 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Nexen 7 mm	Rear Left Side:	Hankook 8 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	AGENDA 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,359.37	867.82	1,491.55	63.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	470.00	1,900.00	80.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,729.37	1,337.82	3,391.55	71.71
Approved Total (Overridden) (\$\$)		1,050.00		
Nett Amount (\$\$)	4,729.37	1,050.00	3,679.37	77.80

INSPECTION

Date of Assignment:	04/05/2018	
Date Inspected:	04/05/2018 Inspected At:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2018)
Parts:	143	TOYOTA COROLLA 1.5 G AXIO HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8649J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	836.70 FL	*477.20 FL
2	1		*REAR BUMPER RETAINER	Distorted	197.50 FL	*131.00 FL
3	1		*REAR BUMPER LAMP R/H	Serviceable	115.30 FL	*- FL
4	1		*REAR BUMPER BRACKET	Repair	89.40 FL	*- FL
5	1		*REAR END PANEL	Repair	487.50 FL	*- FL
6	1		*REAR END PANEL GARNISH	Serviceable	309.70 FL	*- FL
7	1		*REAR TAIL LAMP ASSY R/H	Cut	648.90 FL	*548.90 FL
8	1		*REAR FENDER DUST COVER	Serviceable	127.50 FL	*- FL
9	1		*SET REVERSE SENSOR	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,062.50	1,157.10
- List Item Discount on L Items 25.00/25.00% (S\$)	703.13	289.28
Total Parts (S\$)	2,359.37	867.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	1,000.00	200.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	200.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	80.00	-
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	80.00	-
6	TO INSTALL REVERSE SENSORS	New	60.00	50.00
Gross Labour Cost (S\$)			2,370.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >