

INS. CASE OWNER

JIMMY

CC 6, A161800 8187, Uhas 9

LKK
IDAC

Surveyor

mppms

DOI

ASSIGNMENT

4/5/18

Date / Time

Registered in Merimon

4/5/18
7/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SPB 9903 U

Name of Insured

KHEO KAM Bee

Insured Tel No.

HP:

96990609

Excess Sec II : S\$

D.O.A.

30/4/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SD 619218



INSRS:
WSP:
Tel:
Liability:
RMKS:

chammas.



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

15/5/18
15/5/18

SD 619218 - 152/ADA 12028419 / Uhas ; DA 25/4/18
SPB 9903 U - X

STAGE DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):

15/05/18

- PUB REPAIRWORK. 2 Veh. C.C.; 01 2ND CAR
- BUILT LIABILITY CLAIM

Call OI: 4/5/18/18

AC-ON
2/5/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):
After call ltr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:

15/5/2018
4:30pm

Spoke to OI confirmed involved in 3 part chain collision. OI
is the 2nd vehicle and was pushed forward by behind vehicle.
Informing OI about TP Uhas and MLE. It will be settle
and advise the HIC will be withheld for flow being. Send letter
to OI.

- MINUSSED.
- ORIGINAL TP LOB IN

19/06/19

- TYPE REPORT FOR WANDATE APPROVAL
- REPORT LONG

21/02/19

- SPB WANDATE APPROVAL TO AIG

23/08/19

- AIG APPROVED WANDATE

26/08/19

- SEND ACCEPTANCE EMAIL TO TP.

PRELIMINARY ADVICE

Date/Time:

Sent By:

- All work in order

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: Lb

S\$ 8,900.00 (6 days) Reduction: 57 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lta : 0%

Repair Cost:

S\$ 8,900.00

(to VHM.C.C. 01 2ND)

Loss of Rental (LOR):

S\$ 840.00 (7 days) X \$120.00

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☒ LOU only ☐

LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$320.00

Total:

S\$ 9,747.45

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 9,747.45

Name 1:

CHIN HONG MOTORS

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

-

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

A16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDG/9213at Workshop mis Cherry

of _____

Insured: SKB 99034

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 80

IDAC Accident Report: _____ Consistent?: Yes or No

GA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 93603

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDG/9213 Yr Regn: 4, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Audi A4 C.C. 1798Colour: white A/C: Insured / Std / Nil / NASp. Reading: 117377 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAD 2228K7 DA19821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 255/35 ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or nexenFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/4/18 D.O.I. 4/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11A 53719 Rep 13L10 \$8,900.00(CASH: \$11,777.65/57%)L11: \$80,000 (est)L12: \$53,719 (est)N11: \$26,281 (est)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS, \$/

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18008187/Uha3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-05-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 9903U	Veh. Inspected	SDG 1921B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/04/2018	Inspection Date	04/05/2018
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

振明摩哆

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST145/18/TP
Your Ref: TP claim against SKB9903U
3-May-18
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Audi A4 no: SDG1921B

Date of accident: 30-04-2018

Parts supply:

1 pc Boot hinge *no/buc* 1937.90
2 pcs Boot hinges @ \$217.30 *per*
1 pc Boot emblem - Logo *per* 108.15
1 pc Boot emblem - LRT *per* 105.32
1 pc Boot emblem - A4 *per* 85.60
1 pc Boot weatherstrip *4m/per*
1 pc Boot insulator *1-1*
12 pcs Boot insulator clips @ \$5.00 *1-1*
2 pcs Boot lamps @ \$700.93 *1-1*
1 pc Boot inner lock *1-1*
2 pcs Boot stoppers @ \$17.17 *1-1*
2 pcs Taillamps @ \$800.97 *one*
2 pcs Taillamp clips @ \$17.15 *1-1*
1 pc Rear bumper *dis* 1633.40
1 pc Rear bumper tow cover *to in*
1 pc Rear bumper reinforcement *but* 267.53
2 pcs Rear bumper retainers @ \$90.97 *but*
2 pcs Rear bumper brackets @ \$87.99 *but*
8 pcs Rear bumper clips @ \$4.50 *per*
1 pc Rear bumper lower lip *dis*
1 pc Rear bumper sponge *NE*
4 pcs Rear bumper PDC sensor @ \$217.30 *each* 185 x 32 54.5
1 pc Rear end panel *by 1272.30*
1 pc Rear end panel garnish *try*
1 pc Spare tyre panel *n*
1 pc Exhaust muffler *n*
2 pcs Exhaust muffler bush @ \$117.33 *n*

SS	2,499.76	
	434.60	<i>x</i>
	188.77	<i>—</i>
	120.17	<i>—</i>
	119.79	<i>—</i>
	380.79	<i>2</i>
	225.50	<i>x</i>
	60.00	<i>x</i>
	1,401.86	<i>x</i>
	190.75	<i>—</i>
	34.34	<i>2</i>
	1,601.94	<i>2</i>
	34.30	<i>x</i>
	1,900.93	<i>—</i>
	47.65	<i>—</i>
	649.70	<i>—</i>
	181.94	<i>—</i>
	175.98	<i>—</i>
	36.00	<i>—</i>
	299.76	<i>—</i>
	106.80	<i>x</i>
	869.20	<i>3 pcs</i>
	1,899.76	<i>2</i>
	200.93	<i>2</i>
	2,345.80	<i>x</i>
	1,970.97	<i>x</i>
	234.66	<i>x</i>
	18,212.65	
	45.00	<i>x</i>
	18,257.65	

S/Nett Items

1 pc Rear no. plate with cover (S/Nett)

Not Allowed
2/5 8900/
6dy.
4/5/18
Tele phone after 4pm

5%
9381.14

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Re: Estimated cost of repair to Audi A4 no: SDG1921B

Date of accident: 30-04-2018

Parts supply:

Balance b/f:

S\$ 18,257.65

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit rear reverse sensor.

To reset fault code after repair.

To apply underseal

To check wirings.

1,200.00 1100

1,000.00 980

60.00 50

80.00 50

50.00 50

30.00 30

S\$ 20,677.65

2260

LiKk Auto Transperts hence notify the Repairer of the following:

- To observe safety rules while working
- To replace damaged parts during survey
- All parts are subject to inspection
- Third party survey is on a "Without Prejudice" basis
- No re-assembly is allowed
- Supplementary items must be surveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST145/18/TP
Your Ref: TP claim against SKB9903U
3-May-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Audi A4 no: SDG1921B

Date of accident: 30-04-2018

Parts supply:

1 pc Boot lid *no/bucc*
2 pcs Boot hinges @\$217.30 *111*
1 pc Boot emblem - Logo *ner*
1 pc Boot emblem - 1.8T *ner*
1 pc Boot emblem - A4 *ner*
1 pc Boot weatherstrip *4m/ner*
1 pc Boot insulator *11*
12 pcs Boot insulator clips @\$5.00 *11*
2 pcs Boot lamps @\$700.93 *11*
1 pc Boot inner lock *111*
2 pcs Boot stoppers @\$17.17 *11*
2 pcs Taillamps @\$800.97 *one*
2 pcs Taillamp clips @\$17.15 *11*
1 pc Rear bumper *dis*
1 pc Rear bumper tow cover *to in*
1 pc Rear bumper reinforcement *but*
2 pcs Rear bumper retainers @\$90.97 *but*
2 pcs Rear bumper brackets @\$87.99 *but*
8 pcs Rear bumper clips @\$3.50 *111*
1 pc Rear bumper lower lip *dis*
1 pc Rear bumper sponge *NT*
4 pcs Rear bumper PDC sensor @\$217.30 *each*
1 pc Rear end panel *body*
1 pc Rear end panel garnish *111*
1 pc Spare tyre panel *11*
1 pc Exhaust muffler *11*
2 pcs Exhaust muffler bush @\$117.33 *11*

S/Nett Items

1 pc Rear no. plate with cover (S/Nett)

*Not Allowed
2/5 3
627.
4/5/18
Tele phone after 4pm*

SS	2,499.76	—
	434.60	<i>x</i>
	188.77	—
	120.17	—
	119.79	—
	380.79	<i>2</i>
	225.50	<i>x</i>
	60.00	<i>x</i>
	1,401.86	<i>x</i>
	190.75	—
	34.34	<i>x</i>
	1,601.94	<i>2</i>
	34.30	<i>x</i>
	1,900.93	—
	47.65	—
	649.70	<i>1</i>
	181.94	—
	175.98	<i>2</i>
	36.00	—
	299.76	—
	106.80	<i>x</i>
	869.20	<i>3 pcs</i>
	1,899.76	<i>2</i>
	200.93	<i>2</i>
	2,345.80	<i>x</i>
	1,970.97	<i>x</i>
	234.66	<i>x</i>
	18,212.65	—
	45.00	<i>x</i>
	18,257.65	—

5%

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Re: Estimated cost of repair to Audi A4 no: SDG1921B

Date of accident: 30-04-2018

Parts supply:

Balance b/f:

S\$ 18,257.65

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit rear reverse sensor.

To reset fault code after repair

To apply underseal

To check wirings.

1,200.00 1100

1,000.00 980

60.00 50

80.00 50

50.00 50

30.00 30

S\$ 20,677.65

2260

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9360B

Vehicle Details

Vehicle No.: SDG1921B
Vehicle to be Exported: No
Intended De-registration Date: 04 May 2018
Vehicle Make: AUDI
Vehicle Model: A4 1.8 TFSI MU (NAVIGATION & XENON)
Primary Colour: White
Manufacturing Year: 2013
Engine No.: CJE046562
Chassis No.: WAUZZZ8K7DA198211
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$36,146.00
Original Registration Date: 29 Apr 2013
First Registration Date: 29 Apr 2013
Transfer Count: 1
Actual ARF Paid: \$32,605.00 16302

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Apr 2023
PARF Rebate Amount: \$22,823.00

Intended COE Rebate Details

COE Expiry Date: 28 Apr 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$62,000.00
COE Rebate Amount: \$30,896.00
Total Rebate Amount: \$53,719.00

Message

Transfer of ownership or de-registration is not allowed for this vehicle.

The information contained herein is correct as at 04 May 2018

OK

sgCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum


Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Altis 1.6A.



\$2800 Down Payment Monthly From \$688 Onwards. Lowest 3.68%F.A&GV Cars Financing. GV Credit Pte Ltd - StarAd



click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category

Sort by Date Posted

20 results/page

15 vehicles

Audi A4

Advanced Search

Submit

Search Selection

</

Vic (LKKAuto)

From: Foo, Chityan <Chityan.Foo@aig.com>
Sent: Thursday, 15 August, 2019 3:06 PM
To: Vic (LKKAuto)
Cc: Admin A
Subject: OUR REF: 3617247048SG; LKK REF: CC6/AIG18008187/Uha3

Dear

We refer to your email dated 31.07.19

We seek your clarification on the replacement parts as follow:

- Boot Weatherstrip 80/119 - 81/119
- Boot Inner Lock 44/119
- TailLamps 104-105 - 108-109
- Rear Bumper Retainers 25-119 29-119
- Rear Bumper Brackets 83/119 99/119
- Rear End Panel Assy 100/119 - 101/119 - 114/119 - 115/119
- Rear End Panel Assy Garnish 77/119 - 78/119

Kindly let us hear from you before approval of mandate in merimen.

Kind regards,

Jimmy Foo
AIG
Complex Claims Examiner
AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1945 | Fax +(65) 6835 7416

Chityan.foo@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SDG1921B (3617247048SG)
[SKB9903U]**

TP
TAN YONG JUN
Apr 30 2018 7:00PM
[KHOO KAH BEE]
Chin Meng Motors

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 23/08/2019 14:37 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9747.45) - SDG1921B - Claim Handler: Foo, Chit Yan

Approved:9747.45:Subject to final repair bill, rental agreement and rental invoice.

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: CMM263/18/TP
Your Ref: TP claim against SJG5055D

4-Dec-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Accident Involving SDG1921B and SKB9903U on 30-04-2018 along AYE towards MCE

We refer to the above matter. The accident was caused solely by the negligence of your insured and as a result, our client had incurred the following cost and losses:-

Cost of Repair (Surveyed by your surveyor):	SS	8,900.00
Rental 07 days (6 days + 1 Sunday) @\$120.00 :		840.00
GIA search fee:		7.45
	SS	<u>9,747.45</u>

Enclosed are copies of following documents for your perusal:

- (X) Repair bill
- (X) Letter of authorisation
- (X) GIA report
- (X) Photocopy of driver's IC & DL
- (X) GIA search fee

CHIN MENG MOTORS





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18008187/Uha3

15th May 2018

KHOO KAH BEE

Block 267A Compassvale Link,
#16-77,
Singapore 541267.

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING SKB 9903U, SBF 99K AND SDG 1921B ALONG MCE ON 30.04.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Pohkin, Chong
Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)


I, TAN YONG JUN ("the third party claimant")
of 20 SIMEI ST 4 #07-45 (S) 528720 (address),
owner of SP619215 (vehicle no.) hereby authorize
CHIN MENA MOTORS
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SP619215 that was
damaged pursuant to the accident which occurred on 30/4/18 (date) along
AHE (location)
involving vehicle no/s SKB99034 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 4 day of 5 (month) 2018 (year)


Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, CHIN MENG MOTORS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 8,900.00 (repair costs), S\$ 840.00 (loss of ~~use~~/rental) S\$ 7.15 (search fees) for vehicle no. SDG 1921B that was damaged pursuant to the accident which occurred on 30/04/18 (date) along AME (location) involving vehicle no/s SKB 9903 U.

This is pursuant to the inspection conducted on 04/05/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN YONG JUN ("third party claimant") of vehicle no. SDG 1921B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SDG 1921B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 day of 05 (month) 20 19 (year)



CHS

Signed by AIG appointed surveyor

CHIN MENG MOTORS

[Signature]
Chopped & Signed by "the workshop"

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5016
cmmotors@singnet.com.sg

Our Ref: CMM263/18/TP
Your Ref: TP claim against SJG5055D

4-Dec-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Final cost of repair to Audi A4 no: SDG1921B
Date of accident: 30-04-2018

Total cost of repair and labour charge incurred for dismantling and replacement for parts of the above mentioned vehicle etc as recommended in nett as lump sum by surveyor.

Total lump sum: S\$ 8,900.00

Dollars: Eight thousand and nine hundred only.

CHIN MENG MOTORS





DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/000

No. 19324

Date.

2/5/18

OFFICIAL RECEIPT

Received from

Tan Yong Jun
Eight hundred forty only

the sum of Dollars

being Payment Of

SKH 4897 E (2/5/18 - 9/5/18)

DAWN ENTERPRISES

\$

840/7

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Chin Meng
SOG 19218

Nº 35646

RENTAL AGREEMENT

DATE

2/5/18

HIRER'S PARTICULARS

Name TAN YONG JUN
Address 21C SIMELI ST
07-49
S 528720
I/C or Passport No. 38729360B Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) 98509337 (Residence) _____

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry 2000 passengers only.
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$5,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

CHARGES

7 Day at \$ <u>120.00</u> per days	\$ <u>840.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	
TOTAL AMOUNT	\$ <u>840.00</u>
AMOUNT PAID	\$ <u>840.00</u>
BALANCE DUE	
Days Extension From _____ To _____	
Amount Deposit (refundable) \$	

SCHEDULE

MODEL

SKH A997E

T/A997E

Date	Time	Mileage
<u>2/5/18</u>		
<u>9/5/18</u>		

FROM

2/5/18

TO

9/5/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 02 May 2018 / 15:52:01

Receipt Date/Time : 02 May 2018 / 15:52:01

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180502-001593

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKB9903U				
As at 30 Apr 2018/19:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SKB9903U Enquiry Fee 20180502155042054423	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx0994	Credit Card: Visa/MasterCard		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2018 Edit Reg		04 May 2018 00:00 Edit Adj Rpt	S\$8,900.00 Edit Estimates	S\$8,900.00 View Rpt		Pending for Survey Report Cancel Case
























































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KHOO KAH BEE , ID: 56832294D								
Main Claimant:	TAN YONG JUN , ID: 58729360B								
Vehicle Reg. No.:	SDG1921B	Date of Loss:	30/04/2018 19:00 - :59 [60 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3617247048SG	Policy/Cover Note No.:	2100507276 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKB9903U	Policy No. (Claimant):	DMPPHQ17-005881						
	Excess:								
Repairer:	Chin Meng Motors (HQ) 1 Kaki Bukit Ave 6 #01-40/63, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 4810								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (23/08/2019): Alert - Adj Mandate Approved (S\$9747.45) - SDG1921B - Claim Handler: Foo, Chit Y... AIG_SG_EXPRESS (15/08/2019): Alert - Adj Mandate Maintained - SDG1921B - Claim Handler: Foo, Chit Yan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDG1921B (3617247048SG)
[SKB9903U]

TP
TAN YONG JUN
Apr 30 2018 7:00PM
[KHOO KAH BEE]
Chin Meng Motors

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit				
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
2	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
3	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
4	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
5	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
6	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
7	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
8	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
9	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
10	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
11	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
12	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
13	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
14	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
15	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
16	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
17	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
18	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
19	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
20	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
21	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
22	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
23	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
24	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
25	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
26	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
27	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
28	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
29	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
30	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
31	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
32	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
33	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
34	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
35	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
36	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
37	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
38	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
39	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			
40	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
60	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
61	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
62	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
63	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
64	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
65	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
66	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
67	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
68	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
69	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
70	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
71	04/12/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
72	04/12/18 07:40	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
73	04/12/18 07:40	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
74	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	04/12/18 07:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
100	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
103	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
104	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
105	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
106	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
107	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
109	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
110	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
111	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
112	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
113	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
114	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
115	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
116	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
117	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
118	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
119	04/12/18 07:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/05/18 00:04	TP ESTIMATE - MARKED		Load PDF	
2	15/05/18 00:04	TP GIA REPORT		Load PDF	
3	15/05/18 17:14	LETTER TO OI		Load PDF	
4	26/07/19 09:29	RENTAL RECEIPT		Load PDF	
5	26/07/19 09:29	LTA SEARCH		Load PDF	
6	16/09/19 08:54	WORKSHOP INVOICE		Load PDF	
7	16/09/19 08:54	AUTHORISATION TO ACT FORM		Load PDF	
8	16/09/19 08:54	Release Voucher		Load PDF	
9	16/09/19 08:54	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/05/18 10:08	OI GIA REPORT		Load PDF	
2	09/05/18 12:35	E-filed GIA report SBF99K		Load PDF	
3	09/05/18 12:35	E-filed GIA report SDG1921B		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKB9903U (Insd veh)	Model:	AUDI A4 1.8 (A)
	SDG1921B (TP veh)		
Date of Accident:	30/04/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	20,677.65
Final Repair Cost	:	\$	8,900.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	840.00 7 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	9,747.45
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Chin Meng Motors	:	\$ 9,747.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

16 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008187/UHA3Q2

Date: 16/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507276
Claimant
Vehicle No : SDG1921B **Insured Vehicle No :** SKB9903U
Date of Loss: 30/04/2018 **Nature of Claim:** TP **Claim No:** 3617247048SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDG1921B
Make & Model: AUDI A4, 1.8 (A) **Engine No:** CJE046562
Reg. Date: 29/04/2013 (Man. Year: 2013) **Chassis No:** WAUZZZ8K7DA198211
Colour: White **Odometer:** 117377 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 255/35Z R19 **Rear Tyre Size:** 255/35Z R19
Front Left Side: Nexen 6 mm **Rear Left Side:** Nexen 6 mm
Front Right Side: Nexen 6 mm **Rear Right Side:** Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,257.65	8,912.08	9,345.57	51.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	2,260.00	160.00	6.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,677.65	11,172.08	9,505.57	45.97
Approved Total (Overridden) (S\$)		8,900.00		
Nett Amount (S\$)	20,677.65	8,900.00	11,777.65	56.96
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,747.45		

INSPECTION

Date of Assignment: 04/05/2018
Date Inspected: 04/05/2018 **Inspected At:** Chin Meng Motors (HQ)
 1 Kaki Bukit Ave 6 #01-40/63, Autobay
 @ Kaki Bukit
 Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	2,499.76 F	*1,937.90 FL
2	2		*BOOT HINGES	Not Necessary	434.60 F	*- FL
3	1		*BOOT EMBLEM -LOGO	Necessary	188.77 F	*108.15 FL
4	1		*BOOT EMBLEM -1.8T	Necessary	120.17 F	*105.32 FL
5	1		*BOOT EMBLEM -A4	Necessary	119.79 F	*85.80 FL
6	1		*BOOT WEATHERSTRIP	Twisted / Necessary	380.79 F	*380.79 FL
7	1		*BOOT INSULATOR	Not Necessary	225.50 F	*- FL
8	12		*BOOT INSULATOR CLIPS	Not Necessary	60.00 F	*- FL
9	2		*BOOT LAMPS	Not Necessary	1,401.86 F	*- FL
10	1		*BOOT INNER LOCK	Twisted	190.75 F	*190.75 FL
11	2		*BOOT STOPPERS	Not Necessary	34.34 F	*- FL
12	2		*TAILLAMPS	Cracked	1,601.94 F	*1,601.94 FL
13	2		*TAILLAMP CLIPS	Not Necessary	34.30 F	*- FL
14	1		*REAR BUMPER	Distorted	1,900.93 F	*1,633.40 FL
15	1		*REAR BUMPER TOW COVER	Torn	47.65 F	*47.65 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	649.70 F	*567.53 FL
17	2		*REAR BUMPER RETAINERS	Bent	181.94 F	*181.94 FL
18	2		*REAR BUMPER BRACKETS	Bent	175.98 F	*175.98 FL
19	8		*REAR BUMPER CLIPS	Necessary	36.00 F	*36.00 FL
20	1		*REAR BUMPER LOWER LIP	Distorted	299.76 F	*299.76 FL
21	1		*REAR BUMPER SPONGE	Not fitted	106.80 F	*- FL
22	4		*REAR BUMPER PDC SENSOR	Shorted (3 PCS ONLY)	869.20 F	*555.00 FL
23	1		*REAR END PANEL ASSY	Badly Dented	1,899.76 F	*1,272.30 FL
24	1		*REAR END PANEL ASSY GARNISH	Twisted	200.93 F	*200.93 FL
25	1		*SPARE TYRE PANEL	Repair	2,345.80 F	*- FL
26	1		*EXHAUST MUFFLER	Repair	1,970.97 F	*- FL
27	2		*EXHAUST MUFFLER BUSH	Not Necessary	234.66 F	*- FL
28	1		*REAR NO.PLATE WITH COVER	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,257.65	9,381.14
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	469.06
Total Parts (\$\$)	18,257.65	8,912.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	1,200.00	1,100.00
2	TO RESPRAY AFFECTED PART	New	1,000.00	980.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	60.00	50.00
4	TO RESET FAULT CODE AFTER REPAIR	New	80.00	50.00
5	TO APPLY UNDERSEAL	New	50.00	50.00
6	TO CHECK WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			2,420.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >