

22/05/2019

ASS. REC. BY:

REF: CS/MSK/3008192/KTB12

Special Instructions:

Survey: Kenneth

ASSIGNMENT (Office)

From (Person): Lionel Tan

of MS16

Date/Time: 4th May 2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 5790L

Insured: SJX 88415

at Workshop m/s Autowork House

Tel:

of Sin Ming Drive #02-01

Policy No: A27932184MCY

Claim No: 557296

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction
	Johny ( )
12/11/19	11 Pm 8400pl email confirm (Red: 10503.61 : 72%)
10:08am	check with dennis days of repair is 5 days.

Driver:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 24 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKR 5770C Yr Regn: 02 15Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perodua Fluena c.c. 1461Colour: Black A/C: Insured / Std / NI / NASp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF1L7LF0E 52015760Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrakes: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

R/Bal. 7 mm

Rear

R/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 30/4/18D.O.I. 7/5/18Survey held at ✓Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 NOV 2019

Data/Time, File Pass to?

15/11/2019

Data/Time, File Return to?

2



Prell. Report



Final Report

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inva (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

\$ - RS - \$

Photos

Others

TOTAL

200

11

211

Report Format: TPLump Sum / I.B.I. (\$ 4000/-)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Assigned	Status
Main	03 May 2018		04 May 2018 10:16 <a href="#">Edit Adj Rpt</a>		Last:IA 10 May 2018 14:35		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>HEXABUILD PTE LTD</b> , Co. Reg. No.: 199804397M, Tel: +6590116588								
Main Claimant:	<b>BLJQ</b> , Co. Reg. No.: 53340562M								
Vehicle Reg. No.:	<b>SKR5770C</b>	Date of Loss:	30/04/2018 16:00 - :59 [38 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 557296</b>	Policy/Cover Note No.:	A27932184MCY (Comprehensive) Coverage: 20/07/2017 - 19/07/2018						
Vehicle Reg. No. (Insured):	<b>SJX8841S</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Autoworx House - Sin Ming (HQ)</b> 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Lionel Tan Tian Pel</b> - 6643 1307]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 03/06/2018]								
Driver/Custodian (Insured):	NARAYANASWAMY MURALITHARAN (42 / Male) , NRIC: S7565253D Email:								
Adj Asg. Remarks:	Please appoint LKK AUTO CONSULTANTS PTE LTD to conduct the survey. Kindly contact the workshop directly @ 6452 8211								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/05/2018 12:50
Date Of Accident	30/04/2018 17:45
Exact Location Of Accident	HOUGANG AVE 2 TOWARDS HOUGANG AVE 3(LAMP POST 72)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKR5770C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BLJQ
Co Reg No	53340562M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81305000
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	FLUENCE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093692557
Cover Note Number	
<b>Driver</b>	
Name of Driver	LONG JIQIANG, BENJAMIN
NRIC No	S8117199H
Date Of Birth	13/06/1981
Occupation	OUTDOOR
Date Of Driving Pass	18/09/2000
Driving Experience	17 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81305000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 533 SERANGOON NORTH AVENUE 4 #03-227
Postcode	550533
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX8841S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NARAYANASWAMY MURALITHARAN
NRIC/Passport Number	S7565253D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
 Policyholder's Signature  
 Date & Time:



  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Hougang Ave 2 on the 2nd lane from left. Upon reached the traffic junction of Hougang Ave 2 & Hougang Ave 8, I stopped at the red lights. After stopped for some time, vehicle B, 53X 8841J collided into the rear of my vehicle with a hard impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 2nd May 18

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 2nd May 18

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

BLJQ

c/o 46 Lenton Plain  
Singapore 786548

*Not Authorized*  
*61 Lp 84000*  
*Missing After Rain 5 days*

Date: 04/05/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE: RENAULT FLUENCE / SKR 5770 C</b>		
1 pc	rear bumper	836.70
2 pcs	rear bumper side retainer	197.50
2 pcs	rear bumper reflector	@ 185.30 370.60
1 pc	rear bumper lower pad	466.30
1 pc	rear bumper tow cover	287.30
1 pc	rear bumper centre moulding	274.00
2 pcs	rear bumper corner bracket	@ 98.20 196.40
1 pc	rear parking sensor	@ 369.40 1,477.60
1 pc	rear boot lid	1,664.00
2 pcs	rear boot lamp	@ 597.30 1,194.60
1 pc	rear boot lock	244.00
1 pc	rear boot lock catch	76.00
1 pc	rear boot lock sensor	309.00
1 pc	rear boot weatherstrip	187.00
1 pc	rear boot emblem 'FLUENCE'	148.70
1 pc	rear boot emblem LOGO	159.00
1 pc	rear end panel	487.50
1 pc	rear end panel garnish	309.70
2 pcs	rear tail lamp assy	@ 647.10 1,294.20
1 pc	rear exhaust silencer	1,884.00
Sub-total		12,064.10
Less 10%		1,206.41
Sub-total		10,857.69
1 set	number plate	s.nett 45.00
Sub-total		10,902.69



Balance carried forward.	10,902.69
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<sup>400</sup> ? 1,000.00
To check wiring system.	200 50.00
To spray painting on affected areas.	660 1,100.00
To apply rust proofing on affected areas.	200 150.00 <sup>300</sup>
To apply waterproof sealant on affected areas.	200 150.00
<b>Total</b>	<b>13,352.69</b>
	14503.61

# AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 64520715 FAX: 64529250

## ESTIMATE

BLJQ  
c/o 46 Lenton Plain  
Singapore 786548

Date: 7/6/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b>RE: Supplementary for Renault Fluence / SKR5770C</b>	
1 pc	Rear bumper reinforcement <i>580.00</i>	<i>CM</i> 796.00 ✓
1 pc	Rear bumper top pad retainer	<i>SM</i> 458.00 X
4 pc	Rear bumper top pad rivet @ 6.20	<i>na</i> 24.80 ✓
	sub-total	1,278.80
	less 10%	127.88
	Total	1,150.92

# AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 64520715 FAX: 64529250

## ESTIMATE

BLJQ  
c/o 46 Lenton Plain  
Singapore 786548

Date: 7/6/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b><u>RE: Supplementary for Renault Fluence / SKR5770C</u></b>	
1 pc	Rear bumper reinforcement	796.00
1 pc	Rear bumper top pad retainer	458.00
4 pc	Rear bumper top pad rivet @ 6.20	24.80
	sub-total	1,278.80
	less 10%	127.88
	Total	<u>1,150.92</u>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008192/KTBN2

Date: 20/11/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27932184MCY
Claimant Vehicle No :	SKR5770C	Insured Vehicle No :	SJX8841S
Date of Loss:	30/04/2018	Nature of Claim:	TP
		Claim No:	557296

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKR5770C	Engine No:	K9KN837D173665
Make & Model:	RENAULT FLUENCE, 1.5 D T dCi (A)	Chassis No:	VF1LZLF0E52015760
Reg. Date:	16/02/2015 (Man. Year: 2014)	Odometer:	0 km
Colour:	Beige		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,053.61	3,988.39	8,065.22	66.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,130.00	1,320.00	53.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,503.61</b>	<b>5,118.39</b>	<b>9,385.22</b>	<b>64.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,503.61</b>	<b>4,000.00</b>	<b>10,503.61</b>	<b>72.42</b>

## INSPECTION

Date of Assignment:	04/05/2018		
Date Inspected:	07/05/2018	Inspected At:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2019)
<b>Parts:</b>	143	RENAULT FLUENCE 1.5 D T dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKR5770C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	836.70 FL	*836.70 FL
2	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	197.50 FL	*98.75 FL
3	1		*REAR BUMPER REFLECTOR	N/s Scratched	370.60 FL	*185.30 FL
4	1		*REAR BUMPER LOWER PAD	Dented/Cut	466.30 FL	*466.30 FL
5	1		*REAR BUMPER TOW COVER	Serviceable	287.30 FL	*- FL
6	1		*REAR BUMPER CENTRE MOULDING	No such part	274.00 FL	*- FL
7	2		*REAR BUMPER CORNER BRACKET	Repair	196.40 FL	*- FL
8	1		*REAR PARKING SENSOR (4 Pcs)	Scratched (1 Pc only)	1,477.60 FL	*268.00 FL
9	1		*REAR BOOT LID	Bent	1,664.00 FL	*1,664.00 FL
10	2		*REAR BOOT LAMP	Serviceable	1,194.60 FL	*- FL
11	1		*REAR BOOT LOCK	Repair	244.00 FL	*- FL
12	1		*REAR BOOT LOCK CATCH	Repair	76.00 FL	*- FL
13	1		*REAR BOOT LOCK SENSOR	Serviceable	309.00 FL	*- FL
14	1		*REAR BOOT WEATHERSTRIP	Serviceable	187.00 FL	*- FL
15	1		*REAR BOOT EMBLEM FLUENCE	Necessary	148.70 FL	*148.70 FL
16	1		*REAR BOOT EMBLEM LOGO	Necessary	159.00 FL	*159.00 FL
17	1		*REAR END PANEL	Repair	487.50 FL	*- FL
18	1		*REAR END PANEL GARNISH	Serviceable	309.70 FL	*- FL
19	2		*REAR TAIL LAMP ASSY	Serviceable	1,294.20 FL	*- FL
20	1		*REAR EXHAUST SILENCER	Repair	1,884.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Cracked	796.00 FL	*580.00 FL
22	1		*REAR BUMPER TOP PAD RETAINER	Serviceable	458.00 FL	*- FL
23	4		*REAR BUMPER TOP PAD RIVET	Necessary	24.80 FL	*24.80 FL
24	1		*SET NUMBER PLATE	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>13,387.90</b>	<b>4,431.55</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>1,334.29</b>	<b>443.16</b>
<b>Total Parts (S\$)</b>	<b>12,053.61</b>	<b>3,988.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	1,000.00	400.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	660.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	30.00
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>2,450.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >