

ASS. REC. BY:

REF: C83 / CIL18008193 / K12462 Special Instruction:

SUPERVISOR

Mellman

ASSIGNMENT (Office)

From (Person): Chong Soon Sen of CIL Date/Time: 04052018 9:10am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G8G 9315Y Insured: SGJ 7024A

at Workshop m/s: DAS Auto Tel: 9857 9525

of 3018A Ubi Rd 1 #01-23

Policy No: DMPCSN3055771700 Claim No: 9NM18D02150C02

Sum Insured: Excess:

Make of Veh: D.O.A. 21042018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpr

Date/Time: 04052018 1034am Person Contacted: Mr. (noh) H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	G8G 9315Y - x
	SGJ 7024A - x
	Dismantle Part: 07052018

PRS

REF: CTL

SPECIALIST

MURKIN

ASSIGNMENT

From:

Date: 04/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

ABG 9315Y

at Workshop m/s

QAS Auto

of

3018A Ubi Rd 1 #01-23

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G B 9315Y

Yr Regn: 29 Nov 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace Van

C.C. 29SL

Colour:

White/Red

A/C: Ins: Std / NI / NA

Sp. Reading:

11149

T/Radio: Ins: Std / NI / NA

Eng/No:

C/No:

JTFHT02P30023K21

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inord / Jammed / Leaked / Burnt or

Brake: Inord / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15C

R:

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

26/4/18

D.O.I:

4/5/18 1742

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$6-7K

8 hrs.

11/5/18 Submit PRS Report

RECEIVED 14 MAY 2018

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

150

150

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018		04 May 2018 09:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AWALLUDDIN BIN KADIR, ID: S6835682B		
Main Claimant:	UKA LEASING PTE LTD, Co. Reg. No.: 201105072Z		
Vehicle Reg. No.:	GBG9315Y	Date of Loss:	26/04/2018 08:00 - :59
Claim Type:	TP / SNM18D02150C02	Policy/Cover Note No.:	DMPCSN3055771700 (Comprehensive)
Vehicle Reg. No. (Insured):	SGJ7024A	Policy No. (Claimant):	5083353963-02
		Excess:	S\$0.00
Repairer:	QAS AUTO PTE LTD (HQ) 3018A Ubi Road 1, #01-23, 408711 Ubi - Tel: 98579525		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]		
Driver/Custodian (Insured):	HUZAINAH BINTE HUSSAIN (46 / Female), NRIC: S7147914E, Tel: +6591692521		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018		04 May 2018 09:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AWALLUDDIN BIN KADIR , ID: S6835682B								
Main Claimant:	UKA LEASING PTE LTD , Co. Reg. No.: 201105072Z								
Vehicle Reg. No.:	GBG9315Y	Date of Loss:	26/04/2018 08:00 - :59 [4 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02150C02	Policy/Cover Note No.:	DMPCSN3055771700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGJ7024A	Policy No. (Claimant):	5083353963-02						
		Excess:	S\$0.00						
Repairer:	QAS AUTO PTE LTD (HQ) 3018A Ubi Road 1, #01-23, 408711 Ubi - Tel: 98579525								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 15/05/2018]								
Driver/Custodian (Insured):	HUZAINAH BINTE HUSSAIN (46 / Female), NRIC: S7147914E, Tel: +6591692521								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG9315Y (SNM18D02150C02)
[SGJ7024A]
TP
UKA LEASING PTE LTD
Apr 26 2018 8:00AM
[AWALLUDDIN BIN KADIR]
QAS AUTO PTE LTD

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:12	Accident Statement	Load HTM	☐

Photos/Images			3 per page	☒
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	27/04/18 10:11	Accident Photo [Linked Accident Report Documents]	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/05/18 09:10	PRS	Load PDF	☐
2	04/05/18 09:10	OI GIA REPORT	Load PDF	☐

No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:11	Sketch Plan [Linked Accident Report Documents]	Load TIF	☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/18 12:03	LKKPhotosIn6-1	Load PDF	☐
2	11/05/18 11:26	LKKPhotosIn6-2.pdf	Load PDF	☐

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:12	Accident Statement	Load HTM	☐

Photos/Images			3 per page	☒
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:11	Accident Photo	Load JPG	☒
2	27/04/18 10:11	Accident Photo	Load JPG	☒
3	27/04/18 10:11	Accident Photo	Load JPG	☒
4	27/04/18 10:11	Accident Photo	Load JPG	☒
5	27/04/18 10:11	Accident Photo	Load JPG	☐

Assessment Reports			1 per page	☒
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
				☒
6	27/04/18 10:11	Accident Photo	 Load JPG	☒
7	27/04/18 10:11	Accident Photo	 Load JPG	☒
8	27/04/18 10:11	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:11	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18008193/K1Z4BE2

Date: 15/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3055771700

Claimant Vehicle
No: GBG9315YInsured Vehicle
No: SGJ7024A

Date of Loss: 26/04/2018

Nature of Claim: TP

Claim
No: SNM18D02150C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG9315Y**
 Make & Model: TOYOTA HIACE, 3.0 (A)
 Reg. Date: 29/11/2017 (Man. Year: 2017)
 Colour: White/Red
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2753131
 Chassis No: JTFHT02P300234211
 Odometer: 11149 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/05/2018

Date Inspected: 04/05/2018

Inspected At:

QAS AUTO PTE LTD (HQ)
 3018A Ubi Road 1, #01-23
 Singapore 408711

Estimated Period of Repair: 8.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 May 2018)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9315Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >