

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0524/2018/GW
Date : 4-May-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. SJK 3168 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr . Bangi Balasaheb Abhay
Address : 130 Tanjong Rhu Road
Singapore 436918

Telephone : (HP) 96608949
Type of Claim : Own Damage Claims
Policy No. : 2100482804-01
Vehicle No : **SJK 3168 D**
Model Code : Audi A6 1.8 TFSI S- T
Model / Year :
Engine No :
Chassis No :
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Apr-18
Place of Accident : Leburaya Utara-Selatan KM417

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3168 D.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00	?
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 6,300.00	1750.
4	To respray front bumper, both front fenders and bonnet. ✓ (LH only).	\$ 3,400.00	1650
TOTAL LABOUR CHARGES - FRONT		: \$ 11,380.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER <i>Dislodged</i>	\$ 2,650.00	✓
2	FRONT BUMPER GRILLE <i>crushed</i>	\$ 112.00	✓
3	FRONT BUMPER FIXING PARTS ?	\$ 464.00	?
4	FRONT BUMPER COVER MOUNT KIT ?	\$ 43.00	?
5	FRONT BUMPER SECURING STRIP <i>MC</i>	2 \$ 12.00	+
6	FRONT BUMPER ADAPTER-LH/RH <i>MC</i>	2 \$ 64.00	+
7	FRONT BUMPER CLOSING ELEMENT <i>MC</i>	\$ 188.00	+
8	FRONT BUMPER SPOILER <i>del</i>	\$ 817.00	✓
9	RADIATOR GRILLE <i>crushed</i>	\$ 1,697.00	✓
10	RADIATOR GRILLE COVER <i>del</i>	\$ 32.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>LH missing</i>	2 \$ 868.00 434.	
12	FRONT BUMPER COVER -LH/RH <i>del</i>	2 \$ 88.00 44.	
13	FOAM FILLER PIECE ?	\$ 203.00	?
14	FRONT BUMPER SIDE REINFORCEMENT ?	\$ 702.00	?
15	FRONT BUMPER HOLDER BRACKET-LH/RH ?	\$ 446.00	?
16	FRONT BUMPER SUPPORT-LH/RH ?	2 \$ 21.00	?
17	FRONT BUMPER GUIDE PIECE-LH/RH <i>MC</i>	2 \$ 64.00	+
18	FRONT BUMPER BRACE-LH/RH <i>MC</i>	2 \$ 50.00	+
19	FRONT BUMPER COVER <i>del</i>	\$ 105.00	+
20	SIGN "CAUTION" <i>MC</i>	\$ 12.00	✓
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		\$ 8,638.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Pa	
		S/NETT	RE
21	FRONT PARKING AID - OUTER ?	2 \$	421.00 ?
22	FRONT PARKING AID - INNER <i>Not in</i>	2 \$	392.00 x
23	FRONT SUPPORT PARKING AID-LH ?	\$	59.00 +
24	FRONT SUPPORT PARKING AID-RH ?	\$	59.00 x
25	FRONT FENDER-LH <i>Buckled</i>	\$	1,220.00 ✓
26	FRONT FENDER ATTACHMENT PARTS-LH ?	\$	88.00 ?
27	FRONT FENDER STONE GUARD FILM-LH <i>in</i>	\$	105.00 ✓
28	FRONT FENDER BRACE-LH/RH ?	2 \$	144.00 ?
29	FRONT WHEEL HOUSING LINER-LH	\$	246.00 +
30	WHEEL HOUSING LINER ATTACHMENT PARTS } <i>in</i>	\$	62.00 +
31	FRONT WHEEL SPOILER-LH/RH	2 \$	464.00 +
32	LED HEADLIGHT-LH/RH <i>LH cracked</i>	2 \$	16,772.00 8386
33	POWER MODULE FOR DAY DRIVING LIGHTS ?	\$	501.00 ?
34	POWER MODULE FOR DIPPED BEAM ?	\$	486.00 ?
35	HEADLAPMS FAN-LH ?	\$	345.00 ?
36	HOSE-LH <i>in</i>	\$	37.00 x
37	HEADLAMPS ASSEMBLY ADJUSTMENT <i>in</i>	\$	40.00 x.
38	LIFT CYLINDER-LH ?	\$	208.00
39	COVER CAP-LH/RH <i>LH Deformed</i>	2 \$	98.00 49.
40	BONNET <i>Deformed</i>	\$	4,771.00 ✓
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		<u>\$ 26,518.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Pa	
		S/NETT	RE
41	BONNET ATTACHMENT PARTS ?	\$	153.00?
42	BONNET CATCH HOOK	\$	122.00 X
42	BONNET LOCK BAR-LH/RH } <i>new</i>	\$	87.00 X
43	BONNET LATCH HOOK	\$	15.00 X
44	LID LOCK -LH/RH <i>new</i>	2 \$	376.00 X
45	AIR CONDITIONER STICKER <i>new</i>	\$	17.00 ✓
46	HEADLIGHT MOUNTING ?	2 \$	206.00 ?
47	RADIATOR MOUNTING LOCK CARRIER ?	\$	1,024.00?
48	AIR GUIDE-LH/RH ?	2 \$	48.00 ?
49	CHARGE AIR COOLER <i>new</i>	\$	492.00 X
50	A/C CONDENSER <i>new</i>	\$	683.00 X
51	COOLER FOR COOLANT <i>new</i>	\$	752.00 X
52	RUBBER BUSH-CENTER	2 \$	12.00 X
53	RUBBER BUSH -UPPER	2 \$	17.00 X
54	RUBBER BUSH -LOWER	2 \$	23.00 X
55	COOLANT CONCENTRATE	4 \$	133.00 X
56	COOLANT REGULATOR SUPPORT	\$	64.00 X
57	REFRIGERANT PIPE	\$	223.00 X
58	FRONT NO. PLATE <i>Best</i>	\$	25.00 ✓
TOTAL SPARE PARTS CHARGES - FRONT		\$	39,628.00
TOTAL LABOUR CHARGES - FRONT		\$	11,380.00
GRAND TOTAL - FRONT		\$	51,008.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3168 D.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according damage.	S/N \$ 280.00 ✓
2	To remove and transfer lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ✓
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner rear cross panel and connecting plates. Renew rear bumper and rear lid, align to position. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,200.00 2500.
5	To respray rear bumper, rear lid, hinges and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,700.00 1650
7	To carry out diagnostic check.	S/N \$ 384.00 ✓ 192
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ <u><u>8,324.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Distorted.</i>	\$ 2,519.00	✓
2	REAR BUMPER FIXING PARTS <i>?</i>	\$ 234.00	?
3	REAR BUMPER SPOILER <i>Distorted</i>	\$ 416.00	✓
4	REAR BUMPER SECURING <i>Distorted</i>	\$ 191.00	✓
5	REAR BUMPER CLOSING ELEMENT-LH/RH <i>?</i>	\$ 138.00	?
6	REAR BUMPER SENSOR <i>new</i>	4 \$ 842.00	+
7	EXHAUST TAIL PIPE TRIM-LH/RH <i>lit missing</i>	2 \$ 994.00 497.	
8	REAR BUMPER CARRIER <i>?</i>	\$ 851.00	?
9	REAR BUMPER IMPACT BAR GASKET-LH/RH <i>new</i>	2 \$ 24.00	✓
10	REAR BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 56.00	+
11	REAR BUMPER CONNECTING PIECE <i>new</i>	2 \$ 21.00	+
12	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 92.00	+
13	REAR BUMPER GUIDE PROFILE-LH/RH <i>?</i>	2 \$ 114.00	?
14	REAR BUMPER GUIDE SECTION-CENTRE <i>?</i>	\$ 91.00	?
15	REAR BUMPER HOLDING STRAP-LH/RH <i>?</i>	2 \$ 108.00	?
16	REAR BUMPER WIRING <i>new</i>	\$ 603.00	+
17	REAR LID <i>Dented</i>	\$ 2,485.00	✓
18	REAR LID BRACKET <i>new</i>	\$ 30.00	✓
19	REAR LID ATTACHEMENT PARTS <i>?</i>	\$ 93.00	?
20	REAR LID PUSH BUTTON <i>new</i>	\$ 1,181.00	+
SUB-TOTAL SPARE PARTS		\$ 11,083.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR GASKET FLAP <i>new</i>	\$ 181.00	✓
22	REAR LID MOTOR STRIKER PLATE <i>new</i>	\$ 550.00	X.
23	REAR LID LOCK <i>new</i>	\$ 170.00	✓
24	ADHESIVE PACKING <i>2</i>	\$ 15.00	✓
25	AUDI EMBLEM	\$ 108.00	✓
26	INSCRIPTION " A6 "	\$ 83.00	✓
27	INSCRIPTION " TFSI "	\$ 83.00	✓
28	REAR LID DECORATIVE TRIM <i>new</i>	\$ 317.00	✓
29	BOOT LID CONTROL UNIT <i>new</i>	\$ 372.00	X.
30	TAILGATE SENSOR LINE ?	\$ 184.00	?
31	CABLE TERMINAL <i>new</i>	6 \$ 39.00	X.
32	REAR CROSS PANEL <i>Dented</i>	\$ 274.00	✓
33	REAR CROSS PANEL REINFORCEMNT <i>Dented</i>	\$ 639.00	✓
34	REAR CONNECTIN PLATE -LH/RH ?	2 \$ 78.00	?
35	REAR NO. PLATE <i>Bent</i>	S/N \$ 25.00	✓
36	ACRYLIC SEALER <i>2</i>	S/N \$ 180.00	?
37	CAVITY WAX <i>?</i>	S/N \$ 140.00	?
38	STONE CHIP <i>?</i>	S/N \$ 180.00	?
39	SUNDRIES ?	\$ 600.00	?
TOTAL PARTS FRT/REAR		: \$ 15,301.00	
TOTAL LABOUR FRT/REAR		\$ 8,324.00	
GRAND TOTAL :		\$ 23,625.00	
TOTAL PARTS / LABOUR FRONT		\$ 51,008.00	
GRAND TOTAL FOR FRONT & REAR		\$ 74,633.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 04/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 15 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant