

INS. REC. BY: Adrian Ling

REF:

CC3 / ALH18008198 / Avber

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ **QD** TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100 482804 - 01

Claims No. _____

Sum Insured: _____ Excess: 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 15512

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 hrs. days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJK3168D Yr Regn: 2016, Sept

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 cc 1798

Colour: Black A/C: ☒ Insured / Std / NI / NA

Sp. Reading: 16264 T/Radio: ☒ Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ4G2HNO31027

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 30/4/18 D.O.I. 04/05/18

Survey held at Premium

Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TX 07A14</u>
<u>7/5/18</u>	<u>Revert by merimen</u>
<u>8/5/18</u>	<u>Recd approved \$37,520 from Victor by merimen</u>
<u>8/5/18</u>	<u>Informed Grant c/A ex \$800 by email</u>
<u>20/8/18</u>	<u>Final fig \$37,325.84 confirmed by email (Ref 38,757.16, 5190)</u>
RECEIVED 21 SEP 2018	

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2) 20/9 - typist

Report Format: merimen

Lump Sum / I.B.I. (\$) 37,325.84

Days Of Repair: 15

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation: \$ + RS \$

Photos

Others

TOTAL

200

10

210

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 8 May 2018 11:50 AM
To: 'Claims'; SUR
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear Grant,

As instructed by our client , please proceed to repair the insured vehicle **SJK 3168D (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 8 May 2018 9:58 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Good morning all,

Attachment with owner towing receipt to claim refer AIG insurance.
Owner have intention to claim his oversea towing bill.
Please assist and follow up with owner directly.

Kindly advice for authorize approval also.

Thanks.

Best Regards,
Grant Chong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Monday, 7 May 2018 9:32 AM

To: Claims Dept; SUR

Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear Jeffery,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]

Sent: Friday, 4 May 2018 1:33 PM

To: SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear all,

Kindly assist in the Own Damage Claims for the above mentioned vehicle.

Survey was carried out earlier this.

Many thanks!

Best regards,

Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199901271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SJK3168D (9735912051SG)**

OD

Apr 30 2018 3:00PM

[BANGI BALASAHEB ABHAY]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/05/2018 11:40 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$37520.00) - SJK3168D - Claim Handler: Tr, Tinesh

Approved:37520.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16 Singapore 079120	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Dally Amri, Mimi Zarina	Date:	07 May 2018

Preliminary Advice

Vehicle No	: SJK3168D	Accident Date	: 30/04/2018
Make	: AUDI A6	Policy No.	: 2100482804-01
Assignment Date	: 04/05/2018	Excess	: S\$0.00
Date of Inspection	: 04/05/2018	Est. Duration of Repair	: 15.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	74,633.00
Revised Amount	:S\$	37,520.00
Check Items (Estimated)	:S\$	9,694.00
Total	:S\$	47,214.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	80,329.00
Salvage Value	:S\$	
Margin for Repair	:S\$	74,671.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3983I
Vehicle Details	
Vehicle No.:	SJK3168D
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CYG016132
Chassis No.:	WAUZZZ4G2HN031027
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$40,385.00
Original Registration Date:	19 Sep 2016
First Registration Date:	19 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$43,539.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2026
PARF Rebate Amount:	\$32,654.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$47,675.00
Total Rebate Amount:	\$80,329.00

The information contained herein is correct as at 07 May 2018

OK

Text size + -

**Register New Vehicle (Acknowledgement)****Vehicle Particulars**

Vehicle No.	SJK3168D		
Vehicle Type	P10 - Passenger Motor Car	Vehicle Scheme	Normal
Vehicle Attachment 1	No Attachment		
Vehicle Attachment 2	-	Vehicle Attachment 3	-
Vehicle Make	AUDI	Vehicle Model	A6 1.8 TFSI ULTRA (PI) (NAV)
Chassis No	WAUZZZ4G2HN031027	Engine No	CYG016132
Motor No	-	Trailer Chassis No	-
Propellant	Petrol	Passenger Capacity	4
Engine Capacity	1798 cc	Power Rating	-
Maximum Power Output: 140.0 kW (187 bhp)			
Unladen Weight	1645 kg	Maximum Laden Weight	2150 kg
Primary Colour	Black	Secondary Colour	-
First Registration Date	19 Sep 2016	Original Registration Date	19 Sep 2016
Manufacturing Year	2016	Open Market Value	\$40,385.00
PARF Eligibility	Yes	Minimum PARF Benefit	\$21,769.00
No. of Transfers	0	Additional Registration Fee Rate	First \$20,000.00 (100%), next \$20,385.00 (140%)
Actual ARF Paid	\$43,539.00		

Owner Particulars

Owner Name	BANGI BALASAHEB ABHAY
Owner ID Type	Singapore NRIC
Owner ID	S8083983I
Registered Address Type	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.	68
Registered Street Name	MARINE PARADE ROAD
Registered Unit No.	# 06 - 19
Registered Building Name	-
Registered Postal Code	449301
COE No. / Expiry Date	2016100103001012M / 18 Sep 2026
COE Bid Category	B - Car (above 1600cc or 97kW (130bhp))
QP Paid	\$57,002.00

Transaction Details

Business Transaction Ref. No.	20160919151543324159
Business Transaction Date	19 Sep 2016
Business Transaction Time	15:15:43

Message

63386200
AIG 24hr assist.



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR - PRIVATE VEHICLE

Name of Policyholder : BANGI BALASABEB ABHAY
Period of Insurance : 18 Sep 2017 To 18 Sep 2018
Engine No. : CYG016132
Chassis No. : WAUZZZ4G2HN031027

Vehicle No. : SJK3168D
Policy No. : 2100482804-01
Endorsement No. :
Issued Date : 28 Aug 2017

ABOUT THE COVER

Make/Model	AUDI A5 1.8 TFSI ULTRA			First Year of Registration	2016
Engine Capacity/Tonnage	1.788.00 CC	Sum Insured	Market Value	Insuring with CNEIPARF	Yes
Driver Restriction	NA	Off Peak Cover	No		

Person or Classes of Persons Entitled to Drive*

a. The Policyholder
b. Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$5,000 as "Unauthorized Driver Excess" (UDRE) if you are an Unauthorized Driver (named or unnamed) who has less than 2 years driving experience.

Age Condition : 35 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, game driving, industry trial or speed-testing. The carriage of goods other than vehicles in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Indemnity is subject to the provisions of Section 8 of the Motor Vehicles (Third Party Risk and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia). It is not to be included under these headings.

EXCESS

Section 1 :
Fire - \$0; Own Damage - \$500; Theft - \$0; Flood Cover - \$0

Section 2 :
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

BANGI BALASABEB ABHAY - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. AIG Customer Service Centre: Tel: 65 (6) 6338 6200 (Singapore) 404555 63382175

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 9728 6700. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile app. Entry search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Where Purchase Company/Employer's Loan: DBS BANK LTD

* This policy is subject to the policy to which this Certificate of Insurance refers is issued in accordance with the provisions of the Motor Vehicles (Third Party Risk and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risk) Rules, 1988 (Malaysia).

Insurance Broker:
MILAN LEASING & LES
100, KILANG ROAD, ALUX CUSTOMER SERVICE CENTRE
SINGAPORE, 159534
Insured by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORIZED REPRESENTATIVE

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (subject to availability)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to report any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicles.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised insurers within 24 hours of the end working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicles, if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised insurers within 24 hours of the end working day of the accident.

What should I do in the event of an accident?

- If possible, first move your car to a safe place.
- Do not leave the vehicle until you have seen the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised insurers within 24 hours of the end working day of the accident.
- Submit AIG Questionnaire/Correspondence form (not provided) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **3** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408698

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm


*The Rental Car Company's Terms & Conditions apply i.e. refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.



Policy No.	2100482604-01
Period of Insurance	19 Sep 2017 to 18 Sep 2018

Issued Date: 28 Aug 2017

Name of Policyholder	BANGI BALASAHEB ABHAY
Address	130 TANJONG RHU ROAD #06-01 SINGAPORE 436218
Occupation/Nature of Business	Proprietor/Business Owner/Company Owner

Registration No.	SJK168D	Engine Capacity/Tonnage	1.798.00 CC
Chassis No.	WAUZZZ4G3HN031027	Engine No.	CYG016132
Seating Capacity	5	First Year of Registration	2016
Make/Model	AUDI A6 1.8 TFSI ULTRA	Body Type	Sedan
Hire Purchase Company/Employer's Loan	DBS BANK LTD		

Sum Insured	Market Value	Off Peak Car	No
Driver Restriction	NA	Insuring with COE/PARF	Yes

Person or Classes of Persons Entitled to Drive

© 1999 Blackwell Science Ltd

© 1997 Blackwell Science Ltd *Journal of Clinical Pharmacy and Therapeutics*, 22, 1-6

Only use these tags: *em*, **b>,**

See Table 1 only at section 401(a)(9) of \$1,000 as "Supplemental Driver Excess" (SDE). If you are or have authorized driver insured or licensed has less than 3 years driving experience.

Age Condition 35 years old and Above

... as for us

[illegible]

What May Policy Benefits

*MSRP. Excludes tax, license, title, destination charge, dealer prep, handling fee, and optional equipment. Dealer sets actual price. MSRP includes \$600 destination charge. **MSRP. Excludes tax, license, title, destination charge, dealer prep, handling fee, and optional equipment. Dealer sets actual price. MSRP includes \$600 destination charge. ***MSRP. Excludes tax, license, title, destination charge, dealer prep, handling fee, and optional equipment. Dealer sets actual price. MSRP includes \$600 destination charge.

PREMIUM

Premium	\$	1,460.76
GST (7%)	\$	102.25
Total	\$	1,563.01

Your Premium includes the following discounts:

Rent Driver Discount - 5.00%, Group Discount - 10.00%, No Claim Discount - 5.00%

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S80839831**

Name: **BANGI BALASAHEB ABHAY**

Birth Date: **03 Mar 1980**

Issue Date: **28 Jul 2010**

001876584A




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S80839831**

Name: **BANGI BALASAHEB ABHAY**

Race: **INDIAN**

Date of birth: **03-03-1980**

Sex: **M**

Country of birth: **INDIA**

S80839831




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg **28 Jul 2010**

NP 428A

Licence No: S80839831



8886388

NRIC No: **S80839831**

Race: **INDIAN**

Date of issue: **28-10-2007**

130 TANJONG RHU ROAD #08-01

SINGAPORE 438818

NRIC No: **S80839831**

Date: **05/10/2016**






Type	Country Code	Passport No
PA	SGP	KD1943188
Name		

ABHAY BANGI

Sen

4

Date of birth.

03 MAR 1980

Date of issue
12 JAN 2000

19 JAN 2018
Date of revision:

19 JAN 2023

19 JAN 2023
Modifications

SEE PAGE 2

National ID file

580839831

Nationality

SINGAPORE CITIZEN

Place of birth

INDIA

Authority
98-5442-0-00

MINISTRY OF HOME AFFAIRS



PASGPBANGI<<ABHAY<<<<<<<<<<<<<<<<<<<<<<<<<
K0194318B1SGP8003030M2301192S8083983I<<<<<76

IC COLLECTION SLIP FOR NEW SINGAPORE CITIZEN

NRIC NO. **S8083983I** (PINK IC)

NAME **** ABHAY BANGI**

FEES: **\$10.00**



REGISTRATION OFFICER: **K Parameswari**

DATE OF ISSUE: **17/01/2018**



DOCUMENTS ARE TO BE PRESENTED AT GRC CITIZENSHIP CEREMONY



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 16:01
Date Of Accident	30/04/2018 15:00
Exact Location Of Accident	LEBURAYA UTARA-SELATAN KM 417
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK3168D
Insured/Policyholder	
Name Of Registered Owner	BANGI BALASAHEB ABHAY
NRIC No	S8083983I
Email Address	ABHAY.BANGI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96608949
Alternative Phone No	OFFICE-96608949

Vehicle Particulars

Manufacturer	AUDI
Model	A6 1.8 TFSI S-TRONIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100482804-01
Cover Note Number	

Driver

Name of Driver	BANGI BALASAHEB ABHAY
NRIC No	S8083983I
Date Of Birth	03/03/1980
Occupation	INDOOR
Date Of Driving Pass	28/07/2010
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96608949
Fax Number	
Contact Number	OFFICE-96608949
Email Address	ABHAY.BANGI@GMAIL.COM

Address	130 TANJONG RHU ROAD #09-01
Postcode	436918
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	WB8616L (PRIVATE CAR)
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : MEESA BANGI GENDER: : FEMALE
Passenger 2	NAME: : KYSA BANGI GENDER: : FEMALE
Passenger 3	NAME: : JAYA BANGI GENDER: : FEMALE
Passenger 4	NAME: : AKANSHA BANGI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO MALAYSIA POLICE REPORT: R111865. ON 30/04/2018 AT AROUND 1500 HRS, I WAS WITH MY FAMILY COMING BACK FROM CAMERON HIGHLAND AND GOING TO JOHOR BAHRU, DRIVING MY CAR, SJK3168D AUDI A6 ,THROUGH LEBURAYA- SELATAN, AROUND KM 417, HEADING SOUTHWARDS, I SAW CAR NO: AKE 7535, MODEL HYUNDAI ELANTRA, THAT WAS IN AN ACCIDENT, AND THEN I BRAKED TO SLOW MY CAR THEN I WAS HIT BY ANOTHER CAR NO WB 8676 L, MODEL TOYOTA VIOS, PUSHING MY CAR AHEAD CAUSING ME TO HIT THE STATIONARY CAR AHEAD OF ME (CAR NO. AKE 7535, MODEL HYUNDAI ELANTRA). DUE TO THIS, MY CAR SUFFERED DAMAGE TO THE FRONT BUMPER, GRILL, LEFT HEADLAMP, BONNET AND REAR BUMPER. I AND MY FAMILY ARE NOT INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WB8678L
Vehicle Make/Model/Colour	TOYOTA VIOS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	AKE7535
Vehicle Make/Model/Colour	HYUNDAI ELANTRA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


OFFICIAL NOTICE

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Alley Boney

Policyholder's Signature

Date & Time:

Alley Boney

Driver's Signature

(if driver is not the policyholder)



Reporting Centre Personnel's Signature

Name:

MALAYSIA POLICE REPORT

Salinan Repot Polis

Page 1 of 2

POLIS DIRAJA MALAYSIA
REPOT POLIS

Balai : BUKIT SENTOSA
 Daerah : HULU SELANGOR
 Kontinjen : SELANGOR
 No. Repot : TRAFIK HULU SELANGOR/00294018
 Tarikh : 30/04/2018
 Waktu : 1725 PM
 Bahasa Carian : B. Malaysia

Pegawai Penyiasat : R111865

Bulit-bulit Penerima Repot

Nama : AZMAN B. MAT RAJ

No. Personal : R108750

Pangkat : KPL

Bulit-bulit Jurubahasa (Jika Ada)

Nama : —

No. K/P (Baru) : —

No. Polis/Tentara : —

No. Pasport : —

Bahasa Asal : —

Alamat : —

Bulit-bulit Pengadu

Nama : ADIKY BANGSI

No. K/P (Baru) : —

No. Polis/Tentara : —

No. Pasport : K01543168

No. Sijil Beranak : —

Jantina : Lelaki

Tarikh Lahir : 23/03/1980

Umur : 38 tahun 1 bulan

Kebumuhan : India

Warganegara : Engage

Pekerjaan : CONSULTANT

Alamat Tempaat Tinggal : 130 TANJONG RHU ROAD 0801, B 438918, 438918

Alamat Ibu/Bapa : —

Alamat Pejabat : —

No. Tel (Rumah) : —

No. Tel (Pejabat) : —

No. Tel (HP) : 00659660854

Email : —

Pengadu Menyatakan:-

On 30/04/2018 at around 1500 hrs, I was with my family coming back from Cameron highland and going to Johor Bahru, driving my car SJK 3158 D AJOH 46 through Laburaya Utara-Selatan, around Km 417, heading southwards. I saw car no. AKE 7535, model Hyundai Elantra, that was in an accident, and then I braked to slow my car and then I was hit from the back by another car no. WBS 8678 L, model TOYOTA VIOS, pushing my car ahead causing me to hit the stationary car ahead of me (car no. AKE 7535, model Hyundai Elantra). Due to this my car suffered damage to the front bumper, grill, left headlamp, bonnet and rear bumper. I and my family are not injured.

Thank you. This is my report.

Tandatangan Pengadu

Tandatangan Jurubahasa (Jika Ada)

Tandatangan Penerima Repot

MALAYSIA POLICE REPORT

Salinan Report Polis

Page 2 of 2

ID Pencetak | Tarikh @ Masa Cetak

R108755 | 30/04/2018 05:53:16 PM

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0524/2018/GW
Date	:	4-May-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SJK 3168 D**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr . Bangi Balasaheb Abhay
Address	:	130 Tanjong Rhu Road Singapore 436918
Telephone	:	(HP) 96608949
Type of Claim	:	Own Damage Claims
Policy No.	:	2100482804-01
Vehicle No	:	SJK 3168 D
Model Code	:	Audi A6 1.8 TFSI S- T
Model / Year	:	
Engine No	:	
Chassis No	:	
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Apr-18
Place of Accident	:	Leburaya Utara-Selatan KM417

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3168 D.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00 ?	✓
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed. ✓ (LH only).	\$ 6,300.00	2750 1750.
4	To respray front bumper, both front fenders and bonnet. ✓	\$ 3,400.00	1650 ✓
TOTAL LABOUR CHARGES - FRONT		: \$ 11,380.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Dislodged</i>	\$ 2,650.00	✓ 2120
2	FRONT BUMPER GRILLE <i>crushed</i>	\$ 112.00	✓ 89.30
3	FRONT BUMPER FIXING PARTS <i>Not Nec</i>	\$ 464.00	? X
4	FRONT BUMPER COVER MOUNT KIT <i>Not Nec</i>	\$ 43.00	? X
5	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 12.00	+
6	FRONT BUMPER ADAPTER-LH/RH <i>new</i>	2 \$ 64.00	+
7	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 188.00	✓ 150
8	FRONT BUMPER SPOILER <i>del</i>	\$ 817.00	✓ 653.60
9	RADIATOR GRILLE <i>crushed</i>	\$ 1,697.00	✓ 1357.60
10	RADIATOR GRILLE COVER <i>Byd</i>	\$ 32.00	✓ 24.96
11	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>LH missing</i>	2 \$ 868.00	434. 317.20
12	FRONT BUMPER COVER -LH/RH <i>del</i>	2 \$ 88.00	44. 314.56
13	FOAM FILLER PIECE <i>Not Nec</i>	\$ 203.00	? X
14	FRONT BUMPER SIDE REINFORCEMENT <i>Not Nec</i>	\$ 702.00	? X
15	FRONT BUMPER HOLDER BRACKET-LH/RH <i>Not Nec</i>	\$ 446.00	? X
16	FRONT BUMPER SUPPORT-LH/RH <i>LH only</i>	2 \$ 21.00	? 8.40
17	FRONT BUMPER GUIDE PIECE-LH/RH <i>new</i>	2 \$ 64.00	✓ 35.36
18	FRONT BUMPER BRACE-LH/RH <i>new</i>	2 \$ 50.00	+
19	FRONT BUMPER COVER <i>del</i>	\$ 105.00	✓ 84
20	SIGN "CAUTION" <i>new</i>	\$ 12.00	✓ 9.28
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		\$ 8,638.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description			Damage Pa	S/NETT	RE
21	FRONT PARKING AID -OUTER <i>Not New</i>	2	\$	421.00	?	X
22	FRONT PARKING AID - INNER <i>Not New</i>	2	\$	392.00	+	
23	FRONT SUPPORT PARKING AID-LH <i>Not New</i>		\$	59.00	+	
24	FRONT SUPPORT PARKING AID-RH <i>Not New</i>		\$	59.00	+	
25	FRONT FENDER-LH <i>Buckled</i>		\$	1,220.00	✓	976
26	FRONT FENDER ATTACHMENT PARTS-LH <i>Not New</i>		\$	88.00	?	X
27	FRONT FENDER STONE GUARD FILM-LH <i>Not New</i>		\$	105.00	+	
28	FRONT FENDER BRACE-LH/RH <i>Not New</i>	2	\$	144.00	?	X
29	FRONT WHEEL HOUSING LINER-LH <i>Not New</i>		\$	246.00	+	
30	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>		\$	62.00	+	
31	FRONT WHEEL SPOILER-LH/RH <i>Not New</i>	2	\$	464.00	+	
32	LED HEADLIGHT-LH/RH <i>LH could</i>	2	\$	16,772.00	8386	6708.80
33	POWER MODULE FOR DAY DRIVING LIGHTS <i>Not New</i>		\$	501.00	?	X
34	POWER MODULE FOR DIPPED BEAM <i>Not New</i>		\$	486.00	?	X
35	HEADLAPMS FAN-LH <i>Not New</i>		\$	345.00	?	X
36	HOSE-LH <i>Not New</i>		\$	37.00	+	
37	HEADLAMPS ASSEMBLY ADJUSTMENT <i>Not New</i>		\$	40.00	+	
38	LIFT CYLINDER-LH <i>Buckled</i>		\$	208.00	166	
39	COVER CAP-LH/RH <i>LH Buckled</i>	2	\$	98.00	49	39.12
40	BONNET <i>Dented</i>		\$	4,771.00	3816.80	
SUB-TOTAL SPARE PARTS CHARGES - FRONT :				\$ 26,518.00		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description		Damage Pa	
			S/NETT	RE
41	BONNET ATTACHMENT PARTS	Not Nec	\$ 153.00?	X
42	BONNET CATCH HOOK		\$ 122.00	X
42	BONNET LOCK BAR-LH/RH	new	\$ 87.00	+
43	BONNET LATCH HOOK		\$ 15.00	+
44	LID LOCK -LH/RH	new	2 \$ 376.00	X
45	AIR CONDITIONER STICKER	new	\$ 17.00	- 13.44
46	HEADLIGHT MOUNTING	crushed.	2 \$ 206.00	? 85.40
47	RADIATOR MOUNTING LOCK CARRIER	crushed.	\$ 1,024.00?	819.20
48	AIR GUIDE-LH/RH	LH Only.	2 \$ 48.00	? 98.64
49	CHARGE AIR COOLER	new	\$ 492.00	+
50	A/C CONDENSER	new	\$ 683.00	X
51	COOLER FOR COOLANT	new	\$ 752.00	X
52	RUBBER BUSH-CENTER		2 \$ 12.00	+
53	RUBBER BUSH -UPPER		2 \$ 17.00	+
54	RUBBER BUSH -LOWER		2 \$ 23.00	+
55	COOLANT CONCENTRATE	new	4 \$ 133.00	X
56	COOLANT REGULATOR SUPPORT		\$ 64.00	X
57	REFRIGERANT PIPE		\$ 223.00	X
58	FRONT NO. PLATE	Best	\$ 25.00	✓ 25
TOTAL SPARE PARTS CHARGES - FRONT			\$ 39,628.00	
TOTAL LABOUR CHARGES - FRONT			\$ 11,380.00	
GRAND TOTAL - FRONT			\$ 51,008.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3168 D.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according damage.	S/N \$ 280.00 ✓ ✓
2	To remove and transfer lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓ ✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ✓ ✓
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner rear cross panel and connecting plates. Renew rear bumper and rear lid, align to position. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,200.00 2750 2500 ✓
5	To respray rear bumper, rear lid, hinges and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,700.00 1650 ✓
7	To carry out diagnostic check.	S/N \$ 384.00 192 ✓
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 8,324.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Distorted.</i>	\$ 2,519.00	✓ 2015.00
2	REAR BUMPER FIXING PARTS <i>Not New</i>	\$ 234.00	? X
3	REAR BUMPER SPOILER <i>Distorted</i>	\$ 416.00	✓ 332.80
4	REAR BUMPER SECURING <i>Distorted</i>	\$ 191.00	✓ 152.80
5	REAR BUMPER CLOSING ELEMENT-LH/RH <i>Distorted</i>	\$ 138.00	? 109.44
6	REAR BUMPER SENSOR <i>1 piece damaged.</i>	4 \$ 842.00	+ 168.40
7	EXHAUST TAIL PIPE TRIM-LH/RH <i>LH missing</i>	2 \$ 994.00	497.397.60
8	REAR BUMPER CARRIER <i>Not New</i>	\$ 851.00	? X
9	REAR BUMPER IMPACT BAR GASKET-LH/RH <i>Not New</i>	2 \$ 24.00	- 18.56
10	REAR BUMPER GUIDE SECTION-LH/RH <i>Not New</i>	2 \$ 56.00	X
11	REAR BUMPER CONNECTING PIECE <i>Not New</i>	2 \$ 21.00	+
12	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>Not New</i>	2 \$ 92.00	+
13	REAR BUMPER GUIDE PROFILE-LH/RH <i>Not New</i>	2 \$ 114.00	? X
14	REAR BUMPER GUIDE SECTION-CENTRE <i>Not New</i>	\$ 91.00	? X
15	REAR BUMPER HOLDING STRAP-LH/RH <i>Distorted</i>	2 \$ 108.00	? 85.92
16	REAR BUMPER WIRING <i>Not New</i>	\$ 603.00	X
17	REAR LID <i>Distorted</i>	\$ 2,485.00	✓ 1988
18	REAR LID BRACKET <i>Not New</i>	\$ 30.00	✓ 23.28
19	REAR LID ATTACHEMENT PARTS <i>Not New</i>	\$ 93.00	? X
20	REAR LID PUSH BUTTON <i>Not New</i>	\$ 1,181.00	X
SUB-TOTAL SPARE PARTS		\$ 11,083.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR GASKET FLAP <i>new</i>	\$ 181.00	✓ 1144.80
22	REAR LID MOTOR STRIKER PLATE <i>new</i>	\$ 550.00	X
23	REAR LID LOCK <i>new</i>	\$ 170.00	+
24	ADHESIVE PACKING <i>2</i>	\$ 15.00	✓ 11.60
25	AUDI EMBLEM	\$ 108.00	✓ 86
26	INSCRIPTION " A6 "	\$ 83.00	✓ 66.16
27	INSCRIPTION " TFSI "	\$ 83.00	✓ 66.16
28	REAR LID DECORATIVE TRIM <i>new</i>	\$ 317.00	✓ 253.20
29	BOOT LID CONTROL UNIT <i>new</i>	\$ 372.00	X
30	TAILGATE SENSOR LINE <i>Not New</i>	\$ 184.00	? X
31	CABLE TERMINAL <i>new</i>	6 \$ 39.00	+
32	REAR CROSS PANEL <i>Bent</i>	\$ 274.00	2 ✓ 219.20
33	REAR CROSS PANEL REINFORCEMNT <i>Bent</i>	\$ 639.00	2 ✓ 511.20
34	REAR CONNECTIN PLATE -LH/RH <i>Not New</i>	2 \$ 78.00	? X
35	REAR NO. PLATE <i>Bent</i>	S/N \$ 25.00	✓ 25
36	ACRYLIC SEALER <i>2</i>	S/N \$ 180.00	? 180
37	CAVITY WAX <i>New</i>	S/N \$ 140.00	? 140
38	STONE CHIP	S/N \$ 180.00	? 180
39	SUNDRIES <i>New</i>	\$ 600.00	? 68.96
TOTAL PARTS FRT/REAR		:	\$ 15,301.00
TOTAL LABOUR FRT/REAR			\$ 8,324.00
GRAND TOTAL :			\$ 23,625.00
TOTAL PARTS / LABOUR FRONT			\$ 51,008.00
GRAND TOTAL FOR FRONT & REAR			\$ 74,633.00 76,083

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

76033

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lim
04/05/18

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 15 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/0524/2018/GW
Date	17-May-18
Service Advisor	Jeffery Tan
Pages	1
Regn No	SJK 3168 D
Model No	Audi A6 1.8 TFSI S- T

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear bumper bracket - RHS <i>Paid</i>	\$ 50.00	
	TOTAL	\$ 50.00	

For Premium Automobiles Pte Ltd

HL
Adrian Ling

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0524/2018/GW
Date 14-May-18
Service Advisor Jeffery Tan
Pages 1
Regn No SJK 3168 D
Model No Audi A6 1.8 TFSI S-T

Quantity	Description	Unit Price	Amount
LABORS			
1	$250 + 550 = 800$ To repair & respray LHS rear fender.	\$ 1,400.00	800.
TOTAL		\$ 1,400.00	

For Premium Automobiles Pte Ltd

Adrian Ling


Authorised Signature

Veron Chen (LKKAUTO)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 8 May 2018 9:58 AM
To: Veron Chen (LKKAUTO); SUR
Cc: 'Claims'
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)
Attachments: SAftersales18050809540.pdf

Good morning all,

Attachment with owner towing receipt to claim refer AIG insurance.
Owner have intention to claim his oversea towing bill.
Please assist and follow up with owner directly.

Kindly advice for authorize approval also.

Thanks.

Best Regards,
Grant Chong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199901271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sq/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 7 May 2018 9:32 AM
To: Claims Dept; SUR
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear Jeffery,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Friday, 4 May 2018 1:33 PM

To: SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear all,

Kindly assist in the Own Damage Claims for the above mentioned vehicle.

Survey was carried out earlier this.

Many thanks!

Best regards,

Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

AL-BUKHARY TOWING SERVICE



NO. 73, JALAN JEJARAN 3A, BUKIT BERUNTUNG,
48300 RAWANG, SELANGOR, DARUL EHSAN

012-2888 985 @ 019-241 5616

SMART ASSIST PERODUA
FAST LANE



(002191265-D)

30 HOURS TOWING SERVICE A1241

TO: _____ DATE: 30/4/2018

NAME: OWNER Audi

CAR MODEL: Audi

CAR NUMBER: SJK 21680

DESTINATION: BB tol KM: _____

TO: Johor

TIME: _____ AM PM

TOTAL COST RM: RM 1800

REMARKS: _____

OWNER SIGN

TOWING DRIVER SIGN

SUPERVISOR SIGN

Yong Crane & Towing Service
No. 8, Jalan Keris 11, Taman Puteri Wangsa, 81800 Ulu Tiram, Johor.
H/P : (Yong) 016-704 7552 / 012-220 8076

Yong Crane & Towing Service
No. 8, Jalan Keris 11, Taman Puteri Wangsa, 81800 Ulu Tiram, Johor.
H/P : (Yong) 016-704 7552 / 012-220 8076

CASH SALES

No. 05705

M/s

No. Flat

DESCRIPTION 要

Unit Price

Sl. No.	Amount	RM	Rs
---------	--------	----	----

No

Darken RWR
John to SPUR

1000	и
------	---

總計
TOTAL R

TOTAL RM

注意：貨物出門概不退換
N.B. Goods sold are not returnable

Issued By

被賞人

Received By _____

Veron Chen (LKKAUTO)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 17 May 2018 8:29 PM
To: Veron Chen (LKKAUTO); SUR
Cc: claims@premiumauto.com.sg
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)
Attachments: SAftersales18051720360.pdf

Dear all,

Attached the list of supplementary for your kind reference.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Monday, 14 May, 2018 3:15 PM
To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear all,

Attached the supplementary list for your kind reference.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]

Sent: Saturday, 12 May, 2018 3:28 PM

To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear all,

Kindly arrange for the resurvey of ??? item @ BLK10 Sin Ming Industrial Estate, Sector C #01-12, Sg 575645 on Monday.

Many thanks!

Best regards,

Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 8 May, 2018 11:50 AM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear Grant,

As instructed by our client , please proceed to repair the insured vehicle **SKJ 3168D (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 8 May 2018 9:58 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Good morning all,

Attachment with owner towing receipt to claim refer AIG insurance.
Owner have intention to claim his oversea towing bill.
Please assist and follow up with owner directly.

Kindly advice for authorize approval also.

Thanks.

Best Regards,
Grant Chong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, 7 May 2018 9:32 AM
To: Claims Dept; SUR
Subject: RE: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear Jeffery,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 4 May 2018 1:33 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SKJ 3168 D Own Damage Claims (Vehicle IN)

Dear all,

Kindly assist in the Own Damage Claims for the above mentioned vehicle.

Survey was carried out earlier this.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0524/2018/GW
Date	:	4-May-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SJK 3168 D**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

15 days - ok - jb - 19 Jul 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr . Bangi Balasaheb Abhay
Address	:	130 Tanjong Rhu Road Singapore 436918
Telephone	:	(HP) 96608949
Type of Claim	:	Own Damage Claims
Policy No.	:	2100482804-01
Vehicle No	:	SJK 3168 D
Model Code	:	Audi A6 1.8 TFSI S- T
Model / Year	:	
Engine No	:	
Chassis No	:	
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Apr-18
Place of Accident	:	Leburaya Utara-Selatan KM417

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3168 D.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system. <i>(Lock carrier replaced)</i>	S/N \$ 1,200.00	\$ 1,200.00
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed. <i>(Added \$1000.00 for lock carrier replacement)</i>	\$ 6,300.00	\$ 2,750.00
4	To respray front bumper, both front fenders and bonnet.	\$ 3,400.00	\$ 1,650.00
TOTAL LABOUR CHARGES - FRONT		: \$ 11,380.00	\$ 6,080.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,650.00	\$ 2,120.00
2	FRONT BUMPER GRILLE	\$ 112.00	\$ 89.20
3	FRONT BUMPER FIXING PARTS	\$ 464.00	
4	FRONT BUMPER COVER MOUNT KIT	\$ 43.00	
5	FRONT BUMPER SECURING STRIP	2 \$ 12.00	
6	FRONT BUMPER ADAPTER-LH/RH	2 \$ 64.00	
7	FRONT BUMPER CLOSING ELEMENT	\$ 188.00	\$ 150.00
8	FRONT BUMPER SPOILER	\$ 817.00	\$ 653.60
9	RADIATOR GRILLE	\$ 1,697.00	\$ 1,357.60
10	RADIATOR GRILLE COVER	\$ 32.00	\$ 24.96
11	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 868.00	\$ 347.20
12	FRONT BUMPER COVER -LH/RH	2 \$ 88.00	\$ 34.56
13	FOAM FILLER PIECE	\$ 203.00	
14	FRONT BUMPER SIDE REINFORCEMENT	\$ 702.00	
15	FRONT BUMPER HOLDER BRACKET-LH/RH	\$ 446.00	
16	FRONT BUMPER SUPPORT-LH/RH	2 \$ 21.00	\$ 8.40
17	FRONT BUMPER GUIDE PIECE-LH/RH	2 \$ 64.00	\$ 25.36
18	FRONT BUMPER BRACE-LH/RH	2 \$ 50.00	
19	FRONT BUMPER COVER	\$ 105.00	\$ 84.00
20	SIGN "CAUTION"	\$ 12.00	\$ 9.28
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		\$ 8,638.00	\$ 4,904.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		c/f	\$	
				4,904.16
21	FRONT PARKING AID -OUTER	\$	421.00	
22	FRONT PARKING AID - INNER	\$	392.00	
23	FRONT SUPPORT PARKING AID-LH	\$	59.00	
24	FRONT SUPPORT PARKING AID-RH	\$	59.00	
25	FRONT FENDER-LH	\$	1,220.00	\$ 976.00
26	FRONT FENDER ATTACHMENT PARTS-LH	\$	88.00	
27	FRONT FENDER STONE GUARD FILM-LH	\$	105.00	
28	FRONT FENDER BRACE-LH/RH	\$	144.00	
29	FRONT WHEEL HOUSING LINER-LH	\$	246.00	
30	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	62.00	
31	FRONT WHEEL SPOILER-LH/RH	\$	464.00	
32	LED HEADLIGHT-LH/RH	\$	16,772.00	\$ 6,708.80
33	POWER MODULE FOR DAY DRIVING LIGHTS	\$	501.00	
34	POWER MODULE FOR DIPPED BEAM	\$	486.00	
35	HEADLAPMS FAN-LH	\$	345.00	
36	HOSE-LH	\$	37.00	
37	HEADLAMPS ASSEMBLY ADJUSTMENT	\$	40.00	
38	LIFT CYLINDER-LH	\$	208.00	\$ 166.00
39	COVER CAP-LH/RH	\$	98.00	\$ 39.12
40	BONNET	\$	4,771.00	\$ 3,816.80
SUB-TOTAL SPARE PARTS CHARGES - FRONT		\$	26,518.00	\$ 16,610.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		c/f	\$	16,610.88
41	BONNET ATTACHMENT PARTS	\$	153.00	
42	BONNET CATCH HOOK	\$	122.00	
42	BONNET LOCK BAR-LH/RH	\$	87.00	
43	BONNET LATCH HOOK	\$	15.00	
44	LID LOCK -LH/RH	\$	376.00	
45	AIR CONDITIONER STICKER	\$	17.00	\$ 13.44
46	HEADLIGHT MOUNTING	\$	206.00	\$ 82.40
47	RADIATOR MOUNTING LOCK CARRIER	\$	1,024.00	\$ 819.20
48	AIR GUIDE-LH/RH	\$	48.00	\$ 18.64
49	CHARGE AIR COOLER	\$	492.00	
50	A/C CONDENSER	\$	683.00	
51	COOLER FOR COOLANT	\$	752.00	
52	RUBBER BUSH-CENTER	\$	12.00	
53	RUBBER BUSH -UPPER	\$	17.00	
54	RUBBER BUSH -LOWER	\$	23.00	
55	COOLANT CONCENTRATE	\$	133.00	
56	COOLANT REGULATOR SUPPORT	\$	64.00	
57	REFRIGERANT PIPE	\$	223.00	
58	FRONT NO. PLATE	\$	25.00	\$ 25.00
	TOTAL SPARE PARTS CHARGES - FRONT	\$	39,628.00	\$ 17,569.56
	TOTAL LABOUR CHARGES - FRONT	\$	11,380.00	\$ 6,080.00
	GRAND TOTAL - FRONT	\$	51,008.00	\$ 23,649.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3168 D.

S/N	Nature of Jobs	Estimated Charges	
	<i>Labour front c/f</i>	\$ 11,380.00	\$ 6,080.00
1	To remove and transfer rear parking aid. Check function and renew according damage.	S/N \$ 280.00	\$ 280.00
2	To remove and transfer lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	\$ 480.00
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner rear cross panel and connecting plates. Renew rear bumper and rear lid, align to position. Re-organise rear crash management components. Reinstall all parts removed. (Add \$250.00 for repairing s/tyre housing)	\$ 4,200.00	\$ 2,750.00
5	To respray rear bumper, rear lid, hinges and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,700.00	\$ 1,650.00
7	<i>Added labour charges</i>	\$ 1,400.00	\$ 800.00
8	To carry out diagnostic check.	S/N \$ 384.00	\$ 192.00
SUB-TOTAL LABOUR CHARGES - (REAR)		\$ 21,104.00	\$ 12,512.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	<i>Materials front c/f</i>	\$ 39,628.00	\$ 17,569.56
1	REAR BUMPER	\$ 2,519.00	\$ 2,015.20
2	REAR BUMPER FIXING PARTS	\$ 234.00	
3	REAR BUMPER SPOILER	\$ 416.00	\$ 332.80
4	REAR BUMPER SECURING	\$ 191.00	\$ 152.80
5	REAR BUMPER CLOSING ELEMENT-LH/RH	\$ 138.00	\$ 109.44
6	REAR BUMPER SENSOR	4 \$ 842.00	\$ 168.40
7	EXHAUST TAIL PIPE TRIM-LH/RH	2 \$ 994.00	\$ 397.60
8	REAR BUMPER CARRIER	\$ 851.00	
9	REAR BUMPER IMPACT BAR GASKET-LH/RH	2 \$ 24.00	\$ 18.56
10	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 56.00	
11	REAR BUMPER CONNECTING PIECE	2 \$ 21.00	
12	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 92.00	
13	REAR BUMPER GUIDE PROFILE-LH/RH	2 \$ 114.00	
14	REAR BUMPER GUIDE SECTION-CENTRE	\$ 91.00	
15	REAR BUMPER HOLDING STRAP-LH/RH	2 \$ 108.00	\$ 85.92
16	REAR BUMPER WIRING	\$ 603.00	
17	REAR LID	\$ 2,485.00	\$ 1,988.00
18	REAR LID BRACKET	\$ 30.00	\$ 23.28
19	REAR LID ATTACHEMENT PARTS	\$ 93.00	
20	REAR LID PUSH BUTTON	\$ 1,181.00	
SUB-TOTAL SPARE PARTS		\$ 50,711.00	\$ 22,861.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3168 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	c/f	\$ 50,711.00	\$ 22,861.56
21	REAR GASKET FLAP	\$ 181.00	\$ 144.80
22	REAR LID MOTOR STRIKER PLATE	\$ 550.00	
23	REAR LID LOCK	\$ 170.00	
24	ADHESIVE PACKING	\$ 15.00	\$ 11.60
25	AUDI EMBLEM	\$ 108.00	\$ 86.00
26	INSCRIPTION " A6 "	\$ 83.00	\$ 66.16
27	INSCRIPTION " TFSI "	\$ 83.00	\$ 66.16
28	REAR LID DECORATIVE TRIM	\$ 317.00	\$ 253.20
29	BOOT LID CONTROL UNIT	\$ 372.00	
30	TAILGATE SENSOR LINE	\$ 184.00	
31	CABLE TERMINAL	6 \$ 39.00	
32	REAR CROSS PANEL	\$ 274.00	\$ 219.20
33	REAR CROSS PANEL REINFORCEMNT	\$ 639.00	\$ 511.20
34	REAR CONNECTIN PLATE -LH/RH	2 \$ 78.00	
35	REAR NO. PLATE	S/N \$ 25.00	\$ 25.00
36	ACRYLIC SEALER	S/N \$ 180.00	\$ 180.00
37	CAVITY WAX	S/N \$ 140.00	\$ 140.00
38	STONE CHIP	S/N \$ 180.00	\$ 180.00
40	SUNDRIES	\$ 600.00	\$ 68.96
	MATERIALS FRONT/REAR	\$ 54,929.00	\$ 24,813.84
	LABOUR CHARGES FRONT/REAR	\$ 21,104.00	\$ 12,512.00
	GRAND TOTAL :	\$ 76,033.00	\$ 37,325.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0524/2018/GW 14-May-18 Jeffery Tan 1 SJK 3168 D Audi A6 1.8 TFSI S- T	
Quantity	Description	Unit Price	Amount	
<u>LABORS</u>				
1	To repair & respray LHS rear fender.	\$ 1,400.00	\$	800.00
TOTAL		\$ 1,400.00	\$	800.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0524/2018/GW 17-May-18 Jeffery Tan 1 SJK 3168 D Audi A6 1.8 TFSI S- T
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear bumper bracket - RHS	\$ 50.00	
TOTAL		\$ 50.00	SUNDRY

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 20 August 2018 3:25 PM
To: 'Boo seng yak'; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SJK3168D - OD AIG - SURVEYED 4 MAY 18

Dear Mr Boo,

Confirm repair cost of \$37,325.84 before excess \$800 and GST @ 15 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 19 July 2018 7:24 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SJK3168D - OD AIG - SURVEYED 4 MAY 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$37,325.84 @ 15 days of repairs.

Your colleague re-inspected vehicle on 14 May 18.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJK 3168 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0524/2018/JT

14th September 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SJK 3168 D, Audi A6 1.8 TFSI S-tronic

With reference to the above-mentioned vehicle, no. **SJK 3168 D** claimant, **Mr. Bangi Balasaheb Abhay**, please find the related document per attached.

1. A copy of the Original invoice no. 8501 2921 – S\$39,082.65
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJK 3168 D

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 1 14:50

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone 6388 2223
Telefax 6475 1023

Customer Service
Service Appointment 6388 2223
Hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012921 Date : 07/09/2018 Order : SJK31680 Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJK31680 (V 31389) Regn Date: 19/09/2016 Mileage: 16264 WIP No.: 64171
Model: A6 1.8 TFSI S tronic 40066 IN Chassis: WAUZZZ452H031027 Engine: CY6 016132 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	50.00	1.00	50.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET, RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS.	2750.00	1.00	2,750.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 2735

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408679
Telephone 6388 1333
Telefax 6475 1023

Customer Service
Service Appointment 6388 2223
Hour Breakdown Service 9628 1233
Email customer.care@premiumauto.com.sg

Page 2 14:50

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012921 Date : 07/09/2018 Order : SJK31680 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJK31680 (V 31389) Regn Date: 19/09/2016 Mileage: 16264 WIP No.: 64171
Model: A6 1.8 TFSI S tronic 45C065 (N Chassis: WAUZZZ462H031027 Engine: CYB 016132 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M:	1650.00	1.00	1,650.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET M:	280.00	1.00	280.00
S	BODYWORK	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING DAMAGE. M:	280.00	1.00	280.00
S	BODYWORK	TO REMOVE AND TRANSFER LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS M:	480.00	1.00	480.00
S	BODYWORK	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS. M:	2750.00	1.00	2,750.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733
Page 3 14:50

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 400634
Telephone: 3366 1622
Telefax: 3341 7127

Customer Service
Service Appointment: 6386 2223
Hour Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012921 Date : 07/09/2018 Order : SJK31680 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJK31680 (V 31389) Regn Date: 19/09/2016 Mileage: 16264 WIP No.: 64171
Model: A6 1.8 TFSI S tronic 400000 (N Chassis: WAUZZZ4G2H0031027 Engine: CYB 016132 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	PANEL AND CONNECTING PLATES,RENEW REAR BUMPER AND REAR LID,ALIGN TO POSITION.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED M:	1650.00	1.00	1,650.00
S	BODYWORK	TO RESPRAY REAR BUMPER,REAR LID,HINGES AND END PANELLING.TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	500.00	1.00	500.00
S	BODYWORK	TO SUPPLY ACRYLIC SEALER,CAVITY WAX AND STONE CHIP M:	800.00	1.00	800.00
X	A460807717B GRU	TO REPAIR AND RESPRAY LHS REAR FENDER			
X	A460807245D	SPOILER (V) Less 020%	1.00	817.00	653.60
X	A460807364C	COVER(V) (G) Less 020%	1.00	43.20	34.56
		PLATE Less 020%	1.00	68.40	54.72
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6834 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6888 2223
Telefax 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408809
Telephone 4368 7211

Customer Service
Service Appointment : 6366 2323
Hour Breakdown Service 6428 1233
Email : customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 14:50

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012921 Date : 07/09/2018 Order : SJK31680 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJK31680 (V 31389) Regn Date: 19/09/2016 Mileage: 16264 WIP No.: 64171
Model: A6 1.8 TFSI S tronic 40000 (N Chassis: WAUZZZ462H031027 Engine: CYB 016132 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A400853651AET94	GRILLE Less 020%	1.00	1697.00	1,357.60
X	A400941773J	HEADLIGHT Less 020%	1.00	8386.00	6,708.80
X	A400821101	FENDER Less 020%	1.00	1220.00	976.00
X	A405827023C	LTD (V) Less 020%	1.00	2485.00	1,988.00
X	A405827705D	WTHRSTRIP (V) Less 020%	1.00	181.00	144.80
X	A400807081D	COVER Less 020%	1.00	105.00	84.00
X	A400807521T 989	SPOILER Less 020%	1.00	416.00	332.80
X	A400807611F	PLATE Less 020%	1.00	187.50	150.00
X	A400805594C	CARRIER Less 020%	1.00	1024.00	819.20
X	A405813331	REINFORCEM Less 020%	1.00	639.00	511.20
X	A405813307	REAR APRON Less 020%	1.00	274.00	219.20
X	A400823029A	HOOD Less 020%	1.00	4771.00	3,816.80
X	A400807065A66AU	COVER Less 020%	1.00	2650.00	2,120.00
X	A405807067K GRU	COVER Less 020%	1.00	2519.00	2,015.20
X	A4F0053741 22Z	INSCRIPTION 'A6' Less 020%	1.00	82.70	66.16
X	A400807363C	PLATE Less 020%	1.00	68.40	54.72
X	A400807329	STRAP Less 020%	1.00	53.70	42.96
X	A400807330	STRAP Less 020%	1.00	53.70	42.96
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6836 2223
Main Telefax: 6471 3733
Page 5 14:50

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 3323
Telefax: 6441 0844

Customer Service
Service Appointment: 6388 2323
Hour Breakdown Service: 6828 1223
Email: customer.care@premiumauto.com.sg

INSURANCE INVOICE
Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012921 Date: 07/09/2016 Order: SJK31680 Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SJK31680 (V 31389) Regn Date: 19/09/2015 Mileage: 16264 WIP No.: 64171
Model: A6 1.8 TFSI S tronic 4GC066 (N Chassis: WAUZZZ4G2H0031027 Engine: CY6 016132 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A8X0053737A 22Z	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	A4G5053742 22Z	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	A4G50079000 989	STRIP	Less 020%	1.00	191.00	152.80
X	A8D0053419F	PACKING	Less 020%	1.00	14.50	11.60
X	A8K0253144M	BRACKET	Less 020%	1.00	49.90	39.92
X	A4G0253025M	PIPETIP (V)	Less 020%	1.00	497.00	397.60
X	A4G0027310	CLIP	Less 020%	2.00	2.10	3.36
X	A8R0027199	BRACKET (V)	Less 020%	1.00	29.10	23.28
X	A4G0007333	SUPPORT	Less 020%	1.00	10.50	8.40
X	A4G0007669	GASKET	Less 020%	1.00	11.60	9.28
X	A4G0007670	GASKET	Less 020%	1.00	11.60	9.28
X	A4G0007283	GUIDE	Less 020%	1.00	31.70	25.36
X	A4G0007647B BKT	GRILL	Less 020%	1.00	434.00	347.20
X	A4G0005607A	MOUNTING	Less 020%	1.00	103.00	82.40
X	A4G0053037D	COVER	Less 020%	1.00	31.20	24.96
X	A4G0955275H GRU	CAP	Less 020%	1.00	48.90	39.12
X	A4G0955101A	CYLINDER	Less 020%	1.00	207.50	166.00
X	A1S0919275C GRU	SENSOR	Less 020%	1.00	210.50	168.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre
33 Ubi Road 1
Singapore 408722
Telephone: 6385 2223
Telefax: 6441 1023

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6886 2223
9628 1233

Page 5 14:50

INS TAX INVOICE
Company Reg. No. U39902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012921 Date : 07/09/2016 Order : SJK31680 Term : 30	Accounts: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No.: SJK31680 (V 31389) Regn Date: 19/09/2016 Mileage: 16264 WIP No.: 64171

Model: A6 1.8 TFSI S tronic 40C066 (N Chassis: WAUZZZ4G2H0031027 Engine: CYB 016132 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A1T0919133C 704	WASHER Less 020%	4.00	1.10	3.52
X	A8K0010520A	PLATE Less 020%	1.00	11.60	9.28
X	A4G0010515P	STICKER Less 020%	1.00	16.00	13.44
X	A4G0121283BT	AIR DUCT Less 020%	1.00	23.30	18.64
X	A4G5945253	TRIM Less 020%	1.00	25.10	20.08
X	A4G0007683C	GRILLE Less 020%	1.00	111.50	89.20
X	AN 90765701	RIVET Less 020%	2.00	1.30	2.08
X	A4G5853927 22Z	HOLDING Less 020%	1.00	316.50	253.20

Parts 24,263.84
Labour 0.00
Sublet 13,062.00
Menus 0.00
Lubricant 0.00

Sub-Total 36,525.84

7% GST 2,556.81

Grand Total 39,082.65



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJK 3168 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0524/2018/GC
21 May 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi A6 1.8 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZ4G2HN031027
Vehicle Regn No. : **SJK 3168 D**
Vehicle Mileage : 16264 KM
Vehicle Owner : Mr. Bangi Balasaheb Abhay
Certificate No : 2100482804-01
Policy Excess : S\$856.00 (inclusive GST)
Accident Date : 30 April 2018
Place : Lebuhraya Utara-Selatan KM 417 Malaysia
Repair Cost : \$39,082.65
WIP No. : 64171
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

22/5/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 May 2018 08:20		04 May 2018 15:50 Edit Adj Rpt	S\$37,325.84 Edit Estimates	S\$37,325.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

BANGI BALASAHAB ABHAY, ID: S80839831, Tel: +6596608949, Email: ABHAY.BANGI@GMAIL.COM

Vehicle Reg. No.:

SJK3168D

Date of Loss:

30/04/2018 15:00 - :59
[19 Months and 11 Days From LTA Reg Date (Man Yr)]

Claim Type:

OD / 9735912051SG

Policy/Cover Note No.:

2100482804-01 (Comprehensive)

Excess:

S\$800.00

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 15/05/2018]

Driver/Custodian:

BANGI BALASAHAB ABHAY (38 / Male), NRIC: S80839831, Tel: +6596608949

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (08/05/2018): Alert - Adj Mandate Approved (S\$37520.00) - SJK3168D - Claim Handler: Tr, Tinesh
- AIG_SG (07/05/2018): SJK3168D / OD / 30/04/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJK3168D (9735912051SG)
OD
Apr 30 2018 3:00PM
[BANGI BALASAHEB ABHAY]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page ☐	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	07/05/18 09:24	Adjuster Immediate Advice		
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 08:20	General View	 Load JPG	☒
2	07/05/18 08:20	General View	 Load JPG	☒
3	07/05/18 08:20	General View	 Load JPG	☒
4	07/05/18 08:20	General View	 Load JPG	☒
5	07/05/18 08:20	General View	 Load JPG	☒
6	07/05/18 08:20	General View	 Load JPG	☒
7	07/05/18 08:20	General View	 Load JPG	☒
8	07/05/18 08:20	General View	 Load JPG	☒
9	07/05/18 08:20	General View	 Load JPG	☒
10	07/05/18 08:20	General View	 Load JPG	☒
11	07/05/18 08:20	General View	 Load JPG	☒
12	07/05/18 08:20	General View	 Load JPG	☒
13	07/05/18 08:20	General View	 Load JPG	☒
14	07/05/18 08:20	General View	 Load JPG	☒
15	07/05/18 08:20	General View	 Load JPG	☒
16	07/05/18 08:20	General View	 Load JPG	☒
17	07/05/18 08:20	General View	 Load JPG	☒
18	07/05/18 08:20	General View	 Load JPG	☒
19	07/05/18 08:20	General View	 Load JPG	☒
20	07/05/18 08:20	General View	 Load JPG	☒
21	07/05/18 08:20	General View	 Load JPG	☒
22	07/05/18 08:20	General View	 Load JPG	☒
23	07/05/18 08:20	General View	 Load JPG	☒
24	07/05/18 08:20	General View	 Load JPG	☒
25	07/05/18 08:20	General View	 Load JPG	☒
26	07/05/18 08:20	General View	 Load JPG	☒
27	07/05/18 08:20	General View	 Load JPG	☒
28	07/05/18 08:20	General View	 Load JPG	☒
29	07/05/18 08:20	General View	 Load JPG	☒
30	07/05/18 08:20	General View	 Load JPG	☒
31	07/05/18 08:20	General View	 Load JPG	☒
32	07/05/18 08:20	General View	 Load JPG	☒
33	07/05/18 08:20	General View	 Load JPG	☒
34	07/05/18 08:20	General View	 Load JPG	☒
35	07/05/18 08:20	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	07/05/18 08:20	General View	 Load JPG	☒
37	07/05/18 08:20	General View	 Load JPG	☒
38	07/05/18 08:20	General View	 Load JPG	☒
39	07/05/18 08:20	General View	 Load JPG	☒
40	07/05/18 08:20	General View	 Load JPG	☒
41	07/05/18 08:20	General View	 Load JPG	☒
42	07/05/18 08:20	General View	 Load JPG	☒
43	07/05/18 08:20	General View	 Load JPG	☒
44	07/05/18 08:20	General View	 Load JPG	☒
45	07/05/18 08:20	General View	 Load JPG	☒
46	07/05/18 08:20	General View	 Load JPG	☒
47	07/05/18 08:20	General View	 Load JPG	☒
48	07/05/18 08:20	General View	 Load JPG	☒
49	07/05/18 08:20	General View	 Load JPG	☒
50	07/05/18 08:20	General View	 Load JPG	☒
51	07/05/18 08:20	General View	 Load JPG	☒
52	07/05/18 08:20	General View	 Load JPG	☒
53	07/05/18 08:20	General View	 Load JPG	☒
54	07/05/18 08:20	General View	 Load JPG	☒
55	07/05/18 08:20	General View	 Load JPG	☒
56	07/05/18 08:20	General View	 Load JPG	☒
57	07/05/18 08:20	General View	 Load JPG	☒
58	07/05/18 08:20	General View	 Load JPG	☒
59	07/05/18 08:20	General View	 Load JPG	☒
60	07/05/18 08:20	General View	 Load JPG	☒
61	07/05/18 08:20	General View	 Load JPG	☒
62	07/05/18 08:20	General View	 Load JPG	☒
63	07/05/18 08:20	General View	 Load JPG	☒
64	07/05/18 08:20	General View	 Load JPG	☒
65	07/05/18 08:20	General View	 Load JPG	☒
66	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
67	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
68	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
69	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
70	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
71	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
72	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
73	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
74	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
75	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
76	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
77	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
78	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
79	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
80	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
81	17/08/18 16:39	Reinspection Photo	 Load JPG	☒
82	17/08/18 16:39	Reinspection Photo	Load JPG	☒
83	17/08/18 16:39	Reinspection Photo	Load JPG	☒
84	17/08/18 16:40	Reinspection Photo	Load JPG	☒
85	17/08/18 16:40	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
87	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
88	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
89	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
90	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
91	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
92	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
93	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
94	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
95	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
96	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
97	17/08/18 16:40	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 09:24	Singapore Accident Statement	 Load PDF	
2	07/05/18 09:24	MALASIA POLICE REPORT (PAGE 1)	 Load PDF	
3	07/05/18 09:25	MALAYSIA POLICE REPORT (PAGE 2)	 Load PDF	
4	07/05/18 09:25	Certificate of Insurance	 Load PDF	
5	07/05/18 09:26	Insured's Driving License	 Load PDF	
6	07/05/18 09:26	MARK ESTIMATE	 Load PDF	
7	19/10/18 11:34	Workshop Invoice	 Load PDF	
8	19/10/18 11:34	Discharge Voucher	 Load PDF	
9	19/10/18 12:17	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/05/18 16:44	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/05/18 16:32	MALAYSIA POLICE REPORT	 Load JPG	☒
2	02/05/18 16:32	MALAYSIA POLICE REPORT	 Load JPG	☒
3	02/05/18 16:42	Accident Photo	 Load JPG	☒
4	02/05/18 16:42	Accident Photo	 Load JPG	☒
5	02/05/18 16:42	Accident Photo	 Load JPG	☒
6	02/05/18 16:42	Accident Photo	 Load JPG	☒
7	02/05/18 16:42	Accident Photo	 Load JPG	☒
8	02/05/18 16:42	Accident Photo	 Load JPG	☒
9	02/05/18 16:42	Accident Photo	 Load JPG	☒
10	02/05/18 16:42	Accident Photo	 Load JPG	☒
11	02/05/18 16:42	Accident Photo	 Load JPG	☒
12	02/05/18 16:42	Accident Photo	 Load JPG	☒
13	02/05/18 16:42	Accident Photo	 Load JPG	☒
14	02/05/18 16:42	Accident Photo	 Load JPG	☒
15	02/05/18 16:42	Accident Photo	 Load JPG	☒
16	02/05/18 16:42	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/05/18 16:31	Sketch Plan	 Load JPG	☒
2	02/05/18 16:31	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18008198/AVBE2

Date: 19/10/2018

REFERENCE

Insured/Claimant: BANGI BALASAHEB ABHAY
Date of Loss: 30/04/2018

Policy No: 2100482804-01
Nature of Claim: OD

Claim No: 9735912051SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK3168D**
Make & Model: AUDI A6, 1.8 TFSI S-tronic (A)
Reg. Date: 19/09/2016 (Man. Year: 2016)
Colour: Black
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$155,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CYG016132
Chassis No: WAUZZZ4G2HN031027
Odometer: 16264 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17
Front Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Rear Tyre Size: 225/55 R17
Rear Left Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,929.00	24,813.84	30,115.16	54.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,104.00	12,512.00	8,592.00	40.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	76,033.00	37,325.84	38,707.16	50.91
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	75,233.00	36,525.84	38,707.16	51.45
+ GST 7.00/7.00% (S\$)	5,266.31	2,556.81	2,709.50	51.45
Nett Amount (S\$)	80,499.31	39,082.65	41,416.66	51.45

INSPECTION

Date of Assignment: 04/05/2018

Date Inspected: 04/05/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	2,650.00 FS	*2,120.00 FS
2	1	*FRONT BUMPER GRILLE	Cracked	112.00 FS	*89.20 FS
3	1	*FRONT BUMPER FIXING PARTS	Not Necessary	464.00 FS	*- FS
4	1	*FRONT BUMPER COVER MOUNT KIT	Not Necessary	43.00 FS	*- FS
5	2	*FRONT BUMPER SECURING STRIP	Not Necessary	12.00 FS	*- FS
6	2	*FRONT BUMPER ADAPTER - LH/RH	Not Necessary	64.00 FS	*- FS
7	1	*FRONT BUMPER CLOSING ELEMENT	Necessary	188.00 FS	*150.00 FS
8	1	*FRONT BUMPER SPOILER	Deformed	817.00 FS	*653.60 FS
9	1	*RADIATOR GRILLE	Cracked	1,697.00 FS	*1,357.60 FS
10	1	*RADIATOR GRILLE COVER	Damaged	32.00 FS	*24.96 FS
11	1	*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	N/S Missing	868.00 FS	*347.20 FS
12	1	*FRONT BUMPER COVER - LH/RH	N/S Deformed	88.00 FS	*34.56 FS
13	1	*FOAM FILLER PIECE	Not Necessary	203.00 FS	*- FS
14	1	*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	702.00 FS	*- FS
15	1	*FRONT BUMPER HOLDER BRACKET - LH/RH	Not Necessary	446.00 FS	*- FS
16	1	*FRONT BUMPER SUPPORT - LH/RH	N/S Damaged	21.00 FS	*8.40 FS
17	2	*FRONT BUMPER GUIDE PIECE - LH/RH	Necessary	64.00 FS	*25.36 FS
18	2	*FRONT BUMPER BRACE - LH/RH	Not Necessary	50.00 FS	*- FS
19	1	*FRONT BUMPER COVER	Deformed	105.00 FS	*84.00 FS
20	1	*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
21	1	*FRONT SUPPORT PARKING AID - LH	Not Necessary	59.00 FS	*- FS
22	1	*FRONT SUPPORT PARKING AID - RH	Not Necessary	59.00 FS	*- FS
23	1	*FRONT FENDER - LH	Buckled	1,220.00 FS	*976.00 FS
24	1	*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	88.00 FS	*- FS
25	1	*FRONT FENDER STONE GUARD FILM - LH	Not Necessary	105.00 FS	*- FS
26	2	*FRONT FENDER BRACE - LH/RH	Not Necessary	144.00 FS	*- FS
27	1	*FRONT WHEEL HOUSING LINER - LH	Not Necessary	246.00 FS	*- FS
28	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
29	2	*FRONT WHEEL SPOILER - LH/RH	Not Necessary	464.00 FS	*- FS
30	2	*LED HEADLIGHT - LH/RH	N/S Cracked	16,772.00 FS	*6,708.80 FS
31	1	*POWER MODULE FOR DAY DRIVING LIGHT	Not Necessary	501.00 FS	*- FS
32	1	*POWER MODULE FOR DIPPED BEAM	Not Necessary	486.00 FS	*- FS
33	1	*HEADLAMPS FAN - LH	Not Necessary	345.00 FS	*- FS
34	1	*HOSE-LH	Not Necessary	37.00 FS	*- FS
35	1	*HEADLAMPS ASSEMBLY ADJUSTMENT	Not Necessary	40.00 FS	*- FS
36	1	*LIFT CYLINDER - LH	Cracked	208.00 FS	*166.00 FS
37	1	*BONNET	Dented	4,771.00 FS	*3,816.80 FS
38	1	*BONNET ATTACHMENT PARTS	Not Necessary	153.00 FS	*- FS
39	1	*BONNET CATCH HOOK	Not Necessary	122.00 FS	*- FS
40	1	*BONNET LOCK BAR - LH/RH	Not Necessary	87.00 FS	*- FS
41	1	*BONNET LATCH HOOK	Not Necessary	15.00 FS	*- FS
42	2	*LID LOCK - LH/RH	Not Necessary	376.00 FS	*- FS
43	1	*AIR CONDITIONER STICKER	Necessary	17.00 FS	*13.44 FS
44	2	*HEADLIGHT MOUNTING	Cracked	206.00 FS	*82.40 FS
45	1	*RADIATOR MOUNTING LOCK CARRIER	Cracked	1,024.00 FS	*819.20 FS
46	1	*AIR GUIDE - LH/RH	N/S Damaged	48.00 FS	*18.64 FS
47	1	*CHARGE AIR COOLER	Not Necessary	492.00 FS	*- FS
48	1	*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
49	1	*COOLER FOR COOLANT	Not Necessary	752.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
50	2	*RUBBER BUSH - CENTER	Not Necessary	12.00 FS	*- FS
51	2	*RUBBER BUSH - UPPER	Not Necessary	17.00 FS	*- FS
52	2	*RUBBER BUSH - LOWER	Not Necessary	23.00 FS	*- FS
53	4	*COOLANT CONCENTRATE	Not Necessary	133.00 FS	*- FS
54	1	*COOLANT REGULATOR SUPPORT	Not Necessary	64.00 FS	*- FS
55	1	*REFRIGERANT PIPE	Not Necessary	223.00 FS	*- FS
56	1	*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
57	1	*REAR BUMPER	Distorted	2,519.00 FS	*2,015.20 FS
58	1	*REAR BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
59	1	*REAR BUMPER SPOILER	Distorted	416.00 FS	*332.80 FS
60	1	*REAR BUMPER SECURING	Damaged	191.00 FS	*152.80 FS
61	1	*REAR BUMPER CLOSING ELEMENT - LH/RH	Damaged	138.00 FS	*109.44 FS
62	1	*REAR BUMPER SENSOR (4PCS)	Damaged-1pc only	842.00 FS	*168.40 FS
63	1	*EXHAUST TAIL PIPE TRIM - LH/RH	N/S Missing	994.00 FS	*397.60 FS
64	1	*REAR BUMPER CARRIER	Not Necessary	851.00 FS	*- FS
65	2	*REAR BUMPER IMPACT BAR GASKET - LH/RH	Necessary	24.00 FS	*18.56 FS
66	2	*REAR BUMPER GUIDE SECTION - LH/RH	Not Necessary	56.00 FS	*- FS
67	2	*REAR BUMPER CONNECTING PIECE	Not Necessary	21.00 FS	*- FS
68	2	*REAR BUMPER UPPER GUIDE SECTION - LH/RH	Not Necessary	92.00 FS	*- FS
69	2	*REAR BUMPER GUIDE PROFILE - LH/RH	Not Necessary	114.00 FS	*- FS
70	1	*REAR BUMPER GUIDE SECTION - CENTRE	Not Necessary	91.00 FS	*- FS
71	2	*REAR BUMPER HOLDING STRAP -LH/RH	Damaged	108.00 FS	*85.92 FS
72	1	*REAR BUMPER WIRING	Not Necessary	603.00 FS	*- FS
73	1	*REAR LID	Dented	2,485.00 FS	*1,988.00 FS
74	1	*REAR LID BRACKET	Necessary	30.00 FS	*23.28 FS
75	1	*REAR LID ATTACHEMENT PARTS	Not Necessary	93.00 FS	*- FS
76	1	*REAR LID PUSH BOTTON	Not Necessary	1,181.00 FS	*- FS
77	1	*REAR GASKET FLAP	Necessary	181.00 FS	*144.80 FS
78	1	*REAR LID MOTOR STRIKER PLATE	Not Necessary	550.00 FS	*- FS
79	1	*REAR LID LOCK	Not Necessary	170.00 FS	*- FS
80	1	*ADHESIVE PACKING	Necessary	15.00 FS	*11.60 FS
81	1	*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
82	1	*INSCRIPTION A6	Necessary	83.00 FS	*66.16 FS
83	1	*INSCRIPTION TFSI	Necessary	83.00 FS	*66.16 FS
84	1	*REAR LID DECORATIVE TRIM	Necessary	317.00 FS	*253.20 FS
85	1	*BOOT LID CONTROL UNIT	Not Necessary	372.00 FS	*- FS
86	1	*TAILGATE SENSOR LINE	Not Necessary	184.00 FS	*- FS
87	6	*CABLE TERMINAL	Not Necessary	39.00 FS	*- FS
88	1	*REAR CROSS PANEL	Dented	274.00 FS	*219.20 FS
89	1	*REAR CROSS PANEL REINFORCEMENT	Dented	639.00 FS	*511.20 FS
90	2	*REAR CONNECTIN PLATE - LH/RH	Not Necessary	78.00 FS	*- FS
91	1	*REAR NO. PLATE	Bent	25.00 FS	*25.00 FS
92	1	*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
93	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
94	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
95	1	*SUNDRIES	Necessary	600.00 FS	*68.96 FS
96	2	*FRONT PARKING AID - OUTER	Not Necessary	421.00 FS	*- FS
97	2	*FRONT PARKING AID - INNER	Not Necessary	392.00 FS	*- FS
98	1	*COVER CAP-LH/RH	N/S Deformed	98.00 FS	*39.12 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 54,929.00 24,813.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	2,750.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET	New	3,400.00	1,650.00
5	TO REMOVE AND TRANSFER LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
7	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,700.00	1,650.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	192.00
9	TO REPAIR & RESPRAY LHS REAR FENDER	New	1,400.00	800.00
10	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING DAMAGE	New	280.00	280.00
11	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR OUTER, INNER REAR CROSS PANEL AND CONNECTING PLATES. RENEW REAR BUMPER AND REAR LID, ALIGN TO POSITION. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	2,750.00
Gross Labour Cost (S\$)			21,104.00	12,512.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >