



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
1 Soon Lee Street #04-44/45
Pioneer Centre
Singapore 627605
Tel: 626204438 Fax: 6484 1111

CKK

TO	: 21426 MID,	DATE	: 30-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SGG3065Z
ADDRESS	:	MODEL	: NISSAN MURANO
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : MICHAEL 9018 3598 / KUMAR 9897 3736			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH	1	\$1,432.80	\$ 1,432.80
2	REAR FENDER RH	1	\$1,548.00	\$ 1,548.00
3	REAR AXLE	1	\$2,145.00	\$ 2,145.00
4	REAR EXHAUST PIPE	1	\$1,245.00	\$ 1,245.00

TOTAL PRICE \$ 6,370.80
LESS 30% \$ 1,911.24
SUB TOTAL PRICE \$ 4,459.56

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 754.00	\$ 754.00
2	REAR BUMPER SIDE RETAINER	2	\$ 45.20	\$ 90.40
3	REAR BUMPER REFLECTOR RH	1	\$ 47.60	\$ 47.60
4	TAIL LAMP RH	1	\$ 489.00	\$ 489.00
5	REAR FENDER GLASS WITH MOULDING RH	1	\$ 598.00	\$ 598.00
6	REAR FENDER INNER TRIM RH	1	\$ 689.00	\$ 689.00
7	REAR FENDER INNER COWLING RH	1	\$ 168.00	\$ 168.00
8	REAR DOOR WHEATHER STRIP	1	\$ 214.00	\$ 214.00
9	REAR DOOR PROTECTOR	1	\$ 211.00	\$ 211.00
10	REAR DOOR OUTER MOULDING	1	\$ 189.00	\$ 189.00
12	REAR DOOR INNER LOCK RH	1	\$ 421.00	\$ 421.00
13	REAR DOOR LOCK CATCHER RH	1	\$ 34.60	\$ 34.60
14	REAR FENDER RUBBER	1	\$ 144.00	\$ 144.00
15	REAR FENDER AIR VENT	1	\$ 78.00	\$ 78.00

16	REAR SHOCK ABSORBER RH	1	\$ 426.00	\$ 426.00	X
17	REAR WHEEL HUP RH	1	\$ 397.90	\$ 397.90	?
18	REAR WHEEL HUP BEARING RH	1	\$ 180.20	\$ 180.20	?
19	REAR LOWER ARM	1	\$ 448.00	\$ 448.00	X
20	REAR KNUKLE ARM	1	\$ 541.00	\$ 541.00	?
21	REAR UPPER ARM	1	\$ 415.00	\$ 415.00	X
22	REAR ADJUSTER ARM	1	\$ 428.00	\$ 428.00	X

TOTAL PRICE \$ 6,963.70

LESS 10% \$ 696.37

SUB TOTAL PRICE \$ 6,267.33

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ 65.00	30 new ✓
2	TAIL LAMP CLIP SET	1	\$ 20.00	\$ 20.00	X
3	REAR FENDER SEALANT RH	1	\$ 80.00	\$ 80.00	40 new ✓
4	REAR FENDER COWLING CLIP RH SET	1	\$ 65.00	\$ 65.00	20 new ✓
5	REAR FENDER INNER TRIM CLIP SET	1	\$ 60.00	\$ 60.00	X
6	REAR QUARTER GLASS SEALANT	1	\$ 60.00	\$ 60.00	40 new ✓
7	REAR QUARTER GLASS INNER SEAL	1	\$ 40.00	\$ 40.00	20 new ✓
8	REAR DOOR SEALANT RH	1	\$ 80.00	\$ 80.00	20 new ✓
9	REAR DOOR INNER TRIM CLIP RH SET	1	\$ 90.00	\$ 90.00	20 new ✓
10	REAR DOOR PROTECTOR CLIP SET	1	\$ 50.00	\$ 50.00	10 new ✓
11	REAR DOOR WINDOW FRAME STICKER(BLACK) RH	1	\$ 80.00	\$ 80.00	new ✓
12	REAR WHEEL TYRE RH	1	\$ 450.00	\$ 450.00	X
13	REAR WHEEL RIM RH	1	\$ 750.00	\$ 400 750.00	mt ✓
14	BRAKE OIL	1	\$ 40.00	\$ 40.00	X

TOTAL \$ 1,930.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,600.00	900
2	TO SPRAY PAINT AFFECTED AREA	\$1,500.00	750
3	TUFF COAT	\$250.00	40
4	WIRING CHECK	\$150.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$250.00	60

6	REMOVE & REFIX REAR QUARTER GLASS RH	\$100.00		60.
7	REMOVE AND REFIX REAR UNDERCARRIAGE	\$550.00		Photo 100?
8	TO PRESS REAR WHEEL BEARING	\$40.00		X
9	FOUR WHEEL ALIGNMENT	\$120.00		80.
10	TRANSFER REAR DOOR MECHANISM	\$80.00		60.
11	REMOVE & REINSTALL REAR WINDOW GLASS	\$60.00		X
12	CONDUCT WATER LEAKAGE TEST	\$120.00		20.
13	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00		30.
14	RESET ABS LIGHT	\$350.00		X

TOTAL \$5,250.00

TOTAL PARTS COST : \$ 12,656.89
TOTAL LABOUR COST : \$ 5,250.00
TOTAL REPAIR COST : \$ 17,906.89

Tanji 97498749
- WP -
3/5/18 e6 pro

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Lump sum
Resurvey after repair.
7 days

LKX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: