

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 15 May 2018

Preliminary Advice

Vehicle No	: SKV9199E	Accident Date	: 03/05/2018
Make	: SUZUKI VITARA	Policy No.	: PNPV2018-00003801
Assignment Date	: 04/05/2018	Excess	: S\$500.00
Date of Inspection	: 14/05/2018	Est. Duration of Repair	: 3.00
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,162.00
Revised Amount	:S\$	2,180.00
Check Items (Estimated)	:S\$	832.00
Total	:S\$	3,012.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	56,179.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,821.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :