

22/03/2002

ASS. REC. BY:

REF: CS / C118008208 / Krbnz

Special Instruction:

Survivor

ASSIGNMENT (Office)

M/Men

From (Person):

Jadyn Jay

of

CTL

Date/Time:

04/05/2018 3:12pm

Estimated Cost:

Bill to:

OD / ~~FF~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QBE 9877C

Insured:

SLT 2403K

at Workshop m/s

City Auto

Tel:

6453 1235

of

Blk 160 San ming Drive #05-01

Policy No:

DMPCSN3072141700

Claim No:

SUM1800214002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 1.01

H.O.D. Endorsement:

Date/Time:

04/05/2018 3:20pm

Person Contacted:

Vronica

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

QBE 9877C - X

SLT 2403K - X

15/11 11 Lm & 1650 Cg form (Fed: 4 2 218.43, 571.)

ASS. REC. BY:

REF: CTZ/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

9/5 File pass to Catherine

RECEIVED 15 NOV 2018

Veh No:

GBE P871C

Yr Regn:

05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

Denz

c.c.

2P82

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

95228

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFA T35Y 60K 206401

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F. Ravelo

193 R13 X8

R: Yokco

155R 12 X 8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

22

mm

L/Bal.

9

mm

L/Bal.

22

mm

D.O.A.

28/4/18

D.O.A.

8/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1) t.pnt



: Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. \$

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / L.B. (\$) :

1650.00

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 May 2018		04 May 2018 15:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIM QIU YIN, KELLY, ID: S9246143B								
Main Claimant:	SEGAR VIGNESHWARAN								
Vehicle Reg. No.:	GBE9877C	Date of Loss:	28/04/2018 08:00 - :59						
Claim Type:	TP / SNM18D02190C02	Policy/Cover Note No.:	DMPCSN3092141700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLT2403K	Policy No. (Claimant):							
		Excess:	\$50.00						
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]								
Adj Asg. Remarks:	EST \$4139.22, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6901M
Vehicle Details	
Vehicle No.:	GBE9877C
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2609392
Chassis No.:	JTFAT35Y60K206401
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	18 May 2016
First Registration Date:	18 May 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,705.00
COE Rebate Amount:	\$30,152.00
Total Rebate Amount:	\$30,152.00

The information contained herein is correct as at 13 Oct 2018

OK



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201805-000009(00)

Date : 02/05/2018

Vehicle No. : GBE9877C

Make/Model : TOYOTA TOYOTA DYNA 150
MANUAL

Mileage (km) : 0

Chassis No. : JTFAT35Y60K206401

Accident Date : 28/04/2018 00:00:00

Claim No. : SLT2403K

Reference : GBE9877C

Policy No. : 5090679918

CHINA TAIPING INSURANCE (S) PTE LTD

3

ANSON RD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Fuse Design PTE LTD

Contact : 97817981

Fax No. : 62247175

*Not withstanding
L1Lm 8/6/5d
Paying After Pay*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	LH Taillamp	1.0	242.70	For 242.70 ✓
2	Tailgate LH latch	1.0	145.70	Ry 145.70 ✓
3	Tailgate LH stopper	1.0	55.80	M11 55.80 ✓
4	Exhaust muffler	1.0	1,878.35	R 1,878.35 X
5	Exhaust muffler mounting	3.0	52.70	Sm 158.10 X
6	Spare tyre bracket	1.0	256.10	Alm 256.10 ✓
7	Number plate bracket	1.0	97.40	Ry 97.40 ✓
List Total :				2,834.15
25% Discount S\$				708.52
				2,125.63
SPECIAL NET :				
1	Reverse sensor	1.0	250.00	shca 250.00 ✓
2	Tailgate sticker - TOYOTA	1.0	135.00	m 135.00 ✓
3	Tailgate sticker - 13 pax	1.0	25.00	m 25.00 ✓
4	Tailgate sticker - Dyna	1.0	37.80	m 37.80 ✓
5	Tailgate sticker - 70km/h	1.0	25.00	m 25.00 ✓
6	Number plate	1.0	25.00	Ry 25.00 2018 ✓
SPECIAL NET Total S\$:				497.80
LABOUR :				
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts		1.0	550.00	4801 550.00 ✓
- Spray painting on affected & replace parts		1.0	650.00	5001 650.00 ✓
*To check and re-wiring		1.0	45.00	201 45.00 ✓
				1,245.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

CONTINUE NEXT PAGE

Page 1 of 2



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201805-000009(00)

Date : 02/05/2018

Vehicle No. : GBE9877C

Make/Model : TOYOTA TOYOTA DYNA 150
MANUAL

Mileage (km) : 0

Chassis No. : JTFAT35Y60K206401

Accident Date : 28/04/2018 00:00:00

Claim No. : SLT2403K

Reference : GBE9877C

Policy No. : 5090679918

CHINA TAIPING INSURANCE (S) PTE LTD

3

ANSON RD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Fuse Design PTE LTD

Contact : 97817981

Fax No. : 62247175


S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$: 3,868.43

GST 7% S\$: 270.79

Amount Due S\$: 4,139.22


for CITY AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118008208/KRBN2

Date: 16/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3092141700
Claimant Vehicle No :	GBE9877C	Insured Vehicle No :	SLT2403K
Date of Loss:	28/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02190C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9877C	Engine No:	1KD2609392
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y60K206401
Reg. Date:	18/05/2016 (Man. Year: 2016)	Odometer:	95228 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8 (D)
Front Left Side:	Rovelo 9 mm	Rear Left Side:	Yokohama 8/8 mm
Front Right Side:	Rovelo 9 mm	Rear Right Side:	Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,623.41	1,041.07	1,582.34	60.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,245.00	1,000.00	245.00	19.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,868.41	2,041.07	1,827.34	47.24
Approved Total (Overridden) (\$\$)		1,650.00		
(\$\$)	3,868.41	1,650.00	2,218.41	57.35
+ GST 7.00/7.00% (\$\$)	270.79	115.50	155.29	57.35
Nett Amount (\$\$)	4,139.20	1,765.50	2,373.70	57.35

INSPECTION

Date of Assignment:	04/05/2018	
Date Inspected:	08/05/2018 Inspected At:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01, Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Nov 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9877C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH TAILLAMP	Scratched	242.70 FL	*242.70 FL
2	1		*TAILGATE LH LATCH	Bent	145.70 FL	*145.70 FL
3	1		*TAILGATE LH STOPPER	Missing	55.80 FL	*55.80 FL
4	1		*EXHAUST MUFFLER	Repair	1,878.35 FL	*- FL
5	3		*EXHAUST MUFFLER MOUNTING	Serviceable	158.10 FL	*- FL
6	1		*SPARE TYRE BRACKET	Bent/Jammed	256.10 FL	*256.10 FL
7	1		*NUMBER PLATE BRACKET	Bent	97.40 FL	*97.40 FL
8	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
9	1		*TAILGATE STICKER TOYOTA	Necessary	135.00 FS	*135.00 FS
10	1		*TAILGATE STICKER 13PAX	Necessary	25.00 FS	*25.00 FS
11	1		*TAILGATE STICKER DYNA	Necessary	37.80 FS	*37.80 FS
12	1		*TAILGATE STICKER 70KM/H	Necessary	25.00 FS	*25.00 FS
13	1		*NUMBER PLATE	Bent	25.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,331.95	1,240.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	708.54	199.43
Total Parts (\$\$)	2,623.41	1,041.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	550.00	480.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	650.00	500.00
3	TO CHECK AND RE-WIRING	New	45.00	20.00
Gross Labour Cost (\$\$)			1,245.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >