

23/05/2018

ASS. REC. BY:

REF:

CS/MSH 18008210/Ktb

Special Instruction:

Survivor

McLaren

Kenneth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSLH

Date/Time:

04052018 226pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 1300Z

Insured:

GBD 9787J

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Bik 7 Gin Ming Ind Est #01-76

Policy No:

J8791913mke

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02052018

CA / REV / REP: / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

04052018 3:04pm

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKN 1300Z - X

GBD 9787J - X

lump Sum \$9650/- Cred: 6920.54 (41%)

ASS. REC. BY:

REF: MSG-1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKN13007

Yr Regn:

05, 14

Type: M-Car / M-Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Ty NIT

c.c

1598

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

59198

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053RE1410400 2816

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

2/5/18

D.O.I.

4/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/5

Pls pers to Corbin

RECEIVED 4 2 JUN 2018

Date/Time, File Pass to?



Prell. Report

1) 12/6 Typist



Final Report

Date/Time, File Return to?

Days Of Repair:

12

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S = RS. \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

9650

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		04 May 2018 14:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS <div style="float: right;">[Created by insurer]</div>									
Insured:		JIA SENG TRADING PTE LTD, Co. Reg. No.: 200800861K							
Main Claimant:		LOO CHIN HAN, ID: S2505303F							
Vehicle Reg. No.:		SKN1300Z	Date of Loss:	02/05/2018 00:00 - :59 [47 Months and 17 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP	Policy/Cover Note No.:	28791913MKC Coverage: 06/08/2017 - 05/08/2018					
Vehicle Reg. No. (Insured):		GBD9787J	Policy No. (Claimant):						
			Excess:						
Repairer:		Alan's United Auto Pte Ltd (SIN MING) BLOCK 7, SIN MING INDUSTRIAL ESTATE, #01-76, 575642 Sin Ming - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/05/2018]							
Adj Asg. Remarks:		TP agree with SJE - To Appoint LKK, Mr Kenneth Kong as surveyor							
ASSOCIATED MAIL RECEIVED <div style="float: right;"> View All Compose Case Mail </div>									
There are no mail for this case.									
ALL ASSOCIATED TASKS <div style="float: right;"> View All Search Tasks Create New Task Complete </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5303F
Vehicle Details	
Vehicle No.:	SKN1300Z
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	1ZR406853
Chassis No.:	MR053REH104002816
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,544.00
Original Registration Date:	15 May 2014
First Registration Date:	15 May 2014
Transfer Count:	0
Actual ARF Paid:	\$13,544.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2024
PARF Rebate Amount:	\$10,158.00
Intended COE Rebate Details	
COE Expiry Date:	14 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,602.00
COE Rebate Amount:	\$47,309.00
Total Rebate Amount:	\$57,467.00

The information contained herein is correct as at 07 May 2018

OK

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: S2505303F

Owner ID Type: Singapore NRIC

☐ Owner Name: LOO CHIN HAN

Registered Address: 42 TU FU AVENUE SINGAPORE 787249

Mailing Address: -

Birth Date: 23 Sep 1955

Vehicle Particulars

☐ Vehicle No.: SKN1300Z

Previous Vehicle No.: -

Effective Date of Ownership: 15 May 2014

Original Regn Date: 15 May 2014

Registration Date: 15 May 2014

Year of Manufacture: 2014

Vehicle Type: Passenger Motor Car

PARF Eligibility Expiry Date: 14 May 2024

Minimum PARF Benefit: \$6,772.00

No. of Transfers: 0

IU Label No.: 1125296277

COE No.: 2014040101000470H

COE Expiry Date: 14 May 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)

Quota Premium (QP) / Prevailing
Quota Premium: \$78,602.00 / -

Actual QP Paid: \$78,602.00

QP (Regn Cat): \$78,602.00

OPC Cash Rebate Eligibility: No

QP during COE Bidding Exercise: \$78,602.00

Additional Registration Fee Rate: First \$18,544.00 (100%)

Actual ARF Paid: \$13,544.00

Vehicle Lifespan Expiry Date: No Lifespan

CO2 Emission: 151.00 (g/km)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 16:39
Date Of Accident	02/05/2018 08:45
Exact Location Of Accident	KALIDASA AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN1300Z
Insured/Policyholder	
Name Of Registered Owner	LOO CHIN HAN
NRIC No	S2505303F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96660989
Alternative Phone No	OTHERS-96660989

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100373237-03000
Cover Note Number	

Driver

Name of Driver	KWA SIEW HWA
NRIC No	S1367607J
Date Of Birth	20/12/1959
Occupation	INDOOR
Date Of Driving Pass	25/01/1980
Driving Experience	38 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90299377

Fax Number

Contact Number

Email Address

SIEWHWA.KWA@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: S6927273H

Accident along Kulidasa Avenue, Teachers' Estate.

Date : 2 May 2018

Time : ~ 8.45 am.

My Vehicle :- Toyota Altis SKN 1300Z

The other vehicle : Truck GBD 9787 J

Details

I was driving along Kulidasa Road, heading out of the estate. Just as I crossed Li Po Avenue (a road perpendicular to Kulidasa Avenue), I saw a truck turning out of the side road (see photo). It was impossible for me to brake in time and I heard a loud "bang". My car was hit.

I stepped out of my car and saw that the right side of my car was badly damaged. The truck that hit me had a small dent on the left side of the front of the truck (see photo). The impact on my car was quite big as my glove compartment opened and could not be closed back.

Details of the driver is as shown in the attached photograph.



DR KWA SIEW HWA
S 1367607 J

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBD9787J
Accident Date : 02-May-2018

No. : 05775

Date : 03-May-2018

Our Ref : 218077 (MSIG) / CHAN

PAGE : 1

LOO CHIN HAN
42 TU FU AVENUE
Singapore 787249

*Not Authorized
L1 Syg 896501
Reserving After Paint*

12 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SKN1300Z

1 pc Bonnet		As 1,028.10	✓
1 pc Bonnet insulator		Sm 253.10 X	
10 pcs Bonnet insulator clip	@ S\$ 3.80	Sm 38.00	✓
1 pc Bonnet stand		As 73.40 X	
1 pc Bonnet stand clip		Sm 19.30	✓
1 pc Bonnet rubber		Sm 54.30 X	
2 pcs Bonnet hinge	@ S\$ 50.10	Dis 100.20	✓
1 pc Bonnet inner lock		Dis 128.90	✓
1 pc Radiator grille		CM 559.60	✓
1 pc Radiator top garnish		As 81.20	✓
1 pc Front support panel		As 977.60	✓
1 pc Brace panel		As 103.10	X
1 pc Radiator assy		Sm 1,764.10	✓ X
1 pc Radiator fan cowling		Sm 246.90 X	
1 pc Fan cowling top cover		Sm 79.30	✓ X
1 pc Radiator spare tank		Dis 155.70	✓
1 pc Radiator lower hose		Sm 71.20 X	
1 pc Radiator top hose		Sm 42.20 X	
1 pc W/s glass washer tank		Dis 170.40	✓
2 pcs Headlamp	elsem n/s mtycm @ \$2202.70	4,405.40	✓
1 pc Air con condenser		Sm 1,404.20	X
1 pc Front o/s fender		As 716.60	✓
1 pc Front o/s fender inner shield		CM 236.70	✓
1 pc Front o/s fender VVTi emblem		As 38.30	✓
1 pc Front bumper fascia		CM 458.10	✓
1 pc Front bumper reinforcement		As 379.20	✓
1 pc Front bumper inner sponge		CM 91.20	✓
2 pcs Front bumper side retainer	@ S\$ 82.80	165.60	elsem
1 pc Front bumper lower grille		CM 139.30	✓

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBD9787J

Page : 2

- 1 pc Wiper garnish
- 2 pcs Wiper side garnish
- 1 pc Front bumper under cover
- 1 pc Groove compartment cover

614.10 X
 @ S\$ 35.80 71.60 X
 145.80 X
 463.60 X

 15,276.30
 Less 25% : 3,819.08

10566.50
 2646.63
 7924.87

- 1 pc Front no.plate with box
- 1 pc Radiator coolant

11,457.22
 50.00 sn X
 30.00 sn 20%

To towing

60.00 Sol

To rewire damaged parts and refocus headlamp beam.to diagnostic & reset

120.00 Sol

To apply undersealing

60.00 ✓

To putty and spray replaced parts

1,000.00 Sol

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

1,200.00 Sol

Total : S\$13,977.22

Singapore Dollars Thirteen Thousand Nine Hundred and Seventy Seven and Cents Twenty Two Only

c/sump 98506 P 7924.87
~~9850.00~~
 KENNETH RS
 CASHIER 7/1/18
 S.P 1328.32
 SN 20.00
 L 1790.00
 S.L 1265.00

 12328.19
 2465.64

 9862.55

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBD9787J (MSIG)

Date : 07-05-2018

Accident Date : 02-05-2018

Our Ref : 218077 /CHAN

LOO CHIN HAN

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR TOYOTA ALTIS SKN1300Z

1 PC	FRONT O/S CHASSIS MEMBER	<i>By</i>	\$1,084.20	—
1 PC	FRONT O/S CHASSIS MEMBER BRACKET	<i>By</i>	\$74.20	—
1 PC	RH ENGINE MOUNTING	<i>CM</i>	\$423.90	—
1 PC	FRONT ENGINE MOUNTING	<i>CM</i>	\$188.80	—
			\$1,771.10	
		LESS 25%	\$442.78	
			<u>\$1,328.32</u>	

\$1,328.32

TO COMPUTER ALIGNMENT	\$65.00	<i>60</i>
TO LOWER FRONT UNDERCARRIAGE	\$200.00	<i>180</i>
TO LIFT OUT ENGINE ASSY	\$450.00	<i>300</i>
TO PUTTY AND SPRAY REPLACE PARTS	\$250.00	<i>200</i>
TO PANEL BEATING ,CUT OUT, REMOVE DAMAGED PARTS ,ALIGN ,ADJUST		
AND REFIX REPLACE PARTS	\$300.00	✓
	<u>\$2,593.32</u>	

Singapore Dollars Two Thousand Five Hundred Ninety Three And Cents Thirty Two Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05775

Vehicle Insured : GBD9787J
Accident Date : 02-May-2018

Date : 03-May-2018

Our Ref : 218077 (MSIG) / CHAN

PAGE : 1

LOO CHIN HAN
42 TU FU AVENUE
Singapore 787249

*Not Notified
L1 By 8?
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SKN1300Z

1 pc	Bonnet			By	1,028.10	✓
1 pc	Bonnet insulator			Sm	253.10	X
10 pcs	Bonnet insulator clip	@ S\$ 3.80		Sm	38.00	✓
1 pc	Bonnet stand			Sm	73.40	X
1 pc	Bonnet stand clip			Sm	19.30	✓
1 pc	Bonnet rubber			Sm	54.30	X
2 pcs	Bonnet hinge	@ S\$ 50.10		Di	100.20	✓
1 pc	Bonnet inner lock				128.90	?
1 pc	Radiator grille grille				559.60	?
1 pc	Radiator top garnish				81.20	?
1 pc	Front support panel			By	977.60	✓
1 pc	Brace panel			X	103.10	X
1 pc	Radiator assy				1,764.10	?
1 pc	Radiator fan cowling			Sm	246.90	X
1 pc	Fan cowling top cover				79.30	?
1 pc	Radiator spare tank			Red	155.70	✓
1 pc	Radiator lower hose			Sm	71.20	X
1 pc	Radiator top hose			Sm	42.20	X
1 pc	W/s glass washer tank				170.40	?
2 pcs	Headlamp	<i>olsep n/s m30m</i> @ \$2202.70			4,405.40	✓
1 pc	Air con condenser				1,404.20	?
1 pc	Front o/s fender			Br	716.60	✓
1 pc	Front o/s fender inner shield			CM	236.70	✓
1 pc	Front o/s fender VVTi emblem			Sm	38.30	✓
1 pc	Front bumper fascia			CM	458.10	✓
1 pc	Front bumper reinforcement			By	379.20	✓
1 pc	Front bumper inner sponge			CM	91.20	✓
2 pcs	Front bumper side retainer	@ S\$ 82.80			165.60	<i>olsep</i>
1 pc	Front bumper lower grille				139.30	?

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cont Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBD9787J

Page : 2

1 pc Wiper garnish
2 pcs Wiper side garnish
1 pc Front bumper under cover
1 pc Groove compartment cover

614.10 *sn* 614.10 *X*
@ S\$ 35.80 *sn* 71.60 *X*
145.80 *?*
463.60 *?*

15,276.30
Less 25% : 3,819.08

1 pc Front no.plate with box
1 pc Radiator coolant

11,457.22
sn 50.00 *sn X*
sn 30.00 *sn 20,*

To towing

60.00 *sol*

To rewire damaged parts and refocus
headlamp beam.to diagnostic & reset

120.00 *sol*

To apply undersealing

60.00 *✓*

To putty and spray replaced parts

1,000.00 *sol*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

sol
1,200.00

Total : S\$13,977.22
=====

Singapore Dollars Thirteen Thousand Nine Hundred
and Seventy Seven and Cents Twenty Two Only






































...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		04 May 2018 14:26 Edit Adj Rpt	S\$9,650.00 Edit Estimates	S\$9,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: JIA SENG TRADING PTE LTD , Co. Reg. No.: 200800861K									
Main Claimant: LOO CHIN HAN , ID: S2505303F									
Vehicle Reg. No.: SKN1300Z		Date of Loss: 02/05/2018 08:00 - :59 [47 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 557557		Policy/Cover Note No.: 28791913MKC (Comprehensive) Coverage: 06/08/2017 - 05/08/2018							
Vehicle Reg. No. (Insured): GBD9787J		Policy No. (Claimant):							
		Excess: S\$700.00							
Repairer: Alan's United Auto Pte Ltd (SIN MING) BLOCK 7, SIN MING INDUSTRIAL ESTATE, #01-76, 575642 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 05/05/2018]									
Adj Asg. Remarks: TP agree with SJE - To Appoint LKK, Mr Kenneth Kong as surveyor									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN1300Z (557557)
[GBD9787J]
TP
LOO CHIN HAN
May 2 2018 8:00AM
[JIA SENG TRADING PTE LTD]
Alan's United Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
2	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
3	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
4	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
5	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
6	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
7	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
8	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
9	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
10	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
11	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
12	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
13	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
14	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
15	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
16	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
17	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
18	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
19	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
20	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
21	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
22	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
23	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
24	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
25	12/06/18 15:50	General View			Load JPG	<input checked="" type="checkbox"/>					
26	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
27	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
28	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
29	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
30	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
31	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
32	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
33	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
34	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
35	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
36	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					
37	12/06/18 15:54	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 15:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/05/18 11:39	Estimate	 Load PDF	
2	04/05/18 11:40	GBD9787J GIA Rpt	 Load PDF	
3	04/05/18 11:40	SKN1300Z GIA Rpt	 Load PDF	
4	04/05/18 11:41	Email frm TP - PRI	 Load PDF	
5	04/05/18 15:04	IMG_7667	 Load JPG	<input checked="" type="checkbox"/>
6	04/05/18 15:04	IMG_7672	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 10:37	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008210/KTBQ2

Date: 13/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28791913MKC

Claimant Vehicle No : SKN1300Z

Insured Vehicle No : GBD9787J

Date of Loss: 02/05/2018

Nature of Claim: TP

Claim No: 557557

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN1300Z

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZRX406853

Reg. Date: 15/05/2014 (Man. Year: 2014)

Chassis No: MR053REH104002816

Colour: Metallic Grey

Odometer: 59198 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 3 mm

Rear Left Side: Dunlop 3 mm

Front Right Side: Dunlop 3 mm

Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,865.55	9,273.20	3,592.35	27.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,705.00	2,830.00	875.00	23.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,570.55	12,103.20	4,467.35	26.96
Approved Total (Overridden) (S\$)		9,650.00		
(S\$)	16,570.55	9,650.00	6,920.55	41.76
+ GST 7.00/7.00% (S\$)	1,159.94	675.50	484.44	41.76
Nett Amount (S\$)	17,730.49	10,325.50	7,404.99	41.76

INSPECTION

Date of Assignment: 04/05/2018

Date Inspected: 04/05/2018 Inspected At:

Alan's United Auto Pte Ltd (SIN MING)
 BLOCK 7, SIN MING INDUSTRIAL
 ESTATE, #01-76
 Singapore 575642

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN1300Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,028.10 FL	*1,028.10 FL
2	1		*BONNET INSULATOR	Bracket cracked	253.10 FL	*- FL
3	10		*BONNET INSULATOR CLIP	Necessary	38.00 FL	*38.00 FL
4	1		*BONNET STAND	Repair	73.40 FL	*- FL
5	1		*BONNET STAND CLIP	Necessary	19.30 FL	*19.30 FL
6	1		*BONNET RUBBER	Serviceable	54.30 FL	*- FL
7	2		*BONNET HINGE	Distorted	100.20 FL	*100.20 FL
8	1		*BONNET INNER LOCK	Distorted	128.90 FL	*128.90 FL
9	1		*RADIATOR GRILLE	Cracked	559.60 FL	*559.60 FL
10	1		*RADIATOR GRILLE TOP GARNISH	Dented	81.20 FL	*81.20 FL
11	1		*FRONT SUPPORT PANEL	Bent	977.60 FL	*977.60 FL
12	1		*BRACE PANEL	Repair	103.10 FL	*- FL
13	1		*RADIATOR ASSY	Serviceable	1,764.10 FL	*- FL
14	1		*RADIATOR FAN COWLING	Serviceable	246.90 FL	*- FL
15	1		*FAN COWLING TOP COVER	Serviceable	79.30 FL	*- FL
16	1		*RADIATOR SPARE TANK	Dented	155.70 FL	*155.70 FL
17	1		*RADIATOR LOWER HOSE	Serviceable	71.20 FL	*- FL
18	1		*RADIATOR TOP HOSE	Serviceable	42.20 FL	*- FL
19	1		*W/S GLASS WASHER TANK	Dented	170.40 FL	*170.40 FL
20	2		*HEADLAMP	O/S Cracked /N/S Mtg Cracked	4,405.40 FL	*4,405.40 FL
21	1		*AIR CON CONDENSER	Serviceable	1,404.20 FL	*- FL
22	1		*FRONT O/S FENDER	Buckled	716.60 FL	*716.60 FL
23	1		*FRONT O/S FENDER INNER SHIELD	Cracked	236.70 FL	*236.70 FL
24	1		*FRONT O/S FENDER VVTI EMBLEM	Necessary	38.30 FL	*38.30 FL
25	1		*FRONT BUMPER FASCIA	Cracked	458.10 FL	*458.10 FL
26	1		*FRONT BUMPER REINFORCEMENT	Bent	379.20 FL	*379.20 FL
27	1		*FRONT BUMPER INNER SPONGE	Cracked	91.20 FL	*91.20 FL
28	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	165.60 FL	*82.80 FL
29	1		*FRONT BUMPER LOWER GRILLE	Cracked	139.30 FL	*139.30 FL
30	1		*WIPER GARNISH	Cut	614.10 FL	*614.10 FL
31	2		*WIPER SIDE GARNISH	Serviceable	71.60 FL	*- FL
32	1		*FRONT BUMPER UNDER COVER	Cracked	145.80 FL	*145.80 FL
33	1		*GROVE COMPARTMENT COVER	Serviceable	463.60 FL	*- FL
34	1		*FRONT NO PLATE WITH BOX	Serviceable	50.00 FS	*- FS
35	1		*RADIATOR COOLANT	Necessary	30.00 FS	*20.00 FS
36	1		*FRONT O/S CHASSIS MEMBER	Bent	1,084.20 FL	*1,084.20 FL
37	1		*FRONT O/S CHASSIS MEMBER BRACKET	Bent	74.20 FL	*74.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*RH ENGINE MOUNTING	Cracked	423.90 FL	*423.90 FL
39	1		*FRONT ENGINE MOUNTING	Cracked	188.80 FL	*188.80 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,127.40	12,357.60
- List Item Discount on L Items 25.00/25.00% (\$\$)					4,261.85	3,084.40
Total Parts (\$\$)					12,865.55	9,273.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOWING	New	60.00	50.00
2	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM TO DIAGNOSTIC & RESET	New	120.00	80.00
3	TO APPLY UNDERSEALING	New	60.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	800.00
5	TO REMOVE,CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,200.00	800.00
6	TO COMPUTER ALIGNMENT	New	65.00	60.00
7	TO LOWER FRONT UNDERCARRIAGE	New	200.00	180.00
8	TO LIFT OUT ENGINE ASSY	New	450.00	300.00
9	TO PUTTY AND SPRAY REPLACE PARTS	New	250.00	200.00
10	TO PANEL BEATING ,CUT OUT ,REMOVE DAMAGED PARTS ,ALIGN ,ADJUST AND REFIX REPLACE PARTS	New	300.00	300.00
Gross Labour Cost (\$\$)			3,705.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >