

23/03/2012

ASS. REC. BY:

REF: CS/CT18008211 / TH 6

Special Instruction:

SURVEYOR
MIRANDA

ASSIGNMENT (Office)

From (Person):

Juwyn Tay

of

CTE

Date/Time:

04/05/2018 1.23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 8531J

Insured:

SKZ 1105Y

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Rd

Policy No:

DMPCSH 30047 01802

Claim No:

SHM 180 02268C02

Sum Insured:

Excess:

Make of Veir:

(Client's Record)

D.O.A.

02052018

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

04/05/2018 2:48pm

Person Contacted:

Cerdine

Vehicle-IN/OUT

| Date/Time | Action/Instruction (<input checked="" type="checkbox"/>) Estimate |
|-----------|---|
| | SKH 8531J - x |
| | SKZ 1105Y - x |
| | Confirm final figure @ \$3273.10 (Red. 1929.80; 37%) |

Signature *Tanpin*

REF: CTI

ASSIGNMENT

From: _____ Date: 15/5/18

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKH 8531 J

at Workshop m/s Performance

of 303 Alexandra Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SKH 8531 J Yr Regn: 2010, June

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 320i c.c. 1995

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 5456 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA PG 56000NM 22753

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: n n

(Policy Condition)

| | |
|-----|-----|
| N/S | O/S |
| X | |

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$40K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1 up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

| | | | |
|-----------------|----|----------------------|----|
| Front | | Rear | |
| R/Bal. <u>6</u> | mm | R/Bal. <u>6</u> | mm |
| L/Bal. <u>6</u> | mm | L/Bal. <u>6</u> | mm |
| D.O.A. | | D.O.I. <u>1/5/18</u> | |

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 31 AUG 2018

Date/Time File Pass to? Preli. Report

31/8 TYPIST Final Report

Date/Time File Return to? _____

Report Format: TP

Lump Sum / I.B.I: (\$) 3273.10

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Week-end (\$)

Photos _____

Others _____

TOTAL _____

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 21 August 2018 4:06 PM
To: PBSP; Taufikh (LKKAuto); SUR
Subject: RE: FINAL REPORT / SKH8531J

Dear Caroline ,

Confirm final figure at 3273.10, 3days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 19 June 2018 1:47 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKH8531J

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,164.00
Total Parts : 1,109.10
Total Labour & Parts : 3,273.10

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

ise Tay (LKKAuto)

: PBSP <pml-pbsp@simedarby.com.sg>
: Tuesday, 19 June 2018 1:47 PM
: Taufikh (LKKAuto); SUR
Subject: FINAL REPORT / SKH8531J
Attachments: Final Report SKH8531J.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,164.00

Total Parts : 1,109.10

Total Labour & Parts : 3,273.10

Repair days: 3

Thank you,

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sino Derby Group
 Co. Reg. No. 19740159W, GST Reg. No. M2-002081-K



FINAL REPORT

Estimate No. : b1 46821
 Date Estimated : 03/05/2018
 Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
 Aw Zhan Hao @Aw Kok Hin
 11 Toh Tuck Road, High Oak Condominium
 #04-08

- ACCOUNT - 135
 China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

Singapore 596290

| REGN NO | CHASSIS NO | REGN DATE | MODEL | MILEAGE | | |
|---|------------|------------|----------------|---------|---------|----------|
| SKH8531J | NM22753 | 25/06/2010 | 320i/4 (A) | 0 | | |
| DESCRIPTION | | | ORIGINAL PRICE | DISC. % | | NETT |
| To replace rear bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident | | | 850.00 | | | 850.00 |
| To respray rear bumper | | | 934.00 | | | 934.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. | | | 150.00 | | | 150.00 |
| To check electrical wiring systems and lightings at the rear section for proper function. | | | 150.00 | | | 150.00 |
| Sundries. | | | 80.00 | | | 80.00 |
| DESCRIPTION | | | UNIT PRICE | QTY | DISC. % | NETT |
| RR BUMPER (PDC) | | | 1,109.10 | 1.00 | | 1,109.10 |

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|-----------------|
| Total Labour : | 2,164.00 |
| Total Parts : | 1,109.10 |
| Total Labour & Parts : | 3,273.10 |
| Deduction for Excess : | |
| Total Repair Costs less Excess: | 3,273.10 |
| GST @7%: | 229.12 |
| Grand Total : | 3,502.22 |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------|
| Date Of Report | 03/05/2018 17:13 |
| Date Of Accident | 02/05/2018 19:00 |
| Exact Location Of Accident | BT TIMAH EXIT 26B |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------|
| Vehicle Registration Number | SKH8531J |
| Insured/Policyholder | |
| Name Of Registered Owner | AW ZHAN HAO @ AW KOK HIN |
| NRIC No | S6832174C |
| Email Address | ZHANHAO@HOTMAIL.COM |
| Mobile Phone No | (LOCAL) +65-90214213 |
| Alternative Phone No | OFFICE-90214213 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | BMW |
| Model | 320i |
| Exact Purpose for which vehicle was being used at time of accident | NORMAL USAGE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | |
| Cover Note Number | |

Driver

| | |
|----------------------|--------------------------|
| Name of Driver | AW ZHAN HAO @ AW KOK HIN |
| NRIC No | S6832174C |
| Date Of Birth | 23/08/1968 |
| Occupation | INDOOR |
| Date Of Driving Pass | 30/03/1990 |
| Driving Experience | 28 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90214213 |
| Fax Number | |
| Contact Number | OFFICE-90214213 |
| Email Address | ZHANHAO@HOTMAIL.COM |

| | |
|---|-----------------------|
| Address | 11 TOH TUCK RD #04-08 |
| Postcode | 596290 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 4 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | YES |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|-----------------|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| POLICE STATION NAME [OTHER] | BUKIT TIMAH NPP |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---|
| Vehicle Registration Number | SKZ1403Y |
| Vehicle Make/Model/Colour | HONDA VEZEL |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | DAN KOH |
| NRIC/Passport Number | |
| Contact Number | 96931828 |
| Address | |
| Postcode | |
| Insurance Company Name | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SGJ6580S |
|-----------------------------|----------|

| | |
|-------------------------------------|---------------|
| Vehicle Make/Model/Colour | PERODUA |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | TAN LAI THENG |
| NRIC/Passport Number | |
| Contact Number | 87870336 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF OTHER VEHICLE PROPERTY 3

| | |
|-------------------------------------|--------------|
| Vehicle Registration Number | SJH1519D |
| Vehicle Make/Model/Colour | HONDA STREAM |
| Details Of Properties | |
| Vehicle Category | PRIVATE HIRE |
| Name of Driver | CHEW HETAH |
| NRIC/Passport Number | |
| Contact Number | 83530571 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
 Policyholder's Signature
 Date & Time:

X 
 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: 03/05/18
 (3.56 PM)


 Reporting Central Personnel's Signature
 Name:
 NRIC/PIV No.:



**SINGAPORE
POLICE FORCE**



T/20180502/2182

1 of 3

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

Report No. T/20180502/2182

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|-------------------------------------|--------------------------|
| Date/Time Report Made: 02/05/2018 20:43 | Vide Report No.: D/20180502/0091 | Station Diary No.: 40 |
|--|-------------------------------------|--------------------------|

Informant's Particulars

| | | | |
|--|------------|--|------------------------------|
| Name of Informant: AW ZHAN HAO | | Address: 11 TOH TUCK ROAD #04-08 SINGAPORE 596290 | |
| ID Type / ID No.: NRIC NO / S6832174C | | Contact No.: Home/Office: Mobile: 90214213 | |
| Nationality: SINGAPORE CITIZEN | | Email: | |
| Sex: Male | Age: 49 | Date of Birth: 23/08/1968 | Type of Informant: Driver |
| Race: Chinese | | Language: | Institution / School Name: |
| Occupation: Manager | | Driving Licence Information: Class: 2B,3,4 | Date of Expiry: |

General Information of the Accident

| | | | | |
|---|---------------------------|------------------------------------|--|--------------------------------------|
| Type of Accident: | Injury Attended by Police | Drink Drive: No | Date/Time of Accident: 02/05/2018 19:00 | Type of Location: Straight Road |
| Location: Along Road 1 PAN ISLAND EXPRESSWAY Toward Changi at exit 26B | | | | |
| Weather: Clear | | Road Surface: Wet | | Road Speed Limit: |
| Traffic Flow: Dual Carriage Way | | Traffic Control: Not Controlled | | Traffic Volume: Heavy |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | | Anyone conveyed by ambulance: Yes |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|------|-------|-------|-------------------|-----------------|
| SGJ6580S | Car | | | | Seriously Damaged | 4 |
| SJH1519D | Car | | | | Seriously Damaged | 1 |
| SKH8531J | Car | | | | Slightly Damaged | 1 |
| SKZ1403Y | Car | | | | Slightly Damaged | 1 |



**SINGAPORE
POLICE FORCE**



T/20180502/2182

2 of 3

Report No. T/20180502/2182

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date, time and location, I was heading back home and was queuing at exit 26b. The traffic at that material time was heavy thus car moving slowly. I was stationary when suddenly I felt an impact from the rear. I then went out from my vehicle and discovered that 4 cars are involved in a chain accident. I then check on the other drivers to see if any assistance needed. Shortly after, traffic police and ambulance arrived at the accident scene.

I was then advised to lodge a police report. I'm not injured due to this accident. There is no in car video installed in my car.



**SINGAPORE
POLICE FORCE**



T/20180502/2182

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 3

Report No. T/20180502/2182

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

| | | | |
|--|--------------------------------|---------------------------|------------------------|
| Signature Of Officer Recording The Report: D / Sgt 3 SAIFULBAHRI BIN SHA'ARI | Signature Of Informant: | | |
| Signature Of Interpreter: Not applicable | Date/Time: 02/05/2018 20:43 | | |
| Officer In Charge Of Case: TP / GIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436 | Classification Of Case: | | |
| Authentication Stamp NP168 | | | |
| <table border="1"> <tr> <td data-bbox="377 1844 776 2023"> SINGAPORE POLICE FORCE </td> <td data-bbox="776 1844 879 2023"> SN 38 SIGNATURE </td> </tr> </table> | | SINGAPORE POLICE FORCE | SN 38 SIGNATURE |
| SINGAPORE POLICE FORCE | SN 38 SIGNATURE | | |

Tues 15/05 @ 10am
S&R

SKH8531J



BMW Dealer:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796634 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

03 MAY 2018

@ 5.30pm

| | |
|-----------------------------|-------------------|
| Estimate No. : b1 46821 | Page No. : 1 of 2 |
| Date Estimated : 03/05/2018 | |
| Prepared By : Han Kwan Yong | |

| | |
|---|--|
| - ESTIMATE REPAIR FOR - Aw Zhan Hao @Aw Kok Hin 11 Toh Tuck Road, High Oak Condomin #04-08 Singapore 596290 | - ACCOUNT - 40000 Cash Sales - Service Singapore |
|---|--|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|------------|---------|
| SKH8531J | NM22753 | 25/06/2010 | 320i/4 (A) | 0 |

| DESCRIPTION | VALUE |
|---|-----------------|
| To replace rear bumper & attachments including to knock out dented area caused by the accident | 850 1,275.00 |
| To respray rear bumper | 934 1,038.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. | 150 177.00 |
| To check electrical wiring systems and lightings at the rear section for proper function. | 150 177.00 |
| Sundries. | all? 80.00 |
| Total Labour 1: | 2,747.00 |

| DESCRIPTION | QTY | PRIC | VALUE |
|-------------------------------------|-----|----------|-----------------|
| # REAR BUMPER SET MOUNTING PAR | 1 | 33.15 | 33.15 |
| RR BUMPER CARRIER | 1 | 424.25 | 424.25 |
| RR BUMPER CTR GUIDE | 1 | 31.60 | 31.60 |
| RR BUMPER LH GUIDE | 1 | 57.05 | 57.05 |
| # RR BUMPER (PDC) | 1 | 1,109.10 | 1,109.10 |
| DECOUPLING RING PDC TORQUE CONVERTE | 2 | 5.05 | 10.10 |
| PDC sensor | 2 | 368.80 | 737.60 |
| (DG/SL) ADHESIVE SET K6 | 1 | 53.05 | 53.05 |
| Total Parts : | | | 2,455.90 |

Performance Motors Limited

A member of the Sime Darby Group
 Co., Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Tel. 63190100 (Sales & Admin)
 63190111 (AfterSales)
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Tel. 63190888 (AfterSales)
 Fax. 83449772

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Tel. 63190528 (AfterSales)
 63190533/530 (Motorrad)
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

| | |
|-----------------------------|-------------------|
| Estimate No. : b1 46821 | Page No. : 2 of 2 |
| Date Estimated : 03/05/2018 | |
| Prepared By : Han Kwan Yong | |

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|------------|---------|
| SKH8531J | NM22753 | 25/06/2010 | 320i/4 (A) | 0 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Claims CD / 0 / Uninsured losses / Direct Subcontract

Reg No. _____ Claim No. _____

Deal Time 16/5/18 @ 1010 Excess \$ _____

Surveyor's Name Taufan Sign Taufan

Surveyor's Tel 97495749 Insured Yes/No _____

Authorised By _____ Title _____

RESURVEY PARTS MUST BE BY SURVEYOR 0 / INC. FILE YES/NO _____

Surveyor's Email taufan@lkkauto.com

Max of Working Days 3 days

| | | |
|--------------------|---|-----------------|
| Labour 1 | : | 2,747.00 |
| Parts | : | 2,455.90 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 364.20 |
| Grand Total | : | 5,567.10 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **






























...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 04 May 2018 | | 04 May 2018 13:23 Edit Adj Rpt | S\$3,273.10 Edit Estimates | S\$3,273.10 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | KOH SAI YEOW , ID: S1767332G | | | | | | | | |
| Main Claimant: | AW ZHAN HAO @ AW KOK HIN , ID: S6832174C | | | | | | | | |
| Vehicle Reg. No.: | SKH8531J | Date of Loss: | 02/05/2018 19:00 - :59 [94 Months and 7 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM18D02268C02 | Policy/Cover Note No.: | DMPCSN3004701802 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SKZ1403Y | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174] | | | | | | | | |
| Claimant's Insurer: | Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/05/2018] | | | | | | | | |
| Driver/Custodian (Insured): | KOH SAI YEOW (51 / Female), NRIC: S1767332G | | | | | | | | |
| Adj Asg. Remarks: | EST \$5567.10, CASE WITH SJE. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SKH8531J (SNM18D02268C02)
[SKZ1403Y]
TP
AW ZHAN HAO @ AW KOK HIN
May 2 2018 7:00PM
[KOH SAI YEOW]
Performance Motors Limited

| Upload Documents Upload Photos Compose New Letter | | | View | View in Browser <input type="button" value="v"/> |
|---|-----------------|---|--|--|
| Assessment Reports | | | 1 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 03/05/18 17:32 | Accident Statement |  Load HTM | <input type="checkbox"/> |
| Photos/Images | | | 3 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 4 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 5 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 6 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 7 | 03/05/18 17:28 | Accident Photo [Linked Accident Report Documents] |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 4 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 5 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 6 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 7 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 8 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 9 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 10 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 11 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 12 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 13 | 30/08/18 17:25 | General View |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 14 | 30/08/18 17:25 | Reinspection Photo |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 15 | 30/08/18 17:25 | Reinspection Photo |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 16 | 30/08/18 17:25 | Reinspection Photo |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 17 | 30/08/18 17:25 | Reinspection Photo |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 18 | 30/08/18 17:25 | Reinspection Photo |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 19 | 30/08/18 17:25 | Reinspection Photo |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 04/05/18 13:23 | PRS |  Load PDF | <input type="checkbox"/> |
| 2 | 04/05/18 13:23 | OI GIA REPORT |  Load PDF | <input type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 03/05/18 17:27 | Sketch Plan [Linked Accident Report Documents] | Load TIF | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 03/05/18 17:32 | Accident Statement | Load HTM | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|--|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |
| 2 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |
| 3 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |
| 4 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |
| 5 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |
| 6 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |
| 7 | 03/05/18 17:28 | Accident Photo | Load JPG <input checked="" type="checkbox"/> | |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 03/05/18 17:27 | Sketch Plan | Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| <div style="border: 1px solid black; width: 100%; height: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118008211/T1TBQ2
Date: 06/09/2018

REFERENCE

| | | |
|--|------------------------------|--------------------------|
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: DMPCSN3004701802 | |
| Claimant Vehicle No: SKH8531J | Insured Vehicle No: SKZ1403Y | |
| Date of Loss: 02/05/2018 | Nature of Claim: TP | Claim No: SNM18D02268C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | |
|--|-------------------------------|
| Reg No: SKH8531J | |
| Make & Model: BMW 320i, 2.0 (A) | Engine No: B233i619N46B20BD |
| Reg. Date: 25/06/2010 (Man. Year: 2010) | Chassis No: WBAPG56000NM22753 |
| Colour: Red | Odometer: 59956 km |
| Engine Capacity: 1995 cc | |
| Market Value/New Car Price: N/A | |
| Sum Insured (S\$): Market Value/New Car Price | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | |
|------------------------------------|-----------------------------------|
| Front Tyre Size: 205/55 R16 | Rear Tyre Size: 205/55 R16 |
| Front Left Side: Continental 6 mm | Rear Left Side: Continental 6 mm |
| Front Right Side: Continental 6 mm | Rear Right Side: Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 2,535.90 | 1,189.10 | 1,346.80 | 53.11 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,667.00 | 2,084.00 | 583.00 | 21.86 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 5,202.90 | 3,273.10 | 1,929.80 | 37.09 |
| + GST 7.00/7.00% (S\$) | 364.20 | 229.12 | 135.08 | 37.09 |
| Nett Amount (S\$) | 5,567.10 | 3,502.22 | 2,064.88 | 37.09 |

INSPECTION

| | | |
|--------------------------------------|---------------|--|
| Date of Assignment: 04/05/2018 | | |
| Date Inspected: 16/05/2018 | Inspected At: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941 |
| Estimated Period of Repair: 1.0 days | | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|---|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 05 Sep 2018) |
| Parts: 143 | BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKH8531J) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------|-----|----------|--------------------------------------|---------------|-----------------|-----------------|
| 1 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *80.00 FS |
| 2 | 1 | | *REAR BUMPER SET MOUNTING PAR | Not Necessary | 33.15 FS | *- FS |
| 3 | 1 | | *RR BUMPER CARRIER | Not Necessary | 424.25 FS | *- FS |
| 4 | 1 | | *RR BUMPER CTR GUIDE | Not Necessary | 31.60 FS | *- FS |
| 5 | 1 | | *RR BUMPER LH GUIDE | Not Necessary | 57.05 FS | *- FS |
| 6 | 1 | | *RR BUMPER (PDC) | Deformed | 1,109.10 FS | *1,109.10 FS |
| 7 | 2 | | *DECOUPLING RING PDC TORQUE CONVERTE | Not Necessary | 10.10 FS | *- FS |
| 8 | 2 | | *PDC SENSOR | Not Necessary | 737.60 FS | *- FS |
| 9 | 1 | | *(DG/SL) ADHESIVE SET K6 | Not Necessary | 53.05 FS | *- FS |
| Total Parts (S\$) | | | | | 2,535.90 | 1,189.10 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT | New | 1,275.00 | 850.00 |
| 2 | TO RESPRAY REAR BUMPER | New | 1,038.00 | 934.00 |
| 3 | TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION | New | 177.00 | 150.00 |
| 4 | TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION | New | 177.00 | 150.00 |
| Gross Labour Cost (S\$) | | | 2,667.00 | 2,084.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >