

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0175/18
DATE : 13-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : PANG LIM KWEE
ADDRESS : BLK 604 BEDOK RESERVOIR RD
#05-590
S(470604)
TELEPHONE NO : 93697270/90934751

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SJK1195M
MODEL CODE : BDUARCA11EHJ-----
MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (MC)
ENGINE NO : HR15032731B
CHASSIS NO : JN1BAAG11Z0106864
MILEAGE : 135400 KM
DATE IN : 13/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 12/03/2018

96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJK1195M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TRUNK LID & REAR BUMPER.	1300.00	750
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	1000
3	ZZ/003	TRANSFER TRUNK LID MECHANISM.	80.00	/
4	ZZ/004	RENEW REVERSE SENSOR.	55.00	✓
5	ZZ/005	APPLY SEALANT TO REAR PANEL.	100.00	X.
6	ZZ/006	PERFORM RUST PROOFING TO REAR PANEL.	120.00	X.
7	ZZ/007	SUPPLY REAR LICENCE PLATE.		
TOTAL LABOUR CHARGES			2855.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJK1195M

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		100.00 ?
2	REAR LICENCE PLATE <i>new</i>	RLP		60.00 *.
3	REAR PANEL <i>Repaired</i>	79110-EW000	438.70	+
4	L/R LAMP PACKING ?	26558-EW00A	17.60	?
5	R/R LAMP PACKING ?	26553-EW00A	17.60	?
6	L/R TRUNK LAMP <i>lit</i>	26555-EW01A	109.90	✓
7	R/R TRUNK LAMP <i>new</i>	26550-EW01A	109.90	+
8	REAR COMB LAMP LH <i>new</i>	26555-EW00A	219.80	+
9	REAR COMB LAMP RH <i>lit</i>	26550-EW00A	219.80	✓
10	CARPET-TRUNK FLOOR <i>new</i>	84902-EW01A	511.00	+
11	TRUNK LID INNER CENTRE FINISHER <i>new</i>	84966-EW00A	148.90	+
12	TRUNK TOP PLATE MASK <i>new</i>	84994-EW00A	4.20	✓
13	TRUNK TOP PLATE <i>Repaired</i>	84921-EW01A	192.00	✓
14	EMBLEM REAR SYLPHY <i>new</i>	84895-EW000	87.00	✓
15	EMBLEM REAR NISSAN <i>new</i>	84890-EW000	46.10	✓
16	WSTRIP-TRUNK LID <i>new</i>	84830-EW000	106.30	+
17	STRIKER-TRUNK LID <i>new</i>	84621-ED400	63.70	+
18	LOCK ASSY-TRUNK <i>new</i>	84631-EW000	112.00	+
19	TRUNK LID LOWER MLDG <i>lit</i>	84860-EW000	152.70	✓
20	TRUNK LID TOP MLDG <i>lit</i>	84810-EW005	270.60	✓
21	LID TRUNK <i>Repaired</i>	H430M-EX1MA	796.70	✓
22	SENSOR-REVERSE <i>new</i>	SENSOR		200.00 +.
23	REAR BUMPER REFLECTOR LH <i>new</i>	26565-EW00A	55.00	+
24	REAR BUMPER REFLECTOR RH <i>new</i>	26560-EW00A	55.00	+
25	REAR BUMPER MLDG <i>new</i>	85072-EW000	162.80	✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJK1195M

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
26	ENERGY ABSORBER REAR BUMPER ?	85090-EW000	37.00	>
27	REAR BUMPER SIDE BRKT LH free	85227-EW000	36.60	✓
28	REAR BUMPER SIDE BRKT RH	85226-EW000	36.60	✓
29	CLIP REAR BUMPER @ \$1.20 EACH are	01553-10501	7.20	✓
30	REAR BUMPER FASCIA Dehd	85022-EW025	660.60	✓
SUB TOTAL			4675.30	0.00 360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			935.06	0.00 0.00
GRAND TOTAL			3740.24	0.00 360.00
OVERALL TOTAL			4100.24	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJK1195M

TOTAL LABOUR CHARGES	2855.00
TOTAL SPARE PARTS CHARGES	4100.24

GRAND TOTAL	6955.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Adrian Lim	86893735.
SURVEYED DATE	:	07/05/18.	
AUTHORIZED DATE	:		
EXCESS CLAUSE	:	0.00	06 days.
LIABILITY	:	0.00	
REMARKS	:		

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.