



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2007778
INV Date 18/11/2020
Reference CC4/QBE18008234/Kea3q2
Code QBE



PROFESSIONAL SERVICE FEE

Vehicle No. YN 4782E
Insured Veh. WC 5370K
Claim No. V0008782
Policy No. 8-V0008782-MVA-R003
Accident Date 27/04/2018
Inspection Date 04/05/2018

Description	Total
Survey Inspection	300.00
Digital Photographs	
Transportation	
Subtotal	300.00
GST (7%)	21.00
Grand Total	321.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : V0008782

Date: 18th Nov 2019

Our Ref : CC4/QBE18008234/Kea3q2

M/s QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY #29-10

SOUTH TOWER

Singapore 048583

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YN 4782E
INSURED VEHICLE WC 5370K ACCIDENT ON 27/04/2018**

Instruction was received to inspect the vehicle Reg. No. YN 4782E. The inspection was conducted on 04/05/2018 at the premises of M/s Cheng Hoe Motor Pte Ltd, 38 Woodlands Industrial Park E1#05-04/05, Singapore 757700.

The following vehicle information was recorded:

Registration Number	: YN 4782E
Make/Model	: Mitsubishi Canter
Year of Registration	: 2014
Body Colour	: White
Chassis Number	: FEB21EA00310
Engine Capacity	: 2998 cc
Speedometer Reading	: -

The vehicle sustained damages at the front o/s portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	50,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	29,644.00)
Nett Liability	S\$	20,356.00
		=====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 4782E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

