

Hsiao Tong (LKKAuto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Thursday, 30 August 2018 11:24 PM
To: Hsiao Tong (LKKAuto)
Subject: Our Ref: 2541145077SG-003; mandate request

Hi Hsiao Tong

Referring to above.

Pls refer to our In-House comments on following:

1. Front Bonnet Lock Panel (No Photo)
2. Front Bumper Side Retainer (Not Damaged)
3. Front Bumper Inner Sponge (Not Damaged)
4. Front Bumper Reinforcement (Not Damaged)
5. Front Support Panel (Repair)
6. Front Support Panel Top Cover (Reuse)
7. Front Support Panel Top Cover Clips (No Needed)
8. Rear Boot Lid Center Chrome Moulding (Not Changed)
9. Rear Boot Lid Inner Lock (Not Damaged)
10. Rear Boot Lid Inner Rubber (Not Damaged)
11. Rear Tail Lamp (RH – Not Changed)
12. Rear Bumper Side Retainer (Not Damaged)
13. Rear Fender (Repair)
14. Rear Exhaust (Not Damaged)
15. Towing Fee (Tow Slip?)

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no

responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.