

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 14 September 2018 3:46 PM
To: Tan, Bennie-WZ (Bennie-WZ.Tan@aig.com)
Subject: RE: Our Ref: 2541145077SG-003; mandate request *LKK REF: CC6/AIG18008244/Apa3

Hi Bennie,

Kindly refer to the below for your perusal: -

| Particulars: | Remarks: |
|--------------------------------------|-----------------------------------|
| Front Bonnet Lock Panel | Photo 19 in Merimen |
| Front Bumper Side Retainer | Necessary Items |
| Front Bumper Inner Sponge | Photo 124, 125 in Merimen |
| Front Bumper Reinforcement | Photo 148 - 151 in Merimen |
| Front Support Panel | Photo 12 -14, 152 - 156 |
| Front Support Panel Top Cover | Photo 130 - 131 |
| Front Support Panel Top Cover Clips | Necessary Items |
| Rear Boot Lid Center Chrome Moulding | Photo 99 - 102 |
| Rear Boot Lid Inner Lock | Photo 49, 95, 96 |
| Rear Boot Lid Inner Rubber | Photo 42, 43, 112, 113 |
| Rear Tail Lamp | Photo 105 – 106 |
| Rear Bumper Side Retainer | Necessary Item |
| Rear Fender | Photo 61 - 71 |
| Rear Exhaust | Photo 164 - 173 |
| Towing Fee | Pending receipt from third party. |

Kindly let us have your mandate/ instruction on this matter after reviewing the matter.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Thursday, 30 August 2018 11:24 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Our Ref: 2541145077SG-003; mandate request

Hi Hsiao Tong

Referring to above.

Pls refer to our In-House comments on following:

1. Front Bonnet Lock Panel (No Photo)
2. Front Bumper Side Retainer (Not Damaged)
3. Front Bumper Inner Sponge (Not Damaged)
4. Front Bumper Reinforcement (Not Damaged)
5. Front Support Panel (Repair)
6. Front Support Panel Top Cover (Reuse)
7. Front Support Panel Top Cover Clips (No Needed)
8. Rear Boot Lid Center Chrome Moulding (Not Changed)
9. Rear Boot Lid Inner Lock (Not Damaged)
10. Rear Boot Lid Inner Rubber (Not Damaged)
11. Rear Tail Lamp (RH – Not Changed)
12. Rear Bumper Side Retainer (Not Damaged)
13. Rear Fender (Repair)
14. Rear Exhaust (Not Damaged)
15. Towing Fee (Tow Slip?)

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.