

Surveyor: AWK DOI: 31518 Date/Time: 31/5/18

Prc-assign / CCU / FTE



Insured Vehicle No. : G8D 6287E  
Name of Insured : SING COLO SURFACE PLU  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A : 27/4/18  
Is driver the owner? ( YES /  NO ) Nature of Accident :

Claim No. : SWM1800277202  
Policy No. : DMCVRN1701561A01  
Make / Model : TOYOTA  
Place of Accident : BUKIT PANJANG BANG RO

If NO, Driver Name / Age : Amin Rutilul OI GIA REPORT:  YES / NO ; TP GIA REPORT:  YES / NO  
Driver Tel No. : 97385249 (V/L:  YES / NO) Insured Liability : % Final ? Yes / No

SHC 2005 M



INSRS: \_\_\_\_\_  
WSP: CD66 boyang  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
<u>17/8</u> <u>AW</u>	<u>SACTOOSM X: G8D 6287E - X</u>	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	<u>After 3/9/18</u>
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>
	<b>RECEIVED 12 SEP 2018</b>	

PRELIMINARY ADVICE Date/Time: 17/5 Sent By: [Signature]

FINALIZATION Date/Time: 7-5-18 Confirm with: dumani Confirm by: AWK

Repair Cost: PP \$54,056.56 ( 3 days) Reduction: 3 % Email  Call

FINAL SETTLEMENT Date/Time: 7/9/18 Confirm with WUWAM Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : NIL If NO or B 28, Ass. Lia :

Repair Cost: WSP: \$54,340.50 0.00 ROLL BACK HIT TP.

Loss of Rental (LOR): \$534.00 (      days) x hit

Loss of Use (LOU): \$5 - ( \$ x      days)

Loss of Income (LOI): \$5100.00 ( \$50 x      days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search \$57.49

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/Independent)

Legal Cost \$5 -

Total: \$54,683.01 Global Sum SS:

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$54,683.01 Name 1: COMFORTBELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.) \$5 Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$5 Name 3: \_\_\_\_\_

**CLAIM SETTLE**  
17/9/18

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TR
- 3) Survey fee: 400

08/11/13  
 Survei Mr. Kalvin

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimasi: 100%  
 OD / TP N/S / TP RES / OD RES / EVA / INV / MV  
 To Insp Vehicle No: \_\_\_\_\_  
 di Work Shop ms \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No 0  
 Claims No  
 Sum Ins Unit: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDA Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: - % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 2005 M Yr Regn: 20 Dec 2017  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Ix2 cc 1600  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 38082 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMHLB41UMH4100080  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD Alloy or  
 Tyre Size: F: 205/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Michelin  
 Front 7 mm Rear 7 mm  
 R/Bal. 7 mm L/Bal. 7 mm  
 L/Bal. 7 mm D.O.A. 22/4/18 D.O.I. 3/5/18  
 Survey held at CDGE (Layang)  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Front.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/5/18	Check PIP # 405656 / 3 by (REQ: + 889.08 18%) CTZ PIP

Date/time, file Pass to?  : Prel. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/time, file Return to?  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech \_\_\_\_\_ (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS, SI \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Other \_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18008245/K1ea3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 07-05-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 6287E	Veh. Inspected	SHC 2005M
Policy No.	DMCVSN1701S61801	Coverage (\$)	0.00
Claim No.	SNM18D02272C02	Excess (\$)	0.00
Assign From		Assign Date	07/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/04/2018	Inspection Date	03/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Mei Kwan (LKKAuto)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Tuesday, 8 May, 2018 3:13 PM  
**To:** Mei Kwan (LKKAuto)  
**Subject:** RE: Direct Settlement - Accident Involving GBD6287E (OI : CAI - SNM18D02272C02) and SHC2005M (TP : LKK REF - CC3/CTI18008245/K1ea3) on 27/04/2018  
**Attachments:** leeSZ\_SNM18D02272C02-GBD6287E-LKKDirectSettlementAccidentLtr\_CLCR95.238.pdf; MSNH18057612-GBD6287E.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



**Disclaimer :**

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 7 May, 2018 6:44 PM  
**To:** Claims Dept of CTI  
**Cc:** Irene Tay; Lucas Lee; Joy Irene (LKKAuto); Asher Sng (LKKAuto); Hsiao Tong (LKKAuto); Admin A  
**Subject:** Direct Settlement - Accident Involving GBD6287E (OI : CAI - TBA) and SHC2005M (TP : LKK REF - CC3/CTI18008245/K1ea3) on 27/04/2018

**WITHOUT PREJUDICE**

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 2005M at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200206384E

Our Reference: **SNM18D02272/C02/5**

Date : **08 MAY 2018**

via Ordinary & Registered Mail

**SING SOLID SURFACE PTE LTD  
18 SUNGEI KADUT STREET 6**

**SINGAPORE 728863**

Dear Sir / Madam

**ACCIDENT INVOLVING GBD6287E AND SHC2005M ON 27 APRIL 2018  
ALONG BUKIT PANJANG RING ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC2005M** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd  
Attn : ASHER  
Ref : CC3/CT118008245/K1EA3  
Contact No : 68416051  
via Email : ASHER@LKKAUTO.COM

CC : Agent - (DR0683B) - SING SOLID SURFACE PTE LTD

F01/LKKDS-2013

ARC Repair TP(CLS0)1

**JOB CARD** Sales Order:

JC NO: 305155828

COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)	REGN NO: SHC2005M	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: I-40	DATE/TIME IN: 03.05.2018 09:40
	YR OF MANU: 2012.2017	TARGET DATE
	CHASSIS CODE: KMHLE41UMHU100080	COMPLETION DATE/TIME:

ARD NO.

JOB DESCRIPTION

ent Date: 27.04.2018  
 E: 3P 27.04.18

LABOR CODE

DESCRIPTION

PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ent Slip

Exit Pass

SHC2005M

JU CHINA

Vehicle No.:

SHC2005M

Service Advisor

Signature/Date

Name of Service Advisor

Date

To Service Reception upon collection

To be kept by Security Guard

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 2005M

DATE 3/5/2018 10:44

*Anna  
LKK  
JM*

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet ✓			\$ 1,526.00
	Bonnet Lock ✗			\$ 50.90
	Radiator Grille ✓			\$ 1,480.00
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Side Bracket ?		\$ 14.30	\$ 28.60
	<b>SUB TOTAL</b>			<b>\$ 4,850.80</b>
	<b>LESS 20%</b>			<b>\$ 970.16</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,880.64</b>
	Front Number Plate ✗			\$ 25.00 <b>Nett</b>
	Front No Plate Trim Cover ✓			\$ 30.00 <b>Nett</b>
				<b>\$ 55.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>500.00</del>
	Spray Painting Charge			\$ <del>400.00</del> <b>360</b>
	Tuff Kote			\$ <del>50.00</del> <b>20</b>
	<b>TOTAL LABOUR</b>			<b>\$ 1,010.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,945.64</b>

*Kaku' (11/11/14)  
3/5/18 1105 hrs.  
3 DYS.  
P/P  
Before Paint photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before painting
- To display estimate to customer
- Parts prices
- Third party
- No illegal
- Supplier
- is subject to

Acknowledged by  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 2005M

DATE 3/5/2018 10:44

MAKE :

MODEL : HYUNDAI i40

*Handwritten notes:*  
 ONMG  
 LKIC  
 JU

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet / <i>Det</i>			\$ 1,526.00
	Bonnet Lock <i>X sec</i>			\$ 50.90
	Radiator Grille / <i>cr</i>			\$ 1,480.00
	Front Bumper Cover / <i>cr</i>			\$ 1,052.20
	Front Bumper Sponge <i>X sec</i>			\$ 142.20
	Front Bumper Reinforcement <i>X sec</i>			\$ 526.10
	Front Bumper Bracket Top (LH/RH) <i>X sec</i>	\$	22.40	\$ 44.80
	Front Bumper Side Bracket <i>X sec</i>	\$	14.30	\$ 28.60
	<b>SUB TOTAL</b>			<b>\$ 4,850.80</b>
	<b>LESS 20%</b>			<b>\$ 970.16</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,880.64</b>
	Front Number Plate <i>X sec</i>			\$ 25.00 <b>Nett</b>
	Front No Plate Trim Cover / <i>cr</i>			\$ 30.00 <b>Nett</b>
				<b>\$ 55.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>560.00</del> <i>400</i>
	Spray Painting Charge			\$ <del>400.00</del> <i>360</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,010.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,945.64</b>

*Handwritten notes:*  
 Kaku (11/11/14)  
 3/5/18 1105 hrs.  
 3 Dgs.  
 P/P  
 Before Paint photo

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys are on a "without prejudice" basis
- No illegal modifications allowed
- Supplemental charges are subject to confirmation

Acknowledged by Repairer:  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 04.05.2018

## REPAIR ESTIMATE

Time: 16:06:54

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS: COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305155828  
 REGN NO : SHC2005M  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 20.12.2017  
 DATE/TIME IN : 03.05.2018 09:40  
 ACCIDENT DATE : 27.04.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-2164-G	I40V3 GRILLE ASSY-RADIATO	1	1,480.00 20.00 1,184.00
0002	04-01-0103-0572-A	I40VC PANEL ASSY-HOOD+	1	1,526.00 20.00 1,220.80
0003	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20 20.00 841.76

SUB-TOTAL : 3,246.56

## JOB NATURE

0000 L	FNP TRIM COVER	30.00
0001 L	PANEL BEATING- FRT.	400.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	360.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00

SUB-TOTAL : 810.00

TOTAL : 4,056.56

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6548 8156

Our Job Ref No : 305155828

Date : 04/05/18

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC2005M

Date of Accident : 27.04.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBD6287E  
###
2. The finalized amount shall be:
 


(a) Spare Parts after List discount		<u>\$3,246.56</u>
(b) Labour Charges	###	<u>\$810.00</u>
<b>Total for Part-By-Part Repair Cost</b>		<b><u>\$4,056.56</u></b>
(c) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		<u>                    </u>
Final Lumpsum Repair cost		<u>                    </u>

3. Estimated normal period for repairs: 3 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Kalvin

Date : 7/5/18

#### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18008245/K1ea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 13-09-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 6287E	Veh. Inspected	SHC 2005M
Policy No.	DMCVSN1701S61801	Coverage (\$)	0.00
Claim No.	SNM18D02272/C02/5	Excess (\$)	0.00
Assign From		Assign Date	03/05/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU100080	Colour	BLUE
Odometer	38082	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/04/2018	Inspection Date	03/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2005M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	DENTED	1,526.00	1,526.00
1	BONNET LOCK	SERVICEABLE	50.90	-
1	RADIATOR GRILLE	CRACKED	1,480.00	1,480.00
1	FRONT BUMPER COVER	CUT	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	SERVICEABLE	142.20	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	526.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER SIDE BRACKET @\$14.30	SERVICEABLE	28.60	-
	LESS 20% DISCOUNT		-970.16	-811.64
			3,880.64	3,246.56
<b>SPECIAL NETT ITEMS</b>				
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	FRONT NO PLATE TRIM COVER (SN)	CRACKED	30.00	30.00
			55.00	30.00
<b>LABOUR</b>				
	PANEL BEATING . .		560.00	400.00
	SPRAY PAINTING CHARGE.		400.00	360.00
	TUFF KOTE.		50.00	20.00
			1,010.00	780.00
<b>GRAND TOTAL</b>			<b>4,945.64</b>	<b>4,056.56</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,056.56</b>

Report Ref No. CC3/CT118008245/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.