

**COMFORT DELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 2005M

DATE 3/5/2018 10:44

MAKE :

MODEL : HYUNDAI i40

*Omni*  
*LHC*  
*JU*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>Det</i>			\$ 1,526.00
	Bonnet Lock <i>X sec</i>			\$ 50.90
	Radiator Grille <i>com</i>			\$ 1,480.00
	Front Bumper Cover <i>cut</i>			\$ 1,052.20
	Front Bumper Sponge <i>X sec</i>			\$ 142.20
	Front Bumper Reinforcement <i>X sec</i>			\$ 526.10
	Front Bumper Bracket Top (LH/RH) <i>X sec</i>	\$	22.40	\$ 44.80
	Front Bumper Side Bracket <i>X sec</i>	\$	14.30	\$ 28.60
	<b>SUB TOTAL</b>			<b>\$ 4,850.80</b>
	<b>LESS 20%</b>			<b>\$ 970.16</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,880.64</b>
	Front Number Plate <i>X sec</i>			\$ 25.00 <b>Nett</b>
	Front No Plate Trim Cover <i>com</i>			\$ 30.00 <b>Nett</b>
				<b>\$ 55.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>560.00</del> <i>400</i>
	Spray Painting Charge			\$ <del>400.00</del> <i>360</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,010.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,945.64</b>

*Kakar (11/11/14)*  
*3/5/18 1105 hrs.*  
*3 Dgs.*  
*P/P*  
*Before Paint photo*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary work to the approved work is subject to final approval by the insurance company

Acknowledged by Repairer:  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.