


SMRT Accident Vehicle Repair Estimates

China.

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB304T
 Ref. No : TAX/05/18/2006
 Reg. Date : 06/08/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LEE YONG KIANG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 02/05/2018 01:10:00 PM
 Accident Reported Date / Time : 02/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095846
 Special Instruction to ARC,if any :
 GBD5828B
 Prepared Date : 02/05/2018 03:41:53 PM



*Sebastian.
3/5/18.*

- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705747331

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 756.00	0.00
Total Material Charges	: 1,641.79	1,641.79
Other Charges	: 705.00	0.00
TOTAL	: 3,609.79	0.00
Lum Sum Total	: 3,600.00	0.00
No. of Repair Days	: 4.00	0.00 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 02/05/2018 05:07:51 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/05/2018 05:07:51 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	507.00	0.00 200
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✕
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 ✕
TO TRANSFER DOOR MECHANISM	120.00	0.00 ✕
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 ✕
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✕
TO REPLACE SUNDRY PARTS	100.00	0.00 ✕
TO WASH AND VACUUM	60.00	0.00 ✕
Total Other Costs	705.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>R</i>	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace <i>✓ NEC</i>	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>R</i>	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace <i>✓ NEC</i>	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>✓ NEC</i>	No
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace <i>X</i>	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								2,052.25	2,052.24	
TOTAL MATERIALS(Discounted)								1,641.79	1,641.79	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									