

INS. CASE OWNER:

CC 4/LPC1800 8261, Sebanz

LKK:
IDAC:

Surveyor:

Sebastian

DOI:

ASSIGNMENT

2/5/18

Date / Time:

3/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJK 9112A

Name of Insured:

TAN KAR BOON

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

2/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN AN MOON

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

1414/18/UP1 010584

Policy No.:

21700504099

Make / Model:

PERODUA

Place of Accident:

SJK TMS UE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLJ 77782



INSRS:

WSP:

Tel:

Liability:

RMKS:

world
Auto

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
9/5/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☒ ☐
	Others:	☐ ☐
PRELIMINARY ADVICE	Date/Time: 8/5/18	Sent By: Du
FINALIZATION	Date/Time: 10.10.18	Confirm with: Sophia
Repair Cost:	S\$ 3,500	(6 days) Reduction: 70 %
FINAL SETTLEMENT	Date/Time: 09.01.19	Confirm with: Sophia
Final Liability:	S\$ 100	(Agreed / Assessed) BOLA S/N No.: 28
Repair Cost:	S\$ 2,675.00	3 VET C.C. OLD AND
Loss of Rental (LOR):	S\$ -	(days)
Loss of Use (LOU):	S\$ 360.00	(\$ 60 x 6 days)
Loss of Income (LOI):	S\$ -	(\$ x days)
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	S\$ 0.00	
Medical:	S\$ -	
Disbursement:	S\$ -	(e.g. Tow/ Independent)
Legal Cost	S\$ -	
Total:	S\$ 3,037.00	Global Sum S\$:
FINAL PAYMENT	Date/Time: 09.01.19	Confirm with: Sophia
Payee 1:	S\$ 3,037.00	Name 1: WORLD AUTO PTE LTD
Payee 2: (Strike if N.A.)	S\$ -	Name 2:
Payee 3: (Strike if N.A.)	S\$ -	Name 3:

REF: **LPC**

ASSIGNMENT

From: _____ Date: **07052018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MYTo Inspect Vehicle No: **SLJ 7778Z**

at Workshop m/s

of:

Insured:

Policy No.:

Claims No.:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLJ 7778Z** Yr Regn: **27/12/2016**Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Shuttle**C.C. **1496**Colour: **Silver**

A/C: Insured / Std / NI / NA

Sp. Reading: **101714**

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: **185/60R15** **Pirelli**R: **11** **Rowelo**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 2/5/18D.O.I. 7/5/18

Survey held at

World Auto.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45 + 2,500 (RED + 5.95% 70%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18008261/Seb3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 07-05-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 9112A	Veh. Inspected	SLJ 7778Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/05/2018	Inspection Date	07/05/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 LEBI AVE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18008261/Seb3

Date: 08.05.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLJ7778Z

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.05.2018 at the premises of M/s World Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,456.00
Revised Estimate Amount	: S\$	3,522.00
"Check" Items Amount	: S\$	920.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
100 BEACH RD #19-00 SHAW TOWER
S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES000102

Date : 03/05/2018

Vehicle Num. : SLJ 7778Z (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 02/05/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID <i>R</i>		1,150.00
2.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) <i>✓ NEC</i>		- 100.00
3.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) <i>✓ NEC</i>		- 100.00
4.	1	REAR BUMPER <i>✓ Defam.</i>		- 1,200.00
5.	1	REAR BUMPER RETAINER RH <i>X</i>		180.00
6.	1	REAR BUMPER REFLECTOR GARNISH RH <i>✓ SCR</i>		150.00
7.	1	REAR BUMPER REFLECTOR LENS RH <i>✓ SCR</i>		190.00
8.	1	REAR BUMPER INNER FOAM - RH <i>?</i>		150.00
9.	1	REAR FENDER RH <i>R</i>		1,100.00
10.	1	REAR FENDER AIR GRILLE - RH <i>?</i>		150.00
11.	1	REAR TAIL LAMP - RH <i>?</i>		850.00
12.	1	REAR FENDER INNER TRIM COVER RH <i>✓ Defam.</i>		550.00
List TotalS\$:				5,870.00
20.00% Discount S\$:				1,174.00
				4,696.00
SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP <i>✓ NEC</i>	30	50.00
2.	1	REVERSE SENSOR <i>✓ DMG.</i>	200	280.00
3.	1	REAR FENDER INNER TRIM COVER CLIPS <i>✓ NEC</i>	30	50.00
Special Nett Total S\$:				380.00
LABOUR :				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				30 180.00
REMOVE & REFIT REAR WINDSCREEN GLASS				X 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
100 BEACH RD #19-00 SHAW TOWER
S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES000102

Date : 03/05/2018

Vehicle Num. : SLJ 7778Z (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 02/05/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REPLACE FENDER 1/4 GLASS	X	180.00
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	X	180.00
		TO DEACTIVE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.	X	380.00
		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.	X	380.00
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	800.	1,100.00
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)	600.	800.00
		Labour Total S\$:		3,380.00

E. & O.E.

Total S\$: 8,456.00

for WORLD AUTO PTE LTD

Sebastian
7/5/18.
- Imp Sun Repair.
- Question Mark Item
Photo.
- Photo After Paint
9003621
sebastianyong@lkkauto.com.

6 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD

100 BEACH RD #19-00 SHAW TOWER

S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES000102

Date : 03/05/2018

Vehicle Num. : SLJ 7778Z (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 02/05/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID <i>R</i>	1,150.00	
2.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) <i>✓ NEC</i>	- 100.00	88.60
3.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) <i>✓ NEC</i>	- 100.00	85.40
4.	1	REAR BUMPER <i>✓ Defam.</i>	- 1,200.00	1100.
5.	1	REAR BUMPER RETAINER RH <i>X NN</i>	180.00	
6.	1	REAR BUMPER REFLECTOR GARNISH RH <i>✓ SCR</i>	✓ 150.00	130
7.	1	REAR BUMPER REFLECTOR LENS RH <i>✓ SCR</i>	✓ 190.00	180.
8.	1	REAR BUMPER INNER FOAM - RH <i>X NN</i>	✓ 150.00	
9.	1	REAR FENDER RH <i>R</i>	1,100.00	
10.	1	REAR FENDER AIR GRILLE - RH <i>X NN</i>	✓ 150.00	
11.	1	REAR TAIL LAMP - RH <i>X NN</i>	✓ 850.00	
12.	1	REAR FENDER INNER TRIM COVER RH <i>✓ Defam.</i>	✓ 550.00	250.
List TotalS\$:			5,870.00	
20.00% Discount S\$:			1,174.00	
			4,696.00	

SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP <i>✓ NEC</i>	30	50.00
2.	1	REVERSE SENSOR <i>✓ DMG.</i>	200	280.00
3.	1	REAR FENDER INNER TRIM COVER CLIPS <i>✓ NEC</i>	30	50.00
Special Nett Total S\$:			380.00	

LABOUR :

WIRINGS CHECK AND RECTIFY WHERE NECESSARY

REMOVE & REFIT REAR WINDSCREEN GLASS

30 . 180.00

X 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES000102

Date : 03/05/2018
 Vehicle Num. : SLJ 7778Z (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 02/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REPLACE FENDER 1/4 GLASS	X	180.00
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	X	180.00
		TO DEACTIVE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.	X	380.00
		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.	X	380.00
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	800.	1,100.00
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)	600.	800.00
		Labour Total S\$:		3,380.00

E. & O.E.

Total S\$: 8,456.00

=====

for WORLD AUTO PTE LTD

Sebastian
 7/5/18.
 - Imp Sum Repair.
 - Question mark Item
 Photo.
 - Photo After Paint
 9003621
 sebastianyong@lkkauto.com.

6 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ashley

Celine Fong (LKKAUTO)

From: tgttan@worldauto.com.sg
Sent: Friday, 12 October 2018 4:20 PM
To: Celine Fong (LKKAUTO)
Subject: RE: OUTSTANDING FILES BY SEBASTIAN - VEHICLE NO. SLJ 7778Z

Hi Celine

Finalised COR \$2500 (LUMP SUM) and 6 days of repairs.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Sent: Thursday, 11 October 2018 2:20 PM
To: tgttan@worldauto.com.sg
Subject: RE: OUTSTANDING FILES BY SEBASTIAN - VEHICLE NO. SLJ 7778Z

Dear Sophia,

Lump sum \$2,500.00, 6 days

Please check.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tgttan@worldauto.com.sg <tgttan@worldauto.com.sg>
Sent: Tuesday, 11 September 2018 5:53 PM
To: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Subject: FW: OUTSTANDING FILES BY SEBASTIAN

Hi Celine

I think your boss chasing NAZ to finalise.

These matters are more urgent.

Is Naz finalising these matters as well.

If he is, better finalise these files first.

Thanks

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Thursday, 3 May, 2018 4:54 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/18/18/VP05/020584 DOA: 2/5/18 Request for Third Party Motor Claim Survey

Dear Catherine / Nivitha,

Kindly ignore previous email and refer to email below.

Please proceed to conduct a survey of the vehicle SLJ 7778Z on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Ainee31 [mailto:aine31@worldauto.com.sg]
Sent: Thursday, 3 May, 2018 4:06 PM
To: MT_Claim_SG
Subject: Request for Third Party Motor Claim Survey

07052018 @ 10.01am

Ainee veh in.

Sebastian

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLJ7778Z
Your Insured: SJK9112A
DOA: 02-05-2018

Our vehicle is currently in the workshop, address as follow;
AINEE
World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks a lot Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 64557576

Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 9 May 2018 9:46 AM
To: Shu Pei (LKKAUTO); ERIC WOO JUN KIAT; GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)
Subject: RE: Our Ref: 17/18/18/VP05/020584 DOA: 2/5/18 Request for Third Party Motor Claim Survey ***LKK REF:CC4/LPC18008261/Seb3
Attachments: SJK9112A 020518 (2).PDF

Dear Shu Pei

Please see our Insured's GIA report attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 8 May, 2018 6:40 PM
To: ERIC WOO JUN KIAT; GERALD POH WEE BIN; ONG LI LI
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)
Subject: RE: Our Ref: 17/18/18/VP05/020584 DOA: 2/5/18 Request for Third Party Motor Claim Survey ***LKK REF:CC4/LPC18008261/Seb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLJ 7778Z at M/s World Auto Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 7 May 2018 10:02 AM

To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 17/18/18/VP05/020584 DOA: 2/5/18 Request for Third Party Motor Claim Survey

Dear Eric,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Thursday, 3 May, 2018 4:54 PM

To: assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Our Ref: 17/18/18/VP05/020584 DOA: 2/5/18 Request for Third Party Motor Claim Survey

Dear Catherine / Nivitha,

Kindly ignore previous email and refer to email below.

Please proceed to conduct a survey of the vehicle SLJ 7778Z on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Ainee31 [<mailto:ainee31@worldauto.com.sg>]

Sent: Thursday, 3 May, 2018 4:06 PM

To: MT_Claim_SG

Subject: Request for Third Party Motor Claim Survey

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLJ7778Z

Your Insured: SJK9112A

DOA: 02-05-2018

Our vehicle is currently in the workshop, address as follow;

AINEE

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 64557576



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18008261/Seb3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 23-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 9112A	Veh. Inspected	SLJ 7778Z
Policy No.	Z17VP05014099	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020584	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	03/05/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GP71104112	Colour	SILVER
Odometer	101714	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	PIRELLI	6 mm
L/H Front Tyre	185/60 R15	PIRELLI	6 mm
R/H Rear Tyre	185/60 R15	ROVELO	6 mm
L/H Rear Tyre	185/60 R15	ROVELO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/05/2018	Inspection Date	07/05/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 7778Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,150.00	-
1	REAR BOOT HYBRID EMBLEM (SHUTTLE)	NECESSARY	100.00	88.60
1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	NECESSARY	100.00	85.40
1	REAR BUMPER	DEFORMED	1,200.00	1,100.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	180.00	-
1	REAR BUMPER REFLECTOR GARNISH RH	SCRATCHED	150.00	130.00
1	REAR BUMPER REFLECTOR LENS RH	SCRATCHED	190.00	180.00
1	REAR BUMPER INNER FOAM -RH	NOT NECESSARY	150.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,100.00	-
1	REAR FENDER AIR GRILLE -RH	NOT NECESSARY	150.00	-
1	REAR TAIL LAMP -RH	NOT NECESSARY	850.00	-
1	REAR FENDER INNER TRIM COVER RH	DEFORMED	550.00	250.00
	LESS 20% DISCOUNT		-1,174.00	-366.80
			4,696.00	1,467.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR FENDER INNER TRIM COVER CLIPS (SN)	NECESSARY	50.00	30.00
			380.00	260.00
<u>LABOUR</u>				
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	30.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	REMOVE & REPLACE FENDER 1/4 GLASS.	NOT NECESSARY	180.00	-
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.	NOT NECESSARY	180.00	-
	TO DEACTIVE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.	NOT NECESSARY	380.00	-
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,CUT/WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR FENDER RH .		1,100.00	800.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		800.00	600.00
			3,380.00	1,430.00
GRAND TOTAL			8,456.00	3,157.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC4/LPC18008261/Seb3n2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.