

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD

100 BEACH RD #19-00 SHAW TOWER

S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES000102

Date : 03/05/2018

Vehicle Num. : SLJ 7778Z (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 02/05/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID <i>R</i>		1,150.00
2.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) <i>✓ NEC</i>		100.00
3.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) <i>✓ NEC</i>		100.00
4.	1	REAR BUMPER <i>✓ Defam.</i>		1,200.00
5.	1	REAR BUMPER RETAINER RH <i>X</i>		180.00
6.	1	REAR BUMPER REFLECTOR GARNISH RH <i>✓ SCR</i>		150.00
7.	1	REAR BUMPER REFLECTOR LENS RH <i>✓ SCR</i>		190.00
8.	1	REAR BUMPER INNER FOAM - RH <i>?</i>		150.00
9.	1	REAR FENDER RH <i>R</i>		1,100.00
10.	1	REAR FENDER AIR GRILLE - RH <i>?</i>		150.00
11.	1	REAR TAIL LAMP - RH <i>?</i>		850.00
12.	1	REAR FENDER INNER TRIM COVER RH <i>✓ Defam.</i>		550.00
List TotalS\$:				5,870.00
20.00% Discount S\$:				1,174.00
				4,696.00

SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP <i>✓ NEC</i>	<i>30</i>	50.00
2.	1	REVERSE SENSOR <i>✓ DMG</i>	<i>200</i>	280.00
3.	1	REAR FENDER INNER TRIM COVER CLIPS <i>✓ NEC</i>	<i>30</i>	50.00
Special Nett Total S\$:				380.00

LABOUR :

WIRINGS CHECK AND RECTIFY WHERE NECESSARY

REMOVE & REFIT REAR WINDSCREEN GLASS

30 180.00*X* 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES000102

Date : 03/05/2018
 Vehicle Num. : SLJ 7778Z (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 02/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REPLACE FENDER 1/4 GLASS	X	180.00
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	X	180.00
		TO DEACTIVE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.	X	380.00
		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.	X	380.00
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	800	1,100.00
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)	600	800.00
		Labour Total S\$:		3,380.00

E. & O.E.

Total S\$: 8,456.00

=====

6 days.

for WORLD AUTO PTE LTD

Sebastian.
 7/5/18.
 - hump Sun Repair.
 - Question Mark Item
 Photo.
 - Photo After Paint
 9003621
 sebastianyeng@lkkauto.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: